Recommendation(s) Status: Person trapped in doors and pulled along platform at King's Cross Station

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into six categories:

Key	to	Recommendation	Status
-----	----	----------------	--------

Implemented:	All actions to deliver the recommendation have been completed.
Implemented by alternative	The intent of the recommendation has been satisfied in a way that was not identified by the RAIB
means:	during the investigation.
Implementation ongoing:	Work to deliver the intent of the recommendation has been agreed and is in the process of being
	delivered.
In-progress:	The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is
	in place to implement the recommendation; and work is in progress to provide this.

Non-implementation:	Regulation $12(2)(b)(iii) =$ recommendation considered and no implementation action to be taken.

Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the	
	recommendation.	

RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following:





The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

The white triangle shows recommendations where the RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Note: The tables which follow, report the status of recommendations on 31 December 2015. In some other cases the end implementer has already sent information to the relevant safety authority about the actions it has taken, or proposes to take and the safety authority is considering whether it is satisfied that those actions and the associated timescales are accepted.

Inv Title / Current Status from the relev	Summary of current status (based on latest report from the relevant safety authority or public body)	
Person trapped in doors and pulled along providing a modified door seal arrangement on Class 365 trains, that it has taken when the existing seals are replaced during the major overhaul ORR proposes to the term of term	ed that Eversholt Rail UK (Ltd) has reported actions in response to this recommendation. to take no further action unless they become information provided becomes inaccurate.	

seals require replacement before the scheduled date; and •make available to other train owners suitable and sufficient information for these owners to establish whether a similar approach should be considered for any of their train doors (paragraph 48).

Summary of ourrant status (based on latest r port ody)