ACCIDENT

Aircraft Type and Registration: Pegasus Quik Quik, G-CCOW

No & Type of Engines: 1 Rotax 912ULS piston engine

Year of Manufacture: 2004 (Serial no: 8008)

Date & Time (UTC): 31 July 2016 at 1000 hrs

Location: Atheys Airfield, Northumberland

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Pod, keel, roll bracket, nose plate, front strut

sleeve and spats

Commander's Licence: National Private Pilot's Licence

Commander's Age: 53 years

Commander's Flying Experience: 62 hours (of which 62 were on type)

Last 90 days - 5 hours Last 28 days - 0 hours

Information Source: Aircraft Accident Report Form submitted by the

pilot

The pilot and one passenger were taking off from grass Runway 26 for a local flight. The wind direction and speed was reported as "light easterly between 10 kt and 12 kt". The pilot stated that, as the aircraft became airborne, there was a sudden change in wind direction that resulted in the wing dropping to the right and the aircraft stalling, following which it turned through approximately 230° before impacting the ground near the side of the runway. The pilot and passenger were uninjured.

© Crown copyright 2016 60