

ACCIDENT

Aircraft Type and Registration:	Denney Kitfox Mk 2, G-BSUZ	
No & Type of Engines:	1 Rotax 582 piston engine	
Year of Manufacture:	1990 (Serial no: PFA 172-11875)	
Date & Time (UTC):	12 September 2016 at 1500 hrs	
Location:	Brimpton Airfield, Berkshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - 1 (Minor)	Passengers - 1 (Minor)
Nature of Damage:	Substantial	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	68 years	
Commander's Flying Experience:	123 hours (of which 13 were on type) Last 90 days - 14 hours Last 28 days - 8 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The pilot reported that, after a normal approach to Runway 25 at Brimpton Airfield, the aircraft bounced on landing, porpoised and overturned. Both occupants were able to leave the aircraft via its doors. Having recently purchased the aircraft, the pilot was undertaking conversion training with an instructor.