

BULLETIN CORRECTION

Aircraft Type and Registration:	Embraer EMB-505 Phenom 300, HZ-IBN
Date & Time (UTC):	31 July 2015 at 1408 hrs
Location:	Blackbushe Airport, Surrey
Information Source:	AAIB Field Investigation

AAIB Bulletin No 12/2016, page 34 refers

The above Field Investigation Report contained an error in the 'Survival aspects' section. The original text stated '*right side of the fuselage*' but should have stated '*left*'. The first sentence of this section should now read:

Due to the resting attitude of the fuselage, in which the cabin entry door was on the upper **left** side of the fuselage, the aircraft manufacturer was requested to calculate the cabin door opening forces for this condition.

The online version of the report was amended on 12 January 2017.