

ACCIDENT

Aircraft Type and Registration:	Denney Kitfox Mk 3, G-DJNH
No & Type of Engines:	1 Rotax 582 piston engine
Year of Manufacture:	1991 (Serial no: PFA 172-11896)
Date & Time (UTC):	14 April 2017 at 1250 hrs
Location:	Eshott Airfield, Northumberland
Type of Flight:	Training
Persons on Board:	Crew - 2 Passengers - None
Injuries:	Crew - None Passengers - N/A
Nature of Damage:	Impact damage to airframe
Commander's Licence:	Commercial Pilot's Licence
Commander's Age:	68 years
Commander's Flying Experience:	15,500 hours (of which 60 were on type) Last 90 days - 80 hours Last 28 days - 45 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The accident occurred during a training flight to practise go-arounds. As the student applied full power after touching down on the fourth go-around, the aircraft began to drift to the right. The instructor allowed the takeoff to continue, but the aircraft left the side of the runway, became airborne and then collided with trees. The weather was fine with a light headwind.