

BULLETIN CORRECTION

Aircraft Type and Registration:	Bombardier BD-700-1A11 (Global 5000), VP-CKM
Date & Time (UTC):	15 November 2016
Location:	On approach to Hong Kong International Airport
Information Source:	AAIB Field Investigation

AAIB Bulletin No 12/2017, page 60 refers

The report states incorrectly that the aircraft involved in the serious incident was a Bombardier Global Express BD700. The aircraft was a **Bombardier BD-700-1A11 (Global 5000)**.

The online version of the report was amended on 22 December 2017.