

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: RE: A120 Birchanger inspection 25-04-17
Date: 25 April 2017 18:06:27

All,
Please see defect numbers below in red.

Regards

[REDACTED]
NCC, Operational Controller, Area 6&8 ASC

Kier Services | Highways | RCC South Mimms, Potters Bar, Hertfordshire, EN6 3NP
[REDACTED]

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#) | follow us on [Google+](#) | follow us on [Instagram](#)
Our values are enthusiastic, collaborative and forward-thinking




Kier Highways Limited | Registered in England No. 5606089
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

From: [REDACTED]
Sent: 25 April 2017 15:05
To: [REDACTED]
Cc: [REDACTED]
Subject: A120 Birchanger inspection 25-04-17

Good afternoon.
Can we have job numbers for today's potholes please.

| Road | Direction | MP/ Location | Carriageway | Track | Site | Defect | Job number |
|------|-----------|-----------------------------|-------------|-------|------------------------------------|--|---------------|
| A120 | EB | Near top of slip | L2 | rw | Airport off slip | Pothole | 00568 |
| A120 | EB | 326 | L1 | Lwt | | Pothole | 00570 |
| A120 | WB | Onslip | | | Dunmow west off slip | Pothole | 00571 |
| A120 | WB | 270 | L2 | | | Pothole | 00572 |
| A120 | WB | Off slip, half way up | | rw | Takley off slip | Pothole | 00574 |
| A120 | WB | Top of slip road | | lwt | Takley off slip | Pothole | 00575 |
| A120 | WB | On slip by patch | | rw | Takley on slip | Pothole | 00577 |
| A120 | WB | 202 | L2 | rw | Airport on slip | Pothole | 00578 |
| A120 | WB | Priory Wood off slip | | | Between slip and carriageway | Multi potholes along white lines | 00580 |

Regards


Kier Highways | Unit 3000 | Cambridge Research Park | Waterbeach | Cambs | CB25 9PD
 

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#)

Kier Group plc | Registered in England No. 2708030
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

This email is sent on behalf of Kier Group. This email and any attachments are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the addressee, please do not use or publish its contents, please notify Kier Group on +44 (0) 845 505 2456 immediately and then delete it. Contracts cannot be concluded with us nor services effected by email. Emails are not secure and may contain viruses, you are advised to scan all messages for viruses with your own anti-virus programme. Kier Group may monitor emails.

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: RE: A120 safety inspection 02-05-17
Date: 02 May 2017 14:18:07

Incident numbers below

[REDACTED]
NCC, Operational Controller, Area 6&8 ASC

Kier Services | Highways | RCC South Mimms, Potters Bar, Hertfordshire, EN6 3NP
[REDACTED] www.kier.co.uk

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#) | follow us on [Google+](#) | follow us on [Instagram](#)
Our values are enthusiastic, collaborative and forward-thinking

Kier Highways Limited | Registered in England No. 5606089
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

From: [REDACTED]
Sent: 02 May 2017 13:09
To: [REDACTED]
Cc: [REDACTED]
Subject: A120 safety inspection 02-05-17

Good afternoon.

Could you detail job numbers for the following A120 defects and return to all please?

One defect for Ardleigh and ten for Birchanger

| Road | Direction | MP/ Location | Carriageway | Track | Site | Defect | Job number |
|------|-----------|-----------------|-------------------------------------|-------------------|------------------------------------|----------------------|-----------------|
| A120 | WB | Stisted | WB footpath | Footpath | Stisted junction to house | Multiple potholes | INC00764 |
| A120 | EB | 325/326 | L1 | LWT | | Pothole | INC00766 |
| A120 | WB | 457 | L1 | Gully surround | Cholesterol corner | Pothole | INC00767 |
| A120 | WB | 270 | L2 | RWT | | Pothole | INC00768 |
| A120 | WB | 190 | L1 main carriageway | LWT | At the start of the off slip | Potholes | INC00770 |
| A120 | EB | 216+50 | L1 | LWT | | Pothole | INC00771 |
| A120 | EB | Dunmow South | L2 Off slip | RWT | Halfway down slip | Pothole | INC00772 |
| A120 | WB | Panners | 1 st Panners off slip | RWT | Top of slip | Pothole | INC00773 |
| A120 | WB | Dunmow | Off slip | C/ Line | | Multiple | |

| | | | | | | | |
|------|----|----------------|------------|----------|------------|----------------------|-----------------|
| | | West | | | | potholes | INC00774 |
| A120 | WB | Dunmow West | On slip | LWT | Halfway | Pothole | INC00776 |
| A120 | WB | Priory Wood | Roundabout | C/ Lines | Around rbt | Multiple potholes | INC00777 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Regards



Kier Highways | Unit 3000 | Cambridge Research Park | Waterbeach | Cambs | CB25 9PD



www.kier.co.uk

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#)

Kier Group plc | Registered in England No. 2708030
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

From: [REDACTED]
To: [REDACTED]
Subject: RE: A120 inspection and defects for Birchanger
Date: 09 May 2017 17:02:10

Hi All,
As requested

Regards

[REDACTED]
NCC, Operational Controller, Area 6&8 ASC

Kier Services | Highways | RCC South Mimms, Potters Bar, Hertfordshire, EN6 3NP
[REDACTED] | [REDACTED] | www.kier.co.uk

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#) | follow us on [Google+](#) | follow us on [Instagram](#)
Our values are enthusiastic, collaborative and forward-thinking

Kier Highways Limited | Registered in England No. 5606089
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

From: [REDACTED]
Sent: 09 May 2017 14:07
To: [REDACTED]
Subject: A120 inspection and defects for Birchanger


Afternoon.

Could you raise job numbers for the following defects and return to all please?

Thank you

| Road | Direction | MP/ Location | Carriageway | Track | Site | Defect | Job number |
|------|-----------|--------------------|--------------|-------|--------------------|----------------------|---------------|
| A120 | WB | 303 | C/ res | | | Barrier hit | 00932 |
| A120 | EB | 217 – 50 | L1 | LWT | | Pothole | 00933 |
| A120 | EB | 226 | L1 | LWT | | Pothole | 00934 |
| A120 | WB | 392 | L2 | LWT | | Pothole | 00935 |
| A120 | WB | 265 | L2 | LWT | | Pothole | 00939 |
| A120 | WB | 215 | L2 | | | Pothole | 00940 |
| A120 | WB | 210 | L2 | RWT | | Pothole | 00941 |
| A120 | WB | 198 | L1 / L2 line | | | Pothole | 00943 |
| A120 | WB | 190 | L2 | | | Multiple Potholes | 00944 |
| A120 | WB | End of off slip | L2 | LWT | Priory Wood rbt | Pothole | 00946 |
| A120 | WB | On slip | L1 and L2 | | Priory Wood | Potholes | 00947 |
| | | | | | | | |
| | | | | | | | |

Regards


Kier Highways | Unit 3000 | Cambridge Research Park | Waterbeach | Cambs | CB25 9PD
Tel: 07860860286 | www.kier.co.uk

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#)

Kier Group plc | Registered in England No. 2708030
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

This email is sent on behalf of Kier Group. This email and any attachments are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the addressee, please do not use or publish its contents, please notify Kier Group on +44 (0) 845 505 2456 immediately and then delete it. Contracts cannot be concluded with us nor services effected by email. Emails are not secure and may contain viruses, you are advised to scan all messages for viruses with your own anti-virus programme. Kier Group may monitor emails.

From: [REDACTED]
 To: [REDACTED]
 Cc: [REDACTED] C
 Subject: INC01115, INC01119, INC01121, INC01123 - A120 POTHOLES
 Date: 16 May 2017 15:11:55
 Attachments: [INC01119.pdf](#)
[INC01121.pdf](#)
[INC01123.pdf](#)
[INC01115.pdf](#)

Hi all ,

Please find attached NCC incident log(s).

ATTENDANCE REQUIRED FOR THE BELOW POTHOLES

| Road | Direction | MP/ Location | Carriageway | Track | Site/ detail | Defect | Job number |
|------|-----------|--|-------------|-------|---|----------------------|---------------|
| A120 | EB | 219 | L1 | LWT | Brewers End | Pothole | 01115 |
| A120 | WB | Takley off slip | | | About halfway up the slip and also at the top of the slip | Multiple Potholes | 01119 |
| A120 | WB | 190 Priory off slip | | | Multiple locations at the start of the slip | Multiple potholes | 01121 |
| A120 | WB | 1 st Panners off slip | | | Multiple potholes at the start of the off slip | Multiple potholes | 01123 |
| | | | | | | | |
| | | | | | | | |

Regards

[REDACTED]
 NCC, Operational Controller, Area 6&8 ASC

Kier Services | Highways | RCC South Mimms, Potters Bar, Hertfordshire, EN6 3NP
 [REDACTED] | www.kier.co.uk

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#) | follow us on [Google+](#) | follow us on [Instagram](#)
 Our values are enthusiastic, collaborative and forward-thinking

Kier Highways Limited | Registered in England No. 5606089
 Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

| DamageId | IncidentDt | IncidTm | LocationDetail | IncidentTypeDescr | ResourceDescription | SecClassDescription |
|----------|------------|---------|---|--|---------------------|---------------------|
| 01119 | 16/May/17 | 14.63 | A120 WB TAKLEY OFF SLIP - About halfway up the slip and also at the top of the slip - MULTIPLE POTHOLES | MAIN CARRIAGEWAY DEFECT (E.G. POTHOLE, P | BRONZE DUTY AGENT | Pothole |

| DamageId | IncidentDt | IncidTm | LocationDetail | IncidentTypeDescr | ResourceDescription | SecClassDescription |
|----------|------------|---------|--|--|---------------------|---------------------|
| 01121 | 16/May/17 | 14.76 | A120 WB 190PRIOR OFF SLIP Multiple locations at the start of the slip - MULTIPLE POTHOLE | MAIN CARRIAGEWAY DEFECT (E.G. POTHOLE, P | BRONZE DUTY AGENT | Pothole |

| DamageId | IncidentDt | IncidTm | LocationDetail | IncidentTypeDescr | ResourceDescription | SecClassDescription |
|----------|------------|---------|---|--|---------------------|---------------------|
| 01123 | 16/May/17 | 14.90 | A120 WB 1ST PANNERS OFF SLIP MULTIPLE POTHOLE AT THE START OF THE OFF SLIP | MAIN CARRIAGEWAY DEFECT (E.G. POTHOLE, P | BRONZE DUTY AGENT | Pothole |

| DamageId | IncidentDt | IncidTm | LocationDetail | IncidentTypeDescr | ResourceDescription | SecClassDescription |
|----------|------------|---------|--|--|---------------------|---------------------|
| 01115 | 16/May/17 | 14.48 | A120 EB MP 21/9 L1 LWTBREWERS END - POTHOLE FILL REQUIRED | MAIN CARRIAGEWAY DEFECT (E.G. POTHOLE, P | BRONZE DUTY AGENT | Pothole |

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: RE: A120 and M11 potholes 22-05-17
Date: 22 May 2017 13:17:06

Causeway is not working at the moment – when it comes back we will let you know

[REDACTED]
NCC Operational Controller
[REDACTED]

From: [REDACTED]
Sent: 22 May 2017 12:07
To: [REDACTED]
Cc: [REDACTED]
Subject: A120 and M11 potholes 22-05-17

Good afternoon.
Can you raise some pothole numbers and reply to all please?

| Road | Direction | MP/ Location | Carriageway | Track | Site/ detail | Defect | Job number |
|------|-----------|-----------------|-------------|-------|--|---------|---------------|
| A120 | WB | Panners bump | L1 | | Panners interchange (depot aware) | Pothole | |
| M11 | SB | | | | | | |
| M11 | SB | 249 | L1 | LWT | Pothole in lane 1 bridge joint | pothole | |
| M11 | NB | 249 | L1 | | Potholes in first bridge joint LWT and RWT | Pothole | |
| M11 | NB | 249 +30 | L1 | | Potholes in second bridge joint LWT and RWT | Pothole | |

Regards

[REDACTED]
Kier Highways | Unit 3000 | Cambridge Research Park | Waterbeach | Cambs | CB25 9PD
[REDACTED] | www.kier.co.uk

Connect with us | follow us on [LinkedIn](#) | like us on [Facebook](#) | follow us on [Twitter](#)

Kier Group plc | Registered in England No. 2708030
Registered Office: Tempsford Hall, Sandy, Bedfordshire, SG19 2BD

This email is sent on behalf of Kier Group. This email and any attachments are confidential and intended solely for the use of the individual or entity to whom they

are addressed. If you are not the addressee, please do not use or publish its contents, please notify Kier Group on +44 (0) 845 505 2456 immediately and then delete it. Contracts cannot be concluded with us nor services effected by email. Emails are not secure and may contain viruses, you are advised to scan all messages for viruses with your own anti-virus programme. Kier Group may monitor emails.

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 06/06/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 19/06/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 27/06/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 04/07/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| DATE: 11/07/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | |
|---------------------|-----------------------------------|------------------------|------|----|----------------------------------|--------------|---------|
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | | FINISH TIME: 12:00 | | |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | ACTION TAKEN | INC No. |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | |
| | | | | | | | |

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 13/07/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 18/07/17 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| | | | | | | | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE - 25/07/2017 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:00 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | No Safety Critical defects found | | | |
| | | | | | | | | |

| DATE: 08/08/2017 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | |
|---------------------|-----------------------------------|------------------------|-------|-----------|--|--------------|---------|
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | | FINISH TIME: 12:00 | | |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | ACTION TAKEN | INC No. |
| A120 | Priory Wood to Marks Tey and back | E/B + W/B | | | One defect found see below. | | |
| A120 | 1585A120/370 | W/B | C/res | 27/5-25/9 | Blocked gulley tops in central res causing large amounts of water to build up. | | |
| | | | | | | | |

| Date: 15/08/2017 | | Inspectors: [REDACTED] | | | Route: BH01 | | |
|---------------------|----------------|------------------------|------|-----|----------------------------------|--------------|------------|
| Vehicle: [REDACTED] | | Start Time: 08:00 | | | 10:30 | | |
| Road | Link & Section | C/Way | Lane | M/P | Location & Defect | Action Taken | INC Number |
| A120 | | | | | No Safety Critical Defects Found | | |
| | | | | | | | |

| Date: 22/08/2017 | | Inspectors: [REDACTED]s | | | Route: BH01 | | |
|---------------------|-----------------------------------|-------------------------|------|--------------------|-------------------|--------------|------------|
| Vehicle: [REDACTED] | | Start Time: 06:00 | | Finish Time: 09:00 | | | |
| Road | Link & Section | C/Way | Lane | M/P | Location & Defect | Action Taken | INC Number |
| A120 | Priory wood RBT-Marks tey EB & WB | EB&WB | | | No defects found | N/A | |
| | | | | | | | |

| Date: 29/08/2017 | | Inspectors: [REDACTED] | | | Route: BH01 | | |
|---------------------|-----------------------------------|------------------------|------|--------------------|-------------------|--------------|------------|
| Vehicle: [REDACTED] | | Start Time: 14:00 | | Finish Time: 17:00 | | | |
| Road | Link & Section | C/Way | Lane | M/P | Location & Defect | Action Taken | INC Number |
| A120 | Priory wood RBT-Marks tey EB & WB | EB&WB | | | No defects found | N/A | |
| | | | | | | | |

| Date: 12/09/2017 | | Inspectors: [REDACTED] | | | Route: BH01 | | |
|---------------------|--|------------------------|------|--------------------|----------------------------------|--------------|------------|
| Vehicle: [REDACTED] | | Start Time: 10:30 | | Finish Time: 14:00 | | | |
| Road | Link & Section | C/Way | Lane | M/P | Location & Defect | Action Taken | INC Number |
| A120 | Priory wood RBT to Prince of wales RBT EB & WB INC Slips | | | | No safety critical defects found | | |
| | | | | | | | |
| | | | | | | | |

| | | | | | | | | |
|---------------------|----------------------------|------------------------|------|--------------------|----------------------------------|--|--------------|---------|
| DATE: 19/09/2017 | | INSPECTORS: [REDACTED] | | | ROUTE: BH01 | | | |
| VEHICLE: [REDACTED] | | START TIME: 10:00 | | FINISH TIME: 12:30 | | | ACTION TAKEN | INC No. |
| ROAD | LINK & SECTION | C/WAY | LANE | MP | LOCATION / DEFECT | | | |
| A120 | From Stansted to Marks Tey | | | | No safety critical defects found | | | |
| | | | | | | | | |

| INSPECTION | | | | | | MAKE SAFE / REPAIR | | |
|---------------------|----------------|------------------------|------|--------------------|--|---------------------------------------|---------|----------|
| DATE: 28/11/2017 | | INSPECTORS: [REDACTED] | | ROUTE: BH01 | | CREW NAMES: | | |
| VEHICLE: [REDACTED] | | START TIME: 08:30 | | FINISH TIME: 12:00 | | | | |
| ROAD | LINK & SECTION | CW | LANE | MP | LOCATION / DEFECT | ON-SITE ACTION TAKEN & MATERIALS USED | TIME ON | TIME OFF |
| A120 | 1500A120/300 | EB | 1 | 20/3+20 | Pothole - L1 LWT | | | |
| A120 | 1500A120/311 | EB | 1 | 22/3 | Pothole - L1 | | | |
| A120 | 1500A120/565 | WB | 1 | 41/5-20 | Pothole - The usual suspect at Panners | | | |
| A120 | 1500A120/370 | WB | 2 | 26/2-40 | Pothole - L2 LWT | | | |

| INSPECTION | | | | | | MAKE SAFE / REPAIR | | |
|---------------------|-------------------------|-------------------------|------|--------------------|------------------------------|---------------------------------------|---------|----------|
| DATE: 28/12/2017 | | INSPECTORS: [REDACTED]s | | ROUTE: BH01 | | CREW NAMES: | | |
| VEHICLE: [REDACTED] | | START TIME: 08:30 | | FINISH TIME: 12:00 | | | | |
| ROAD | LINK & SECTION | CW | LANE | MP | LOCATION / DEFECT | ON-SITE ACTION TAKEN & MATERIALS USED | TIME ON | TIME OFF |
| A120 | Priory wood - Marks tey | EB & WB | 1&2 | | No safety defects identified | | | |

