NMM Changes log for Version 1.8 July 09

Part Number	Description of change
0	 Table of contents page changed to include 11.6 Road Safety Data Types & their Uses as per AMM 107/09. AMM table updated with entries for AMMs 103/08 to 106/08 and 107/09 to 109/09 inclusive and to reflect that AMM 97/08, 98/08 and 101/08 have been replaced. Modifications to Glossary table consequential to revisions in Part 7 on the HA Road Death Investigation Guidance. Slight amendments within Acronym for SSR, TO and NetServ. Addition of acronyms for DDA, MSU, POPE, PQ, TRL and VM, consequential of AMMs 107/09 and 108/09. Replacement of acronym MLC with MCC (Mobile Carriageway Closure) Addition to Definitions regarding Road Safety Partnership, Wider Road Safety Partnership and Safety Camera Partnership.
1	 Paragraphs 1.3.6.2, 1.3.6.3 and IAN entry within Table D of 1.5 updated to correctly cross reference with IAN 105/08. (Issue 209) Gathering of Supply Chain Incident Data included at 1.6, with paragraphs 1.6.3 and 1.6.4 being re-titled and amended, as detailed in AMM 105/08 (Issue 208)
2	Minor edits to Contents to correct headings for 2.6.1 to 2.6.4
3	 Erroneous reference to Annex 3.7.1 deleted from Contents page Chapter 3.5 updated to take account of AMM 104/08. (Issue 207) Chapter 3.7.2 updated to include ref to BS 7669-3 and references to maintenance (Issue 211) Paragraph 3.16.3 Maintenance Requirements deleted from chapter 3.16 Retained Litter Clearing Duties to prevent duplication with requirements for footway and cycle tracks specified in 3.14 Sweeping and Cleaning and Routine & Winter Service Code. (Issue 156)
4	 Document wide: initial capitalisation of Road Safety Partnership, Wider Road Safety Partnership and Safety Camera Partnerships. Guidance inserted at Chapter 4.1.3 concerning Mobile Carriageway Closures Chapter 4.4.3 amended to include cross reference to MDCHW Volume 2 (IAN 113/08 has now been incorporated) (Issue 203) Chapter 4.4.7 amended to update the team to NetServe.
5	 Dates for Service Provider's submission of and Service Manager's comment on Severe Weather Plan amended at 5.2.1 to agree with AMM 109/09. Severe Weather Template 2009/10 included at Annex 5.2.1 as per AMM 109/09.
6	 Chapter 6.3 Minor changes to show correct revision date for 'Provision of Temporary Traffic Signs to Special Events" policy (Issue 198) Chapter 6.5 Abnormal Load Routing and Management updated to include policy issued under cover of AMM 106/08. (Issue 200) Annex 6.1.4 amended to include cross references to IAN 113/08 as instructed by CHE 226/08 (Issue 203) Annex 6.5.1 6.5.2 and 6.5.3 inserted to show Abnormal Indivisible Load Special Order Processes (Issue 200)
7	 Modified 7.11 to account for new livery instructions (Issue 196) New guidance inserted at 7.16 <i>Incident Investigation</i> consequential to the update of the Road Death Investigation Manual 2007 and Highways Agency's Road Death Investigation

	 Manual Guidance. Other aligned, minor changes, at 7.2, 7.4.7, 7.7 and 7.15.1. (Issue 197) E-mail for CCTV Services Team corrected within <i>Use of non-standard CCTV</i> chapter at 7.19.6. (Issue 190) Errors corrected within <i>Service Provider Contingency Plan Model Document</i> at Annex 7.8.12. Formatting changes made to improve readability and some minor paragraph numbering issues. (Issue 194) Amendments made to Chapter 7.17 to include cross-reference to <i>Managing and Identifying Canine Fatalities Form</i> included at Annex 7.17.1 (issue 205) Updated Section 7.11.7 to reflect new name for Preview Graphics Ltd (Issue 212)
8	No change
9	No change
10	 Amendment to paragraph 10.2.5 concerning Value Management as per AMM 108/09 and updated to refer to PAR 5. Cross reference to new chapter 11.6 inserted at 10.3.4.
11	 Next chapter inserted at 11.6 titled Road Safety Data Types & their Uses as per AMM 107/09.