R9/2/6081

UNEXPLODED BOMB REPORT

For Official Use Serial No. BM/ N.A. 18

TO REGIONAL/DISTRICT HEADQUARTERS	Serial No. BM/ N.A. 18	
PART I		
1. EXACT LOCATION L.M. S. Railway Good	is Upral : Pauloy St.	
Tim	e of falling Hot Known Date 3-1	
2. FHASE AFFECTED (Strike out (a) Industrial Was		
where not (b) Communication	s or P.U. Services	
applicable) (e) General Indus	try	
(d) Civil Populat	ion	
3. STATE (a) Diameter of Hole of Entry	(b) Estimated size 50 kg	
(c) Type of Ground .	(d) Reasons for sus-	
(e) Proximity of (i) Buildings	(ii) Gas Mains	
(iii) Water Mains	(iv) Electricity Mains	
(v) Telephone	(vi) Sewers	
4. IF ON RATEWAYS STATE PROXIMITY OF (a) Rumning	g Tracks (b) Cuttings	
(c) Embarkments (d) Railway over		
5. DESCRIBE (a) Any Part of Bomb if exposed:	· · · · · · · · · · · · · · · · · · ·	
(b) any portion of Bomb found anywh	era	
(c) Colour & Markings found on any		
G. STATE where any portions of Bomb may be coll-		
7. ANY SPECIAL REMARKS (Restrictions imposed, etc	0.)	
Libritted for re abandannen	Signed	
der it opendowner	Rank Roll.	
	service Jone Clas &	
SUGGESTED BOYES CATEGORY Sighed	AD THE	
Designation		
For Group/Burgi	n or County Controller.	



To:- Mome Office, Explosives Department, Ref:- 3.18 London, S.W. 1.

Subject: - Final Clearance of UXB Incidents. Date: 34st July 52.

to Reference Report received from _____ 9 Region_ R9/2/6081 - N.A. 18 deted 15th April 1952 reference old abandoned bomb 10 L.M.S. Goods Yard, Lawley Street, Birmingham. 20 This incident is: Remarks Authy:- Home Office, Expl. Dept. XPC131/9/6 - 122/36/9, dated 15th July 1952.

Broadbridge Heath, Nr. Horsham, Susser,

Tele. Broadbridge Heath 182, Ext. B.

Major RE. HQ BD Unit (UK) RE.

Copy Go:- Chief Constable, City Police Headquarters, Birmingham.

Appreciation by Lieut. Goods Yard, Lawley Road, Birmingham.

of incident at L.M.S.Railway

Object. To determine whether or no this incident could be successfully re-opened.

Factors. 1. This incident was never excavated for. It passed through the top arch of large culvert under yard into river Rea.


- 2. No signs of entry hole now visible. Hole was filled in and new reinforced comcrete yard laid.
- 3. Mr Alcroft, Rates Clerk, states Culvert was emptied and searched but no further trace could be found of missile. Entry hole approx 12-14" diameter presumably 50 Kg.
 - 4. Exact position now not known.

Courses open.

Abandon.

23/3/45

Lieut. R.E.



SW

Subject: Finel Clearence of IKB incidents.

Ref: 3.18

Hate: 26th July 52.

122/36/9 Our ret XPC 131/9/6 Room 35, HOME OFFICE,

> EXPLOSIVES BRANCH. WHITEHALL.

> > LONDON, S.W.I

15th July, 1952.

Dear

UXB. Lawley Street Goods Station Birmingham.

I return herewith duly endorsed on behalf of the Secretary of State for the Home Department, two copies of the proforma showing record of further work on the above incident which is now to remain abandoned.

One copy has been sent to the Principal Officer, Home Office Civil Defence Region, Birmingham, for transmission to the Corporation of Birmingham, and one copy has been retained in this Department for record purposes.

HEAD ARTERS sincerely,

2 2 JUL 1952

BOMD L OSAL UNIT

(U.K.) R.E.

Major M.B.E., Headquarters, B.D. Unit (U.K.) R.E.,

Broadbridge Heath Camp.

near Horsham. Sussex.

Sonior Regional Officers

Home Office, Civil Defence, Midland Regional Office, Daimler House, Paradise Street. Birmingham, 1.

Herewith Part IV of U.B Roport No.

for your information and retention.

HQ BD Unit (UE) RE Broadbridge Heath Nr. Horsham, Sussex,

for Contain RE

Tele. Broadbridge Heath 182. Ext. 8 .

ENCLS :-

To be attached to the Final Abandonton's Form in respect of the following insidents:

BERIAL HUMBER (a) BD Serial No. R9/2/6081
(b) Regional Serial No. N.A. 18 (dd ho. 3790)

- 2. LOCATION L.M.S. Goods Yard, Lawley Street, Birmingham.
- ABANDONAGHT ROPM: Corporation of Birmingham.
- A. RECORD OF FURTHER WORK CARRIED OUT:

Reconnaissance carried out in 1949.

5. REASONS FOR FINAL DEGISION TO ALLOW MISSILE TO REMAIN ABANDONED:-

Previous recce reports indicate that no useful purpose would be served in trying to find this missile.

(a) Signature of Ala Pagin ED Unit (UK) NE / April 1952. Major, RE

(b) Signature of Regional
Authority

(c) Recommended by Commander
Disposal Unit (UK) PE 28th April 1994.....

6. APPROVED ON BEHALF OF THE SECRETARY OF STATE I'VE THE.

Date 13.6.52

RECORD OF FURTHER WORK ON FURNIN -PANDONA TOR PARCED POND SHELL INCIDENTS WITCH ARE TO RELVIN A APPUADO

To be esteemed to the Final Abenduered Form in Trapat of the following incidents -

. SERIAL NUMBER- (a) BO Serial No. R9/2/6081

(b) Regional Serial No. . N.A. 18 (bld ho. 3190)

- 2. LOCATION L.M.S. Goods Yard, Lawley Street, Birmingham.
- 3. LOCAL AUTHORITY HOLDING THE FINAL ABANDONMENT FORM: Corporation of Birmingham.
- L. RECORD OF FURTHER WORK CARRIED OUT :-

Reconnaissance carried out in 1949.

5. REASONS FOR FINAL DEGISION TO ALLOW MISSILS TO REMAIN ABANDONED:

Previous recce reports indicate that no useful purpose would be served in trying to find this missile.

Signature of Field Decinco (a) ED Unit (UE)

(b) Signature of Regional Authoraty overcessessesses

(o) Recommended by Sandor Book Disposal Unit (E) 28th April 1952.

S. APPROVED ON BEHALF OF THE SECRETARY OF STATE FOR THE HOME DEPARTMENT

RR - OPENED OLD ABANDONED BORB.

Subject: UKB Report.

Refa 3.5

To: Field Engineer, BD Unit (UK) RE. Date: 15th April 1952.

The following information regarding a suspected UXB has been received by this Headquarters. Please carry out a Rece of the incident. Your completed Reace Report Proforms should be forwarded to this office when the job is completed.

Logs 1000 Loss R	A. 18	ana Unit No.	R9/2/6081	consept Medicines accoming for each square of the finance special states. The
Map Reference	AND ADDRESS OF THE PARTY OF THE	, B'hem City		Dept.
And the first side of the property of the second of the se	inde at Constitution and approximate so to the second seco	1.0 TO a MO a management		BBT (4.487) - 6 EV 1974 (2.995) (1.975 (2.985) (1.975 (2.985) (1.975 (2.985) (1.985) (1.985) (1.985) (1.985)
Diameter of the ho		y 5 registrate executive transcense enterior	ggert engeluggskannskabetabringhatutusswere	en andre super expression andre experience describes and superior of a second
				ion. PR

HQ BD Unit (TM) RE, Broadtridge Heath Camp, Nr. Horsham, Sussex.

for ...mander.

Tale, Broadtraine heath 182 Est. 8.

Copies to:

Home Office, Civil Defence,
Midland Region,
Daimler House,
Paradite Street,
Birmingham 1.

RECCE REPORT.

Incident No. 3790.

at Railway Goods Yard, Lawley Road, Birmingham. MR 72/539076.

Object: To investigate the possibilities of reopening this incident.

Local Contacts.

Birmingham City Surveyors Department. Railway Engineers Department.

Factors.

- 1. A missile penetrated the roof of the South culvert at a distance of 150 yards from the West entrance, but did not penetrate the culvert invert.
- Estimated size 50 Kg.
 Date of falling 3 December 1949.
- 3. The culvert has been twice searched by B.D. parties with no result.
- 4. This culvert takes the flood water of the River Rea, which in the rainy seasons flows through the culvert with considerable force.

Conclusions.

- 1. That a missile entered the culvert, but did not penetrate the
- 2. That the missile has been swept downstream by the strong flow of water.

Recommendations.

That the incident remain abandoned.

Date of Recce:

9th August 1949.

Lifeut. R.E.

Major R.E. Officer Commanding 9 Bomb Disposal Squadron R.E.

Longview Lane, HUYTON, Liverpool. WFD/SK.

INCIDENT No 3790 LOCATION: - RAILWAY GOODS YARD, LAWLEY ROAD, BIRMINGHAM. NOT TO SCALE DISTANCES BY PACING M.R. 72/539076 GOODS OFFICES PARKING AREA. LANDOR STREET 4.5. 12/8/49 O INCIDENT . 6.

INCIDENT Nº 3790 LOCATION: - RAILWAY GOODS YARD, LAWLEY ROAD, BIRMINGHAM. DISTANCES BY PACING NOT TO SCALE M.R. 72/539076 GOODS OFFICES" PARKING AREA. LANDOR STREET 1 2 12/8/49 O TNCIDENT

To: Officer Commanding, 9 Bomb Disposal Coy. R.E.

From:-

R.E.

Subject:- Recce of Previously Abandoned W.X.B. at Lawley Street Goods Station In Culvert River Rea.

- 1. Reference my report dated 23 May 45, a further recce was made this morning.
- 2. The entry hole was discovered in the right hand culvert (from the Upstream Entrance looking downstream) about 50 yards from the entrance. The entry hole has been shuttered to allow concreting to be done in Railway Yard above.
- A mark of some object striking the bed of the Cultert, but not penetrating was found immediately below this shuttering. This mark was approximately 10" to 12" across, and it might be suggested that it bore evidence to what might be expected had a 50 Kg U.X.B. struck the bed of the cultert after penetrating the roof and passing through shallow water.
- A complete search of the culvert was made but there is definitely no U.X.B. present, nor could any marks be found to suggest detonation, shrapnel or ricichet.
- 5. Enquiring showed that this storm culvert has also been cleaned out twice since the incident occurred.
- 6. It is suggested that the missile has been carried downstream in flood waters, and as I was assured that the whole length of River has been cleared to the River Mouth at Fort Dunlop very recently, further search would appear impractible.
- 7. Final abandonment is suggested.

Recce Officer, No. 9 Bomb Disposal Coy. R. E.


25 May 1945.

From: - Lieut

R. E.

Subject:- Recce of Previously Abandoned U.X.B. at Lawley Street Goods Station In culvert, River Rea.

- 1. As instructed, a Recce of this incident was made on Tuesday 22nd May 1945.
- 2. I contacted Mr Griffiths of the Birmingham City Surveyors Department, who met me on the site in company with the Rivers Department Overseer, Mr Whitehead, and local River Ranger. The Railway Surveyor and Engineer was contacted later.
- The River is culverted normally in the centre, with two overflow, or storm culverts, one on each side of the main. At each end of the Culverts which are approximately 450 yards long, there is a dam arrangement to enable N.F.S. to have sufficient depth of water for pumping. Water can be diverted into one or any of the culverts at the entrance upstream. I was informed that in the event of heavy rain or thunderstorms, it is dangerous to be in the culverts and at all times a lookout man must be posted to inform any working parties to leave the culverts on any rise of level.
- 4. The bomb apparently entered one of the culverts about 60/70 yards from the upstream entrance. I examined the roof of the centre culvert for a distance of 350 yards but no entry hole was apparent. Some difficulty was experienced by deep water and mud with objects drifted down causing obstacles below the water surface. Accordingly I arranged with Mr Griffiths to be present on Friday next at 0930 hrs when the downstream dams will be removed thus making the water in the culverts more shallow.
- 5. All three culverts will be scrutinised on this occasion, and watch will be kept at the downstream entrance in case the bomb may wash down on the removal of the dam boards. The culverts have not been cleaned or inspected since 1938 and the possibility must be borne in mind of a ricochet inside the curved brick floor of the culvert and the subsequent rolling of the bomb into the mud and obstacles at the downstream end of the culvert.
- 6. A 6 foot sump is situated in the centre culvert approximately 100 yards from the upstream entrance and the posibility of the bomb rolling into this sump was considered possible by the Railway Engineer. As this sump is understood to be covered over with steel doors, I consider this possibility to be unlikely, but a definite negative cannot be given until the steel doors have been examined, it is hoped that this may be possible on Friday next if the water flow can be diverted from the centre culvert on that day.
- 7. I was accompanied on this Recce by Corporal 1 and I have made arrangements for the same N.C.O. to be with me on Friday next with 2 Sappers.
- 8. The position would appear as below.
 - (a) If the bomb has entered the roof and not the floor of the culvert, then the silt and mud must be examined downstream.
 - (b) If an entry hole is apparent in the fllor of any culvert, then excavation is possible because the water can be diverted, this is more easily achieved if the incident is situated in the side culverts.
 - (c) This work cannot be done in winter or during a heavy rain period owing to the danger of high water.



1. Location: - Lawley Street Goods Station, BIRMINGHAM.
2. Local Authority: Corporation of Birmingham.
3. Serial No.:- 3790
4. Map Reference: - 72/539076
Bomb Data 6. Estimated size of Bomb: - 50 Kg 5. Contacts: - B'ham City Surveyors Dept. 6. GOOD S OFFICES OFFICES
7. Estimated nil Depth:- 8. Date & Time of
fall:-3 Dec'40
Technical Data
9. Review of Incident by B.D.Officer - Date 23 May 45 & 25 May 45
Officer of 9 B.D.Coy.R.E. recce'd this incident on 5 Dec 40 & reported it as possible U.X.A.A. penetrated Culvert into River Real Decided then unnecessary to take any further action.
any further action.
10. Record of work carried out by B.D. Unit: Recce made on 25 May 45 disclosed that object penetrating Culvert had struck and slightly damaged invert but not penetrated it. Search of Culvert shewed that no missile was lodged anywhere and it is assumed that storm and flood waters had carried away the bomb or shell.

11. Result of work by B.D.:
N. T I
12. Final Decision:
To remain abandoned as there is now no missile apparent:

Date: - 18 th huly 46. Signed Water P. F.
, major N. L.
O. C. Mar Q. Romb Dismosal Cov. R. E.
FINAL ABANDONMENT
PECOMORNORD
APPROVED
HOME OFFICE.
