



Lindsey Booth-Huggins  
By email only

**E.ON Climate & Renewables UK**  
**Rampion Offshore Wind Ltd**  
Westwood Way  
Westwood Business Park  
Coventry  
West Midlands  
CV4 8LG  
[www.eon-uk.com/rampion](http://www.eon-uk.com/rampion)  
Eleri Owen- Consents Manager  
[eleri.owen@eon.com](mailto:eleri.owen@eon.com)

**3<sup>rd</sup> October 2014**

**The Rampion Offshore Wind Farm Order 2014 (Order)  
Correction to Schedule 13**

Dear Lindsey,

I would like to notify you of a drafting error in the Rampion Offshore Wind Farm Deemed Marine Licence – array (Schedule 13 of the Rampion Offshore Wind Farm Order 2014).

An error in the co-ordinates number was noted in the DCO and deemed Marine Licence when issued on 16<sup>th</sup> July 2014.

During the examination, it was agreed that an exclusion zone for wind turbine generators and offshore substations would be included within the Order, and the Deemed Marine Licence – array was updated to reflect this as follows:

Schedule 13, Part 2 - Conditions, Design Parameters

1. - (5) *No wind turbine generator or offshore substation forming part of the authorised scheme shall be erected within the area hatched black on the works plan (the “exclusion zone for wind turbine generators and offshore substations”), whose coordinates are specified below-*

<i>Point</i>	<i>Latitude (DMS)</i>	<i>Longitude (DMS)</i>
3	50° 40' 39.19 N	000° 04' 26.23 W
4	50° 39' 31.72 N	000° 01' 28.06 W
5	50° 38' 34.92 N	000° 09' 02.89 W
19	50° 41' 23.11 N	000° 20' 37.74 W

It has been noted that the coordinates provided for point 19 are incorrect, and that, in fact the following table of co-ordinates should be used (correcting the co-ordinates for Point 19):

<i>Point</i>	<i>Latitude (DMS)</i>	<i>Longitude (DMS)</i>
3	50° 40' 39.19 N	000° 04' 26.23 W
4	50° 39' 31.72 N	000° 01' 28.06 W
5	50° 38' 34.92 N	000° 09' 02.89 W
19	50° 40' 55.07 N	000° 05' 50.01 W

This correction has been notified to the Secretary of State with regards to the Main Order, and accepted. However, it is understood that any variation to the Deemed Marine Licence is to be notified to the MMO.

I would be grateful if the MMO could confirm that this correction is accepted, and also when the correction notice would be formally provided.

Should you require any further information, please do not hesitate to contact me.

Yours Sincerely,



Eleri Owen  
Consents Manager  
Rampion Offshore Wind Farm

Registered in England  
And Wales No 07199847

Registered Office:  
Westwood Way  
Westwood Business Park

