

RM Condor - Asbestos Management - Summary of Area Asbestos Hazard Sheets Issued @ 08 March 2010

ANNEX A CONDOR SUMMARY OF ISSUED HAZARD SHEETS					
Record ID	Location	Description	Room Desc	Status	Last Updated
76	DDCI00DDCI01	ARMED FORCES CAREERS OFFICE (LISTED)	Wall panel - Stairwell, main entrance	COMMISSIONED	-
77	DDCI00DDCI01	ARMED FORCES CAREERS OFFICE (LISTED)	White panelling on wall 2 within ceiling void	COMMISSIONED	-
78	DDCI00DDCI01	ARMED FORCES CAREERS OFFICE (LISTED)	Panel on Front of Door	COMMISSIONED	-
79	DDCI00DDCI01	ARMED FORCES CAREERS OFFICE (LISTED)	Wall panel	COMMISSIONED	-
80	DDCI00DDCI01	ARMED FORCES CAREERS OFFICE (LISTED)	As Per Sample 2 - Top floor, panelling beside entrance to attic	COMMISSIONED	-
588	RMCR00CON005	FIRE FIGHTING WATER STORAGE (Aquatrine)	Roof Trusses and Purlins within No Access area	AQUATRINE	-
693	RMCR00CON006	BOOSTER PUMP HOUSE (Aquatrine)	Rope seal	AQUATRINE	-
694	RMCR00CON006	BOOSTER PUMP HOUSE (Aquatrine)	Fuse flash pads	AQUATRINE	-
631	RMCR00CON008	CONDOR CLUB	Ceiling	COMMISSIONED	09 November 2009
640	RMCR00CON008	CONDOR CLUB	Ceiling within Ceiling Void	REMOVED	08 March 2010
664	RMCR00CON008	CONDOR CLUB	Cistern within Walls area	COMMISSIONED	09 November 2009
665	RMCR00CON008	CONDOR CLUB	Ceiling within Ceiling Void	REMOVED	09 November 2009
589	RMCR00CON010	ARCHIVES	Bath Panel	COMMISSIONED	09 November 2009
591	RMCR00CON010	ARCHIVES	Bath Panel	COMMISSIONED	09 November 2009
574	RMCR00CON011	VICT STORE	Roof Covering	COMMISSIONED	11 November 2009
575	RMCR00CON011	VICT STORE	Fascia/Soffit	COMMISSIONED	11 November 2009
576	RMCR00CON011	VICT STORE	Debris on flat roof	COMMISSIONED	11 November 2009
634	RMCR00CON011	VICT STORE	Brown floor tiles	COMMISSIONED	11 November 2009
638	RMCR00CON011	VICT STORE	Ceiling within Ceiling Void	COMMISSIONED	05 November 2009
639	RMCR00CON011	VICT STORE	Ceiling	COMMISSIONED	11 November 2009
641	RMCR00CON011	VICT STORE	Cream vinyl floor tiles	COMMISSIONED	11 November 2009
642	RMCR00CON011	VICT STORE	Adhesive to red vinyl floor tiles	COMMISSIONED	11 November 2009
643	RMCR00CON011	VICT STORE	Red vinyl floor tiles	COMMISSIONED	04 November 2009
644	RMCR00CON011	VICT STORE	Ceiling within Ceiling Void	COMMISSIONED	04 November 2009
692	RMCR00CON011	VICT STORE	Ceiling	COMMISSIONED	11 November 2009
742	RMCR00CON012	PC OFFICES/WORKSHOP STORE	Adhesive on back of Brown vinyl floor tiles	COMMISSIONED	05 November 2009
743	RMCR00CON012	PC OFFICES/WORKSHOP STORE	As Per Sample G35- Roof covering above joinery workshop	REMOVED	08 March 2010
737	RMCR00CON020	D BLOCK TRANSIT (SLA -TRANSIT)	Bitumen roof covering to plant room at rear	REMOVED	08 March 2010
633	RMCR00CON021	Z COY JRSLA (SLA -PERMANENT)	Gasket	COMMISSIONED	10 November 2009
738	RMCR00CON021	Z COY JRSLA (SLA -PERMANENT)	DPC within External Wall	COMMISSIONED	10 November 2009
616	RMCR00CON048	SNR OFFICERS SLA WEST (SLA -PERMANENT)	Dust & Debris within External Wall area	COMMISSIONED	11 November 2009
590	RMCR00CON049	OFFICERS MESS	Boxed in Services within Ceiling Void	COMMISSIONED	10 November 2009
647	RMCR00CON049	OFFICERS MESS	Sink Pad	COMMISSIONED	10 November 2009
601	RMCR00CON068	MARRIED QUARTER (PAULS COTTAGE)	Brown Vinyl Floor Tiles	COMMISSIONED	05 November 2009
725	RMCR00CON068	MARRIED QUARTER (PAULS COTTAGE)	Beige Floor Tiles	COMMISSIONED	11 November 2009
677	RMCR00CON072	SICK BAY	Gaskets throughout pipework	COMMISSIONED	11 November 2009
678	RMCR00CON072	SICK BAY	Ceiling	COMMISSIONED	11 November 2009
679	RMCR00CON072	SICK BAY	Adhesive to floor covering	COMMISSIONED	11 November 2009
685	RMCR00CON072	SICK BAY	Floor Covering within Ceiling Void area	COMMISSIONED	11 November 2009
687	RMCR00CON072	SICK BAY	Adhesive to floor covering	COMMISSIONED	11 November 2009
688	RMCR00CON072	SICK BAY	Floor Covering	COMMISSIONED	11 November 2009
718	RMCR00CON072	SICK BAY	Adhesive to floor covering	COMMISSIONED	11 November 2009
662	RMCR00CON074	NAVY HUB	Roof Covering	COMMISSIONED	-
663	RMCR00CON074	NAVY HUB	Roof Covering	COMMISSIONED	11 November 2009
675	RMCR00CON082	AT STORE	Adhesive on floor	COMMISSIONED	10 November 2009
682	RMCR00CON082	AT STORE	Live Electrics	COMMISSIONED	10 November 2009
637	RMCR00CON085	SKI STORE	Yellow mastic in expansion joints	COMMISSIONED	10 November 2009

**RM Condor - Asbestos Management - Summary of Area Asbestos Hazard Sheets Issued @ 08 March 2010**

Record ID	Location	Description	Room Desc	Status	Last Updated
592	RMCR00CON092	HANGAR C3	Internal - within the roof space Gaskets on inaccessible pipes	COMMISSIONED	11 November 2009
593	RMCR00CON092	HANGAR C3	Adhesive to floor covering	COMMISSIONED	11 November 2009
659	RMCR00CON092	HANGAR C3	Red floor tiles	COMMISSIONED	11 November 2009
603	RMCR00CON103	EDUCATION DEPARTMENT	Remains Of An Old Downpipe At Back Door.	REMOVED	14 January 2011
587	RMCR00CON121	COY HANGAR B1	Gaskets on inaccessible yellow gas pipe	COMMISSIONED	10 November 2009
595	RMCR00CON121	COY HANGAR B1	Evidence of floor adhesive	COMMISSIONED	10 November 2009
586	RMCR00CON141	ABLUTIONS	Cistern within Walls area	COMMISSIONED	10 November 2009
648	RMCR00CON141	ABLUTIONS	Flue/ventilation pipe (External part of pipe only)	COMMISSIONED	10 November 2009
581	RMCR00CON142	BEWLEY HALL CINEMA	Adhesive to rear of blue floor tiles	COMMISSIONED	11 November 2009
582	RMCR00CON142	BEWLEY HALL CINEMA	Streaky blue floor tiles	COMMISSIONED	11 November 2009
583	RMCR00CON142	BEWLEY HALL CINEMA	Redundant electrical fuse box - flash pads	COMMISSIONED	11 November 2009
584	RMCR00CON142	BEWLEY HALL CINEMA	Gasket	COMMISSIONED	05 November 2009
585	RMCR00CON142	BEWLEY HALL CINEMA	Adhesive to floor covering	COMMISSIONED	11 November 2009
705	RMCR00CON146	CDO HEADQUARTERS	Dust & Debris within Ceiling Void area	REMOVED	08 March 2010
706	RMCR00CON146	CDO HEADQUARTERS	Dust & Debris within Ceiling Void area	REMOVED	08 March 2010
671	RMCR00CON154	CDO MT DEL WORKSHOPS	Gutters and Downpipes	COMMISSIONED	11 November 2009
673	RMCR00CON154	CDO MT DEL WORKSHOPS	Adhesive on back of vinyl floor tile	COMMISSIONED	11 November 2009
698	RMCR00CON154	CDO MT DEL WORKSHOPS	Beige vinyl floor covering below blue tile	COMMISSIONED	11 November 2009
707	RMCR00CON154	CDO MT DEL WORKSHOPS	Adhesive on beige floor tile	COMMISSIONED	11 November 2009
720	RMCR00CON156	LIQUID HAZARDOUS STORE	Roof Covering	COMMISSIONED	11 November 2009
676	RMCR00CON183	CHURCH AND EXTENSION	External Boxed in Services	COMMISSIONED	-
689	RMCR00CON183	CHURCH AND EXTENSION	Corrugated roof sheets	REMOVED	08 March 2010
697	RMCR00CON183	CHURCH AND EXTENSION	Adhesive to floor covering	COMMISSIONED	11 November 2009
699	RMCR00CON183	CHURCH AND EXTENSION	Adhesive to floor covering	COMMISSIONED	12 November 2009
701	RMCR00CON183	CHURCH AND EXTENSION	Adhesive to floor covering	COMMISSIONED	11 November 2009
703	RMCR00CON183	CHURCH AND EXTENSION	Adhesive to floor covering	COMMISSIONED	12 November 2009
704	RMCR00CON183	CHURCH AND EXTENSION	Adhesive on rear of blue vinyl	COMMISSIONED	12 November 2009
715	RMCR00CON183	CHURCH AND EXTENSION	Adhesive to floor covering	COMMISSIONED	12 November 2009
716	RMCR00CON183	CHURCH AND EXTENSION	Adhesive to floor covering	COMMISSIONED	12 November 2009
724	RMCR00CON191	BUS SHELTER	Roof Covering	COMMISSIONED	12 November 2009
596	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Roof Covering Above Room 17	COMMISSIONED	12 November 2009
709	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Floor Covering	COMMISSIONED	12 November 2009
711	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Adhesive to floor covering	COMMISSIONED	12 November 2009
719	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Adhesive to floor covering	COMMISSIONED	12 November 2009
721	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Adhesive to floor covering	COMMISSIONED	12 November 2009
733	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Floor Covering	COMMISSIONED	-
740	RMCR00CON222	HANGAR D2 7 BTY FITTER SECTION	Floor Covering	COMMISSIONED	12 November 2009
4317	RMCR00CON255	25 METRE RANGE	External	COMMISSIONED	01 March 2010
745	RMCR00CON520	PROPERTY STORAGE COMPOUND	Roof Covering - (Sheeting on shed)		