

ASC Area 6/8

Process: Deliver Service
 Title: Electrical Scout Sheet

Inventory	HA Process
Generic	KIER
Guidance	

April 17 Scout

Works Order No.	
Road:	A14
Date:	2/05/17 - 5/05/17
Name:	

c = consecutive	Direction	Position
S = Sequential	NB = North Bound, SB = South Bound	L1 = Lane 1, CR = Central reserve
	EB = East Bound, WB West Bound	LV = Left Verge, RV = Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	RTA	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out				
												Lamp /type	Fuse	Ballast	Ignitor	Repair Date
BR054								RBT	LV		HUNTINGTON JCT					
BR056								RBT	LV							
BR009								RBT	LV							
BR048								RBT	LV							
	2721W							RBT	CR							
	2723W							RBT	CR							
BR023								RBT	LV							
BR025								RBT	LV							
	BOLLARD	NO ID						RBT	CR		ELLINGTON JCT					
	BOLLARD	NO ID						RBT	CR							
	0947E							RBT	CR							
	0948E							RBT	CR							
BY023								WB	LV		BYTHORN JCT					
BY032								WB	LV							
	0788E							EB								
	BY85							EB	LV							
	0787E							EB								
BY039								EB	LV							
	0789E							EB								
	0784E							EB	CR							
	0502W							WB	LV		JCT 22 RACE COURSE EXIT WB					
	0501W							WB	RV							
BR028								WB	LV							
BR028A								WB	LV							
BR029								WB	LV							
BR030								WB	LV		JCT 22 RACE COURSE ENTRY					
	BR541							WB	LV		END OF LIFE, TYPE B, MEWP REQUIRED					
HU005								BOTH	CR		JCT 23 SPITTLES TOP					
HU009								EB	CR							
HU010								EB	LV							
HU021								RBT	LV		CABLE FAULT					
HU021A								RBT	LV		CABLE FAULT					
HU024								RBT	LV		CABLE FAULT					
HU025								RBT	LV		CABLE FAULT					
HU026								RBT	LV		CABLE FAULT					
HU029								RBT	LV		CABLE FAULT					
HU031								RBT	LV		CABLE FAULT					
HU032								RBT	LV		CABLE FAULT					
HU033								RBT	LV		CABLE FAULT					
HU034								RBT	LV		CABLE FAULT					
HU035								RBT	LV		CABLE FAULT					
HU036								RBT	LV		CABLE FAULT					
HU037								RBT	LV		CABLE FAULT					
HU038								RBT	LV		CABLE FAULT					
HU041								RBT	LV		CABLE FAULT					
HU042								RBT	LV		CABLE FAULT					
HU043								RBT	LV		CABLE FAULT					
HU044								RBT	LV		CABLE FAULT					
	0386E							RBT	LV		CABLE FAULT					
	0385E							RBT	LV		CABLE FAULT					
HU046								RBT	LV		CABLE FAULT					
HU049								RBT	LV		CABLE FAULT					
HU050								RBT	LV		CABLE FAULT					
HU051								RBT	LV		CABLE FAULT					
	0289W							RBT	LV		CABLE FAULT					
HU056								RBT	LV		CABLE FAULT					
	0474W							RBT	LV		CABLE FAULT					
	0471W							RBT	LV		CABLE FAULT					
HU022								WB	LV		JCT 23 SPITTLES WB ENTRY					
HU023								WB	LV							
	2586							WB	LV							
	2587							WB	RV							
HU027								EB	RV		JCT 23 SPITTLES EB EXIT					
HU028								EB	RV							
HU030								EB	LV							
	0400S							EB	LV		MEWP REQUIRED					
	0434S							EB	LV		JCT 23 SPITTLES EB ENTRY					
	0433S							EB	RV		CABLE FAULT					
HU040								EB	RV		CABLE FAULT					
HU041								EB	RV		CABLE FAULT					
HU045								WB	RV		JCT 23 SPITTLES WB EXIT					
HU046								WB	LV		CABLE FAULT					
HU047								WB	RV		CABLE FAULT					
GM001								EB	LV		JCT 24 GODMANCHESTER EB EXIT					
GM002								EB	LV							
51	24										Totals	0				

Repair Carried out

ASC Area 6/8

Process: Deliver Service
 Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	HA4
Control Number	
Guidance	

Jan 17 Scout Pg. 1
 missing

Works Order No.	A8402120050	c = consecutive	Direction	Position
Road:	A14 page2	S = Sequential	NB = North Bound, SB = South Bound	L1= Lane1, CR= Central reserve
Date:	24/01/2017		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:				

COL Ref	SIGN Bollard Ref	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments	Repair Carried out					
											Lamp /type	Fuse	Bal/Leet	Ignitor	Repair Date	Beyond Repair
										ALCONBERY						
						23		EB	LV	SPITTLBS RBT E/B EXT FROM A14						
	652W					22		WB	LV	HUNTINGDON RACE COARSE WB EXT						
	650W					22		WB	RV	HUNTINGDON RACE COARSE WB EXT						
						22		WB	LV	HUNTINGDON RACE COARSE WB EXT						
						22		WB	LV	HUNTINGDON RACE COARSE WB EXT						
						22		WB	LV	HUNTINGDON RACE COARSE WB EXT						
						22		WB	LV	HUNTINGDON RACE COARSE WB EXT						
	BR641					22		WB	LV	HUNTINGDON RACE COARSE TOP OF WB ENT SLP						
						22		WB	LV	HUNTINGDON RACE COARSE WB ENT SLP						
Totals																

ASC Area 6/8

Process: Deliver Service
 Title: Electrical Scout Sheet

Handbook	HA Process
Generic	
Contract Specific	HA4
Guidance	

Works Order No.		c = consecutive	Direction	Position
Road:	A14	5 = Sequential	NB = North Bound, SB =South Bound	L1=Lane1, CR= Central reserve
Date:	24.1.17		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:				

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out						
											Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair	
A14 JNCT IT																	
164								WB	LV	OFFSLIP							
NO NUM								EB	LV	ONSLIP							
NM4																	
NO NUM								EB	CR	ONSLIP TWIN ARM LEFT SIDE							
NO NUM								EB	CR	ONSLIP BOLLARD							
NO NUM								EB	CR	ONSLIP BOLLARD							
KENTFORD																	
NO NUM								EB	LV	2 WAY TRAFFIC SIGN NO POWER AT BASE							
RUSBY																	
47								WB	LV	OFFSLIP OIS CLAAS							
48								WB	LV	OFFSLIP OIS CLAAS							
48								WB	RV	OFFSLIP OIS CLAAS							
BURY WEST																	
E142								EB	RV	OFFSLIP							
NO NUM								EB	LV	CUT DOWN COL OFFSLIP							
NO NUM								WB	LV	ONSLIP 1ST COL OFFSLIP							
BURY CENTRAL																	
NO NUM								EB	LV	ONSLIP DCP							
NO NUM								WB	LV	OFFSLIP DCP							
BURY EAST																	
E218								EB	LV	OFFSLIP							
E274								EB	RV	OFFSLIP							
E227								EB	LV	ONSLIP							
E226								EB	LV	ONSLIP							
NO NUM								EB	LV	ONSLIP							
NO NUM								WB	RV	OFFSLIP							
NO NUM								WB	LV	ONSLIP ON COL							
ROUGHAN LORRY PARK																	
E154										SIGNS AT ENTRY							
HAUGHLEY																	
256								EB	LV	ONSLIP							
257								EB	RV	ONSLIP							
244								EB	LV	OFFSLIP							
245								EB	RV	OFFSLIP							
Totals																	

ASC Area 6/8

Process: **Deliver Service**
 Title: **Electrical Scout Sheet**

Minority	HA Process
General	HA4
Control Points	
Guidance	

Works Order No.	A8402120050	c = consecutive	Direction	Position
Road:	A14	S = Sequential	NB = North Bound, SB = South Bound	L1=Lane1, CR= Central reserve
Date:	21/12/2016		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:				

COL Ref.	SIGN Bollard Ref.	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out						
											Lamp /type	Fuse	Ballaast	Ignitor	Repair Date	Beyond Repair	
BY0023								WB	LV								
BY0032								WB	LV								
TH004								WB	LV								
	NO ID							EB	LV								
	NO ID							EB	LV								
	BY56							EB	LV								
BY008	BY56							EB	LV								
	BY58							EB	LV								
	0766E							EB	LV								
	0766E							EB	LV								
	0767E							EB	LV								
	0738W							EB	LV								
	BOLLARD							EB	LV								
	0764E							EB	LV								
BR028								WB	LV	Huntingdon Race course jct Fault							
BR029A								WB	RV	Huntingdon Race course jct Fault							
	0602W							WB	LV	Huntingdon Race course jct Fault							
	0601W							WB	LV	Huntingdon Race course jct Fault							
BR02Q								WB	LV	Huntingdon Race course jct Fault							
BR030								WB	LV								
	BR041							WB	LV								
	NO ID							EB	LV	AdS SIGN							
HU006								CR	CR								
HU008								CR	CR								
HU010								EB	LV								
	0070E							EB	RV								
	0434E							EB	LV	Spittles Roundabout Fault							
	0433E							EB	LV	Spittles Roundabout Fault							
	0060V							EB	RV	Spittles Roundabout Fault							
	0060W							EB	LV	Spittles Roundabout Fault							
	2099W							EB	RV	Spittles Roundabout Fault							
	2099W							EB	LV	Spittles Roundabout Fault							
	2071W							EB	LV	Spittles Roundabout Fault							
	0471W							EB	LV	Spittles Roundabout Fault							
HU034			Y					EB	LV	Spittles Roundabout Fault							
HU036			Y					EB	LV	Spittles Roundabout Fault							
HU038			Y					EB	LV	Spittles Roundabout Fault							
HU039			Y					EB	LV	Spittles Roundabout Fault							
HU040			Y					EB	LV	Spittles Roundabout Fault							
HU041			Y					EB	LV	Spittles Roundabout Fault							
HU042			Y					EB	LV	Spittles Roundabout Fault							
HU043			Y					EB	LV	Spittles Roundabout Fault							
HU044			Y					EB	LV	Spittles Roundabout Fault							
HU046			Y					EB	LV	Spittles Roundabout Fault							
HU048			Y					EB	LV	Spittles Roundabout Fault							
HU047			Y					EB	LV	Spittles Roundabout Fault							
HU048			Y					EB	LV	Spittles Roundabout Fault							
HU049			Y					EB	LV	Spittles Roundabout Fault							
HU050			Y					EB	LV	Spittles Roundabout Fault							
HU051			Y					EB	LV	Spittles Roundabout Fault							
HU068			Y					WB	LV								
MD013								WB	RV	M1/A14 LNKS							
GT256								WB	LV	M1/A14 LNKS							
GT258								WB	LV	M1/A14 LNKS							
GT287								WB	LV	M1/A14 LNKS							
GT290								WB	RV	M1/A14 LNKS							
Totals																	