









ASC Area 6/8

Process: Deliver Service  
 Title: Electrical Scout Sheet

Company	HA Process
Generic	HA4
Reference	
Reference	

Works Order No.		A8402120050	e = consecutive	Direction	Position
Road:		A14	S = Sequential	NB = North Bound, SB = South Bound	L1 = Lane 1, CR = Central reserve
Date:		28-4-15		EB = East Bound, WB = West Bound	LV = Left Verge, RV = Right Verge
Name:					

COL Ref.	SIGN Boltard Ref.	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments	Repair Carried out						
											Lamp Type	Fuse	BaBallast	Ignitor	Repair Date	Beyond Repair	
61922								WIB	LV								
60								WIB	CR								
H0056								11	LV								
H0059								11	LV								
BR053								11	LV								
BY032								11	LV								
TH008								WIB	LV								
H005								11	RV								
H0014								11	LV								
H0034								11	LV								
H0036								11	LV								
H0040								11	RV								
H0041								11	RV								
A14 FROM JUNCTION 30 + GIRON INTERCHANGE COULDN'T BE DONE																	
NIGHT CLOSURES FOR MAJOR SCHEME WORK.																	
SPITTLES INTERCHANGE COULDN'T BE DONE DUE TO LANE CLOSURES.																	
Totals																	

13

4



















J34 NO ELECTRICAL SIGNS/COLUMNS.  
E/B & W/B.

COL Ref.	SIGN Bollard Ref.	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct.	Repair Carried out					
											Lamp Type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
CT301		Y				31		N/B	LV	GILTON L <sup>o</sup> S						
CT322		Y				31		N/B	LV	-n- -n-						
CT326		Y				31		N/B	LV	-n- -n-						
CT121		Y				31		E/B	LV	-n- -n-						
IM001		Y				32		E/B	LV	OFF SUP MISSILE (RTA)						
IM003		Y				32		E/B	RV	ON SUP (TOTAL ROAD CLOSED)						
AL002		Y				33		E/B	LV	OFF SUP						
EX001		Y	✓			37		N/B	CR	CR ISLAND DOUBLE HEAD (RTA)						
EX002		Y	✓			37		W/B	LV							
IM005				✓		32		W/B	RV							
IM008			✓			32		E/B	RV							
RA002			✓					W/B	RV	] Possible cable fault						
Totals																

84