





August 2015 Scouting

COL Ref.	SIGN Bollard Ref.	MEWP Y/N	C	S	MP	JCT	H/B	Direction	Position	Comments and/or Additional Location: A Road, Between Slips, Jct to Jct, At Jct.	Repair Carried out					
											Lamp /Type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
A11																
BARTON MILLS DUGLS																
34		X						S	LV							
53		X						N	LV							
SX SIGNS ON CR CABLE FAULT																
Sainsbury's RDBT																
16915		X						N	LV							
16735		X						N	LV							
1680		X						N/S	CR							
BRANDON RDBT																
1728		X						S	CR							
Bollards		X2						N/S	CR							
MUND FORD ROAD RDBT																
No.10								S	LV	ON J TO TURT FORD						
X2										REQUIRE REPLACING						
10.10		X						S	LV	ON RDBT CORNER S/B						
10.10	Bollards							S	CR	X4						
1731								N/S	CR							
1730								N/S	CR							
1741								N/S	CR							
CROXTON																
All	Bollards									BOTH SIDES XL NRS						
X2										BILLAGE LIGHTS OUT ON EB SIDE						
WATTON RD RDBT																
Bollards		X2								E/W CR						
RODDHAM UNDER PASS																
X2										BRIDGE LIGHTS OUT EB						
SHROTHAM UNDER PASS																
X1										OUT EB BRIDGE LIGHT						
STAS RDBT																
X2	Bollards									(N/S CR) X2 LAST ONE TO SWANLEY						
X1										LC WHICH REQUIRES SETTING OUT DUCT						
ATTLEBOROUGH																
none										S CR OFF SLIP DIA						
SPOONER ROAD																
944										S LV						
TUTTLES																
844										S LV 3 ON SLIP						
901										S LV						
Totals																

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Standard	HA Process
Genets	HA4
Calibrated Records	
Guidance	

Works Order No.		c = consecutive	Direction	Position
Road:	A11	S = Sequential	NB = North Bound, SB = South Bound	L1=Lane1, CR= Central reserve
Date:	26-02-15		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:	[Redacted]			

COL Ref.	SIGN Bollards Ref.	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct.	Repair Carried out					
											Lamp Type	Fuse	Bulbset	Ignitor	Repair Data	Beyond Repair
A	TRUCK TRAILER								CR	ON NORWICH SIDE BULLWORTH						
None	BRIDGE LIGHT									AT W SIDE						
None	BRIDGE LIGHT									AT E SIDE						
	ARROW ON END OF								CR	→ NORWICH						
Totals																

ASC Area 6/8

Process: Deliver Service  
 Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	HA4
Contract Specific	
Guidance	

Works Order No.	<u>51008346</u>	c = consecutive	Direction	Position
Road:	<u>A11</u>	S = Sequential	NB = North Bound, SB = South Bound	L1=Lane1, CR= Central reserve
Date:	<u>30-4-2015</u>		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:				

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct.	Repair Carried out						
											Lamp Type	Fuse	Balast	Ignitor	Repair Date	Beyond Repair	
19		✓						SB	LV	QUEENS RD INTERCHANGE							
										BRECKLAND LODGE R/A							
NDNUM		✓						NB	LY	" "							
" "		✓						NB	LY	" "							
" "		✓						SB	LV	" "							
NDNUM		✓						SB	LV	MUNDFORD RD R/A							
1736		✓						NB	LV	" "							
1737		✓						NB	LV	" "							
1747		✓						NB	LV	" "							
1728		✓						SB	CR	BRANDON RD RA							
1680		✓						NB	CR	LONDON RD RA							
1681		✓						NB	CR	" "							
1682		✓						SB	CR	" "							
1683		✓						NB	CR	" "							
1684		✓						SB	CR	" "							
1691		✓						NB	LV	" "							
34		✓						SB	LY	BARTON MILLS							
33		✓						NB	LV	" "							
Totals																	

} Cable Fault

P 171

ASC Area 6/8

Process: Deliver Service  
 Title: Electrical Scout Sheet

Manpower	HA Process
Genaro	HA4
Control Panel	
Guidance	

Works Order No.	A6402120020	c = consecutive	Direction	Position
Road:	A17 N+S BOUND	S = Sequential	NB = North Bound, SB = South Bound	L1= Lane 1, CR= Central reserve
Date:	25-2-2015		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:	[REDACTED]			

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out				
											Lamp /type	Fuse	Ballast	Ignitor	Repair Date
NO NUM		✓	C					SB	RV	KENTFORD ON SLIP					
NO NUM		✓	C					SB	RV	" " "					
										REST OF ROUNDABOUT IS OUT PRIOR TO ON-SLIP					
NO NUM		✓	✓					SB	LV	BRECKLAND LODGE R/A					
NO NUM		✓	✓					SB	LV	" " "					
NO NUM		✓	✓					SB	LV	" " "					
NO NUM		✓	✓					SB	LV	" " "					
NO NUM		✓						NB	LV	" " "					
NO NUM		✓						NB	LV	" " "					
NO NUM								SB	LV	SNETTERTON OFF NO ENTRY					
NO NUM								SB	RV	SNETTERTON OFF NO ENTRY					
NO NUM								SB	RV	SNETTERTON ON C/WAYS					
182		✓						NB	LV	1075 R/A THETFORD					
NO NUM		✓						NB	LV	1075 R/A THETFORD					
163		✓						NB	CR	1075 R/A THETFORD					
NO NUM		✓						SB	LV	MUNDEFORD R/A THETFORD					
1747		✓						NB	LV	" " "					
1746		✓						NB	LV	" " "					
1737		✓						NB	LV	SPLITTER " "					
1719		✓						SB	LV	BRANDON ROAD RA					
1660		✓	✓					NB	CR	LONDON ROAD RA					
1680		✓	✓					SB	CR	" "					
1682		✓	✓					SB	CR	" "					
1681		✓	✓					NB	CR	" "					
1684		✓	✓					SB	CR	" "					
1683		✓	✓					NB	CR	" "					
1691		✓	✓					NB	LV	" "					
1679		✓						SB	LV	" "					
16		5	6							Totals					

Lain H









A11

W/O A642070010

COL Ref:	SIGN Boltard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Locations A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out						
											Lamp Type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair	
4		Y						S/B	LIV	<del>Kennece</del>							
NO NUM		Y						S/B	RIV	LAST COLUMN ON SLIP.							
41		Y	✓					N/B	LIV	<del>BARROW MILLS.</del>							
40		Y	✓					N/B	LIV								
38		Y						S/B	LIV								
46		Y						N/B	LIV								
33		Y						S/B	LIV								
51		Y	✓					N/B	CL								
32		Y	✓					N/B	CL								
24		Y	✓					N/B	CL								
23		Y	✓					S/B	CL								
22		Y	✓						CL	N/B + S/B							
6 x columns out DUE TO CABLE FAULT											SANDERS NOT BY CONTRACTORS.						
1728		Y						S/B	CL	<del>BRANWY W/ LOT</del>							
1737		Y						N/B	CL	<del>A134</del>							
1736		Y						N/B	LIV								
1747		Y						N/B	LIV								
1740		Y						S/B	LIV								
NO NUM		Y						S/B	LIV								
15		Y						S/B	LIV	<del>BRANWY</del>							
487		Y						S/B	RIV	<del>BRANWY</del>							
846		Y						S/B	RIV	<del>TOTTENHAM</del>							
900		Y						S/B	RIV	ON SLIP.							
901		Y						S/B	LIV	ON SLIP.							
852		Y	✓					S/B	LIV								
833		Y	✓					S/B	LIV								
871		Y	✓					S/B	CL								
870		Y	✓					S/B	CL								
867		Y	✓					11	CL	BOTH SIDES							
868		Y	✓					11	CL								
872		Y	✓					11	CL								
874		Y	✓					11	LIV								
Totals																	

57 11

IM CONFIDENT?

Scheme.

TTDO FEB 2015

Locations October 2014

11

All

BATON MILLS PUELS

~~NIB~~ NIB

SIB

COL 40 L/V ✓

COL 30 L/V ✓

Sign 50M / ~~150M~~ L/V

COL 33 L/V ✓

alspond c/Res ✓

COL 22 c/Res ✓

COL 46 L/V ✓

Sign 160 L/V ✓

Chway 157 L/V ✓

COL 51 L/V ✓

COL 52 L/V ✓

COL 24 c/Res ✓

Chway 140 L/V ✓

All Elvedew.

4x Bollards req ✓

Replating sign on when

COL T8 L/V ✓

COL T9 L/V T15 ✓

COL T12 L/V ✓

All LONDON RD MBT

9x col out CABLE FAULT

CONTRACTOR ✓

1691 J. col L/V ✓

SB 318 c/Res ✓

All BRANDON RD MBT

2+ AMERS c/Res. MBT ✓

COL 1726 c/Res ✓

M/S + 30MPH c/Res ✓

2x 8w LITS Repl ✓

M/S nonun L/V ✓

SB 337 c/Res ✓

Chway x 2 bus traffic ✓

COL 1725 L/V ✓

no ~~access~~  
ACCESS