

EM HIGHWAYS Area 3 - South Area Salt Record and Resource Sheet- 2014/2015

Date: 01.02.15

Action Requested + By Who

CONDITION AMBER - MIN RST -5.3 ACTION REQUIRED ON ALL ROUTES AT 19:00hrs AT A RATE OF 18gms PRE WET OR 18gms DRY WHERE PRE WET NOT AVAILABLE. ACTION REQUESTED BY JIM DAY.

Form completed by

Supervisor:
Contact Number:
Role: Supervisor

Depot	Loader	Route	VRN	Fleet No.	Driver	Time		Salt Used (tonnes)	Brine Used (litres)	Salt + Brine
						Out	In			
Dummer		D01	WX08 MTF	WS 046		19:00	20:10	9.58		26.36
		D02	WX08 MUY	WS		19:00	20:32	9.61		
		D03	WX08 MUV	WS 067		19:00	20:45	7.17		
Hook		H01	WX08 VOU	WS 030		19:00	20:40	9.83		18.25
		H02	WX08 VPD	WS 049		19:00	20:40	8.43		
Longmoor		LM01	WM09 FFO	WS 068		19:00	20:57	8.11		27.11
		LM02	WX08 MVM	WS 064		19:00	20:45	6.87		
		LM03	WX08 VPC	WS 055		19:00	20:25	6.08		
		LM04	WX08 MTK	WS 069		19:00	20:26	6.06		
Ower		OW01	WX08 MWV	WS 068		19:00	20:00	6.18		28.62
		OW02	WX08 MWO	WS 056		19:00	20:30	9.35		
		OW03	WX08 MWU	WS 086		19:00	20:25	7.12		
		OW04	WX08 MWP	WS		19:00	20:35	5.98		
Park Gate		PG01	WX08 VPJ	WS 057		19:00	20:25	8.88		26.99
		PG02	WX08 VPA	WS 050		19:00	20:41	10.56		
		PG03	WX08 VPE	WS 070		19:00	20:18	7.55		
Totals								127.33	0.00	127.33

Salt Delivered		
(tonnes)	From (other depot, Salt Union...)	To
		Dummer
		Hook
		Longmoor
		Ower
		Park Gate

Route	If target time of 3 hours per route is not achieved, please give reasons below + any vehicle defects
D01	
D02	
D03	WX08 MUV DIAGNOSTICS PROBLEM. DRIVES OK BUT FFR DIAGNOSTICS CODE IS 00647/10.
H01	
H02	
LM01	
LM02	
LM03	
LM04	
OW01	REQUEST FROM DRIVERS TO CHECK ALL LORRIES AT OWER FOR HYDROLIC OIL. WX08 MWV SOUND LIKE POSSIBLE AIR LEAK.
OW02	
OW03	
OW04	
PG01	
PG02	WX08 VPA DRIVER PUSHING SALT BUTTON AND NOTHING HAPPENS DELAY BETWEEN PUSHING SALT BUTTON AND SALT COMING OUT. LORRY NEEDS CHECKING ASAP.
PG03	WX08 VPE REAR NEARSIDE BEACON NOT WORKING.

Other Comments	
Confirm that adequate labour plant and materials are in place for the next treatment (check box)	YES
Brine tanks at Ower, Dummer and Hook not working.	