



Ministry of Defence

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

Ref: FOI2017/04719

Telephone [MOD]: [REDACTED]

Facsimile [MOD]: [REDACTED]

E-mail: navysef-foimailbox@mod.uk

[REDACTED]
[REDACTED]

11 May 2017

Dear [REDACTED]

Release of Information

Thank you for your correspondence dated 16 April 2017 requesting the following information:

'A copy of the noise survey conducted on board HMS Diamond between sept 15 and jan 16.

I am also after the noise survey conducted between june 2014 and december 2014 by the environmental health team.'

Your enquiry has been considered to be a request for information in accordance with the Freedom of Information Act 2000.

A search for the information has now been completed within the Ministry of Defence and I can confirm that some information in scope of your request is held. The Department is able to provide you with a copy of the Baseline Noise Survey which was conducted on board HMS Diamond in October 2015 and can be found at the attached Annex to this letter. There are no records of any noise surveys having been conducted on board HMS Diamond between June 2014 and December 2014.

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, Ground Floor, Zone D, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.uk). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <http://www.ico.org.uk>.

Yours sincerely

Navy Command Secretariat – FOI Section

HMS Diamond Baseline Noise Survey 15/10/2015

15/10/2015								
15/10/2015	08E	ESM Antenna equip room	76.4	80.2	80		9 knots	SS2
	07E	ESM Equip room	66.3	75.4	80			
	06EA	ESM main equip room	64.6	72.4	80			
	06EZ1	UK CEL equip room	71	74.7	80			
	05EA	Comms equip room no. 1 CER 1	71.1	74.7	80			
	05EZ1	MFR & UK CEL equip room	83.8	86.4	80			
	04EA1	Scot Office	79.2	76.8	65			
	04EA2	MFR equip room	82.1	77.8	80			
	04	Lobby	68	68.2	75			
	03EA	NAV & EO SP equip room	72	68.5	80			
	03EZ1	ATU (2-2)	82.9	83	90/110			
	03EZ4	Space Margin	72.3	73.2	80			
	02DZ	Bridge	60	65.4	65			
	02EA1	Chart Room	63.6	64.6	65			
	02EB1	Bridge Pantry	58.9	61.6	75			
	02EC1	WC/WB	60.4	60.8	80			
	02EY2	Shower	65.8	63.2	80			
	02EZ1	Ordnance workshop	71.5	71.4	80			
	02FA2	ATU (2-1)	81.6	82	90/110			
	02	MET OC Fwd Gyro Room	63.4	65.4	75			
	01D20	CO Day room	46.6	50.4	65			

	01D23	CO Night Cabin	48.3	45.8	60			
	01DA1	CO Bathroom	53.3	47.5	80			
	01DA2	CTU Cabin	46.9	47.4	60			
	01DZ1	CO Pantry	58.7	57.4	75			
	01DZ2	CTU Bathroom	50.8	47.4	80			
	01EA2	ATU (2-6)	77.6	78.3	90/110			
	01EB2	CO Store	60.3	65.8	75			
	01EB4	ATU (2-4)	73.6	75.7	90/110			
	01EZ0	EDR	76	77.7	90/110			
	01FA1	AFU No.2	76.5	77.1	90/110			
	01FB2	A/L & Dress	62.3	63.4	65			
	1D1	Access lobby	60	60.5	75			
	1DZ1	Comms equip No.6 CER6 FWD	65	66.7	70			
	1DZ2	S Planning room & SIO	58.7	53.2	60			
	1E	OPS room	60.6	65	60			
	1EA1	Comms equip No.6 CER6 aft	66.1	65.8	70			
	1EA2	Unallocated planning room	58.6	58.8	60			
	1EY1	CESMO maint space	58.9	68.3	70			
	1EY1	S Fit office	57.6	60	65			
	1EZ4	Joint planning room	58.5	53.4	60			
	1F	Ward	63.6	64.9	60			
	1F	Head	67.7	61.2	80			
	1F	Shower	66.7	61.2	80			
	1FA1	CMS Equip room	65.3	70.6	80			
	1FA2	EDR EDC-1F	68	69.5	70			
	1FA3	ATU (2-3)	93	92.9	90/110			
	1FB2	Transit (Cabin)	55.1	61.7	60			
	1FB4	Transit(Cabin)	55.3	68.5	60			
	1FC4	Washroom	61.5	67.2	80			
	1FC8	Surgery	58.8	61.8	60			

	1FY1	SRE	69.9	72.8	75			
	1FZ3	Space Margin propulsion office	63.6	63.1	65			
	1GA1	Wardroom	60.2	53.4	65			
	1GA2	Wardroom anteroom	63.7	59.6	65			
	1GY2	WC/WB	70.2	69.1	80			
	1GZ1	Wardroom Pantry	71.1	74.8	75			
	1GZ2	WC/WB	79.4	68.1	80			
	1HA3	Lobby	79.4	75.9	75			
	1HB1	Cleansing Station	81	81.5	80			
	1HB2	SE(Air)	71.7	72	75			
	1HB3	Hydraulic power pack	81.6	79.9	90/110			
	1HX1	Shipping area	84.3	85.5	85			
	1HY1	Aviation spares store	70.6	67.5	75			
	1HZ1	Aviation modular store	70.3	68.8	75			
	1JY1	Boat Bay S	67.9	63.4	90/110			
	1KA2	AUASS	62.3	66.5	75			
	1KZ2	Flight Deck ready room	56.3	67.0	65			
	1KZ5	QMs FDO Position	62.3	72.6	65			
		Hanger AFT	68.1	67.8	85			
	2BAZ	Enclosed Fx	72.5	58.2	80			
	2BZ1	Survival Safety equip room	74.7	75.9	80			
	2BZ2	Forward drying room	74.7	75.8	80			
	2C1	ATU 1-1, 1-2	93.5	91.2	90/110			
	2CA4	EMGY Galley & provisions store	58.5	58.2	75			
	2D/1	WC/WB	61.2	57	80			

	2D/1	WB Sink	58.1	55.6	80			
--	------	---------	------	------	----	--	--	--

HMS Diamond Baseline Noise Survey 16/10/2015

[Redacted Header]								
16/10/2015	2D/2	WC/WB	72.2	73.4	80		9 knots	SS2
	2D/3	WC/WB	63.7	62.5	80			
	2D/3	Shower	65.7	65.0	80			
	2DA1	Officer	54.2	54.2	60			
	2DA3	Officer	63.4	65.6	60			
	2DA5	Lobby	74.2	74.3	75			
	2DC1	WOSM	57.4	58.6	60			
	2DC2	Exec WO	54.7	52.6	60			
	2DC3	Officer	56.7	58.6	60			
	2DC4	JR Officer (202)	54.8	55.1	60			
	2DC5	Officer	61.7	62.3	60			
	2DZ1	Officer 2011 (PWO)	51.2	52.1	60			
	2DZ2	Officer	58.5	58.1	60			
	2DZ3	Officer	56.5	57.2	60			
	2DZ4	Officer (V)	59.7	60.1	60			
	2DZ5	Lobby (V)	64.6	66.8	75			
	2EA3	Officer (AWO)	52.9	53	60			
	2EA3	Officer	59.9	60.9	60			
	2EA5	Officer	65.2	64.3	60			
	2EB3	WC/WB	53.1	51.6	60			
	2EB4	WC/WB	59.5	60.2	80			
	2EZ1	SR Officer	55	56.1	80			
	2EZ2	EDR	68.9	68.7	60			
	2EZ3	SR Officer	53.1	53.6	70			
	2EZ4	SR Officer	51.9	52.6	60			
	2EZ5	SNR Officer	55	55.1	60			

	2FA1	Lobby	50.5	52.1	60			
	2FA1	SR Ratings rec space	64.8	70.2	65			
	2FA2	Senior CPO	58.1	55.4	60			
	2FA	WC/WB	62.4	60.6	80			
	2FB2	Senior CPO	53.4	54.1	60			
	2FB6	Shower	60	58.4	80			
	2FC2	Senior CPO	58.3	57.6	60			
	2FC6	Shower	67.6	66.9	80			
	2FD2	Senior CPO	54.9	57.0	60			
	2FE6	Senior CPO	63.3	62.6	60			
	2FG6	Senior CPO	56.1	57.6	60			
	2FH6	Senior CPO	55.1	54.8	60			
	2FY2	WC/WB	63.4	62.9	60			
	2FZ1	EDR ECD-2F	67.4	71.6	70			
	2FZ2	Senior CPO	56.9	55.6	60			
	2FZ4	WC/WB	68.3	66.3	80			
	2G	SRs Dining Hall	63.3	61.1	65			
	2G/H	Integrated Galley (Aft)	79.9	83.9	75			
	2GA2	SCC	62	60.6	60			
	2GZ1	SRs Servery	65.5	64.8	75			
	2GZ2	ATU(3-2)	78.8	84.3	90/110			
	2HA2	NAAFI	69.6	73.6	75			
	2HB2	Technical Office	65	67.9	65			

	2HY2	Regulating Office	62.1	65.4	65			
	2HZ1	JR Servery	69.8	60.2	75			
	2HZ2	Cash Office	60.4	60.4	65			
	2HZ4	UPO	60.9	60.5	65			
	2JY2	JR Rec Space	53.8	54.2	65			
	2JZ1	JR Dining Hall	54.5	59.2	65			
	2KA1	JR Dining Hall/MFS	54.5	59.2	65			
	2KA2	JR Rec Space	71.9	60.9	65			
	2KY1	Boat Gear store	53.3	64.5	75			
	2KZ2	JR SPC FAP	64.6	56.9	65			
	2KZ3	EMR Common	61.9	70.8	65			
	2L/1	Shower	73.4	69.5	80			
	2L/2	Shower	67.1	68.2	80			
	2LA1	Austerity Accom	58.8	62.5	60			
	2LA2	Laundry	74.7	76.1	75			
	2LB4	EDR EDC - 2L	72.9	75	75			
	2LY3	Tel Box Exchange	64.9	54.1	65			
	2LY5	Tel Box Exchange	64.8	52.3	65			
	2LZ2	ATU (4-2)	88.2	90.5	90/110			
	2LZ4	Smoking room	82.8	84.2	80			
	2LZ6	Diving gear store	72.9	73.5	75			
	2MA1	Quarter Dec M	78.8	70.3	85			
	2MA2	Converted	76	73	80			

		spls dist rm						
--	--	-----------------	--	--	--	--	--	--

HMS Diamond Baseline Noise Survey 17/10/2015

17/10/2015								
17/10/2015	2MA3	Aft Hawser store	75.9	76.4	75		9 knots	SS2
	2MA4	Battery charging room	68.4	67.8	70			
	1ABA2	Power room	58.5	61.2	70			
	1JY2	Port Boat bay	62.7	64.3	90/110/			
		Caterers office	68.5	70.2	65			
		Executive Officer	52.4	54.8	60			
		Intergrated Galley (fwd)	82.8	81.2	75			
		Wc/WB	63.5	63.6	80			
		WC/WB	58.6	59.4	80			
	3BA	Sonar Inst Space	70	69.3	70			
	3BA2	FWD main broadcast group	65.3	65.3	70			
	3BB1	FF & DC & FWD NBC Store	68.3	65.8	70			
	3BZ0	Space resin for silo missile	73	73.2	75			
	3BZ2	ATU (1-3)	65.7	65.8	90/110			
	3CA	Lobby	70.6	59.9	75			
	3D	Lobby	56.7	57.2	75			
	3D/3	WB	50.4	54.1	80			
	3D/4	Wc/WB	60.8	55.1	80			
	3D/5	WC/WB	52	54.8	80			
	3DA0	SR Rating	54	54.8	60			
	3DA1	SR Rating	50.9	56.1	60			

	3DA2	SR Rating	57	53.4	60			
	3DA3	SR Rating	53.2	62.4	60			
	3DA4	SR Rating	53.1	63.4	60			
	3DA6	SR Rating	54.4	64.2	60			
	3DC2	SR Rating	56.9	59.9	60			
	3DC4	SR Rating	53.4	56.9	60			
	3DC6	Senior CPO	54.5	67.3	60			
	3DZ1	SR Rating	52.9	60.9	60			
	3DZ2	SR Rating	51.3	61.8	60			
	3DZ3	SR Rating	52.1	59.8	60			
	3DZ3	Senior CPO	67	54.3	60			
	3DZ6	Senior CPO	52.7	59.4	60			
	3DZ7	Shower	65.5	67.2	80			
	3DZ8	Shower	52.1	54.4	80			
	3EA1	Officer	50.7	53.8	60			
	3EA3	Officer	51.9	56.7	60			
	3EA6	JR Officer	52.8	58.2	60			
	3EZ3	Officer	52.4	57.4	60			
	3EZ4	Officer	54.9	58.3	60			
	3EZ6	JR Officer	55.2	58.2	60			
	3FA1	LV Switchboard	73.2	63.6	90/110			
	3FY3	Electrical Workshop	67.9	68.1	70			
	3FZ3	ATU(2-5)	82.7	72.1	90/110			
	3G2	Naval Store No.1	61.1	59.9	75			
	3GA0	Aft gyro Room	65.3	65.8	70			
	3GA1	EDR EDC 3G (1) & (2)	71.3	69.6	70			
	3GA3	Clothing Store	61.7	66.2	75			
	3GB3	SR Beer store	59.8	62.6	75			
	3GZ3	Bulk Naval store	64.8	68.1	75			
	3HA1	AFT HV Switchboard	90.2	93.3	90/110			
	3HA4	Mechanical workshop	72.3	73.2	75			

	3HB4	ATU(3-4)	94	93.8	90/110			
	3JA0	AMR	94.2	54.8	90/110			
	3JA1	JR Rating	54.8	56.5	60			
	3JA2	Jr Rating	52	55.1	60			
	3JB3	Lobby (WC/shower)	58.1	60.1	75			
	3JC2	Lobby	61.4	63.4	75			
	3JC3	Lobby	59.4	61.2	75			
	3JZ1	JR Rating	57.8	69.8	60			
	3JZ2	JR Rating	49.9	50.1	60			
	3JZ3	JR Rating	53.6	55.1	60			
	3JZ4	JR Rating	52.5	54.1	60			
	3JZ5	JR Rating	52.8	53.9	60			
	3KA2	Lobby	53.9	55.6	75			
	3KA5	JR Rating	51.3	52.8	60			
	3KA7	JR Rating	58.5	61.3	60			
	3KB0	SR Rating	56.4	58.2	60			
	3KB2	SR Rating	58.7	60.1	60			
	3KB4	SR Rating	57.7	59.5	60			
	3KZ1	JR Rating	54.9	56.3	60			
	3KZ2	JR Rating	55.5	58.1	60			
	3KZ3	JR Rating	56.6	58.2	60			
	3KZ4	JR Rating	56.4	59.1	60			
	3KZ5	Lobby	67.5	68.2	75			
	3KZ6	Lobby (WC>Showers)	59.3	63.2	75			

HMS Diamond Baseline Noise Survey 18/10/2015

18/10/2015	3LA1	JR Rating	60.3	59.8	60		9 knots	SS2
	3LA2	JR Rating	56.8	59.4	60			
	3LA3	JR Rating	66.2	59.6	60			
	3LA4	JR Rating	61.8	60.1	60			
	3LA4	JR Rating	59	62.2	60			
	3LA5	Passageway	73.3	74.1	75			

		(Wc/Showers)						
	3LA6	Passageway	62.8	63.2	75			
	3LZ1	JR Rating	66.5	67.4	60			
	3LZ2	JR Rating	59.5	60.1	60			
	3LZ3	JR Rating	69	69.2	60			
	3MA4	Filter cleaning space	75	75.4	75			
	3MA6	ATU (4-3)	74.8	75.2	90/110			
	3MB1	TAS Store	75.7	77.1	75			
	3MB6	Aft Deck Store	76.3	77.8	75			
	3MZ0	Refrig mach & dry waste store	77.4	77.3	75			
	3MZ1	Secondary garbage store	79.6	81.2	75			
	4CO	VLS Equip room	70	69.3	80			
	4CO	Passageway	64.9	74.2	75			
	4CA1	PAAMS equip room	67.2	70.1	80			
	4CA2	Forward Pump Space	78.1	63.4	90/110			
	44/5	Shower	62.8	67.4	80			
	4DA0	SR Rating	62.4	66.6	60			
	4DA1	SR Rating	60.6	66.1	60			
	4DA1	SR Rating	70	71.5	60			
	4DA2	SR Rating	61.6	72.3	60			
	4DA2	SR Rating	58.3	75.4	60			
	4DA2	SR Rating	60.5	73.2	60			
	4DA3	SR Rating	64.1	76.3	60			
	4DA4	SR Rating	61.3	77.0	60			
	4DA4	SR Rating	61.3	76.1	60			
	4DB1	Lobby (Shower)	75.7	72.8	75			
	4DB4	Lobby	64	73.5	75			
	4DC1	SR Rating	61.1	67.6	60			
	4DC2	SR Rating	59.6	75.4	60			

	4DC3	SR Rating	61.4	68.7	60			
	4DC4	SR Rating	54.5	75.3	60			
	4DY4	Lobby	72.6	62.9	75			
	4DZ2	SR Rating	56.8	61.9	60			
	4DZ2	SR Rating	61.5	60.9	60			
	4DZ2	SR Rating	49.1	50.4	60			
	4DZ3	SR Rating	53.5	60.9	60			
	4D	Shower	61.8	56.4	75			
		Space provision	74.6	57.3	75			
	5D	FWD Sewage treatment plant	87.5	94.3	90/110			
	5E	FWD Machinery room	87.2	91.4	90/110			
	5F	FWD Gas turbine room	96.5	94.6	90/110			
	5HZ1	AFT Gas turbine room	86.6	86.8	90/110			
	5M	Tiller flat	89.1	90.3	90/110			
		RO Plant room	92.4	93.1	90/110			
		Space prov SSGW power & equip room	82.2	85.2	90/110			

