Refusal of MOT test certificate

① Vehicle identification number

BLLAAKAAAAA821483

2a Registration number
2b Country of registration

AA73LLB GB

Make and model

ROVER 400

S Vehicle categoryMileage47,535 miles

7 Fail

© Do not drive until repaired (dangerous defects)



- Tyre tread depth below requirements of 1.6mm Nearside Front [5.2.3 (e)]
- © Repair immediately (major defects)
 - Stop lamp(s) not working Offside [4.3.1 (a) (ii)]
- © Repair as soon as possible (minor defects)
 - Stop lamp(s) not working Offside [4.3.1 (a) (ii)]
- 3b Date of the test

22.03.2018

3a Location of the test

134, Poison Vale, Aberdeen, Aberdeenshire, Scotland, Aberdeenshire, CA15 8HW

Testing organisation and inspector name

VTS072740 TADLEY TEST CENTRE LIMITED M. C. Peeples

MOT test number

8900 6019 5240

To find out about retests, or if you disagree with the test result, see the fees and appeals poster at the vehicle testing station. Alternatively, visit **www.gov.uk/getting-an-mot**

If any of the details are not correct, please contact DVSA by email at **enquiries@dvsa.gov.uk** or by telephone on 0300 1239000

Find out about the vehicle's MOT history at www.gov.uk/mot-history

