

**NOTICE OF AUTHORIZED AMENDMENT: MAA/NAA/19/26**

RA(s) or Manual Chapter(s):	RA 3049, RA 3261, RA 3263, RA 3274, RA 3510, RA 3536, RA 3550, Manual of Air Traffic Management and Defence Aerodrome Manual
RFC Reference(s):	MAA/RFC/2017/014, 2017/061, 2018/102, 2018/104, 2018/106, 2019/070, 2019/088, 2019/130, 2019/132, 2019/135, 2019/136, 2019/137
NPA Reference(s):	N/A

	Post	Rank/Name	Date
MAA Author	DSA-MAA-Reg-ATM1-Gen	Redacted	12 Sep 19
MAA Supervisor	DSA-MAA-Reg-ATM	Redacted	12 Sep 19
MAA Independent	DSA-MAA-OpAssure-KE-MRP1	Redacted	12 Sep 19
MAA LegAd (if required)	Post	Rank/Name	Date

Amendment Classification (iaw MAA SOP 20)	<b>Minor Change</b>	Publishing Requirements:	Next regular release
---	---------------------	--------------------------	----------------------

Cross-references to Other Documents or Relevant Sources	
Other MRP Amendments	N/A
Service Inquiry Recommendations	DAIB/17/020/1.5.2.a
AAIB Recommendations	N/A
Other Investigation Recommendations	N/A
Any Other Document	N/A

Authorized Amendment
Summary/Overview of the amendment to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.
<b>The Regulated Community is reminded to check this amendment against any applicable AAMC, Waivers or Exemptions to ensure their ongoing validity.</b>
Defence Aerodrome Manual Foreword removed JSP 360 reference updated JSP 426 reference removed and replaced with DSA DFRS02 – Defence Aerodrome Rescue and Fire Fighting (ARFF) Regulation. Removal of MADS reference and replaced with appropriate reference. Reference number updates

Removal of Dii reference  
 Spelling mistakes corrected  
 Manual of Military Air Traffic Management  
 Foreword removed  
 Removal of Annex A which duplicates the 3000 Series table of contents  
 RA 3049, RA 3261, RA 3510  
 JSP 426 reference removed and replaced with DSA DF SR02 – Defence Aerodrome Rescue and Fire Fighting (ARFF) Regulation  
 RA 3263  
 JSP 426 reference removed and replaced with DSA DF SR02 – Defence Aerodrome Rescue and Fire Fighting (ARFF) Regulation  
 GM included regarding reference for determining proportionate medical cover.  
 RA 3536  
 JSP 426 reference removed and replaced with DSA DF SR02 – Defence Aerodrome Rescue and Fire Fighting (ARFF) Regulation  
 Update to Medical cover required at Domestic HLS to align with AP1269.  
 RA 3274  
 Removal of duplicate definitions for Runway and Aerodrome Movement Area Incursion – now in MAA02.  
 RA 3550  
 TATOM reference replaced with 2 Group Operations Manual Part B Temporary Landing Zones.

<b>ISSUE STATE CHANGES</b> (if more lines required, contact the MRP Team)			
<b>Document Title</b>	<b>Previous Issue</b>	<b>New Issue</b>	
Defence Aerodrome Manual (DAM)	Issue 5	To	Issue 6
Manual of Military Air Traffic Management (MMATM)	Issue 11	To	Issue 12
RA 3049 – Defence Contractor Flying Organization responsibilities for UK Military Air System Operating Locations	Issue 4	To	Issue 5
RA 3261 - Aerodrome Service	Issue 6	To	Issue 7
RA 3263 - Aerodrome Classification	Issue 2	To	Issue 3
RA 3274 - Low Visibility Procedures	Issue 3	To	Issue 4
RA 3510 - Permanent Fixed Wing Aerodrome - Reference Information	Initial Issue	To	Issue 2
RA 3536 - Domestic Helicopter Landing Site - Services, Equipment and Installations	Initial Issue	To	Issue 2
RA 3550 - Temporary Landing Zone	Initial Issue	To	Issue 2

<b>Approval</b> (iaw MAA SOP 20)	<b>Post</b>	DSA-MAA-Reg-DepHd	
	<b>Name</b>	Redacted	
	<b>Rank</b>	Redacted	Redacted - Original Signed