

Work Objects

Serial Number: MG48AA
NSN: 2320998939968

Criteria:
Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL
Work Request ID:
Assigned Work Status: ALL
Working Organisation:
Repair Section:

| Fault ID | Work Request ID | Fault Description | Work Status | Fault State | Escalate | Repair Level | Batch Fault Group ID | Fault Occurrence Date | Mission Impact | Reason For Work | Level 3 Description | Working Organisation | Repair Section | Estimated Repair Time |
|-----------------|-----------------|--|-------------|----------------|----------|--------------|----------------------|-----------------------|----------------|------------------|---------------------|----------------------|----------------|-----------------------|
| A00200-2619C001 | | STEERING WHEEL NOT CENTRAL | Closed | Fully Fit | No | Level 2 | | 25 Nov 2018 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | |
| 000000-00B23C06 | | SNV377 - SWIVEL HOUSING | Closed | Fully Fit | No | Level 1 | 000000-0000697B | 29 Mar 2019 | N/A | Inspection | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-00B2127C | | SNV 377 - SWIVEL HOUSING | Closed | Non-Taskworthy | No | Level 1 | 000000-0000697A | 29 Mar 2019 | N/A | Inspection | TUM HS FFR HARD TOP | | | 001:00 |
| A00200-2619C002 | | REMOVE STICKERS FROM WINDSCREEN | Closed | Fully Fit | No | Level 1 | | 25 Nov 2018 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | |
| A00200-24F3A002 | | NO FIRE EXTINGUISHER | Closed | Non-Taskworthy | No | Level 1 | | 18 Aug 2018 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | |
| A00200-24F3A001 | | CUT IN R/H TYRE | Closed | Non-Taskworthy | No | Level 2 | | 18 Aug 2018 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| A00200-24F3A000 | | no indicator /brake lights | Closed | Non-Taskworthy | No | Level 2 | | 18 Aug 2018 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| A00180-24BBE00B | | CARRY OUT THEATRE ENTRY EXAMINATION | Closed | Non-Taskworthy | No | Level 2 | | 01 Aug 2018 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-00AB7405 | | BOWMAN - BIT TEST ONLY, SECURE MODE WILL NEED TO BE COMPLETED BY GAINING ORGANISATION. Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch. | Closed | Limited Role | No | Level 2 | | 30 May 2018 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-00A4395C | | Check No2 ball joint torque tightness as per safety notice LE SNV 00063 | Closed | Non-Taskworthy | No | Level 2 | 000000-000031C8 | 14 Jan 2016 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-0095EF30 | | INCORRECT INFORMATION ON DATA PLATE | Closed | Limited Role | No | Level 1 | | 01 Sep 2013 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-007B0AF2 | | Towing Pintle Assembly | Closed | Limited Role | No | Level 2 | 000000-00001F58 | 09 Oct 2014 | Degraded | Inspection | TUM HS FFR HARD TOP | | | 000:30 |
| 000000-008434D1 | | REVERSE LIGHT LENS PERISHING | Closed | Fully Fit | No | Level 1 | | 02 Sep 2013 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:30 |
| 000000-007B06CE | | RENEW SPARE WHEEL TYRE | Closed | Limited Role | No | Level 1 | | 08 Apr 2013 | N/A | Failure | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-0077C7CD | | GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09 | Closed | Non-Taskworthy | No | Level 1 | 000000-0000081A | 24 Jun 2013 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:45 |
| 000000-007B0692 | | DISPOSAL FAULTS | Closed | Fully Fit | No | Level 2 | | 02 Sep 2013 | N/A | Inspection | TUM HS FFR HARD TOP | | | 005:30 |
| 000000-0077CD88 | | MEI FAULTS | Closed | Fully Fit | No | Level 1 | | 09 Apr 2013 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:45 |
| 000000-0079ACA8 | | Inspect tyres for damage | Closed | Fully Fit | No | Level 2 | 000000-00000835 | 25 Jun 2013 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-0077F371 | | MOD 32 HAS FALLEN OFF | Closed | Fully Fit | No | Level 2 | | 16 Apr 2013 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:30 |
| 000000-0074C0A0 | | MOD 6 SPARE WHEEL VALUE DAMAGE | Closed | Non-Taskworthy | No | Level 1 | | 07 Nov 2012 | N/A | Damage | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-00772DF5 | | MODIFICATION | Closed | Fully Fit | No | Level 2 | | 11 Mar 2013 | N/A | Modification | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-0077C79C | | CARRY OUT TRACKING CHECK | Closed | Non-Taskworthy | No | Level 2 | | 08 Apr 2013 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:45 |
| 000000-0077C796 | | INSPECT AND CLASSIFY SPARE WHEEL DAMAGE / UNEVEN WEAR | Closed | Limited Role | No | Level 1 | | 08 Apr 2013 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-0074C08E | | POWER STEERING RESERVOIR LEAKING | Closed | Non-Taskworthy | No | Level 2 | | 07 Nov 2012 | N/A | Damage | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-0074BFEB | | PLEASE CARRY OUT MOD 41 | Closed | Fully Fit | No | Level 2 | | 07 Nov 2012 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-0074BA6A | | PLEASE CARRY OUT MEI | Closed | Non-Taskworthy | No | Level 2 | | 07 Nov 2012 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | 001:30 |
| 000000-0074345A | | Please carry out a 24 month service iaw aesp 2320-d-128-601 table 7 col c | Closed | Non-Taskworthy | No | Level 1 | | 16 Oct 2012 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | 004:00 |
| 000000-0072FA3C | | CARRY OUT 2 YEARLY/40000KM MAINT. | Closed | Non-Taskworthy | No | Level 2 | | 02 Aug 2012 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | 005:00 |
| 000000-0073B512 | | OUT OF USE STORAGE | Closed | Fully Fit | No | Level 1 | | 20 Sep 2012 | N/A | Closed No Action | TUM HS FFR HARD TOP | | | |
| 000000-00743428 | | OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2) | Closed | Fully Fit | No | Level 2 | | 16 Oct 2012 | N/A | Servicing | TUM HS FFR HARD TOP | | | 006:00 |
| 000000-0073AACE | | OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2) | Closed | Non-Taskworthy | No | Level 2 | | 19 Sep 2012 | N/A | Servicing | TUM HS FFR HARD TOP | | | 006:00 |
| 000000-00742466 | | Please carry out OOPM ser 2 & 3 iaw aesp 2320-d-128-601 table 5 | Closed | Non-Taskworthy | No | Level 1 | | 11 Oct 2012 | N/A | Servicing | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-007429C0 | | Please carry out OOPM ser 1 & 4 iaw aesp 2320-d-128-601 table 5 | Closed | Non-Taskworthy | No | Level 1 | | 09 Oct 2012 | N/A | Servicing | TUM HS FFR HARD TOP | | | 001:30 |
| 000000-00711D78 | | PLEASE CARRY OUT A OUT INSPECTION | Closed | Fully Fit | No | Level 2 | | 09 May 2012 | N/A | Inspection | TUM HS FFR HARD TOP | | | 002:00 |
| 000000-00711D75 | | CARRY OUT 1Y VM TASKS AS PER AESP2320-D-128-601 TABLE 7 | Closed | Fully Fit | No | Level 2 | | 09 May 2012 | N/A | Servicing | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-00711D6A | | CARRY OUT 1Y SERVICE AS PER AESP2320-D-128-601 TABLE 7 | Closed | Fully Fit | No | Level 1 | | 09 May 2012 | N/A | Servicing | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006E4308 | | PLEASE CARRY OUT 6M VM TASKS AS PER AESP 2320-D-128-601 TABLE 7 | Closed | Fully Fit | No | Level 2 | | 06 Dec 2011 | N/A | Servicing | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-006E4305 | | PLEASE CARRY OUT 6M SERVICE AS PER AESP 2320-D-128-601 TABLE 7 | Closed | Fully Fit | No | Level 1 | | 06 Dec 2011 | N/A | Servicing | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-006D76E9 | | PLEASE INSPECT & CLASSIFY TYRE 6MT14 2610-99-131-1549 | Closed | Fully Fit | No | Level 2 | | 27 Oct 2011 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:45 |
| 000000-00565698 | | FIT DIFFY BLANKING PLATE R/H/S | Closed | Fully Fit | No | Level 1 | | 31 Aug 2010 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-00512101 | | RENEW FUSE BOX SCREWS | Closed | Fully Fit | No | Level 1 | | 01 Jun 2010 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-0046BF9D | | FIT SPARE WHEEL MOD INSTR No 29 | Closed | Fully Fit | No | Level 1 | | 13 Aug 2009 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-006CA4A0 | | PLEASE CARRY OUT RE-INSPECTION MEI | Closed | Fully Fit | No | Level 2 | | 15 Sep 2011 | N/A | Inspection | TUM HS FFR HARD TOP | | | 002:00 |
| 000000-006B288A | | RENEW FRONT LEFT HAND WHEEL/ RIM | Closed | Fully Fit | No | Level 1 | | 28 Jun 2011 | N/A | Damage | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-006B15B7 | | PLEASE CARRY OUT 1Y SERVICE AS PER AESP 2320-D-128-601 TABLE7 | Closed | Fully Fit | No | Level 1 | | 23 Jun 2011 | N/A | Servicing | TUM HS FFR HARD TOP | | | 001:00 |
| 000000-006B28D6 | | REPLACE WINDSCREEN | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Damage | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B28E1 | | RENEW NO4 BALLJOINT | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B28DD | | RENEW NO3 BALL JOINT | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B28C7 | | RENEW REAR ANTI ROLL BAR BUSHES | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B2883 | | INVESTIGATE BRAKE LIGHTS INOP | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B15BB | | PLEASE CARRY OUT 1Y VM TASKS AS PER AESP 2320-D-128-601 TABLE7 | Closed | Fully Fit | No | Level 2 | | 23 Jun 2011 | N/A | Servicing | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B288E | | RENEW NO2 BALLJOINT | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B28A6 | | RENEW LEFT HAND REAR SHOCK BUSH | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B289E | | RENEW RIGHT HAND TOP BUSH (REAR SHOCK) | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Failure | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B28CE | | RENEW EXHAUST CENTER BOX | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Inspection | TUM HS FFR HARD TOP | | | 000:00 |
| 000000-006B28ED | | DEMAND MOD 37 (GLOW PLUG INTERFACE) | Closed | Fully Fit | No | Level 1 | | 28 Jun 2011 | N/A | Modification | TUM HS FFR HARD TOP | | | 000:15 |
| 000000-006B28E7 | | DEMAND MOD 35 (EMERGENCY HAMMER) | Closed | Limited Role | No | Level 1 | | 28 Jun 2011 | N/A | Modification | TUM HS FFR HARD TOP | | | 000:15 |

| | | | | | | | | | | | | |
|-----------------|-----------------|--|--------|----------------|----|---------|-----------------|-------------|-----|--------------|---------------------|--------|
| 000000-006B2881 | | Renew left hand headlight | Closed | Non-Taskworthy | No | Level 2 | | 28 Jun 2011 | N/A | Damage | TUM HS FFR HARD TOP | 000:30 |
| 000000-006B1DA5 | | CARRY OUT MODS 35 AND 37 | Closed | Fully Fit | No | Level 2 | | 27 Jun 2011 | N/A | Modification | TUM HS FFR HARD TOP | 000:15 |
| 000000-006B15C1 | | PLEASE CARRY OUT MEI INSPECTION | Closed | Fully Fit | No | Level 2 | | 23 Jun 2011 | N/A | Inspection | TUM HS FFR HARD TOP | 000:00 |
| 000000-006AF5BE | | Insp Steering Drop Arm Tab Washer | Closed | Non-Taskworthy | No | Level 2 | 000000-000002D1 | 22 Jun 2011 | N/A | Inspection | TUM HS FFR HARD TOP | 000:30 |
| 000000-005EC51B | | REPLACE POWER STEERING PUMP | Closed | Non-Taskworthy | No | Level 2 | | 29 Mar 2011 | N/A | Damage | TUM HS FFR HARD TOP | 003:00 |
| 000000-005E9BEA | | CARRY OUT PROJECT REMUS MOD 39 | Closed | Fully Fit | No | Level 3 | | 22 Mar 2011 | N/A | Modification | TUM HS FFR HARD TOP | 048:00 |
| 000000-005D6D9F | | PLEASE CARRY OUT 6M SERVICE AS PER ASEP2320-D-128-601-TABLE7-COLA | Closed | Fully Fit | No | Level 1 | | 27 Jan 2011 | N/A | Servicing | TUM HS FFR HARD TOP | 000:45 |
| 000000-005D6DA5 | | PLEASE CARRY OUT 6M VM TASKS AS PER ASEP2320-D-128-601-TABLE7-COLA | Closed | Fully Fit | No | Level 2 | | 27 Jan 2011 | N/A | Servicing | TUM HS FFR HARD TOP | 000:45 |
| 000000-00565693 | 000000-002C23B9 | RENEW L/H DOOR HINGES | Closed | Fully Fit | No | Level 2 | | 31 Aug 2010 | | | TUM HS FFR HARD TOP | |
| 000000-00565691 | 000000-002C23B9 | RENEW THERMOSTAT | Closed | Fully Fit | No | Level 2 | | 31 Aug 2010 | | | TUM HS FFR HARD TOP | |
| 000000-0056D917 | 000000-002C434C | PLEASE CARRY OUT OOP MAINT REPLACE AIR CLEANER | Closed | Fully Fit | No | Level 1 | | 31 Aug 2010 | | | TUM HS FFR HARD TOP | |
| 000000-00543C43 | 000000-002BEE76 | PLEASE CARRY OUT MEI INSPECTION AS NECESSARY | Closed | Fully Fit | No | Level 2 | | 02 Aug 2010 | | | TUM HS FFR HARD TOP | |
| 000000-00543C42 | 000000-002BEE76 | PLEASE CARRY OUT 2 Y VM TASKS AS NECESSARY | Closed | Fully Fit | No | Level 2 | | 02 Aug 2010 | | | TUM HS FFR HARD TOP | |
| 000000-00543C3D | 000000-002BEE76 | PLEASE CARRY OUT 2 Y SERVICE AS NECESSARY | Closed | Fully Fit | No | Level 1 | | 02 Aug 2010 | | | TUM HS FFR HARD TOP | |
| 000000-0050B783 | 000000-002B457D | RENEW PASSENGERS DOOR LOCK | Closed | Fully Fit | No | Level 2 | | 20 May 2010 | | | TUM HS FFR HARD TOP | |
| 000000-004FF4D4 | 000000-002B170D | PLEASE RE-THREAD 3 X THREADS ON SPARE WHEEL CARRIER. | Closed | Fully Fit | No | Level 2 | | 30 Apr 2010 | | | TUM HS FFR HARD TOP | |
| 000000-004D6270 | 000000-002A9476 | RENEW VEHICLE BATTERIES | Closed | Non-Taskworthy | No | Level 1 | | 10 Feb 2010 | | | TUM HS FFR HARD TOP | |
| 000000-004CAF5B | 000000-002A7601 | CARRY OUT 6 MTHLY SERVICE | Closed | Non-Taskworthy | No | Level 1 | | 10 Feb 2010 | | | TUM HS FFR HARD TOP | |
| 000000-004CAF67 | 000000-002A7601 | OOPM DRAIN AND REPLENISH GEARBOX OIL | Closed | Non-Taskworthy | No | Level 1 | | 10 Feb 2010 | | | TUM HS FFR HARD TOP | |
| 000000-004D77EB | 000000-002A9890 | CARRY OUT 6534 INSPECTION | Closed | Non-Taskworthy | No | Level 1 | | 26 Feb 2010 | | | TUM HS FFR HARD TOP | |
| 000000-004CAF5D | 000000-002A7601 | CARRY OUT 6 MTHLY VM TASKS | Closed | Non-Taskworthy | No | Level 2 | | 10 Feb 2010 | | | TUM HS FFR HARD TOP | |
| 000000-0048B5AA | 000000-00298888 | RENEW ENGINE | Closed | Non-Taskworthy | No | Level 3 | | 21 Oct 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046BF98 | 000000-002955B4 | CENTRALIZE STEERING WHEEL | Closed | Fully Fit | No | Level 1 | | 13 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046BF95 | 000000-002955B4 | SECURE L/H/F HEADLIGHT GUARD | Closed | Fully Fit | No | Level 1 | | 13 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046BF93 | 000000-002955B4 | PLUG HOLES IN BONNET | Closed | Fully Fit | No | Level 1 | | 13 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046BF91 | 000000-002955B4 | RENEW PASSENGER SEAT | Closed | Fully Fit | No | Level 1 | | 13 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046A231 | 000000-00295155 | PLEASE CARRY OUT 5YRLY OOF MAINTENANCE AS NECESSARY | Closed | Fully Fit | No | Level 2 | | 06 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046A22D | 000000-00295155 | PLEASE CARRY OUT MEI INSPECTION AS NECESSARY | Closed | Fully Fit | No | Level 2 | | 06 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046A22B | 000000-00295155 | PLEASE CARRY OUT 1YRLY VM L2 TASKS AS NECESSARY | Closed | Fully Fit | No | Level 2 | | 06 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0046A225 | 000000-00295155 | PLEASE CARRY OUT 1YRLY SERVICE L1TASKS AS NECESSARY | Closed | Fully Fit | No | Level 1 | | 06 Aug 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0043F551 | 000000-002913A3 | RENEW BOTTOM REDATOR HOSE | Closed | Fully Fit | No | Level 2 | | 25 Jun 2009 | | | TUM HS FFR HARD TOP | |
| 000000-004334BC | 000000-002908FD | CARRY OUT 5 YEARLY L1 SERVICING TASKS AS NECESSARY | Closed | Fully Fit | No | Level 1 | | 18 Jun 2009 | | | TUM HS FFR HARD TOP | |
| 000000-004334B4 | 000000-002908FD | CARRY OUT 6 MONTHLY L2 VM TASKS AS NECESSARY | Closed | Fully Fit | No | Level 2 | | 18 Jun 2009 | | | TUM HS FFR HARD TOP | |
| 000000-004334B2 | 000000-002908FD | CARRY OUT 6 MONTHLY L1 SERVICING TASKS AS NECESSARY | Closed | Fully Fit | No | Level 1 | | 18 Jun 2009 | | | TUM HS FFR HARD TOP | |
| 000000-0039710E | 000000-00277217 | ANNUAL MEI | Closed | Non-Taskworthy | No | Level 2 | | 20 Jan 2009 | | | TUM HS FFR HARD TOP | |
| 000000-002E0D52 | 000000-00283AC7 | 2 YR VM TASKS | Closed | Non-Taskworthy | No | Level 2 | | 29 Oct 2008 | | | TUM HS FFR HARD TOP | |
| 000000-003970FF | 000000-00277217 | ANNUAL SERV | Closed | Non-Taskworthy | No | Level 1 | | 20 Jan 2009 | | | TUM HS FFR HARD TOP | |
| 000000-00397103 | 000000-00277217 | ANNUAL VM TASKS | Closed | Non-Taskworthy | No | Level 2 | | 20 Jan 2009 | | | TUM HS FFR HARD TOP | |
| 000000-002E0D50 | 000000-00283AC7 | 2 yr serv | Closed | Non-Taskworthy | No | Level 1 | | 29 Oct 2008 | | | TUM HS FFR HARD TOP | |
| 000000-000AEC97 | | FIT SPARE WHEEL | Closed | Limited Role | No | Level 1 | | 10 Jan 2008 | | | TUM HS FFR HARD TOP | |
| 000000-000AEC99 | | CARRY OUT RBT | Closed | Non-Taskworthy | No | Level 2 | | 10 Jan 2008 | | | TUM HS FFR HARD TOP | |
| 000000-000A5E6C | | DRIVE SHAFT CAP BOLT DIFFY | Closed | Fully Fit | No | Level 2 | | 05 Dec 2007 | | | TUM HS FFR HARD TOP | |
| 000000-000A5E6D | | TIGHTEN LOWER U/J @ STEERING SHAFT | Closed | Fully Fit | No | Level 2 | | 05 Dec 2007 | | | TUM HS FFR HARD TOP | |
| 000000-000A5E6E | | CARRY OUT SMOKE TEST | Closed | Fully Fit | No | Level 2 | | 05 Dec 2007 | | | TUM HS FFR HARD TOP | |
| 000000-000A5E6F | | REMOVE GLUE FROM WINDSCREEN DVRS SIDE | Closed | Fully Fit | No | Level 1 | | 05 Dec 2007 | | | TUM HS FFR HARD TOP | |
| 000000-000A5E70 | | SECURE SPARE WHEEL | Closed | Non-Taskworthy | No | Level 1 | | 05 Dec 2007 | | | TUM HS FFR HARD TOP | |
| 000000-00094A8E | 000000-00273AAD | REQ 6 X TYRES FITTING TO RIMS | Closed | Limited Role | No | Level 2 | | 17 Oct 2007 | | | TUM HS FFR HARD TOP | |
| 000000-0004E757 | | IWFM | Closed | Non-Taskworthy | No | Level 1 | | 14 Feb 2007 | | | TUM HS FFR HARD TOP | |
| 000000-0008D66E | 000000-00272CC6 | 1 YR SERV | Closed | Non-Taskworthy | No | Level 1 | | 26 Sep 2007 | | | TUM HS FFR HARD TOP | |
| 000000-0008D671 | 000000-00272CC6 | 1 VM TASKS | Closed | Non-Taskworthy | No | Level 2 | | 26 Sep 2007 | | | TUM HS FFR HARD TOP | |
| 000000-0008D674 | 000000-00272CC6 | MEI | Closed | Non-Taskworthy | No | Level 2 | | 26 Sep 2007 | | | TUM HS FFR HARD TOP | |
| 000000-000246FC | 000000-0026CB15 | CARRY OUT 1YRLY VM,S | Closed | Fully Fit | No | Level 2 | | 10 Jul 2006 | | | TUM HS FFR HARD TOP | |
| 000000-00012D06 | | REPLACE STEERING BARREL | Closed | Fully Fit | No | Level 2 | | 05 Apr 2006 | | | TUM HS FFR HARD TOP | |
| 000000-0000C836 | | Initial Usage | Closed | Fully Fit | No | Level 1 | | 22 Feb 2006 | | | TUM HS FFR HARD TOP | |
| 000000-0000C846 | | Initial Maintenance | Closed | Fully Fit | No | Level 1 | | 22 Feb 2006 | | | TUM HS FFR HARD TOP | |