

BULLETIN CORRECTION

Aircraft Type and Registration:	Ikarus C42 FB80, G-CDSW
Date & Time (UTC):	5 April 2019
Location:	Deanland Airfield, East Sussex
Information Source:	Aircraft Accident Report Form

AAIB Bulletin No 11/2019, page 64 refers

The report states that the pilot obtained prior permission for the landing at Deanland airfield while at Lydd Airport during the cross-country flight. The pilot has confirmed that prior permission for landing at Deanland had been obtained during the day preceding the flight.

The report incorrectly states that Runway 26 was in use when the aircraft arrived in the vicinity of Deanland Airfield. The correct designation for the runway in use at the time of the accident was Runway 06.

The online version of the report was amended prior to publication.