

BULLETIN CORRECTION

Aircraft Type and Registration:	Slingsby T61F Venture T Mk 2, G-BUGT
Date & Time (UTC):	9 December 2018 at 1335 hrs
Location:	Field near Rufforth Airfield, York
Information Source:	Aircraft Accident Report Form submitted by the pilot and aircraft inspection report

AAIB Bulletin No 3/2019, page 169 refers

Rufforth Airfield was inadvertently referred to as RAF Rufforth when the March Bulletin was sent for printing. The location of the accident should have read:

Field near Rufforth Airfield, York

not

Field near RAF Rufforth, York

The online version of this report was amended prior to publication.