

**NOTICE OF AUTHORIZED AMENDMENT: MAA/NAI/20/44**

RA(s) or Manual Chapter(s):	Type Airworthiness Engineering 5000 Series Review Update to MRP 5800 series RAs
RFC Reference(s):	RFC_2018_036, 2018_046, 2018_082, 2019_029, 2019_035, 2019_089, 2019_094, 2019_121, 2019_129, 2019_139, 2019_158, 2019_169, 2019_174, 2019_178, 2019_192, 2019_203, 2020_005
NPA Reference(s):	NPA 20/13

	Post	Rank/Name	Date
MAA Author	DSA-MAA-Reg-CAw3a-CAM	Redacted	10/11/2020
MAA Supervisor	DSA-MAA-Dep Hd Eng	Redacted	10/11/2020
MAA Independent	DSA-MAA-OpAssure-Compliance	Redacted	10/11/2020
MAA LegAd (if required)	Post	Rank/Name	Date

Amendment Classification (iaw MAA SOP 20)	<b>Minor Change</b>	Publishing Requirements:	Agreed Date
---	---------------------	--------------------------	-------------

Cross-references to Other Documents or Relevant Sources	
Other MRP Amendments	N/A
Service Inquiry Recommendations	N/A
AAIB Recommendations	N/A
Other Investigation Recommendations	N/A
Any Other Document	N/A

Authorized Amendment
Summary/Overview of the amendment to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.
<b>The Regulated Community is reminded to check this amendment against any applicable AAMC, Waivers or Exemptions to ensure their ongoing validity.</b>
As part of the review work to update and improve the 5000 series (MAA/RN/2020/02 refers) the 5800 series of regulations have been updated to align with EASA Part 21 where appropriate and to improve coherency and consistency with use of terminology and to prepare for the subsequent publication of the Manual of Military Air System Certification (MMAC).
The requirements of the Regulations have not fundamentally changed but the Regulations have been amended to achieve greater alignment with EASA Part 21 regulations. Additionally, where

appropriate, non-regulatory process and Guidance Material has been removed. As such the impact to the TAA, Commodity DTL and supporting DOs will be minimal necessitating at most only administrative updates of documentation.

<b>ISSUE STATE CHANGES</b> (if more lines required, contact the MRP Team)			
<b>Document Title</b>	<b>Previous Issue</b>	<b>New Issue</b>	
RA 5805 - Airworthiness Directives and Service Bulletins (MRP Part 21 Subpart A) - Note New Title	2	To	3
RA 5810 - Military Type Certificate (MRP Part 21 Subpart B)	2	To	3
RA 5815 - Instructions for Sustaining Type Airworthiness		To	Initial
RA 5820 - Changes in Type Design (MRP Part 21 Subpart D)	2	To	3
RA 5825 – Fault Reporting and Investigation		To	Initial
RA 5835 – Production Organizations (MRP Part 21 Subpart G)	Initial	To	2
RA 5840 – Certificate of Airworthiness - Withdrawn	Initial	To	2
RA 5850 – Military Design Approved Organization (MRP Part 21 Subpart J)	2	To	3
RA 5855 - Parts and Appliances (MRP Part 21 Subpart K)	2	To	3
RA 5865 – Repairs (MRP Part 21 Subpart M)	2	To	3
RA 5875 – (European) Technical Standard Order (MRP Part 21 Subpart O)	Initial	To	2
RA 5880–Military Permit to Fly (Development) (MRP Part 21 Subpart P)	4	To	5
RA 5885 – Identification of Products, Parts and Appliances (MRP Part 21 Subpart Q)	Initial	To	2
RA 5401 - Provision of Technical Information	4	To	5
RA 5404 – Fault Reporting and Investigation for Contractors	2	To	3

<b>Approval</b> (iaw MAA SOP 20)	<b>Post</b>	DSA-MAA-Dep Hd Eng	Redacted - Original Signed
	<b>Name</b>	Redacted	
	<b>Rank</b>	Redacted	