

Recommendation(s) Status: Passenger train collision with a derailed locomotive at Bromsgrove

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into eight categories:

Key to Recommendation Status

Implemented:	All actions to deliver the recommendation have been completed.
Implemented by alternative means:	The intent of the recommendation has been satisfied in a way that was not identified by the RAIB during the investigation.
Implementation ongoing:	Work to deliver the intent of the recommendation has been agreed and is in the process of being delivered.
Insufficient response:	The end implementer has failed to provide a response; or has provided a response that does not adequately satisfy ORR that sufficient action is being taken to properly consider and address a recommendation.
Progressing:	The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is in place to implement the recommendation; and work is in progress to provide this.
Non-implementation:	Regulation 12(2)(b)(iii) = recommendation considered and no implementation action to be taken.
Closed - carry forward:	ORR intends to take no further action as it has been superseded by another recommendation.
Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.

RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following:

Red – RAIB has concerns that no actions have been taken in response to a recommendation.

Blue – The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

White – The white triangle shows recommendations where the RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Recommendation Status Report



Report Title	Passenger train collision with a derailed locomotive at Bromsgrove
Report Number	14/2020
Date of Incident	23/03/2020

Rec No.	Status	RAIB Concern	Recommendation	RAIB Summary of current status
14/2020/01	Implemented	None	<p>The intent of this recommendation is to improve the management of overrun risk at buffer stops that are not located in station platforms</p> <p>Network Rail should review, and revise if necessary, the processes and standards that it applies to buffer stops installed on non-platform terminal tracks, to ensure that the risks arising from potential buffer stop collisions are being adequately managed (paragraph 90).</p> <p>This recommendation may also be applicable to other infrastructure operators.</p>	<p>ORR has reported that Network Rail has reported that it has completed actions taken in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.</p>