



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:
FOI2021/05958
Date:
1 July 2021

Dear [REDACTED],

I am writing about your email of 4 June 2021, requesting the following information:

I have recently purchased an ex-military LAND ROVER 2.5 LTR TURBO DSL. I have checked the released MERLIN database and the vehicle service history is not contained in the available published MERLIN extract (the vehicle as having only recently come out of service). Therefore I submit a FOI request for the following information:

- 1) Vehicle military service history (Units served etc, as contained in MERLIN)*
- 2) Any Maintenance Records / Work objects related to this vehicle.*

Vehicle Registration: KD37AA

*Description: FFR HARD TOP LAND ROVER 2.5 LTR TURBO DSL VIN number:
SALLDBA67VA109963*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

- Annex A - Ownership History (redacted)
- Annex B - Fault History (redacted)
- Annex C - Inspection History
- Annex D - Modification History (redacted)
- Annex E - Service History

It has proved necessary to withhold some information related to your request. This is some of the Vehicle History (Annex A) which has been redacted under qualified exemption Section 26(1)(a) and (b) (Defence) of the FOI Act. Commercially sensitive information in the Fault History (Annex B) and Modification History (Annex D), relating to contractor repair times, has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 26 applies to information that if disclosed would or would likely; prejudice the defence of the British Islands or any colony; and/or the capability, effectiveness or security of the Armed Forces of the Crown or any forces cooperating with them. Section 43 concerns information which if disclosed

Defence Equipment & Support

would or would likely; prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As these exemptions are qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, releasing the Vehicle Usage History (Annex A) would divulge information that could be used to compromise the ability of UK Armed Forces to carry out operations safely.

The Fault History (Annex B) and Modification History (Annex D) provide details of the time taken by MOD contractors to rectify fault and modification reports. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KD37AA	2320999085944	NB50203101	LV2A/088DUM	TRUCK UTY MED (TUM) (HS) 4X4 FFR HARD TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR) [REDACTED]	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
19/03/1997	SALLDBA67VA109963	0		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KD37AA	3	18/03/1997	CA005A	JSCS ASHCHURCH	CAPITA	24920AA	19/03/1997	
KD37AA	4	23/06/1997	A0577A	1 R IRISH	31358A	633	24/06/1997	
KD37AA	4	23/06/1999	A9056A	UK BG 1 (CSAT)	0212HT	0012HT	23/06/1999	
KD37AA	4	30/09/1999	A0577A	1 R IRISH	170	1137	30/09/1999	H/T
KD37AA	4	24/05/2000	A0590A	1 LANCS	487	1274	24/05/2000	H/T
KD37AA	4	23/01/2001	A0512A	1 WG	337	128	24/01/2001	R86
KD37AA	4	28/01/2002	A0590A	1 LANCS	65	4243	06/02/2002	S86
KD37AA	4	20/06/2003	A9106B	M2T BG	840	6049	16/07/2003	H/T
KD37AA	4	01/11/2003	A0590A	1 LANCS	119	6050	03/11/2003	
KD37AA	4	18/03/2004	A3858A	3 MEDICAL REGIMENT	5	MCR04	30/06/2004	MC4
KD37AA	4	29/10/2004	A9091A	UK MED GP	102	2154	23/11/2004	V53

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KD37AA	4	25/10/2005	A3858A	3 MEDICAL REGIMENT	259	2231	03/01/2006	W80
KD37AA	4	12/05/2006	CB997C	ABRO CATTERICK PLANNED REPAIR	402	HMP127	12/05/2006	X23
KD37AA	4	27/06/2006	A3858A	3 MEDICAL REGIMENT	HMP133	2806	29/06/2006	X37
KD37AA	4	04/09/2006	A0574A	1 R WELSH	482	62407	08/09/2006	X55
KD37AA	3	15/06/2009	A5969A	TFSU (UK)	59774	1684DD	20/10/2009	
KD37AA	4	10/04/2010	A2266A	4 SCOTS	1171D	999	04/05/2010	
KD37AA	3	19/05/2010	A5969A	TFSU (UK)	999999	2785DD	19/05/2010	
KD37AA	4	16/10/2010	A0999A	1 AAC	2048D	31	16/10/2010	
KD37AA	3	27/01/2011	A5969A	TFSU (UK)	999999	3769DD	27/01/2011	
KD37AA	2	13/04/2011	A2971A	BATUS QM(T)	2372D	999	07/06/2011	
KD37AA	4	16/03/2011	CA467A	THEATRE LOG GROUP	105247	177206	24/04/2011	
KD37AA	4	03/09/2011	A3793A	VRS GS SQN TLG	999	999	03/09/2011	MCR
KD37AA	2	19/11/2011	A8319A	BTE	2653	56051	07/12/2011	C42
KD37AA		23/05/2012		BATUS WRP BVSG			23/05/2012	
KD37AA		17/08/2012		BATUS WRP LANDROVER ALL			17/08/2012	
KD37AA		21/09/2012		BATUS QM(T) ET			28/09/2012	
KD37AA		05/10/2012		EX PS CBT BG ARTY BTY TAC GP			05/10/2012	
KD37AA		06/11/2012		BATUS WRP LANDROVER ALL			06/11/2012	
KD37AA		12/04/2013		BATUS VEH TP			16/04/2013	
KD37AA		23/05/2013		EX PS CBT BG A2 ECH			31/05/2013	
KD37AA		26/08/2013		EX PS CBT BG ENGR SQN			26/08/2013	
KD37AA		12/11/2013		BATUS VEH TP			13/11/2013	
KD37AA		14/11/2013		BATUS WRP LANDROVER ALL			14/11/2013	
KD37AA		16/04/2014		BATUS VEH TP			17/04/2014	
KD37AA		23/04/2014		EX PS CBT BG A2 ECH			25/04/2014	
KD37AA		19/06/2014		BATUS CBT BG B ECH			19/06/2014	
KD37AA		12/08/2014		BATUS VEH TP			12/08/2014	

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KD37AA		14/08/2014		EX PS CSS BG MED TP			14/08/2014	
KD37AA		09/10/2014		EX PS RECCE BG HQ			09/10/2014	
KD37AA		05/11/2014		BATUS WRP LANDROVER ALL			05/11/2014	
KD37AA		23/03/2015		BATUS VEH TP			23/03/2015	
KD37AA		21/04/2015		EX PS HQ			22/04/2015	
KD37AA		10/03/2016		BATUS VEH TP			10/03/2016	
KD37AA		06/04/2016		EX PS OPFOR BG HQ			06/04/2016	
KD37AA		26/04/2016		BATUS VEH TP			26/04/2016	
KD37AA		07/06/2016		EX PS CSS BG MED TP			07/06/2016	
KD37AA		16/11/2016		BATUS VEH TP			16/11/2016	
KD37AA		14/08/2017		BATUS VEH TP			15/08/2017	
KD37AA		17/08/2017		EX PS RECCE ARTY GP			17/08/2017	
KD37AA		23/10/2017		BATUS VEH TP			23/10/2017	
KD37AA		09/08/2018		BATUS WKSP			11/08/2018	

Work Objects

Serial Number: KD37AA
 NSN: 232099893744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate	Repair	Batch	Fault Group ID	Fault Occurrence	Mission	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B836C8	000000-00346494	MEI_Investigate no brake vacuum assist	Closed	Non-Taskworthy	No	Level 2			19 Nov 2019	N/A	Inspection	TUM HS FFR HARD TOP		LANDROVER	000:00
000000-00B836Bf	000000-00346494	MEI_Renew missing body mount bolts by transfer gear case	Closed	Non-Taskworthy	No	Level 2			19 Nov 2019	N/A	Inspection	TUM HS FFR HARD TOP		LANDROVER	000:00
000000-00B836A4		MEI_Post Hurricane Out-Insp	Closed	Fully Fit	No	Level 2			03 Dec 2019	N/A	Non Specific	TUM HS FFR HARD TOP		MEI CELL	000:00
000000-00B836AA		MEI_Hurricane Additional Work Complete	Closed	Non-Taskworthy	No	Level 2			03 Dec 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00B6648C		MEI_HURRICANE DE-ACTIVATION.	Closed	Non-Taskworthy	No	Level 2			18 Sep 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00AF56D1		MEI_JAMES MOD REGISTER NOT UP TO DATE	Closed	Fully Fit	No	Level 2			15 Nov 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00A420C7		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch	Closed	Limited Role	No	Level 2	000000-0000451D		28 Jul 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B680		MEI_RENEW FUEL INJECTORS IF CYLINDER COMPRESSION RESULTS = GOOD. (Failed Emissions)	Closed	Non-Taskworthy	Yes	Level 2			18 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00B1B67A		MEI_RECTIFY FAULTY DIFF LOCK DASH WARNING LAMP	Closed	Limited Role	Yes	Level 2			18 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00B1B677		MEI_CARRY OUT FRONT AXLE STEERING ALIGNMENT (Found Toe Out = 1deg. / 7mm)	Closed	Non-Taskworthy	Yes	Level 2			18 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00B1B652		MEI_REPAIR OR RENEW FAULTY BONNET RELEASE CATCH LEVER	Closed	Non-Taskworthy	Yes	Level 2			18 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00B1B64C		MEI_FIT CORRECT BOLTS @ RIGHT SIDE DOOR B PILLAR, LOCK CATCH PLATE	Closed	Non-Taskworthy	Yes	Level 2			18 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP		HURRICANE	000:00
000000-00B20F8		ESG COMMS - RENEW PWR16 AND BRAD 20 CABLES FROM 931	Closed	Limited Role	No	Level 2			29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B3F11A		BVSG_INV NO BRAKE BOOST ASSIST	Closed	Non-Taskworthy	No	Level 2			28 May 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B66494		PRE-HURRICANE DE-ACTIVATION INSP.	Closed	Fully Fit	No	Level 2			19 Sep 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B04427		EX-PP2-18/19-OFF-PLATFORM	Closed	Fully Fit	No	Level 2	000000-000064CE		15 Jan 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B67C		MEI_CARRY OUT DIESEL ENGINE CYLINDER COMPRESSION TEST (Failed Emissions)	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B683		MEI_RENEW ENGINE AIR FILTER ELEMENT	Closed	Non-Taskworthy	Yes	Level 1			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B675		MEI_REMOVE SHEARED BOLT @ LEFT SIDE REAR BRAKE BACK PLATE, AXLE MOUNT & SECURE	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B674		MEI_RENEW REAR AXLE BRAKE DISC'S (Rotors) & PADS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B673		MEI_RENEW ALL REAR AXLE ANTI-ROLL (Sway) BAR LINK ENDS, RUBBER MOUNT BUSHINGS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B672		MEI_REMOVE TWIST FROM REAR AXLE FLEYX BRAKE HOSE	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B670		MEI_RENEW / SECURE RIGHT SIDE REAR AXLE LOWER LINK ARM, AXLE END MOUNT BUSHING	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B66F		MEI_RENEW FRONT AXLE SHOCK ABSORBERS RUBBER MOUNT BUSHINGS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B66E		MEI_RENEW LEFT SIDE T/BOX RUBBER MOUNT	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B66C		MEI_FIT MISSING FLAT WASHERS @ RIGHT SIDE T/BOX CHASSIS MOUNT BKT'	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B66B		MEI_RENEW VEHICLE BATTERY NEG. LEAD TO CHASSIS & T/BOX (Loose & melted)	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B667		MEI_RENEW MISSING TRANSMISSION COOLER PIPES, REAR OF ENGINE SUPPORT BKT.	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B666		MEI_RENEW ALL FRONT AXLE RADIUS ARMS RUBBER MOUNT BUSHINGS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B665		MEI_RENEW MISSING FLAT WASHERS @ ALL STEERING LINKAGE BALL JOINTS CASTLE NUTS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B662		MEI_RECTIFY OIL LEAKS @ POWER STEERING HOSE / PIPE FITTINGS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B661		MEI_FIT CORRECT SIZE / LENGTH BOLT @ LEFT SIDE FRONT TUAAM GROUND (Stud)	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B660		MEI_RENEW STRIPPED ENGINE BREATHER PIPE HOSE CLIP	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B65F		MEI_RECTIFY OIL LEAKS @ ENGINE VALVE COVER	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B65E		MEI_RECTIFY COOLANT LEAKS @ UPPER & LOWER RAD HOSES & THERMOSTAT HOUSING	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B65D		MEI_RECTIFY OIL LEAK @ ENGINE OIL COOLER PIPE	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B65C		MEI_RENEW MISSING AIR FILTER HOUSING RUBBER MOUNTS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B65A		MEI_ADJUST COOLANT SG. TO BATUS SPEC. (Found too strong, off scale)	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B1B654		MEI_RECTIFY FAULTY FFR ALTERNATOR CHARGE WARNING LAMP	Closed	Limited Role	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B653		MEI_RENEW MISSING FFR ALTERNATOR DRIVE BELT	Closed	Limited Role	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B64E		MEI_SECURE LOOSE WINDSHIELD PANEL, HINGE MOUNT BKT'S	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B649		MEI_RENEW MISSING RADIO BATTERIES BREATHER VENT PIPES	Closed	Non-Taskworthy	Yes	Level 1			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B647		MEI_CORRECTLY FIT / SECURE RADIO BATTERIES TERMINALS	Closed	Non-Taskworthy	Yes	Level 1			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B645		MEI_RECTIFY FAULTY RADIO BATTERIES, CORRECT POLARITY TEST BUTTON/BUZZER	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B642		MEI_CORRECTLY FIT / SECURE RAD/HAZ, REAR SHEET	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B63D		MEI_CORRECTLY FIT / SECURE REAR DOOR GROUND LEAD	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B639		MEI_RENEW MISSING REAR DOOR INNER GRAB HANDLE	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B638		MEI_SECURE REAR DOOR INNER TRIM PANEL	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B636		MEI_REPAIR / STRAIGHTEN& SECURE, UNREPORTED LEFT SIDE REAR BODY PANEL DAMAGE (Leave rear crossmember)	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B633		MEI_ADJUST LEFT SIDE DOOR TO CLOSE ONTO SECOND LOCK CATCH	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B631		MEI_RENEW WORN / LOOSE RIGHT SIDE WIPER ARM	Closed	Non-Taskworthy	Yes	Level 1			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B630		MEI_RENEW MISSING VEHICLE NEG. TERMINAL INSULATION COVER	Closed	Fully Fit	Yes	Level 1			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B62E		MEI_RENEW MISSING SLAVE SOCKET SCREW CAP	Closed	Fully Fit	Yes	Level 1			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B62D		MEI_SECURE LOOSE VEHICLE BATTERY NEG. TERMINAL POST @ CENTRE BOLT	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B62C		MEI_REPAIR OR RENEW CORROSION @ LEFT SIDE DOOR NEAR TOP HINGE	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B62A		MEI_SECURE LOOSE LEFT SIDE DOOR INNER GRAB HANDLE	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B629		MEI_RENEW ALL MISSING G/BOX TUNNEL & FLOOR SCREWS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B628		MEI_CORRECTLY FIT / SECURE RIGHT SIDE SEAT BELT @ REEL ANCHOR	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B627		MEI_RENEW DAMAGED RIGHT SIDE DOOR INNER TRIM PANEL & MAP POCKET	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B626		MEI_RENEW RIGHT SIDE DOOR GROUND LEAD	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B622		MEI_CORRECTLY SET CLUTCH PEDAL FREE PLAY / HEIGHT I.A.W. AESP 2320-D-128-522 Chap 2	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B620		MEI_RENEW MISSING LEFT SIDE DASH DEFROST VENT TUBE	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B61E		MEI_RENEW DAMAGED CENTRE DASH TRIM STRIP	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B61D		MEI_SECURE LOOSE DASH GAUGES FASCIA TRIM	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B618		MEI_SECURE LOOSE HEATER SPEED CONTROL LEVER	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B615		MEI_RECTIFY FAULTY DASH GAUGES BACK LIGHT BULBS	Closed	Fully Fit	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B611		MEI_RECTIFY FAULTY TURN SIGNALS, TRAILER LAMP / HAZARD LAMPS, WARNING LAMP	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B60E		MEI_RECTIFY FAULTY REAR TAIL & LICENCE PLATE LAMPS	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B1B60D		MEI_RECTIFY FAULTY ENGINE LOW OIL PRESSURE WARNING LAMP	Closed	Non-Taskworthy	Yes	Level 2			19 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00B2066A		SNvE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A		29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B22C50		SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B		29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AEB557		MEI_REPLACE TURBO, CLEAN OUT INTERCOOLER AND SURROUNDING PIPES	Closed	Non-Taskworthy	No	Level 2			22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00AEB556		MEI_REPLACE LH REAR BUMPER	Closed	Fully Fit	No	Level 2			22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00AEB555	</														

000000-00AEB54E	MEI_REPLACE FCOS ELECTRICAL CONNECTION	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB54D	MEI_REPLACE ACCELERATOR FOOT PEDAL STOP SCREW AND SET UP CORRECTLY	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB54B	MEI_RECTIFY MINIMAL BRAKE SERVO ASSISTANCE @ BRAKE PEDAL	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB549	MEI_RECTIFY NO AMP METER LIGHT	Closed	Limited Role	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB548	MEI_RECTIFY NO VRN PLATE LIGHT	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB547	MEI_REPLACE CLUTCH MASTER CLYINDER	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB546	MEI_FIT MISSING LH TUBE IN DASH FOR BLOWERS TO WINDSCREEN	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB545	MEI_REPLACE DASH PAD	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB543	MEI_REPLACE RH DOOR EARTH STRAP	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB542	MEI_RECTIFY OIL PRESSURE WARNING LIGHT INOP	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB541	MEI_RECIFY TRAILER INDICATOR WARNING LIGHT INOP	Closed	Limited Role	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB540	MEI_REPLACE PLASTIC IN CENTRE OF DASH	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB53F	MEI_CORRECTLY SECURE INSTRUMENT PANEL	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB53C	MEI_REPLACE BOTH FRONT SHOCKS	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB53A	MEI_REPLACE BOTH RADIUS ARM BUSHES	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB539	MEI_REPLACE BOTH SETS OF FRONT BRAKES PADS	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB537	MEI_REPLACE BOTH FRONT TRACTA SEALS	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB535	MEI_REPLACE STEERING DAMPER AND BUSHES	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB523	MEI_REPLACE LH T-BOX MOUNT	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB521	MEI_SECURE REAR LH WHEEL STATION BACKING PLATE	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB51F	MEI_RENEW BOTH REAR BRAKE PADS AND DISCS	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB51E	MEI_REPLACE BOTH REAR LOWER LINK ARM BUSHES	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB51D	MEI_REPLACE A-FRAME BUSHES	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB51B	MEI_REPLACE FUEL TANK BUSHES AND FIT CORRECTLY	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB51A	MEI_REPLACE REAR ANTI ROLL BAR AND ALL BUSHES AND BALL JOINTS	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB519	MEI_REPLACE RH DOOR CARD POCKET	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB518	MEI_FIT ALL MISSING DOOR CARD RIVETS	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB517	MEI_REPLACE REAR BOTTOM DOOR SEAL	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB514	MEI_FIT MISSING REAR DOOR INNER HANDLE	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB513	MEI_SECURE REAR DOOR CARD	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB50F	MEI_CORRECTLY SECURE CENTRE TUNNELING	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB50E	MEI_REPLACE PASS SEAT COMPLETE	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB50C	MEI_REPLACE LH DOOR BOTTOM HINGE	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB503	MEI_FIT MISSING SLEAVE FROM BLOWER CONTROL	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB502	MEI_FIT MISSING WEAPON MOUNT RUBBER PADS	Closed	Limited Role	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB4F	MEI_CORRECTLY SECURE RH MIRROR	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB4FD	MEI_CORRECTLY FIT FFR BATTERIES AND ENSURE TEST BUZZER SOUNDS	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB4E3	MEI_FIT MISSING MAIN NEG TERMINAL COVER	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB4E1	MEI_FIT MISSING MAT ON TOP OF BATTERY BOX	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB4CD	MEI_FIT MISSING RUBBER SLEAVES ON LH DOOR LOCK	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB4CF	MEI_FIT MISSING WINDOW STICKERS	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB3C1	MEI_REPLACE BOTH BONNET HINGE BUSHES	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB3B9	MEI_REPLACE LH TUAM MOUNT	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB3AF	MEI_CORRECTLY SECURE LH HEADLIGHT AND CARRY OUT HEADLIGHT AIM CHECK	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB3A6	MEI_REPLACE ALL RUBBER MOUNTS ON CHARGE AIR COOLER	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB3A3	MEI_REPLACE ALL RUBBER MOUNTS ON RADIATOR	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB38B	MEI_FIT MISSING FFR ALTERNATOR BELT	Closed	Limited Role	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB389	MEI_REPLACE BOTTOM FFR IDLER PULLEY	Closed	Limited Role	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AC5C34	EX-PP1-18/19-OFF-PLATFORM	Closed	Fully Fit	No	Level 2	000000-000059B5	05 Jul 2018	N/A	Non Specific	TUM HS FFR HARD TOP	000:00
000000-00AC5C15	EX-PP1-18/19-INSPECT	Closed	Fully Fit	No	Level 2	000000-000059B4	05 Jul 2018	N/A	OHM Response	TUM HS FFR HARD TOP	000:00
000000-00AEB553	MEI_RE-SET ENGINE VALVE TAPPETS	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB54F	MEI_RECTIFY FUEL LEAK @ FIP	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB54C	MEI_SECURE/REPLACE RH DOOR STAY BAR BRACKET	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB54A	MEI_CORRECTLY SECURE ALL WIRES @ FUSE PANEL	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB544	MEI_RECTIFY NO RESERVE TRAVEL ON HAND BRAKE	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB53E	MEI_RECTIFY OIL SEAP @ FRONT DIFF	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB53D	MEI_RECTIFY OIL SEAP @ FRONT ENGINE OIL SUMP	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB53B	MEI_CORRECTLY ROUTE AND SECURE FRONT AXLE BREATHER	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB538	MEI_RECIFY OIL SEAP @ BOTH ENDS OF FRONT AXLE	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB536	MEI_RECTIFY OIL SEAP @ GEARBOX INTER COOLER	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB526	MEI_RECTIFY OIL SEAP @ BELL HOUSING	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB525	MEI_RECIFY CLUTCH FLUID SEAP @ SLAVE CLYINDER	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB524	MEI_RECTIFY OIL SEAP @ T-BOX SUMP	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB51C	MEI_CORRECTLY SECURE BOTH REAR SHOCKS	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB516	MEI_SECURE INNER ROOF LINER CORRECTLY	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB515	MEI_REMOVE GS SEAT FROM REAR OF VEHICLE	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB511	MEI_RECTIFY LH CES BIN DOOR UNABLE TO BE SECURED IN CLOSE POSTION	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB510	MEI_STRAIGHTEN/REPLACE LH DOOR STAY BAR BRACKET AND SECURE CORRECTLY	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB50A	MEI_SECURE/REPLACE LH DOOR WINDOW PART	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB4FC	MEI_CORRECTLY SECURE LH FOG LIGHT	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3CD	MEI_SECURE LH MIRROR	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3CB	MEI_SECURE LH SIDE LIGHT	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3C5	MEI_FIT MISSING BREATHER PIPE ON STEERING FLUID POT	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3B5	MEI_REPLACE LH SIDE INDICATOR	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3AC	MEI_FIT ALL MISSING SCREWS IN FRONT GRILLE	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB397	MEI_SECURE/REPLACE LH WINDSCREEN HINGE	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB36C	MEI_SET SG READING BETWEEN -37 TO -48	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3E8	LR_vehicle not going into gear	Closed	Non-Taskworthy	No	Level 2		01 Oct 2018	N/A	Failure	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AEB534	MEI_RECTIFY OIL SEAP @ TURBO	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEB533	MEI_RECTIFY OIL SEAP @ ENGINE OIL FILTER	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB522	MEI_TIGHTEN PROP BOLTS @ HAND BRAKE DRUM	Closed	Non-Taskworthy	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB512	MEI_SECURE LH REAR CAM POLE HOLDER	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB506	MEI_FIT CORRECT FUSE @ NO. 16 AND 17	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB505	MEI_RE-POSTION WIPERS	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB501	MEI_TORQUE ALL WHEEL NUTS AND FIT WHEEL NUT INDICATORS CORRECTLY	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB4FF	MEI_CORRECTLY GREASE ALL GREASE POINTS	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB4E2	MEI_SECURE BATTERIES	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3C7	MEI_RECTIFY ENGINE OIL OVER FILLED	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3C3	MEI_REPLACE BOTH WIPERS AND WIPER ARMS	Closed	Non-Taskworthy	No	Level 1		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB3B7	MEI_CORRECTLY FIT FAN COWLING	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB391	MEI_REPLACE STEERING FLUID	Closed	Fully Fit	No	Level 2		22 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AEB4D4	MEI_FIT MISSING RUBBER SLEAVES FROM LH DOOR LOCK	Closed	Fully Fit	No	Level 1		22 Oct 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00AEGC05	MEI_RE-ROUTE UMS MOD CABLE.	Closed	Fully Fit	No	Level 2		09 Oct 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AD1307	WC1- REPLACE MISSING WHEEL NUT INDIC	Closed	Non-Taskworthy	No	Level 2		08 Aug 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00AD1305	WC1- REPAIR LIGHTS	Closed	Non-Taskworthy	No	Level 2		08 Aug 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00

J06760-2476E000	REPLACE CLUTCH	Closed	Non-Taskworthy	No	Level 2	09 Jul 2018	N/A	Failure	TUM HS FFR HARD TOP	000:00
000000-00A0BECF8	PS1_REAR RIGHT BRAKE PADS AND DISC WORN (RECON FAULT)	Closed	Fully Fit	No	Level 2	18 Jun 2018	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A0C93C	MEI_FIT MISSING BONNET ADJUST SCREW RUBBERS	Closed	Fully Fit	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A0C93B	MEI_RENEW R-CLIP AND NAPPY PIN AND CHAINS AT REAR PINTLE	Closed	Limited Role	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A08681B	VEHICLE NOT TO LEAVE CAMP UNTIL FIRE EXTINGUISHER AND JACK HAVE BEEN INSPECTED AND PASSED AS FULLY FIT	Closed	Limited Role	No	Level 1	12 Jan 2018	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A79A8E	MEI_CARRY OUT MOD 46	Closed	Fully Fit	No	Level 1	24 Nov 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A3EFF7	CARRY OUT PRAIRIE PHOENIX 2017/2018	Closed	Fully Fit	No	Level 2	24 Jul 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00AA042F	000000-0032DEA4 LANDROVER_Secure Top Section Of LH Door	Closed	Non-Taskworthy	No	Level 2	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA042E	000000-0032DEA4 LANDROVER_Rectify Leak At Turbo Top Pipe	Closed	Non-Taskworthy	No	Level 2	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA042D	000000-0032DEA4 LANDROVER_Rectify Oil Leak At Oil Filter	Closed	Non-Taskworthy	No	Level 2	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA042B	000000-0032DEA4 LANDROVER_Rectify Coolant Leak Around Water Pump/Thermostat Housing	Closed	Non-Taskworthy	No	Level 2	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA042A	000000-0032DEA4 LANDROVER_Secure LHR Radio Import/Export Hole	Closed	Non-Taskworthy	No	Level 1	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA0428	000000-0032DEA4 LANDROVER_Remove Paint From Diesel Warning Sign At Fuel Cap	Closed	Non-Taskworthy	No	Level 1	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA0426	000000-0032DEA4 LANDROVER_Adjust LH Door Lock Anchor	Closed	Non-Taskworthy	No	Level 1	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00AA0425	000000-0032DEA4 LANDROVER_Adjust Engine Oil To Correct Level	Closed	Non-Taskworthy	No	Level 1	20 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A7DABD	000000-0032DEA4 MEI_RENEW WINDSCREEN	Closed	Non-Taskworthy	No	Level 2	05 Dec 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A73ED7	000000-0032DEA4 MEI_REPLACE STEERING DROP ARM	Closed	Non-Taskworthy	No	Level 2	16 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C95E	000000-0032DEA4 MEI_FIT MISSING FFR BATTERY SECURING BRACKET	Closed	Limited Role	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C95B	000000-0032DEA4 MEI_FIT REMUS CUSHIONS AND COVERS	Closed	Non-Taskworthy	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C959	000000-0032DEA4 MEI_RECTIFY CORRECT OPERATION OF WIPERS (NO SWEEP AT EITHER JET OPERATION OR INTERMITTENT)	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C957	000000-0032DEA4 MEI_WIPERS WORKING INTERMITTENTLY	Closed	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C950	000000-0032DEA4 MEI_RECTIFY FAILED EMISSIONS	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C94E	000000-0032DEA4 MEI_STEAM CLEAN UNDER VEHICLE	Closed	Fully Fit	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C945	000000-0032DEA4 MEI_RECTIFY RIGHT TRACTA SEAL SEEPAGE	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C944	000000-0032DEA4 MEI_RECTIFY COOLANT SEEPAGE AT RADIATOR	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C943	000000-0032DEA4 MEI_RENEW STEERING ROD	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C942	000000-0032DEA4 MEI_FIT MISSING BOWMAN SIDE MOUNT PORT HOLE GROMMET AT HARD TOP	Closed	Fully Fit	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C93F	000000-0032DEA4 MEI_RENEW REAR DOOR CARD AND PULL HANDLE	Closed	Limited Role	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C935	000000-0032DEA4 MEI_PAINT FUEL CAP YELLOW	Closed	Non-Taskworthy	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C932	000000-0032DEA4 MEI_FIT WING NUTS TO ALL FFR BATTERY CONNECTORS	Closed	Limited Role	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C930	000000-0032DEA4 MEI_RENEW BOTH REAR SEAT BELTS AND 1X CLIP IN SECTION	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C92F	000000-0032DEA4 MEI_FIT MISSING PAX SIDE WINDOW (REAR WINDOW HANDLE) INSURE WINDOW LOCKS	Closed	Fully Fit	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C929	000000-0032DEA4 MEI_FIT MISSING PAX SEAT FOLD LEAVER HANDLE	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C926	000000-0032DEA4 MEI_FIT MISSING FUSE COVER SCREW IN CAB	Closed	Fully Fit	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C924	000000-0032DEA4 MEI_CLEAN/RE-GREASE BATTERY TERMINALS WITH CORRECT GREASE (PX-7)	Closed	Non-Taskworthy	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C922	000000-0032DEA4 MEI_FIT MISSING FRONT WINDOW PLASTIC INNER TRIM ON BOTH SIDES	Closed	Fully Fit	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C921	000000-0032DEA4 MEI_ALIGN STEERING WHEEL	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C920	000000-0032DEA4 MEI_SECURE INSTRUMENT PANEL	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C91F	000000-0032DEA4 MEI_FIT MISSING EARTH STRAPS AT BOWMAN CENTER CONSOLE BETWEEN SEATS	Closed	Limited Role	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C91E	000000-0032DEA4 MEI_RECTIFY HAZARD WARNING LAMP AT INSTRUMENT PANEL INOP	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C914	000000-0032DEA4 MEI_RENEW DVRS DOOR CARD AND SECURING GROMMETS	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C910	000000-0032DEA4 MEI_RENEW BONNET CES SECURING STRAPS	Closed	Fully Fit	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C90A	000000-0032DEA4 MEI_RENEW F/L TUAMM EARTH STRAP	Closed	Limited Role	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C902	000000-0032DEA4 MEI_STEAM CLEAN ENGINE BAY	Closed	Fully Fit	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C901	000000-0032DEA4 MEI_RENEW ROCKER COVER GASKET	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C8FF	000000-0032DEA4 MEI_ADJUST SG READING TO CORRECT LEVEL (-34 TO -48)	Closed	Non-Taskworthy	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6F0E3	000000-0032DEA4 ESG_COMMS_INSTALL & TEST BOWMAN SYSTEM FOR EX PP 2	Closed	Non-Taskworthy	No	Level 2	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	ESG Comms 000:00
000000-00A6C934	000000-0032DEA4 MEI_RECTIFY PRESS TO TEST INOP	Closed	Limited Role	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C923	000000-0032DEA4 MEI_RENEW CENTER TOP COOLANT HOSE JUBILEE CLIP AT RADIATOR	Closed	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	LANDROVER 000:00
000000-00A6C912	MEI_RENEW WINDSHIELD AND SEAL	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A79A8B	MEI_CARRY OUT UMS MOD	Awaiting Labour	Fully Fit	No	Level 1	24 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C966	MEI_CHECK/ADJUST HANDBRAKE	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C964	MEI_RENEW REAR BRAKE PADS	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C962	MEI_FIT MISSING REAR SEAT FOLD AWAY SECURING STRAP	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C952	MEI_RECTIFY BRAKE PRESSURE LIGHT FAILING TO COME ON WHEN STARTING VEHICLE	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C94C	MEI_CARRY OUT ALL GREASING TASKS	Awaiting Labour	Non-Taskworthy	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C94A	MEI_TIGHTEN FRONT PROP BOLTS	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C948	MEI_SECURE G-BOX OIL COOLER PIPE BRACKET AT ENGINE	Awaiting Labour	Fully Fit	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C947	MEI_SECURE G-BOX BREATHER PIPES AT REAR OF ENGINE AND FIT MISSING P-CLIP	Awaiting Labour	Fully Fit	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C946	MEI_RENEW PANHARD ROD BUSHES	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C940	MEI_RENEW R/L TOP SHOCK BUSH	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C93D	MEI_RENEW REAR DOOR SEAL	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C938	MEI_RENEW REAR DOOR EARTH STRAP	Awaiting Labour	Limited Role	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C92D	MEI_RECTIFY DVRS DOOR FAILING TO LOCK	Awaiting Labour	Fully Fit	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C92C	MEI_REMOVE SPARE WHEEL MOD BRACKET FROM R/R WHEEL	Awaiting Labour	Non-Taskworthy	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C92A	MEI_RECTIFY PAX DOOR NOT CORRECTLY SHUTTING	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C927	MEI_FIT MISSING PAX SIDE FOOT BLOWING DIRECTION COVER	Awaiting Labour	Fully Fit	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C925	MEI_FIT CORRECT FUSES AT IN CAB FUSE BOX	Awaiting Labour	Non-Taskworthy	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C91D	MEI_SECURE HAZARDS, FOG, LIGHT LEVEL SWITCH SURROUND	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C91C	MEI_FIT MISSING RIFLE RACK RUBBERS	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C91B	MEI_RENEW DVRS SEAT	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C91A	MEI_RENEW DVRS SEATBELT	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C919	MEI_SECURE PAX DOOR CARD	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C917	MEI_RENEW PAX DOOR SEAL	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C910	MEI_RENEW DVRS WIPER BLADE	Awaiting Labour	Non-Taskworthy	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C916	MEI_RENEW BOTH EARTH STRAPS	Awaiting Labour	Limited Role	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C90D	MEI_RENEW BOTH BONNET STAY BAR CLIP AND GROMMET	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C909	MEI_FIT MISSING VEHICLE ALTERNATOR LIVE TERMINAL COVER	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C907	MEI_FIT MISSING SCREWS/WASHERS AT FRONT GRILLE	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C906	MEI_FIT MISSING WASHERS AT GRILL TOP BRACKET	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C904	MEI_RENEW COOLANT HOSE RETAINING CLIP AT WATER PUMP	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C903	MEI_FIT MISSING CABLE SECURING CLIP AT R/L OF AIR FILTER HOUSING	Awaiting Labour	Fully Fit	No	Level 1	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C900	MEI_RENEW FAN BELT	Awaiting Labour	Non-Taskworthy	No	Level 2	31 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A6C968	MEI_EX PP 2017/18 PHASE 1 INSPECTION/JAMES	Closed	Fully Fit	No	Level 1	01 Nov 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-009E6086	4REME_LR_RECTIFY RADIO BATTERY TEST BUTTON INOP.	Closed	Fully Fit	No	Level 2	22 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A64C85	3RHA_IRON_STRIKE_REPLACE FFR BELT	Closed	Non-Taskworthy	No	Level 2	17 Oct 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A64C7C	3RHA_IRON_STRIKE_REPLACE WINDSCREEN	Closed	Non-Taskworthy	No	Level 2	17 Oct 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A48D48	3RHA_IRON_STRIKE_REAR TOWING EYE PIN MISSING	Closed	Limited Role	No	Level 1	14 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A48D47	3RHA_IRON_STRIKE_PASSENGER DOOR BARRREL MISSING	Closed	Fully Fit	No	Level 2	14 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A01FDE	4REME_LR_RENEW DRIVER DOOR SEAL	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A01FDB	4REME_LR_RENEW PASSENGER DOOR SEAL	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00A48D45	3RHA_IRON_STRIKE_REAR SEAT BELT BUCKLE DAMAGED	Closed	Limited Role	No	Level 2	14 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A4C0D0	3RHA_IRON_STRIKE_OBSERVE COOLANT LEAK	Closed	Limited Role	No	Level 2	24 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A4C0D5	3RHA_IRON_STRIKE_REPLACE FUEL FILLER CAP	Closed	Non-Taskworthy	No	Level 1	24 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-00A48D4A	3RHA_IRON_STRIKE_COOLANT LEAK L/H SIDE OF ENGINE	Closed	Non-Taskworthy	No	Level 2	14 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00

000000-00A48D49	3RHA_IRON_STRIKE_VEHICLE ALTERNATOR POSTIVE TERMINAL RIVETS LOOSE	Closed	Non-Taskworthy	No	Level 2	14 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A46DF8	HCR_IRON STRIKE_REPLACE FLASHER CAN	Closed	Non-Taskworthy	No	Level 2	07 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A46DF7	HCR_IRON STRIKE_RECTIFY LEAK @OIL PRESSURE SWITCH	Closed	Non-Taskworthy	No	Level 2	07 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A46DF6	HCR_IRON STRIKE_RENEW PANARD ROD BUSHES	Closed	Non-Taskworthy	No	Level 2	07 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A46DE7	renew flasher can relay	Closed	Non-Taskworthy	No	Level 2	07 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A46DE6	renew oil pressure switch.	Closed	Fully Fit	No	Level 2	07 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-009C2751	000000-0031C4DF COMPLETE EXERCISE PRAIRIE PHOENIX	Closed	Fully Fit	No	Level 2	06 Sep 2016	N/A	Closed No Action	TUM HS FFR HARD TOP	WRP LANDROVER
000000-00A08ABF	Carry out Activation Task (Do Not Remove Until Activation)	Closed	Non-Taskworthy	No	Level 1	06 Mar 2017	N/A	Non Specific	TUM HS FFR HARD TOP	
000000-00A0200E	VEH JACK NOT PRESENTED FOR INSP	Closed	Limited Role	No	Level 1	14 Feb 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A0200C	CES NOT PRESENTED FOR INSP	Closed	Limited Role	No	Level 1	14 Feb 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A0200A	FIRE EXT NOT PRESENTED	Closed	Limited Role	No	Level 1	14 Feb 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A168AE	PS1_4REME_LR_L1_COOLANT LOW	Closed	Fully Fit	No	Level 1	08 Apr 2017	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00A168AD	PS1_4REME_LR_L1_ENGINE OIL LOW	Closed	Fully Fit	No	Level 1	08 Apr 2017	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00A01FD7	000000-0031C4DF 4REME_LR_RENEW REAR BRAKE LIGHT RUBYS	Closed	Fully Fit	No	Level 1	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-00A01FE1	000000-0031C4DF 4REME_LR_RENEW BONNET RETAINING CLIP	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-00A01FDD	000000-0031C4DF 4REME_LR_RENEW FFR ALTERNATOR BELT	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-00A01FDC	000000-0031C4DF 4REME_LR_RENEW PASSENGER DOOR BARRELL	Closed	Fully Fit	No	Level 2	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-00A01FDF	000000-0031C4DF 4REME_LR_RENEW R/H RADIUS ARM TOP BUSH	Closed	Non-Taskworthy	No	Level 2	14 Feb 2017	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6091	000000-0031C4DF 4REME_LR_RENEW N/S/F CAM POLE HOLDER	Closed	Non-Taskworthy	No	Level 1	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-00A01FE0	4REME_LR_RENEW REAR BRAKE PADS	Closed	Non-Taskworthy	No	Level 2	15 Feb 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00A01FD9	4REME_LR_RENEW NEGATIVE BATTERY COVER	Closed	Fully Fit	No	Level 1	15 Feb 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-009E608C	000000-0031C4DF 4REME_LR_RENEW N/S/R LOWER SHOCK.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6088	000000-0031C4DF 4REME_LR_TIGHTEN FRONT AND REARTIE DOWN SHACKLES.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6084	000000-0031C4DF 4REME_LR_RENEW REAR EARTH STRAP AT REAR DOOR	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009FA2CE	000000-0031C4DF 4REME_LR_carry out Ex pp2 17 inspection.	Closed	Non-Taskworthy	No	Level 2	25 Jan 2017	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6092	000000-0031C4DF 4REME_LR_NUMBER PLATE LIGHT LOOSE.	Closed	Fully Fit	No	Level 1	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6090	000000-0031C4DF 4REME_LR_O/S/F WATER LEAK IN INTERLAP.	Closed	Non-Taskworthy	No	Level 1	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E608F	000000-0031C4DF 4REME_LR_N/S/F MIRROR LOOSE.	Closed	Non-Taskworthy	No	Level 1	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E608B	000000-0031C4DF 4REME_LR_FRONT BUMPER DENTED	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E608A	000000-0031C4DF 4REME_LR_RENEW TRACTA SEAL.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6089	000000-0031C4DF 4REME_LR_RENEW FRONT PANHARD ROD BUSH.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6085	000000-0031C4DF 4REME_LR_BATTERY INSECURE.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6083	000000-0031C4DF 4REME_LR_N/S/F WINDOWS DONT OPEN.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6082	000000-0031C4DF 4REME_LR_N/S/F DOOR BOTTOM HINGE LOOSE.	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009E6081	000000-0031C4DF 4REME_LR_REPLACE N/S/F WING	Closed	Non-Taskworthy	No	Level 2	23 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	WRP LANDROVER
000000-009B1738	Passenger window door slide missing	Closed	Fully Fit	No	Level 2	16 Jul 2016	N/A	Failure	TUM HS FFR HARD TOP	
000000-009B1737	Rear door lock U/S	Closed	Fully Fit	No	Level 2	16 Jul 2016	N/A	Inspection	TUM HS FFR HARD TOP	
J06209-1BF6000	investigate excessive black smoke from exhaust	Closed	Fully Fit	No	Level 2	20 Jun 2016	N/A	Inspection	TUM HS FFR HARD TOP	
J06209-1BF6001	Radio batteries not charging	Closed	Limited Role	No	Level 2	20 Jun 2016	N/A	Failure	TUM HS FFR HARD TOP	
J06206-1BB9C000	Read door lock U/S	Closed	Fully Fit	No	Level 2	19 Jun 2016	N/A	Failure	TUM HS FFR HARD TOP	
000000-00999006	RECTIFY FAULTS FOUND ON 932/933. MEI/2016/1117	Closed	Limited Role	Yes	Level 1	31 May 2016	N/A	Inspection	TUM HS FFR HARD TOP	
000000-008011FC	BATTERY PRESS TO TEST SWITCH INOP	Closed	Fully Fit	No	Level 1	10 Apr 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-008011FD	ROOF BLANKING PLATE MOD NOT FITTED	Closed	Fully Fit	No	Level 2	10 Apr 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-008011FF	GLOW PLUG INTERFACE MOD NOT FITTED	Closed	Fully Fit	No	Level 2	10 Apr 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00801200	IMPORT/EXPORT MOD NOT FITTED	Closed	Fully Fit	No	Level 2	10 Apr 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00874ED1	renew panhard rod	Closed	Fully Fit	No	Level 2	16 Feb 2015	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00874ED2	renew strg shaft	Closed	Fully Fit	No	Level 2	16 Feb 2015	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00876203	CARRY OUT WORK PICKED UP ON MEI 16/02/15	Closed	Fully Fit	No	Level 2	16 Feb 2015	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0095E9AB	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	13 Jan 2016	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0098E8A1	**WRP LR** 15/16	Closed	Fully Fit	No	Level 2	04 May 2016	N/A	Inspection	TUM HS FFR HARD TOP	
000000-008B5F75	000000-0030E2E1 **WRP LR** TUM BRP 15/16	Closed	Fully Fit	No	Level 2	11 Aug 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	BATUS WKSP WRP LANDROVER
000000-008D5BA1	**WRP LR** FFR BRP 15/16	Closed	Fully Fit	No	Level 2	04 Nov 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-008C000E	**ESG** LR BRP 15/16	Closed	Fully Fit	No	Level 2	10 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP	BATUS WKSP ESG Comms L2
000000-0088B828	000000-0030ADF8 CARRY OUT 6 MONTHLY SAFETY INSPECTION (6534)	Closed	Non-Taskworthy	Yes	Level 1	20 Aug 2015	N/A	Inspection	TUM HS FFR HARD TOP	
J06166-16CA000	test	Closed	Fully Fit	No	Level 2	29 Apr 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	
J06174-16CA4000	TEST	Closed	Fully Fit	No	Level 1	29 Apr 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0087DABC	Carry out Activation Task (Do Nnot Remove Until Activation)	Closed	Non-Taskworthy	No	Level 1	10 Mar 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-008788A2	issue ces,jack and fire ext	Closed	Non-Taskworthy	No	Level 1	25 Feb 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-008760B9	ESG_BRP15_COMMS_LANDROVER	Closed	Fully Fit	No	Level 2	02 Feb 2015	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0084E8DA	***DEACTIVATION INSPECTION BRP***	Closed	Fully Fit	No	Level 2	02 Nov 2014	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00842E98	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	09 Oct 2014	Degraded	Inspection	TUM HS FFR HARD TOP	
000000-0084B670	REPLACE DAMAGED LH HUB ASSY	Closed	Fully Fit	No	Level 2	26 Oct 2014	Degraded	Inspection	TUM HS FFR HARD TOP	
000000-00841CC5	REPLACE LOWER STEERING UNIVERSAL JOINT	Closed	Fully Fit	No	Level 2	07 Oct 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-008011F8	DIFF LOCK LIGHT INOP	Closed	Fully Fit	No	Level 2	10 Apr 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0082C3CE	RENEW WINDSCREEN	Closed	Limited Role	No	Level 2	08 Aug 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
J00200-12F2A000	RENEW ALTERNATOR	Closed	Non-Taskworthy	No	Level 2	05 Jun 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-008011FA	FIRE EXTINGUISHER NOT PRESENTED	Closed	Non-Taskworthy	No	Level 1	10 Apr 2014	N/A	Inspection	TUM HS FFR HARD TOP	
000000-007CE9C3	REHABILITATE VEHICLE IN ACCORDANCE WITH STANDARD REPAIR ACTIONS LISTED IN BATUS WKSP SOP 4.22(WRP 2014)	Closed	Fully Fit	No	Level 2	21 Nov 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0077D91E	RENEW W/SCREEN SEAL	Closed	Fully Fit	No	Level 2	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D91A	FIT G-BOX OIL COOLER PIPE BRKT AT ENGINE	Closed	Fully Fit	No	Level 2	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-007AE4F0	Pls carry out 6 monthly 6534 insp.	Closed	Fully Fit	No	Level 1	23 Aug 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D9BF	6 MONTHLY 6534 INSP ENTERED INCORRECTLY, NEXT DUE DATE 01-OCT-13	Closed	Fully Fit	No	Level 1	10 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D9AB	MEI ENTERED INCORRECTLY, NEXT DUE 02-APR-2014	Closed	Fully Fit	No	Level 1	10 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D92A	MOD 38 NOT EMBODIED	Closed	Fully Fit	No	Level 2	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D921	FIT BONNET STAY CLIP	Closed	Fully Fit	No	Level 1	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D91C	FIT EGR BREATHER PIPE CLIP	Closed	Fully Fit	No	Level 2	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D91B	LOCATE ENGINE NUMBER FOR NEXT MEI	Closed	Fully Fit	No	Level 2	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D918	FIT PSGR HEAD REST	Closed	Fully Fit	No	Level 1	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D916	FIT FLOOR MATTING	Closed	Fully Fit	No	Level 1	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D913	FIT BATT TERMINAL COVERS	Closed	Fully Fit	No	Level 1	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-007C2C02	ESG-COMMS-BVEH-WRP14	Closed	Fully Fit	No	Level 2	20 Oct 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0077D927	NO JACK PRESENTED	Closed	Limited Role	No	Level 1	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0077D926	NO FIRE EXTINGUISHER PRESENTED	Closed	Limited Role	No	Level 1	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-007977A3	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	24 Jun 2013	N/A	Failure	TUM HS FFR HARD TOP	
000000-0079A803	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	25 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0077D917	FIT PSGR FLOOR BOLTS	Closed	Fully Fit	No	Level 2	02 Apr 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-007578BE	REHABILITATE VEHICLE IN ACCORDANCE WITH STANDARD REPAIR ACTIONS LISTED IN BATUS WKSP SOP 4.22	Closed	Non-Taskworthy	No	Level 2	12 Dec 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-007027DC	RENEW BRAKE FLUID (CARRIED OUT 19/02/12 , NEXT DUE 18/02/14)*** DO NOT REMOVE THIS FAULT ***	Closed	Fully Fit	No	Level 2	19 Mar 2012	N/A	Servicing	TUM HS FFR HARD TOP	
000000-0073B7F9	000000-002DD13C Comms WRP Inspection	Closed	Fully Fit	No	Level 2	19 Sep 2012	N/A	Inspection	TUM HS FFR HARD TOP	BATUS WKSP ESG Comms L2
000000-00742B49	Renew Gearbox	Closed	Non-Taskworthy	No	Level 3	04 Oct 2012	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0073A00A	HAND BACK TO BATUS INSPECTION (SEE JOB SHEET)	Closed	Non-Taskworthy	Yes	Level 2	18 Sep 2012	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-006C5AF9	front anti sway bar bushes perished	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Closed No Action	TUM HS FFR HARD TOP	000:00
000000-0074A1C9	Comms WRP Inspection	Closed	Fully Fit	No	Level 2	30 Oct 2012	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AFB	repair/replace exhaust tailpipe	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5B00	secure both headlight guards correctly	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00

000000-006C5B01		tighten screws above front grill	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AFE		secure dash correctly	Closed	Fully Fit	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5B06		steam clean engine	Closed	Fully Fit	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-007289F4		RENEW WATER PUMP	Closed	Non-Taskworthy	No	Level 2	22 Jul 2012	N/A	Failure	TUM HS FFR HARD TOP	
000000-00705571	000000-002D8CA2	WRP comms inspection	Closed	Fully Fit	No	Level 2	14 Mar 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006C5B08		over due 6534 insp	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5B07		carry out relevant servicing tasks as per james	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5B05		top up oil level, below low	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5B04		replace front left tyre, wall cracked	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5B03		remove spare wheel valve extension from front left wheel	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AFF		refit rubber grommet in vehicle battery box	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AFC		carry out relevant vm tasks as per james	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF8		inv oil leak at transfer box	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF7		renew clutch fluid	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF6		renew number 1 ball joint	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF5		2 yearly brake fluid change needed and entered onto james	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF4		no glow plug warning light on dash	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF3		fit missing rubber grommet behind clutch pedal	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF2		fit handbrake boot correctly	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF1		fit missing dvr door card securing clips	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AF0		dvr window lock inop	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AEF		fit spare wheel and correctly fit spare wheel harness	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AEE		renew rhr tyre	Closed	Non-Taskworthy	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AED		no fuel cap key	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AEC		emergency hammer not present	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AE7		correctly fit radio batts with breather pipes + check polarity buzzer	Closed	Limited Role	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AE6		secure rear door check strap	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AE5		straighten pas side bin to stop fouling	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AE3		remove sharp edge from pas door	Closed	Fully Fit	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AE2		renew pas seat belt	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5AE0		secure veh batt positive pole (not the clamp)	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5ADE		renew "A" pillar/windscreen trim	Closed	Fully Fit	No	Level 1	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5ADD		windscreen demister inop	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C5ADB		left headlight is dim and has no full beam	Closed	Non-Taskworthy	No	Level 2	31 Aug 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006B627C		RECTIFY INCORRECTLY FITTED DROP ARM TAB WASHER	Closed	Non-Taskworthy	No	Level 2	06 Jul 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006AE7E9		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	22 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-00485C0B	000000-0029A51F	RENEW CLUTCH MASTER CYLINDER	Closed	Non-Taskworthy	No	Level 2	09 Oct 2009			TUM HS FFR HARD TOP	
000000-004501F2	000000-00298DAE	CARRY OUT CHASSIS DROP TEST / STEERING GEOMETRY TEST	Closed	Non-Taskworthy	No	Level 3	02 Jul 2009			TUM HS FFR HARD TOP	
000000-004501EF	000000-00298DAE	RENEW ENGINE WOODRUFF KEY WORN	Closed	Non-Taskworthy	No	Level 3	02 Jul 2009			TUM HS FFR HARD TOP	
000000-0047EADF	000000-00298DA9	RENEW ENGINE	Closed	Fully Fit	No	Level 2	25 Sep 2009			TUM HS FFR HARD TOP	
000000-004352A8	000000-00290F72	2 Yr Service and 5 Yr OOPM to WFMA Standard for TXR to TFSU Ashchurch	Closed	Non-Taskworthy	No	Level 1	23 Jun 2009			TUM HS FFR HARD TOP	
000000-004209A6	000000-0028FACB	OBSERVE OIL SEEPAGE AT SUMP	Closed	Fully Fit	No	Level 2	13 May 2009			TUM HS FFR HARD TOP	
000000-004209A1	000000-0028FACB	SECURE WIPER MOTOR SHROUD	Closed	Fully Fit	No	Level 2	13 May 2009			TUM HS FFR HARD TOP	
000000-0042099C	000000-0028FACB	SECURE DVRS DOOR TRIM	Closed	Fully Fit	No	Level 2	13 May 2009			TUM HS FFR HARD TOP	
000000-00420995	000000-0028FACB	CENTRALISE STEERING WHEEL	Closed	Fully Fit	No	Level 2	13 May 2009			TUM HS FFR HARD TOP	
000000-00419AD6	000000-0028C2D5	RENEW HANDBRAKE CABLE	Closed	Non-Taskworthy	No	Level 2	29 Apr 2009			TUM HS FFR HARD TOP	
000000-00419ACE	000000-0028C2D5	CARRY OUT 12 MONTHLY VM TASKS AS PER AESP 601 TABLE 7 COLUMN B	Closed	Non-Taskworthy	No	Level 2	29 Apr 2009			TUM HS FFR HARD TOP	
000000-003DDA85	000000-0028906F	12 Mty Service	Closed	Non-Taskworthy	No	Level 1	09 Mar 2009			TUM HS FFR HARD TOP	
000000-00334401		RENEW FFR ALTERNATOR	Closed	Fully Fit	No	Level 2	24 Nov 2008			TUM HS FFR HARD TOP	
000000-00316630		6534 Inspection	Closed	Fully Fit	No	Level 1	14 Nov 2008			TUM HS FFR HARD TOP	
000000-00180AB7		FAIL MEI 14/4/08 FOR REAR SHOCKS	Closed	Non-Taskworthy	No	Level 2	15 May 2008			TUM HS FFR HARD TOP	
000000-000462E5		Initial Usage	Closed	Fully Fit	No	Level 1	17 Jan 2007			TUM HS FFR HARD TOP	
000000-000462FE		Initial Maintenance	Closed	Fully Fit	No	Level 1	17 Jan 2007			TUM HS FFR HARD TOP	

Work Objects

Serial Number: KD37AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-004E547F		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-007E05AE		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-007E0587		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00202DAB		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-006A5D06		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00AD4ACD		No	FMT931 Comms (2)*	28 Aug 2020	Level 2	Limited Role	CL	000:00		ESG Comms
000000-00592E7B		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	WiP	000:00		
000000-00097A12		No	MEI (2)		Level 2		CL	000:00		
000000-000F5B07		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-003AF65D		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-007843E9		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-0026A10B		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-001C6C60		No	MEI (2)		Level 2			000:00		
000000-00C2C04C		No	Annual Headlight Alignment Check (2)	22 Mar 2021	Level 2	Fully Fit	CL	000:00		
000000-004E547B		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-0026A10A		No	MEI (2)		Level 2			000:00		
000000-00C2C04A		No	Annual Brake Test (2)	22 Mar 2021	Level 2	Fully Fit	CL	000:00		
000000-0089EFD8		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-0094C2D8	000000-0032DEA4	No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		LANDROVER
000000-00BD9ACD		No	FMT931 Comms (2)*	28 Aug 2020	Level 2	Fully Fit	CL	000:00		ESG Comms
000000-0026A0E8		No	MEI (2)		Level 2			000:00		
000000-001C6C61		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-006A5D05		No	MEI (2)		Level 2			000:00		
000000-00BD03BB	000000-00346079	No	FMT932 (W) Mandatory Equipment Inspection (2)*	19 Feb 2021	Level 2	Fully Fit	CL	000:00	BATUS WKSP	MEI CELL
000000-001C6C62		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00C2C04D		No	Annual Smoke Emissions Test(2)	22 Mar 2021	Level 2	Fully Fit	CL	000:00		
000000-0045DD68		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00C2C049	000000-00346079	No	FMT932 (W) 6 Monthly Safety Inspection (2)	21 Aug 2020	Level 2	Fully Fit	CL	000:00	BATUS WKSP	MEI CELL
000000-008AF4B8	000000-0032DEA4	No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		LANDROVER
000000-000801E3		No	MEI (2)		Level 2		CL	000:00		
000000-0000DDA1		No	MEI (2)		Level 2		CL	000:00		
000000-00043A73		No	MEI (2)		Level 2		CL	000:00		

000000-0006D77D		No	MEI (2)		Level 2	CL	000:00		
000000-004E547D		No	6 Monthly 6534 Insp		Level 1 Non-Taskworthy	CL	000:00		
000000-00BD03B9	000000-00346079	No	FMT933 (W) Role Equipment (2)*	19 Feb 2021	Level 2 Non-Taskworthy	CL	000:00	BATUS WKSP	MEI CELL
000000-003AF659		No	MEI (2)		Level 2 Fully Fit	CL	000:00		
000000-004E547E		No	MEI (2)		Level 2 Non-Taskworthy	CL	000:00		
000000-00C3928A		No	FMT930 Landworthiness (AR)		Level 1 Fully Fit	CL	000:00		
000000-00115B3D		No	MEI (2)		Level 2		000:00		
000000-007843EC		No	MEI (2)		Level 2 Non-Taskworthy	CL	000:00		
000000-00C2C051	000000-00346079	No	FMT934 Functional Check (1)*	21 Aug 2020	Level 1 Non-Taskworthy	CL	000:00	BATUS WKSP	MEI CELL

Work Objects

Serial Number: KD37AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description
000000-0066C5A0	00041	Fitting of Battery Negative Isolator Switch
000000-00694EBB	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS
000000-0066C59E	00024	Fitting of Trailer Breakaway Attachment Plate
000000-0066C59F	00044	This instruction details the removal of the existing six way lighting switch and the fitting of a seven way lighting switch to all variants including winter water vehicles.
000000-00015C23	00020	8 Metre Mast Mount Installation Kit
000000-00008DB2	00002	Roof Mounted Communication Installation (Blanking Plate Only)
000000-000091E3	00003	Heli-lift Vehicle Modification (Hard Top Only)
000000-00018E7D	00038	Fitting of a New Import/Export Box Mount Bracket
000000-0000FA88	00033	Rear Door Blackout Blind (FFR Variants) Only
000000-00025862	00019	Blackout Cover for Warning Light Panel
000000-00021F5B	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension
000000-00011C40	00027	Input/Output Porthole for Communication Cables, Cover Modification
000000-00018FD1	00017	Introduction of Battery Retention
000000-00022377	00037	Fitting Glow Plug Timer Interface Harness
000000-0001E475	00016	Radio Battery Isolation Switch and Power Import / Export System
000000-0000AFDC	00007	TUAAM Earth Bonding Improvements
000000-000245E1	00025	Fitting of Spare Wheel Lifting Aid Harness
000000-00014F10	00030	Front Belt Protection Sleeves
000000-0000D95A	00035	Fitting of Emergency Hammer
000000-0000AE66	00001	Radio Rack Fixings
000000-00020317	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit
000000-00014B57	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation
000000-00018062	00008	Input / Output Porthole for Comms / Power Cable Installation
000000-00019C14	00032	Project SHOEHORN Revised Weight Data Plate
000000-000003B0	00028	FITTING OF REAR ANTI-ROLL BAR (RARB)

Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
	No	1/A	Mod				Fully Fit	CL	Level 2			000:00
	No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
	No	-/	UTI				Fully Fit	CL	Level 2			
	No	3/A	Mod				Fully Fit	CL	Level 2			
	No	-/	UTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL	Level 1			
	No	-/	UTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				
	No	1/A	UTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL				
	No	1/A	UTI				Fully Fit	CL				
	No	1/A	UTI				Fully Fit	CL				
	No	1/A	UTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL				
	No	1/A	RTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				
	No	-/	RTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				
	No	-/	UTI				Fully Fit	CL				

Work Objects

Serial Number: KD37AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0045DD6B		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-0026A0DE		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	28 Oct 2021	Level 1			000:00		
000000-007640C1		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	28 Oct 2021	Level 1	Fully Fit	CL	000:00		
000000-0026A0E1		No	First 1600 Kms (AR)		Level 2			000:00		
000000-004E65B6		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	28 Oct 2021	Level 1	Fully Fit	CL	000:00		
000000-001C8713		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1			000:00		
000000-006A1CB4		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-003CD7D5		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-003AF658		No	Yearly/20000 Kms	18 Nov 2020	Level 1	Fully Fit	CL	000:00		
000000-00202DAC		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1			000:00		
000000-007640C2		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	28 Oct 2021	Level 1	Fully Fit	CL	000:00		
000000-00BD9938		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	28 Oct 2021	Level 1	Non-Taskworthy	CL	000:00		HURRICANE
000000-007843EA		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-009FD061		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	27 Oct 2024	Level 1	Non-Taskworthy	CL	000:00		
000000-009FD072		No	2 Yearly/40000 Kms	30 Apr 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-0068DFA9		No	Yearly/20000 Kms	18 Nov 2020	Level 1	Fully Fit	CL	000:00		
000000-00443C4F		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	27 Oct 2024	Level 1			000:00		
000000-004E6570		No	2 Yearly/40000 Kms	30 Apr 2021	Level 1	Fully Fit	CL	000:00		
000000-00206819		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	28 Oct 2021	Level 1			000:00		
000000-00706001		No	2 Yearly/40000 Kms	30 Apr 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-0068DFAA		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	27 Oct 2025	Level 2	Fully Fit	CL	000:00		
000000-00BD993A		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	27 Oct 2025	Level 2	Non-Taskworthy	CL	000:00		HURRICANE
000000-001C8712		No	Yearly/20000 Kms	18 Nov 2020	Level 1			000:00		
000000-00115B12		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1			000:00		
000000-00C2C047		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-0026A11E		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1			000:00		
000000-00BD993B		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	27 Oct 2024	Level 1	Non-Taskworthy	CL	000:00		HURRICANE
000000-0047DDD8		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-00B03938		No	Yearly/20000 Kms	18 Nov 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-0020681A		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	28 Oct 2021	Level 1			000:00		
J06685-205D6003		No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Fully Fit	CL	000:00		
000000-004E65B4		No	Yearly/20000 Kms	18 Nov 2020	Level 1	Fully Fit	CL	000:00		

000000-00BD9939	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	28 Oct 2021	Level 1	Non-Taskworthy	CL	000:00	HURRICANE	
000000-0020682A	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	27 Oct 2025	Level 2			000:00		
000000-00BD9957	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Non-Taskworthy	CL	000:00	HURRICANE	
000000-00B0393A	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-000F3E96	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-0007B062	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-0007ABE6	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-0007FFEE	No	2 Yearly/40000 Kms	30 Apr 2021	Level 1		CL	000:00		
000000-000ED8F2	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-00097728	No	2 Yearly/40000 Kms	30 Apr 2021	Level 1		CL	000:00		
000000-00097729	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-000F5B06	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-000D52FF	No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000E64F5	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-000CEF5A	No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-0007B495	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-0007B496	No	2 Yearly/40000 Kms	30 Apr 2021	Level 1		CL	000:00		
000000-0007B061	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-000049B4	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-000049BA	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-000149DC	No	2 Yearly/40000 Kms	30 Apr 2021	Level 1		CL	000:00		
000000-000E8715	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-000149DD	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00		
000000-000E8716	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-00022EC0	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-00022EC1	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00		
000000-00043B72	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-00043B73	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-0006D20C	No	Yearly/20000 Kms	18 Nov 2020	Level 1		CL	000:00		
000000-0006D20D	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1		CL	000:00		
000000-009FD071	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	28 Oct 2021	Level 1	Non-Taskworthy	CL	000:00		
000000-0026A0DF	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1			000:00		
000000-0058FE0C	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-00206827	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	30 Apr 2024	Level 2			000:00		
000000-004E65B5	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	28 Oct 2021	Level 1	Fully Fit	CL	000:00		
000000-007843EB	No	Yearly/20000 Kms	18 Nov 2020	Level 1	Fully Fit	CL	000:00		
000000-009FD062	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	30 Apr 2024	Level 2	Non-Taskworthy	CL	000:00		
000000-0094C2C8	000000-0032DEA4	No	6 Monthly/10000 Kms	21 Aug 2020	Level 1	Non-Taskworthy	CL	000:00	LANDROVER
000000-0026A11D	No	Yearly/20000 Kms	18 Nov 2020	Level 1			000:00		
000000-00B73DC3	No	Yearly/20000 Kms	18 Nov 2020	Level 1	Non-Taskworthy	CL	000:00	HURRICANE	
000000-00206828	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	27 Oct 2024	Level 1			000:00		
000000-0026A0DD	No	2 Yearly/40000 Kms	30 Apr 2021	Level 1			000:00		
000000-008AF4AC	000000-0032DEA4	No	Yearly/20000 Kms	18 Nov 2020	Level 1	Non-Taskworthy	CL	000:00	LANDROVER
000000-00443C50	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	30 Apr 2024	Level 2			000:00		
000000-0026A0E2	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	28 Oct 2021	Level 1			000:00		
000000-0026A0E0	No	Yearly/20000 Kms	18 Nov 2020	Level 1			000:00		
000000-009FD070	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	28 Oct 2021	Level 1	Non-Taskworthy	CL	000:00		