

Defence Equipment and Support Secretariat #2043 Maple 0a Ministry of Defence Abbey Wood Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

email:

Our Reference: FOI2021/07418

Date: 13 July 2021

Dear ,

I am writing about your email of 8 July 2021, requesting the following information:

Please could you supply me the following details you have on record for a landrover Defender HD TUL with a Service registration number of JZ 86 AA

- 1: The full Service History of the vehicle and which units it was assigned to in its service life.
- 2: The full maintenance records including all fluid and parts replaced or changed during its service life.
- 3: Any details held on large components replaced on the vehicle in its service life.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Ownership History

Annex B - Fault History (redacted)

Annex C - Inspection History

Annex D - Modification History

Annex E – Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate.

**Defence Equipment & Support** 

The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

## **VEHICLE DETAILS**

| ERM    | NATO Stock<br>Number | Asset Code | Contract<br>Number | Description                                     | Colour     |
|--------|----------------------|------------|--------------------|---|------------|
| (a)    | (b)                  | (c)        | (d)                | (e)   | <b>(f)</b> |
|        |                      |            |                    | TRUCK UTY LIGHT (TUL) (HS) 4X4 GS SOFT TOP LAND | Army/NATO  |
| JZ86AA | 2320998939741        | NB42203100 | LV2A/088AM3        | ROVER 2.5 LTR TURBO DSL (WITH EEGR)             | Green IRR  |

| Date In Service | Chassis Number    | Engine No. | Cast | Cast Date  |
|-----------------|-------------------|------------|------|------------|
| (g)             | (h)               | (i)        | (j)  | (k)        |
| 22/10/1997      | SALLDAA67VA123225 | 25L02748A  | Υ    | 11/11/2011 |

## **VEHICLE HISTORY**

| ERM    | Key No. | RIV Date   | UIN    | Unit Title                       | RIV No. | RCP No. | RCP Date   | Batch |
|--------|---------|------------|--------|----------------------------------|---------|---------|------------|-------|
| (a)    | (b)     | (c)        | (d)    | (e)                              | (f)     | (g)     | (h)        | (i)   |
| JZ86AA | 3       | 21/10/1997 | CA005A | JSCS ASHCHURCH                   | CAPITA  | 29680AA | 22/10/1997 |       |
| JZ86AA | 4       | 10/02/1998 | A0214A | 19 REGT RA (AS 90 REGT)          | 36982A  | 2125    | 17/03/1998 |       |
| JZ86AA | 4       | 12/10/1999 | A3720A | 3 LOGISTIC SUPPORT REGT RLC      | 387     | 503     | 15/11/1999 | P79   |
| JZ86AA | 4       | 27/01/2000 | A3720G | 3 CS REGT RLC 10 BDE SP SQN      | 202     | 172     | 24/07/2000 | R50   |
| JZ86AA | 4       | 11/04/2005 | A9108A | QM DEPT UK LOG BN                | 39834   | 1143    | 08/05/2005 | W06   |
| JZ86AA | 4       | 21/10/2005 | A3720G | 3 CS REGT RLC 10 BDE SP SQN      | 4590    | 74062   | 17/01/2006 | W84   |
| JZ86AA | 4       | 21/09/2008 | A4525G | 19 LT BDE CSS BN 10 BDE SP SQN   | 999     | 999     | 21/09/2008 | Z74   |
| JZ86AA | 4       | 21/11/2008 | A4525A | 19 LT BDE CSS BN                 | 122     | 62437   | 27/11/2008 | Z74   |
| JZ86AA | 3       | 03/07/2012 | CQ710A | WITHAM (SPECIALIST VEHICLES) LTD | 999     | 999     | 03/07/2012 | C82   |

Serial Number: NSN: JZ86AA

ALL

2320998939741

Criteria:

Repair Level:

Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL

Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

| E. IUD                             | W. d. D 10      | E. D. D. and M.   | Work   | 5 h 6 r                     | Escalate | •       | Batch Fault Group ID | Fault Occurrence |        | Reason For |                                       | Working      | •       | Estimated   |
|------------------------------------|-----------------|---|--------|-----------------------------|----------|---------|----------------------|------------------|--------|------------|---------------------------------------|--------------|---------|-------------|
| Fault ID                           | Work Request ID | Fault Description   |        | Fault State                 | Work     | Level   | Number               | Date             | Impact | Work       | Level 3 Description                   | Organisation | Section | Repair Time |
| 000000-006CA381                    |                 | 6 Mthly VM TASKS  |        | Non-Taskworthy<br>Fully Fit |          | Level 2 |                      |                  | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006B0FCD<br>000000-006C7614 |                 | BONNET SUPPORT BAR CATCH MISSING Dmn NO 4456/01 6 MTHLY SERVICE     |        | •                           | No<br>No | Level 1 |                      |                  | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006C7614<br>000000-006B2083 |                 | BOTTOM RIGHT OF RADIATOR GRILL BROKE Dmn NO 4456/01                 |        | Non-Taskworthy              | No<br>No | Level 1 |                      |                  | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |
|                                    |                 | •   |        | Fully Fit                   | No<br>No | Level 1 |                      |                  | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006B207A<br>000000-006B2076 |                 | DIFF LIGHT DASH IN OP HEAD LIGHT DASH LIGHT IN OP                   |        | Fully Fit                   | No<br>No | Level 2 |                      |                  | N/A    | Failure    | TUL HS GS SOFT TOP                    |              |         |             |
|                                    |                 | PAINT REAR CONVOY REFLECTIVE PLATE ON REAR AXLE.                    |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Failure    | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED528                    |                 |   |        | Fully Fit                   | No<br>No | Level 1 |                      |                  | N/A    | Inspection |                                       |              |         |             |
| 000000-005ED4D5                    |                 | FIT DIFFY AIR FILTER HOUSING CLIP.                                  |        | Fully Fit                   | No<br>No | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP TUL HS GS SOFT TOP |              |         |             |
| 000000-00606398                    |                 | FIT DIFFY BAULKHEAD RUBBER GROMETS                                  |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Inspection |                                       |              |         |             |
| 000000-006C21C3                    |                 | Screws missing on both bonnet vents                                 |        | Fully Fit                   | No       | Level 1 |                      | -                | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006C21CA                    |                 | Rear Canopy Tail Gate Straps Missing                                |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006B2097                    |                 | REAR CANOPY TAIL GATE STRAPS MISSING                                |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006B2087                    |                 | SCREWS MISSING ON BOTH BONNET VENTS                                 |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006B4736                    |                 | REPLACE STEERING DROP ARM WASHER WITH CORRECT LOCK WASHER           |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006B04AC                    |                 | Insp Steering Drop Arm Tab Washer                                   |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006815F7                    |                 | Please carry out 6534 Serv & inspection                             |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-004641D6                    |                 | PLEASE CARRY OUT MEI  |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Failure    | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED551                    |                 | carry out 28 day re-certification                                   |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         | 4           |
| 000000-0047CAA7                    |                 | RECTIFY RBT FAILURE   |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Failure    | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006067AF                    |                 | CARRY OUT 12 MONTHLY SEVICE IAW AESP 2320-D128-601 TABLE 7 COLOUM B |        | Non-Taskworthy              |          | Level 1 |                      |                  | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-00606396                    |                 | REPLACE REAR L/H SIDE LIGHT   |        | Non-Taskworthy              |          | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4DE                    |                 | SECURE VEHICLE BATTERIES.   |        | Non-Taskworthy              |          | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4D0                    |                 | RENEW RHF & RHR TYRES.  |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-00606394                    |                 | REPLACE STEERING DAMPER BUSHES                                      |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-00606392                    |                 | INVESTIGATE BOTH REAR DISCS ARE DIFFERENT TYPES                     |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-006067BF                    |                 | CARRY OUT 12 MONTHLY VM TASKS IAW AESP 2320-D-128-601 COLOUM B      |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-00602E94                    |                 | REPLACE EGR WIRING HARNESS  |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Damage     | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED523                    |                 | ADJUST AND SECURE HEADLIGHTS.                                       |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4C0                    |                 | CARRY OUT SMOKE EMMISSIONS TEST.                                    |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4B8                    |                 | RECTIFY ENGINE RUNNING POORLY.                                      |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED49D                    |                 | SECURE POWER STEERING FLUID PIPE.                                   |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED497                    |                 | INVESTIGATE ENGINE OIL LEAK.  |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED487                    |                 | FIT DIFFY BACK PLATE @ F/L DISC BRAKE.                              |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4AC                    |                 | ADJUST EXCESSIVE FREEPLAY AT HANDBRAKE.                             |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         | 1           |
| 000000-005ED4F0                    |                 | ADJUST WINDSCREEN WASHER SPRAY DIRECTION.                           |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED503                    |                 | FIT DIFFY BONNET STAY BAR.  |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED490                    |                 | LOCK TAB STEERING BOX DROP ARM NUT.                                 |        | Fully Fit                   | No       | Level 2 |                      | 31 Mar 2011      | N/A    | •          | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005E6C42                    |                 | Renew FIP   |        | Fully Fit                   | No       | Level 2 |                      |                  | N/A    | Failure    | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED519                    |                 | RENEW BOTH REAR SIDE LIGHT RUBYS.                                   |        | Non-Taskworthy              | No       | Level 1 |                      | 31 Mar 2011      | N/A    | •          | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4DA                    |                 | FIRE EXTINGUISHER & JACK NOT PRESENTED FOR INSPECTION.              |        | Limited Role                | No       | Level 1 |                      |                  | N/A    | •          | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4FE                    |                 | ADJUST ALL TYRE PRESSURES.  |        | Non-Taskworthy              |          | Level 1 |                      |                  | N/A    | •          | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4F8                    |                 | TOP UP ENGINE OIL TO CORRECT LEVEL.                                 |        | Non-Taskworthy              | No       | Level 1 |                      |                  | N/A    | •          | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4E5                    |                 | FIT DIFFY BATTERY TERMINAL RUNNER COVERS.                           |        | Fully Fit                   | No       | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005ED4A4                    |                 | DRAIN POWER STEERING FLUID TO CORRECT LEVEL.                        |        | Non-Taskworthy              |          | Level 1 |                      |                  | N/A    | Inspection | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005E4C5A                    |                 | CARRY OUT 6MTH VMS IAW AESP 2320-D-128-601 Table 7                  |        | Non-Taskworthy              |          | Level 2 |                      |                  | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |
| 000000-005E3CC3                    |                 | Please carry out 6 monthly servive IAW AESP 2320-D-128-601 Table 7  | Closed | Non-Taskworthy              | No       | Level 1 |                      | 04 Mar 2011      | N/A    | Servicing  | TUL HS GS SOFT TOP                    |              |         |             |

| 000000-005E3CC6                    |                  | Please carry out 6 monthly service IAW AESP 2320-D-128-601 Table 7   | Closed | Non-Taskworthy | No | Level 2 | 04 Mar 2011 | N/A | Servicing | TUL HS GS SOFT TOP |
|------------------------------------|------------------|--|--------|----------------|----|---------|-------------|-----|-----------|--------------------|
| 000000-005B6599                    |                  | INVESTIGATE SUMP GASKET LEAKING                                      | Closed | Fully Fit      | No | Level 2 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B657A                    |                  | REPLACE RUBBER GROMMETS IN BULKHEAD                                  | Closed | Fully Fit      | No | Level 2 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B651E                    |                  | REPLACE BONNET BUSHES TO BULKHEAD                                    | Closed | Non-Taskworthy | No | Level 2 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B6596                    |                  | INVESTIGATE POWER STEERING LEAK                                      |        | Non-Taskworthy | No | Level 2 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B6519                    |                  | INV COOLANT LEAK AT FRONT RIGHT OF VEHICLE                           |        | Non-Taskworthy | No | Level 2 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005D882B                    |                  | FIT SPARE WHEEL TO RIM   | Closed | Non-Taskworthy | No | Level 2 | 01 Feb 2011 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B6563                    |                  | REPLACE VALVE CAPS AS NECESSARY 2984/1                               | Closed | Fully Fit      | No | Level 1 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-0047B1C9                    |                  | RENEW WIPER arms and blades BLADES (dmd number 2965/1 2965/2 2965/3) | Closed | Non-Taskworthy | No | Level 1 | 18 Sep 2009 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005D3297                    |                  | DMD AND FIR BRIDGEING CABLE FOR BATTERIES                            | Closed | Non-Taskworthy | No | Level 1 | 19 Jan 2011 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B6570                    |                  | REPLACE RIGHT WING MIRROR/ 2984/2                                    | Closed | Fully Fit      | No | Level 1 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B6550                    |                  | FIT MISSING SPARE WHEEL TO VEHICLE (SEE TROOP STORE)                 | Closed | Limited Role   | No | Level 1 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005D3BD4                    |                  | CARRY OUT 2YRL SERV IAW 2320D128601                                  | Closed | Non-Taskworthy | No | Level 1 | 20 Jan 2011 | N/A | Servicing | TUL HS GS SOFT TOP |
| 000000-005D4EC5                    |                  | CARRY OUT 2 YRL VM TASKS IAW 2320D128601                             | Closed | Non-Taskworthy | No | Level 2 | 24 Jan 2011 | N/A | Servicing | TUL HS GS SOFT TOP |
| 000000-005B6578                    |                  | REPLACE DOOR CATCH PLASTIC COVER                                     | Closed | Fully Fit      | No | Level 2 | 10 Nov 2010 | N/A | Failure   | TUL HS GS SOFT TOP |
| 000000-005B6581                    | 000000-002CFE31  | REPLACE BATTERIES, 1043 NUMBER 137                                   | Closed | Non-Taskworthy | No | Level 1 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6546                    | 000000-002CFB34  | CORRECTLY SECURE FRONT LEFT WHEEL ARCH                               |        | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6569                    | 000000-002CFE28  | RE FIT CANOPY  | Closed | Fully Fit      | No | Level 1 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B659F                    | 000000-002CFB2B  | REPLACE WINDERSCREEN WASHER JETS                                     | Closed | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B658B                    | 000000-002CFB34  | REPLACE PASSENGER SEAT BACK REST                                     | Closed | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6558                    | 000000-002CFB2B  | REPLACE WIPER ARMS   | Closed | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6506                    | 000000-002CFB34  | REPLACE LOCKING PIN FOR BONNET STAY BAR                              |        | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B64F7                    | 000000-002CFB2B  | REPLACE BONNET STAY CATCH  |        | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B64F5                    |                  | REPLACE TURBO OUTLET PIPE (LEAKING)                                  |        | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6588                    | 000000-002CFB34  | REPLACE DASH BLANKING PLATE  |        | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6503                    | 000000-002CFB34  | REPLACE BONNET RUBBERS   |        | Fully Fit      | No | Level 2 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6591                    | 000000-002CFE28  | GREASE PROPS AS REQUIRED   |        | Fully Fit      | No | Level 1 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B650E                    | 000000-002CFE28  | TOP UP WASHER BOTTLE   |        | Limited Role   | No | Level 1 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B650B                    | 000000-002CFE28  | TOP UP POWER STEERING FLUID  |        | Limited Role   | No | Level 1 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005B6560                    | 000000 0020, 220 | REPLACE WIPERS   |        | Non-Taskworthy | No | Level 1 | 10 Nov 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-005A9BCE                    | 000000-002CBE4D  | RENEW REAR SHOCKS  |        | Fully Fit      | No | Level 2 | 21 Oct 2010 |     |           | TUL HS GS SOFT TOP |
| 000000 003715DEE                   | 000000 0026B24B  | RECT NON STARTER   |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000 0047B13B                    |                  | REPLACE REAR INDICATOR PLASTICS                                      |        | Fully Fit      | No | Level 2 | 05 Oct 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-0033333C                    |                  | REBUILD DASH AND STEERING COLUMN                                     |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B13A                    |                  | renew intercooler pipe   |        | Fully Fit      | No | Level 2 | 17 Jun 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-00320427<br>000000-0047B1A3 | 000000-002BAD4E  | CARRY OUT MODS 24, 32 AND 33   |        | Fully Fit      | No | Level 2 |             |     |           |                    |
| 000000-0047B1AB                    | 000000-002B2925  | REPLACE ALL MISSING BELTS  |        | •              |    |         | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1AB                    | 000000-002B2925  | REFIT BOTH DOOR CARDS CORRECTLY                                      |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-004781A1                    |                  | Renew L/H/F eyebrow  |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
|                                    |                  | ·  |        | Fully Fit      | No | Level 1 | 17 Jun 2010 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CB8F                    |                  | SECURE L/H/F WHEEL ARCH  |        | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CA98                    |                  | NO LIGHTS CHECK CARRIED OUT  |        | Non-Taskworthy | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1B9                    |                  | SECURE WIPER MOTOR   |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CA52                    |                  | NON STARTER  |        | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1B7                    |                  | SECURE L/H/F WHEL ARCH   |        | Fully Fit      | No | Level 1 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CA4B                    |                  | VEH IGNITION BARALL MISSING  |        | Non-Taskworthy | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CB5F                    | 000000-002B2925  | RECT FUEL SYSTEM @ FILTER  |        | Non-Taskworthy | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CADE                    | 000000-002B2925  | RE NEW FUSE BOX COVER SCREWS   |        | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CAD5                    |                  | RE BUILD DASH  |        | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CAB7                    |                  | RECT DVRS SEAT NOT LOCKING   |        | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1CB                    |                  | RECT POWER STEERING LEAK   |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1B4                    | 000000-002B2925  | RENEW F/L HEAD LAMP GUARD  |        | Non-Taskworthy | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1B2                    | 000000-002B2925  | RECONNECT FUEL SYSTEM AT FUEL FILTER                                 |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1A9                    | 000000-002B2925  | REPLACE RADIATOR BLEED SCREW   | Closed | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1A7                    | 000000-002B2925  | RECT BONNET LOCK MISSING   |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1A5                    | 000000-002B2925  | RECT DVRS WINDOW LOCK INOP   | Closed | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B1A2                    | 000000-002B2925  | RENEW DVRS DOOR SEAL   |        | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B19F                    | 000000-002B2925  | RENEW GEAR SELECTOR KNOB   | Closed | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B19D                    | 000000-002B2925  | RENEW FUSE BOX COVER SCREWS  | Closed | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047B197                    | 000000-002B2925  | RECT DVRS SSEAT NOT LOCATING   | Closed | Fully Fit      | No | Level 2 | 18 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-004641D5                    | 000000-00294ADC  | PLEASE CARRY OUT A 2 YR AND ANY RESULTING WORK                       | Closed | Non-Taskworthy | No | Level 2 | 30 Jul 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CBB9                    | 000000-002B2925  | RECT POWER STEERING LEAK   | Closed | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CB96                    | 000000-002B2925  | SECURE WIPER MOTOR   | Closed | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CB6D                    | 000000-002B2925  | RENEW F/L HEADLIGHT GUARD  | Closed | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CB40                    | 000000-002B2925  | REPLACE ALL BELTS  | Closed | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
| 000000-0047CB2F                    | 000000-002B2925  | RECT RADIATOR BLEED SCEW   | Closed | Fully Fit      | No | Level 2 | 22 Sep 2009 |     |           | TUL HS GS SOFT TOP |
|                                    |                  |  |        |                |    |         |             |     |           |                    |

| 000000-0047CB21 | 000000-002B2925 | RECT BONNET LOCK MISSING                   | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
|-----------------|-----------------|--|-----------------------|----|---------|-------------|--------------------|
| 000000-0047CB1A | 000000-002B2925 | DVRS WINDOW LOCK IN OP                     | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CB0D | 000000-002B2925 | CARRY OUT MODS 24, 32, 33                  | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CB00 | 000000-002B2925 | RENEW DVRS DOOR SEAL                       | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CAF9 | 000000-002B2925 | REFIT BOTH DOOR CARDS CORRECTLY            | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CAEA | 000000-002B2925 | RE NEW GEAR SELECTOR KNOB                  | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CAB2 | 000000-002B2925 | RECT POWER STEERING LEAK                   | Closed Fully Fit      | No | Level 2 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CB9F | 000000-002AAECD | RENEW REAR LEFT AND RIGHT FOG LAMPS LENSES | Closed Non-Taskworthy | No | Level 1 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CB7D | 000000-002AAECD | RENEW FRONT TOW PIN                        | Closed Fully Fit      | No | Level 1 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1C4 | 000000-002AAECD | RENEW REAR RIGHT FOG AND INDICATOR LAMPS   | Closed Non-Taskworthy | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1C2 | 000000-002AAECD | RENEW REAR LEFT FOG LAMP                   | Closed Non-Taskworthy | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1B5 | 000000-002AAECD | RENEW FRONT TOW EYE PIN                    | Closed Fully Fit      | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CBA7 | 000000-002AAECD | RENEW R/L REFLECTOR                        | Closed Non-Taskworthy | No | Level 1 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047CB54 | 000000-002AAECD | FIT ENG FUSE BOX COVER                     | Closed Fully Fit      | No | Level 1 | 22 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1C8 | 000000-002AAECD | FREE OFF REAR TOE EYE                      | Closed Non-Taskworthy | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1C6 | 000000-002AAECD | RENEW REAR LEFT REFLECTOR                  | Closed Non-Taskworthy | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1C1 | 000000-002AAECD | RENEW VEH BATTS                            | Closed Non-Taskworthy | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-0047B1B0 | 000000-002AAECD | RENEW ENGINE FUSE BOX COVER                | Closed Fully Fit      | No | Level 1 | 18 Sep 2009 | TUL HS GS SOFT TOP |
| 000000-00126067 |                 | Initial Usage                              | Closed Fully Fit      | No | Level 1 | 03 Apr 2008 | TUL HS GS SOFT TOP |
| 000000-00126143 |                 | Initial Maintenance                        | Closed Fully Fit      | No | Level 1 | 03 Apr 2008 | TUL HS GS SOFT TOP |
|                 |                 |  |                       |    |         |             |                    |

Serial Number:

JZ86AA

NSN:

2320998939741

Criteria:

Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL

Work Request ID:

Assigned Work Status: ALL

Working Organisation:

|                      | Escalate             |                           | Next Due    | Repair  | Fault | Work   | Estimated   | Working      | Repair  |
|----------------------|----------------------|---------------------------|-------------|---------|-------|--------|-------------|--------------|---------|
| Maintenance Event ID | Work Request ID Work | Maintenance Event Name    | Date        | Level   | State | Status | Repair Time | Organisation | Section |
| 000000-001CBB70      | No                   | MEI (2)                   | 20 Mar 2013 | Level 2 |       |        | 00:00       |              |         |
| 000000-0015C1C4      | No                   | MEI (2)                   | 20 Mar 2013 | Level 2 |       |        | 00:00       |              |         |
| 000000-00151267      | No                   | MEI (2)                   | 20 Mar 2013 | Level 2 |       |        | 00:00       |              |         |
| 000000-00151268      | No                   | First Parade Insp (AR)(1) |             | Level 1 |       |        | 00:00       |              |         |
| 000000-00188FA4      | No                   | 6 Monthly 6534 Insp       | 18 Sep 2012 | Level 1 |       |        | 00:00       |              |         |
| 000000-00168315      | No                   | 6 Monthly 6534 Insp       | 18 Sep 2012 | Level 1 |       |        | 00:00       |              |         |
| 000000-001CBB71      | No                   | 6 Monthly 6534 Insp       | 18 Sep 2012 | Level 1 |       |        | 00:00       |              |         |

Serial Number: JZ86AA

NSN: 2320998939741

Criteria:

Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL
Work Request ID:
Assigned Work Status: ALL

Working Organisation:

|                       | Modification |   | Work Request | Escalate | Production Classification/In | Modification | Apply When   | Embody by   | Usage Counter | Fault     | Work Rep    | air Working     | Repair  | Estimated   |
|-----------------------|--------------|---|--------------|----------|------------------------------|--------------|--------------|-------------|---------------|-----------|-------------|-----------------|---------|-------------|
| Modification Event ID | Number       | Modification Description  | ID           | Work     | Service Classification       | Type         | Usage Equals | Target Date | Units         | State     | Status Leve | el Organisation | Section | Repair Time |
| 000000-00013000       | 00019        | Blackout Cover for Warning Light Panel  |              | No       | -/-                          | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-00015496       | 00024        | Fitting of Trailer Breakaway Attachment Plate                                     |              | No       | -/                           | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-000210DC       | 00025        | Fitting of Spare Wheel Lifting Aid Harness  |              | No       | 1/A                          | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-000227FA       | 00014        | Fitting of Showerproof Dash Cover   |              | No       | -/-                          | RTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-0002506B       | 00031        | Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants |              | No       | -/-                          | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-0000E350       | 00017        | Introduction of Battery Retention   |              | No       | 1/A                          | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-0002437D       | 00037        | Fitting Glow Plug Timer Interface Harness   |              | No       | -/                           | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-00009F8C       | 00006        | Fitting of Spare Wheel Tyre Inflation Valve Extension                             |              | No       | -/                           | RTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-0001A2B3       | 00030        | Front Belt Protection Sleeves   |              | No       | 1/A                          | UTI          |              |             |               | Fully Fit | CL          |                 |         |             |
| 000000-00009817       | 00004        | Fiitting Emergency Lights, Siren and Harness                                      |              | No       | -/-                          | RTI          |              |             |               | Fully Fit | CL          |                 |         |             |

Serial Number:

JZ86AA

NSN:

2320998939741

Criteria:

Repair Level:

ALL

Work Object Status:

Closed

Mission Impact:

ALL

Fault State:

ALL

Escalate Work:

Work Request ID:

ALL

Assigned Work Status:

ALL

Working Organisation:

|                      | Work Request | Escalate |                         | Next Due    | Repair  | Fault | Work   | Estimated   | Working      | Repair  |
|----------------------|--------------|----------|-------------------------|-------------|---------|-------|--------|-------------|--------------|---------|
| Maintenance Event ID | ID           | Work     | Maintenance Event Name  | Date        | Level   | State | Status | Repair Time | Organisation | Section |
| 000000-0014B637      |              | No       | Weekly (AR)(1)          |             | Level 1 |       |        | 00:00       |              |         |
| 000000-0015C8F0      |              | No       | Yearly/20000 Kms        | 20 Mar 2013 | Level 1 |       |        | 00:00       |              |         |
| 000000-00160BAC      |              | No       | Weekly (AR)(1)          |             | Level 1 |       |        | 00:00       |              |         |
| 000000-001CBB68      |              | No       | Yearly/20000 Kms        | 20 Mar 2013 | Level 1 |       |        | 00:00       |              |         |
| 000000-001804F6      |              | No       | Weekly (AR)(1)          |             | Level 1 |       |        | 00:00       |              |         |
| 000000-0018647C      |              | No       | 6 Monthly/10000 Kms     | 19 Sep 2012 | Level 1 |       |        | 00:00       |              |         |
| 000000-0016C945      |              | No       | Weekly (AR)(1)          |             | Level 1 |       |        | 00:00       |              |         |
| 000000-0016A4D1      |              | No       | Weekly (AR)(1)          |             | Level 1 |       |        | 00:00       |              |         |
| 000000-0017E53A      |              | No       | Weekly (AR)(1)          |             | Level 1 |       |        | 00:00       |              |         |
| 000000-0009824A      |              | No       | First 1600 Kms (AR)     |             | Level 2 |       | CL     | 00:00       |              |         |
| 000000-00098357      |              | No       | 6 Monthly/10000 Kms     | 19 Sep 2012 | Level 1 |       | CL     | 00:00       |              |         |
| 000000-00098324      |              | No       | First 1600 Kms (AR)     |             | Level 2 |       | CL     | 00:00       |              |         |
| 000000-000983F8      |              | No       | Yearly/20000 Kms        | 20 Mar 2013 | Level 1 |       | CL     | 00:00       |              |         |
| 000000-000E5C07      |              | No       | 6 Monthly/10000 Kms     | 19 Sep 2012 | Level 1 |       | CL     | 00:00       |              |         |
| 000000-00096927      |              | No       | Yearly/20000 Kms        | 20 Mar 2013 | Level 1 |       | CL     | 00:00       |              |         |
| 000000-00096928      |              | No       | 6 Monthly/10000 Kms     | 19 Sep 2012 | Level 1 |       | CL     | 00:00       |              |         |
| 000000-00055A03      |              | No       | 5 Yearly/100000 Kms (1) |             | Level 1 |       | CL     | 000:00      |              |         |

| 000000-000FC870 | No | 2 Yearly/40000 Kms  | 23 Jan 2013 | Level 1 | CL | 00:00 |
|-----------------|----|---------------------|-------------|---------|----|-------|
| 000000-000C1BDA | No | 6 Monthly/10000 Kms | 19 Sep 2012 | Level 1 | CL | 00:00 |
| 000000-000FC871 | No | Yearly/20000 Kms    | 20 Mar 2013 | Level 1 | CL | 00:00 |
| 000000-001683D5 | No | Weekly (AR)(1)      |             | Level 1 |    | 00:00 |
| 000000-00148245 | No | 6 Monthly/10000 Kms | 19 Sep 2012 | Level 1 |    | 00:00 |
| 000000-001CBB69 | No | 6 Monthly/10000 Kms | 19 Sep 2012 | Level 1 |    | 00:00 |
| 000000-0011581F | No | 2 Yearly/40000 Kms  | 23 Jan 2013 | Level 1 |    | 00:00 |
| 000000-00175AFC | No | Weekly (AR)(1)      |             | Level 1 |    | 00:00 |
| 000000-001799D4 | No | Weekly (AR)(1)      |             | Level 1 |    | 00:00 |
| 000000-0017C112 | No | Weekly (AR)(1)      |             | Level 1 |    | 00:00 |
|                 |    |                     |             |         |    |       |