


Tecalemit Scissor Lift SF/9094 or 5 and SF9064 or 5 (Manufactured 2014 – 2018)

Aspect	Details
Images	 <p>The image shows a blue and yellow scissor lift. It has a platform at the top with yellow safety railings. The lift is supported by four hydraulic scissor arms. To the left of the lift is a black control panel with a yellow emergency stop button and a blue start button.</p>
Alert Number	2112-0572
Product Type	Machinery – Scissor Lift
Product Identifiers	4.5t Service and MOT Class IV Scissor Lift – SF/9094/EV & SF/9095/EV and 5.0t Service and MOT Class VII Scissor Lift SF/9064/EV& SF/9065/EV manufactured 2014 – 2018.
Product Description	Hydraulic scissor lift for lifting vehicles. Capacity 4.5 and 5.0 tonnes.
Country of Origin	Italy
Counterfeit	No
Risk Level	Serious Risk
Risk Type	Injury
Risk Description	<p>The manufacturer has identified a potential weakness in a weld on the scissor lifts. They have provided a kit which should be fitted to the scissor lift. The manufacturer has issued instructions to avoid using the lift with a load exceeding 3.5 tonnes until the kit has been fitted. A product of identical design is now known to have failed with a loading of less than 3.5 tonnes. This product does not comply with the Supply of Machinery (Safety) Regulations 2008.</p>
Corrective measures	All affected scissor lifts have had the manufacturer’s kit fitted or arrangements are in place to have this work done. End users are advised to stop using the scissor lift until the kit has been fitted.
Online Marketplace	N/A
Notifier	HSE