

Defence Equipment and Support Secretariat #2043 Maple 0a Ministry of Defence Abbey Wood Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk



Our Reference: FOI2022/01591 Date: 23 February 2022



I am writing about your email of 6 February 2022, requesting the following information:

'I have recently purchased an EX Military vehicle Pinzgauer 6x6 TMV. Therefore I submit a FOI request for the following information:

1) Vehicle military service history (Units served etc)

2) Any Maintenance Records / Work objects related to this vehicle.

In Service Registration Nr: RR79AA

Description: PINZGAUER 6X6 AMBULANCE TRAUMA MANAGEMENT VEHICLE

VIN number: VAG7183444200005111.'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

Annex A - Transfer History

Annex B - Inspection History

Annex C - Service History

Annex D - Fault History (redacted)

It has proved necessary to withhold some information in accordance with a qualified exemption of the FOI Act. Commercially sensitive information in the Fault History (Annex D) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Fault History provides details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information,

Defence Equipment & Support

this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
				AMBULANCE TRAUMA MANAGEMENT EMERGENCY	
RR79AA	2310999085500	NB10323100	LV2/DBG/143	RESPONSE 2 STRETCHER 6X6 DIESEL STEYR DAIMLER PUCH	

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(i)	(k)
21/07/1999				

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
RR79AA	2	15/03/1999	F5290A	RAF LINTON-ON-OUSE SUPPLY SQN	129/99	249P47	21/07/1999	
RR79AA		06/03/2018		DSG CATTERICK			06/03/2018	
RR79AA		04/10/2019		RAF COSFORD STN MT OPS			10/10/2019	·

Work Objects										
Serial Number:	RR79AA									
NSN:	2310999085500									
INSIN.	2310999063300									-
Criteria:										
Repair Level:	ALL									
Work Object Status:	Closed									
Mission Impact:	ALL									
Fault State:	ALL									
Escalate Work:	ALL									
Work Request ID:										
Assigned Work Status:	ALL									
Working Organisation:										
Repair Section:		-								
	Work Request ID		Maintenance Event Name	Next Due Date	1	-		Estimated Repair Time	Working Organisation	Repair Section
000000-00BB1E1C		No	Ad Hoc Insp (AR)	24 1 2024	Level 1	Fully Fit	CL	000:00		
000000-00CAE083		No	FMT932 (W) Mandatory Equipment Inspection (2)*	24 Jun 2021	Level 2	Limited Role	CL	000:00		
000000-003FB87D		No	MEI (2)		Level 2			000:00		
000000-00B1C62C		No	FMT932 (W) 6 Monthly Safety Inspection (2)	24 Dec 2020	Level 2	Fully Fit	CL	000:00		
000000-00B1C68B		No	FMT933 (W) Role Equipment (2)*	24 Jun 2021	Level 2	Non-Taskworthy	CL	000:00		
000000-004909BE		No	6 Monthly Safety Insp (2)	241 12024	Level 2			000:00		
000000-00CAE9EE		No	Annual Smoke Emissions Test(2)	24 Jul 2021	Level 2	Limited Role	CL	000:00		
000000-00CAEA03		No	FMT933 (W) Role Equipment (2)*	24 Jun 2021	Level 2	Limited Role	CL	000:00		
000000-0029A6A8		No	6 Monthly Safety Insp (2)		Level 2			000:00		
000000-00A3A546		No	6 Monthly Safety Insp (2)		Level 2	Fully Fit	CL	000:00		
000000-00679042		10000	MEI (2)		Level 2			000:00		
000000-0024239C		No	6 Monthly Safety Insp (2)		Level 2		200	000:00		
000000-00B1C629		No	Annual Smoke Emissions Test(2)	24 Jul 2021	Level 2	Fully Fit	CL	000:00		
000000-00CAE85D		No	Annual Headlight Alignment Check (2)	24 Jul 2021	Level 2	Limited Role	CL	000:00		
000000-00B1C418		No	FMT932 (W) Mandatory Equipment Inspection (2)*	24 Jun 2021	Level 2	Fully Fit	CL	000:00		
000000-0029A6A7			MEI (2)		Level 2			000:00		
000000-003FB87E		No	6 Monthly Safety Insp (2)		Level 2		0.00	000:00		
000000-00B1C62A		No	Annual Brake Test (2)	24 Jul 2021	Level 2	Fully Fit	CL	000:00		
000000-00712335		No	6 Monthly Safety Insp (2)		Level 2	Fully Fit	CL	000:00		
000000-00886715		No	6 Monthly Safety Insp (2)		Level 2	Fully Fit	CL	000:00		
000000-0055980E		No	6 Monthly Safety Insp (2)		Level 2			000:00		
000000-005C165A		No	6 Monthly Safety Insp (2)		Level 2			000:00		
000000-007E9103			6 Monthly Safety Insp (2)		Level 2	Fully Fit	CL	000:00		
000000-009A940A			MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00B1C62B		No	Annual Headlight Alignment Check (2)	24 Jul 2021	Level 2	Fully Fit	CL	000:00		
000000-009A940E		No	6 Monthly Safety Insp (2)		Level 2	Fully Fit	CL	000:00		
000000-00CAE840		No	FMT932 (W) 6 Monthly Safety Inspection (2)	24 Dec 2020	Level 2	Limited Role	CL	000:00		
000000-00B6F6AD		No	FMT931 Medical (1)	29 Feb 2020	Level 1	Limited Role	CL	000:00		
000000-0034FC5E		10,000	6 Monthly Safety Insp (2)		Level 2			000:00		
000000-007E915B			MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-0067904F			6 Monthly Safety Insp (2)		Level 2			000:00		
000000-005597EA			MEI (2)	Section Control Annual Control	Level 2			000:00		
000000-00CAE9E5			Annual Brake Test (2)	24 Jul 2021	Level 2		1000	000:00		
000000-00C0867A		No	FMT932 (W) 6 Monthly Safety Inspection (2)	24 Dec 2020	Level 2	Fully Fit	CL .	000:00		

Work Objects										
Serial Number:	RR79AA									
NSN:	2310999085500									
	2020000000									
Criteria:										
Repair Level:	ALL									
Work Object Status:	Closed									
Mission Impact:	ALL									
Fault State:	ALL									
Escalate Work:	ALL									
Work Request ID:	ALL									
Assigned Work Status:	ALL									
Working Organisation:							-			
Repair Section:				_						
Repair Section.										
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Renair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Panair Saction
000000-00DD14F7		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Non-Taskworthy		000:00	Ji king Olganisation	mepan section
000000-0024258D		No	Yearly/16000 Kms	17 Jun 2021	Level 2		-	000:00		
000000-0098C20E		No	Yearly/16000 Kms	17 Jun 2021	Level 2	Fully Fit	CL	000:00		
000000-00511693		No	OOPS 2 Yearly	01 Apr 2021	Level 1	Tally Fit	CL	000:00		
000000-00A3A53E		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	000:00		
000000-00A5A55E		No	OOPS 3 Yearly	29 May 2021	Level 2	Fully Fit	CL	000:00		
000000-005C1668		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	rully rit	CL	000:00		
000000-003C1668		No	OOPS 4 Yearly/60000 Kms		Level 2			000:00		
000000-007CD830		No	OOPS 3 Yearly		Level 2	Cully Cit	CI			
000000-007-CD050 000000-0054C06A	-	No		29 May 2021		Fully Fit	CL	000:00		
000000-0054C00A		No	OOPS 4 Yearly/60000 Kms		Level 2	Non Toolousethu	CI.	000:00		
000000-00C08075 000000-0098C256		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Non-Taskworthy		000:00		
000000-0038C238			OOPS 3 Yearly/48000 Kms		Level 2	Fully Fit	CL	000:00		
000000-007CD832		No	OOPS 2 Yearly	01 Apr 2021	Level 1	Fully Fit	CL	000:00		
		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2			000:00		
000000-0034FC5F		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2			000:00		
000000-00AB71E1		No	OOPS 4 Yearly	10 Apr 2023	Level 2	Fully Fit	CL	000:00		
000000-0051167D		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2			000:00		
000000-003FB90F		No	OOPS 3 Yearly	29 May 2021	Level 2			000:00		
000000-00B00769		No	Yearly/16000 Kms	17 Jun 2021	Level 2	Fully Fit	CL	000:00		
000000-003FB90C		No	Yearly/16000 Kms	17 Jun 2021	Level 2			000:00		
000000-0099B662		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	000:00		
000000-00540DD8		No	OOPS 4 Yearly	10 Apr 2023	Level 2			000:00		
000000-007CD84A		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	000:00		
000000-003FB90D		No	OOPS 3 Yearly/48000 Kms	Contract the Contract of the C	Level 2			000:00		
000000-0098C213		No	OOPS 4 Yearly/60000 Kms		Level 2	Fully Fit	CL	000:00		
000000-0029A6AD		No	Yearly/16000 Kms	17 Jun 2021	Level 2			000:00		
000000-007CD848		No	Yearly/16000 Kms	17 Jun 2021	Level 2	Fully Fit	CL	000:00		
000000-00CAF295		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	000:00		
000000-0051167A		No	Yearly/16000 Kms	17 Jun 2021	Level 2			000:00		
000000-00CAF27C		No	Yearly/16000 Kms	17 Jun 2021	Level 2	Fully Fit	CL	000:00		
000000-00886714		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	000:00		
000000-0029A6AE		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2			000:00		
000000-00B1C36D		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	00:00		
000000-00AB7130		No	OOPS 2 Yearly	01 Apr 2021	Level 1	Fully Fit	CL	000:00		
000000-006914AE		No	OOPS 3 Yearly/48000 Kms		Level 2			00:00		
000000-006738B0		No	Yearly/16000 Kms	17 Jun 2021	Level 2			00:00		
000000-004909B8		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2			000:00		
000000-00712334		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2	Fully Fit	CL	000:00		
000000-00BB235B		No	Receipt Maint (AR)		Level 1	Fully Fit	CL	000:00		
000000-006738C5		No	6 Monthly/8000 Kms	07 Sep 2021	Level 2			000:00		
		No	OOPS 2 Yearly	01 Apr 2021	Level 1			000:00		
000000-0029A6AF		110						000100		

riteria: lepair Level: vork Object Status: dission Impact: All ault State: All Vork Request ID: Paging Status: All Vorking Organisation: epair Section:	NLL	Fault Description Surface corrusion on many parts of the body, needs painting. Surface corrusion on many parts of the body, needs painting. Air conditioner not producing cool air, probably needs re-gassing Batters compartment corroded Side rear door, corroded and in poor condition. Gas strut on rear droop down tep week Bracket missing from fluid warmer locker Missing one of the rear number palate lights. Diesel leak after running engine Garbot oel leak Coolant leak Tignie oil leak Brake peel air has slightly too much travel' a bit spongy Hazard lights, missing rear rusber grommet/guide thingy Hazard lights do not work. Tignie very slugglish/stow pick up Steering wheel worn, rubber unbonding.	Work Status Closed Clos	Fully Fit Limited Role Fully Fit	No No No	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	al Batch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	Mission Impact N/A N/A N/A N/A N/A	Closed No Action Closed No Action Closed No Action	Level 3 Description AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
Vietna	ALL LIOSE LIGHT LI	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	1 Batch Fault Group IO Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
### A	NLE L'Iosed NLE NLE NLE NLE NAC Work Request ID	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	1 Satch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
repair turel: All Mission impact: All Mission imp	Closed ALL ALL ALL ALL ALL ALL ALL ALL ALL AL	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	l Batch Fault Group IO Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
Work Object Status: CA sistoin Impact: Al sistoin myact: Al sistoin myacti myact sistoin	Closed ALL ALL ALL ALL ALL ALL ALL ALL ALL AL	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	l Batch Fault Group IO Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
Mission Impact: Al	NLL	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	I Batch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
Scalate Work: AL Work Request ID: Work Request ID: Sissipend Work Status: AL Works Request ID: Sissipend Work Status: AL Working Cirganization: epair Section: a warm of the work of the w	NLL	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	1 Batch Fault Group IO Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
Work Request ID: ssigned Work Status: Al. Working Organisation: pepil Section: aut. ID Wood Commission: aut. ID Wood Com	ML Work Request ID	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	f Batch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
Vorking Organisation: papir Section: audit ID 00000-00000-00000000 00000-000000000	Work Request ID	Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	f Batch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
repair Section: audit 10 audit 10 woodcoo-coccasia, accordant 10 cocco-coccasia, accordant 10 coccasia, accordant 1		Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	i Batch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
00000-0000A50A 00000-0008F68 00000-0008F68 00000-0008F68 00000-0008F68 00000-0008F540 000000-0008F540		Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	i Batch Fault Group ID Number	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
00000-0000A50A 00000-0008F68 00000-0008F68 00000-0008F68 00000-0008F68 00000-0008F540 000000-0008F540		Surface corresion on many parts of the body, needs painting. Air conditionen net producing coal air, probably needs re-gassing Batters compartment corroded. Batters compartment corroded and in poor condition. Gas strut on rear drop down step weak Bracket missing from fluid warmer locker Missing one of the rear number plats lights. Divesel leak after running engine Granthous of leak Corroll of the Corroll o	Closed	Fully Fit Umitted Role Fully Fit	No N	Level 3 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2	i Batch Fault Group ID Numbe	04 Mar 2021 04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A N/A N/A	Closed No Action Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR	Working Organisation	Repair Section	Estimated Repair Time
00000-0088FC88 000000-0088F469 00000-0088F369 00000-0088F369 00000-0088F369 00000-0088F369 00000-0088F369 00000-0088F369 000000-0088F369 00000-0088F369 000000-0088F369 00000-0088F369 000000-0088F369 00000-0088F369 00000-0088F369 00000-0088F369 00000-0088F369		Battery compartment coronded dister ear door, coronded and in poor condition. Gas strut on rear drop down step weak flacket missing from fluid warmer locker Missing one of the rear number plats lights. Diversel leak after running engine Gearhous oil leak Tiggle oil leak flegie oil leak	Closed	Fully Fit Non-Taskworthy Fully Fit	No No No No No No No No No	Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2 Level 2		04 Mar 2021 27 Jan 2020 04 Nov 2019 01 Nov 2019	N/A	Closed No Action Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00881540 00000-0087169 00000-0087169 00000-00881540 00000-00881540 00000-00881547 00000-00881547 00000-00881549 00000-00881540 00000-00881540 00000-00881540 00000-00881580 00000-00887180 00000-00871640 00000-00871640 00000-00871640 00000-00871640 00000-00871640 00000-00871640 00000-00871640 00000-00871640		Side rear door, correded and in poor condition. Gas strut on rear drop down tep week Bracket missing from fluid warmer locker Ministing one of the rear number plate lights. Diesel leak after running engine Gerarbon ell leak Coolan teak Tignie oil leak Brake predal has slightly too much travel a bit spongy Hand brake abide, missing rear rubber grommet/guide thingy Cab dash vent control stuck Tignie very sluggish/slow picts up Engine very sluggish/slow picts up	Closed	Fully Fit Non-Taskworthy Fully Fit	No No No No No No No	Level 2 Level 2 Level 2 Level 2 Level 2 Level 2		04 Nov 2019 01 Nov 2019						
00000-00077A6F 00000-00081546 00000-00081547 00000-00081547 00000-00081545 00000-00081545 00000-00081545 00000-00081545 00000-00081546 00000-000817A66 00000-00081A66		Gas strut on rear drop down step weak flacket missing from fluid warmer locker Missing one of the rear number plate lights. Discrete leak after running engine Gearbore oil leak Coclaint leak Great beautiful and the structure of	Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed	Fully Fit Non-Taskworthy Fully Fit	No No No No No No	Level 2 Level 2 Level 2 Level 2 Level 2		01 Nov 2019						
00000-00081946 00000-00081549 00000-00081549 00000-00081545 00000-00081545 00000-00081540 00000-00081540 00000-00081540 00000-00081540 00000-00081540 00000-00081540 00000-00081540 00000-000817464 00000-000817464 00000-000817464 00000-000817464 00000-000817464 00000-000817464		Missing one of the rear number plate lights Glearbox or leak Copiant leak Topics of leak Copiant leak Topics of leak Copiant leak That pend it has slightly too much travel' a bit spongy That pend it has slightly too much travel' a bit spongy Cab dash went control stuck Tapara lightly do will not work Topics very sluggish/slow picts up Elesering where work, rubber unbonding	Closed Closed Closed Closed Closed Closed Closed Closed Closed Closed	Fully Fit Fully Fit Fully Fit Fully Fit Fully Fit Non-Taskworthy Fully Fit	No No No No	Level 2 Level 2 Level 2			N/A	Closed No Action	AMBULANCE TRAUMA MGMT 2 STR			
00000-00887-54 00000-00887-54 00000-00887-54 00000-00887-54 00000-00887-54 00000-00887-58 00000-00887-58 00000-00887-58 00000-00887-58 00000-0087-78-6 00000-0087-8-6		Dicsel leak after running engine Gearbon oil leak Coolant leak Tignijen oil leak Brake predal has slightly too much travel/ a bit spongy Hand brake badhs, missing rear rubber grommet/guide thingy Cab dash vent control stuck Razard lights do not work Tigniee very sluggish/slow picts up Steering where worn, rubber urbonding	Closed Closed Closed Closed Closed Closed Closed Closed	Fully Fit Fully Fit Fully Fit Fully Fit Non-Taskworthy Fully Fit	No No No	Level 2 Level 2		01 Nov 2019 27 Jan 2020	N/A N/A	Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00887-54 00000-00887-54 00000-00887-54 00000-00887-58 00000-00887-58 00000-00887-58 00000-0087-786		Coolant leak Tiggine oil leak Titate perals has slightly too much travelf a bit spongy Hand brake padah has slightly too much travelf a bit spongy Cab dash vent control stuck Tasara lights do not work Tingine very sluggish/slow picts up Steering where worn, rubber unbonding	Closed Closed Closed Closed Closed Closed	Fully Fit Fully Fit Non-Taskworthy Fully Fit	No No			24 Jan 2020	N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-0088F542 00000-0088F532 00000-0088F532 00000-0088F536 00000-0088F53E 00000-0088F53E 00000-0088F53E 00000-008F73A66 00000-008F73A6 00000-008F73A6 00000-008F3A6C 000000-008F3ACD 000000-008F3ACD		Engine oil leak Brake pedal has slightly too much travel/ a bit spongy Hand brake cable, missing rear rubber grommet/guide thingy Cab dash west control stuck Braker lights do not work Engine very sluggish/slow pick be Engine very sluggish/slow pick be Engine very nubber unbonding	Closed Closed Closed Closed Closed	Fully Fit Non-Taskworthy Fully Fit	No	Level 2	_	23 Jan 2020 17 Dec 2019	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-00887538 00000-00887905 00000-00889501 00000-00887536 00000-00877A66 00000-00877A64 00000-00877A64 00000-00877A64 00000-00877A64 00000-0087A66 00000-0087A66 00000-0087A66 00000-0087A6A		Hand brake cable, missing rear rubber grommet/guide thingy Cab dash went control stuck Hazard lights do not work Engine very sluggish/slow pick up Steering wheel worn, rubber unbondling	Closed Closed Closed	Fully Fit	No	Level 2		24 Jan 2020	N/A	Closed No Action	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00877A56 00000-0089900 00000-008875H 00000-00877A65 00000-00877A63 00000-00877A64 00000-00877A6A 00000-00877A6A 00000-0087A6A 00000-0082A9CA 00000-0082A9CD 00000-008158A6 000000-00000-00A0C4C		Cab dash vent control stuck Hazard lights do not work Engine very sluggish/slow pick up Steering wheel worn, rubbev unbonding	Closed Closed			Level 2		04 Nov 2019	N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-008F53E 00000-00877A65 00000-00877A53 00000-00877A64 00000-00877A6A 00000-00877A5C 00000-0088A6E3 00000-0082A9CA 00000-008158A6 00000-008158A6 000000-008158A6		Hazard lights do not work Engine very sluggish/slow pick up Steering wheel worn, rubber unbonding	Closed		No No	Level 2 Level 2		04 Nov 2019 01 Nov 2019	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00877A66 00000-00877A53 00000-00877A6A 00000-00877A6A 00000-0083A8E3 00000-0082A9CA 00000-0082A9CD 00000-008158A6 00000-008158A6 00000-00A89F3A		Steering wheel worn, rubber unbonding	closed	Fully Fit	No	Level 2		14 Feb 2020	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
00000-00877A53 00000-00877A64 00000-00877A5C 00000-00877A5C 00000-00838AE3 00000-0082A9CA 00000-008158A6 00000-008158A6 000000-00AD0C4C			Closed			Level 2		04 Nov 2019 01 Nov 2019	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00877A6A 00000-0087A5C 00000-0088AE3 00000-0082A9CA 00000-0082A9CD 00000-008158A6 00000-00AD0C4C			Closed	Fully Fit	No	Level 2		01 Nov 2019	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-00B77ASC 00000-00B3BAE3 000000-00B2A9CA 00000-00B2A9CD 00000-00B15BA6 00000-00AD0C4C		Map light U/S Incorrect? tyres fitted	Closed		No No	Level 2 Level 2		01 Nov 2019 01 Nov 2019	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-0082A9CA 00000-0082A9CD 00000-008158A6 00000-00AD0C4C 00000-00AB9F3A	- 1	Flooring loose on side step, trip hazard	Closed	Fully Fit	No	Level 2		01 Nov 2019	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-00B2A9CD 00000-00B15BA6 00000-00AD0C4C 00000-00AB9F3A		CARRY OUT BRAKE TEST INVESTIGATE AND RECTIFY FAN BELTS SQUEALING	Closed		No No	Level 2 Level 2		22 May 2019 16 Apr 2019	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR			السهور
00000-00AD0C4C 00000-00AB9F3A		INVESTIGATE AND RECTIFY DRIVERS DOOR LOCK INOP/STIFF	Closed			Level 2		16 Apr 2019	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00AB9F3A		INVESTIGATE AND RECTIFY CHARGING FAULT BLUE LIGHTS NOT WORKING	Closed	Non-Taskworthy	No	Level 2		05 Mar 2019	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
30000-00AB9F36		CARRY OUT MOT / MEI PREP	Closed Closed	Non-Taskworthy Fully Fit		Level 2 Level 2		06 Aug 2018 05 Jun 2018	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
		CARRY OUT MOT	Closed			Level 2		05 Jun 2018	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-00ABCB19 00000-00A3EDF2		REPLACE HEATER BOX ASSY REPLACE ENGINE MOUNTS	Closed		No No	Level 2 Level 2		12 Jun 2018 23 Jul 2017	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00A5E084		INVESTIGATE NOISEY OPERATION WHEN IN REVERSE	Closed	Fully Fit	No	Level 2		02 Oct 2017	N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-00AB7758 00000-00A980BB		WORK COMPLETED ON BABCOCK 880149207 RECTIFY EXCESSIVE NOISE FORM ENGINE WHEN RUNNING	Closed	Fully Fit Non-Taskworthy	No No	Level 2 Level 4		30 May 2018 20 Feb 2018	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-00ADECDB		CARRY OUT MOT	Closed			Level 2		20 Mar 2017	N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00A0ECD6 00000-009DCE34		CARRY OUT MOT PREP RECTIFY AIR CON PUMP INOP	Closed			Level 2		20 Mar 2017	N/A		AMBULANCE TRAUMA MGMT 2 STR		1111	
00000-009ECF01		RE-CHARGE AIR CON SYSYTEM AND RECTIFY LEAK	Closed	Non-Taskworthy Limited Role		Level 2 Level 2		08 Nov 2016 01 Dec 2016	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-009ECF02 00000-009D0F91		RE-CHARGE AIR CON SYSYTEM AND RECTIFY LEAK	Closed			Level 2		01 Dec 2016	N/A	Closed No Action	AMBULANCE TRAUMA MGMT 2 STR			
00000-00900E98		REPLACE BOTH REAR AXLE AIR SPRINGS REPLACE DVRS STEP ASSY	Closed		No No	Level 2 Level 2		10 Oct 2016 10 Oct 2016	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-009D0EA3		REPLACE PAX DOOR STAY	Closed	Fully Fit	No	Level 2		10 Oct 2016	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-009D0E96 00000-009D0E85		REPLACE BOTH MIDDLE AXLE SHOCK ABSORBERS CHANGE ALL TYRES	Closed	Non-Taskworthy Fully Fit	No No	Level 2 Level 2		10 Oct 2016 10 Oct 2016	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-0098DBE4		RECTIFY CHARGING FAULT	Closed	Non-Taskworthy		Level 2		18 Aug 2016	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
00000-0097F9CD 00000-0097F9CC			Closed			Level 2 Level 2		21 Mar 2016 21 Mar 2016	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-0097F9CB		CARRY OUT MINOR SERVICE APRIL 2016	Closed	Fully Fit		Level 2		21 Mar 2016	N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-009821A2 00000-0095E2C2		VIN PLATE MODIFICATION under PDS task P047	Closed			Level 3		29 Mar 2016	N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-0095C54B		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063 Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Fully Fit	No No	Level 2 Level 2	000000-000031A3	14 Jan 2016 11 Jan 2016	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-008CB325 00000-008CB320	- 3	RENEW WINDSCREEN WASHER PUMP	Closed			Level 2		08 Oct 2015	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
00000-008CB31D		CARRY OUT 6M SERVICE CARRY OUT 6 MSI	Closed	Fully Fit Non-Taskworthy		Level 2 Level 2		08 Oct 2015 08 Oct 2015	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-008C3FFC		INVESTIGATE AND RECIFY NON STARTER	Closed	Fully Fit	No	Level 2		20 Sep 2015	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
00000-00880E0C 00000-00856EF9			Closed			Level 2 Level 2		17 Mar 2015 23 Nov 2014	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00880E0F		CARRY OUT MEI INSPECTION	Closed	Fully Fit	No	Level 2		17 Mar 2015	N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-00886ED7 00000-00880E0A		RECTIFY DVRS DOOR WONT CLOSE CORRECTLY DUE TO WIND DAMAGE CARRY OUT MOT/MEI PREP	Closed			Level 2 Level 2		06 Apr 2015	N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-007D63A6	- 1	REPAIR / RENEW DVRS DOOR ASSY	Closed	Fully Fit	No	Level 2		17 Mar 2015 12 Dec 2013	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00880E11 00000-00880E17		CARRY OUT 12M SERVICE (MINOR) APRIL 15	Closed			Level 2			N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-008880C7		RECTIFY FUEL LEAK AT REAR OF F.I.P. CASING	Closed			Level 2 Level 2			N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00760013 00000-00880E20			Closed			Level 3			N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-00880E20 00000-00880E21		CARRY OUT 2 YEARLY OOPS AXLE DRIVE OIL APRIL 15 CARRY OUT 2 YEARLY OOPS T BOX OIL APRIL 15	Closed			Level 2 Level 2		17 Mar 2015 17 Mar 2015	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00880E1C		CARRY OUT 2 YEARLY OOPS BRAKE FLUID CHANGE APRIL 15	Closed	Fully Fit	No	Level 2		17 Mar 2015	N/A	Servicing	AMBULANCE TRAUMA MGMT 2 STR			
00000-00856EC8 00000-00856EC0		REPLACE MISSING 24V STRIP LIGHT IN REAR RENEW 2 X 2 KG FIRE EXTINGUISHER	Closed			Level 2		24 Nov 2014 24 Nov 2014	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00847684		CARRY OUT 6M SERVICE (INTER) NOV 14	Closed	Fully Fit	No	Level 2					AMBULANCE TRAUMA MGMT 2 STR			
00000-0084767F 00000-00851EDD			Closed	Fully Fit Non-Taskworthy		Level 2 Level 2			N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00840807		TOWING PINTLE ASSEMBLY	Closed	Limited Role	No	Level 2	000000-00001F44	07 Oct 2014	Degraded	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-00804E49 00000-0081A412			Closed	Fully Fit Non-Taskworthy		Level 2 Level 2		28 Apr 2014	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-0081A40E	-	REPLACE STARTER MOTOR ASSY	Closed	Non-Taskworthy		Level 2		19 Jun 2014 19 Jun 2014	N/A N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-0080105D 00000-00812C2A			Closed	Fully Fit	No	Level 2		09 Apr 2014	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-00812C2A 00000-00812C28		TEMPORARY REPAIR DOOR (STILL AWAITING SPARES) FIT 2 X TRACK ROD ENDS AND SDJUST TRACKING	Closed	Fully Fit Fully Fit		Level 2 Level 2		25 May 2014 25 May 2014	N/A N/A	Inspection Inspection	AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00801068		CARRY OUT OOPS 3 YEARLY COOLANT CHANGE MAY 2014	Closed	Fully Fit	No	Level 2		09 Apr 2014	N/A	Servicing	AMBULANCE TRAUMA MGMT 2 STR			
00000-00801068 00000-00801064			Closed Closed			Level 2 Level 2			N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00801059		CARRY OUT MOT JUNE 2014	Closed	Fully Fit	No	Level 2		09 Apr 2014	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
00000-00801057 00000-007FESF3			Closed	Fully Fit Non-Taskworthy		Level 2 Level 2			N/A N/A		AMBULANCE TRAUMA MGMT 2 STR			
00000-007E6F15		RECTIFY ALTERNATOR BOLTS MISSING	Closed	Non-Taskworthy		Level 2		26 Feb 2014 10 Feb 2014	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
0000-007CEB98 0000-007CEB97		CARRY OUT 6M SERVICE (INTER) DEC 13 CARRY OUT 6 MSI DEC 13	Closed	Fully Fit	No	Level 2		22 Nov 2013	N/A	Servicing	AMBULANCE TRAUMA MGMT 2 STR			
0000-007CE897 0000-007D63A9		CARRY OUT 6 MSI DEC 13 RENEW LAP BELT IN REAR OF AMBULANCE	Closed			Level 2 Level 2		22 Nov 2013 13 Dec 2013	N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
0000-007D63AB		RENEW PUSH LOCKS ON CUPBOARDS IN REAR OF AMBULANCE	Closed	Fully Fit	No	Level 2		13 Dec 2013	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
0000-0078A636 0000-0078A633			Closed			Level 2 Level 2					AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-0078A604		CARRY OUT 6 MSI JUNE 2013	Closed	Fully Fit	No	Level 2		15 May 2013	N/A	Inspection	AMBULANCE TRAUMA MGMT 2 STR			
0000-0078ASC4 0000-0078ASA0			Closed			Level 2 Level 2			N/A N/A		AMBULANCE TRAUMA MGMT 2 STR AMBULANCE TRAUMA MGMT 2 STR			
00000-00780905		RECTIFY EMERGENCY BLUES LIGHTS ON ROOF INOP	Closed	Limited Role	No	Level 2		22 May 2013	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			
00000-00777F53		RECTIFY NON STARTER / CHARGING FAULT	Closed	Non-Taskworthy	No	Level 2		21 Mar 2013	N/A	Failure	AMBULANCE TRAUMA MGMT 2 STR			