




<b>Mecmar FSN15/138T Mobile Grain Dryer</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2203-0163
<b>Product Type</b>	Machinery – Mobile Grain Dryer
<b>Product Identifiers</b>	<p><i>Mecmar FSN15/138T Mobile Grain Dryer</i></p> <p>Manufactured in 2015 – Serial numbers 215027, 215029, 215032, 215033, 215057, 215103, 215189, 215191</p> <p>Manufactured in 2016 – Serial numbers 216016, 216021, 216023, 216025, 216069, 216078, 216124, 216146, 216151</p> <p>Manufactured in 2017 – Serial numbers 217032, 217046, 217047, 217049, 217051, 217083, 217090, 217103, 217104, 217120, 217124, 217126, 217202, 217203</p> <p>Manufactured in 2018 – Serial numbers 218012, 218014, 218059, 218060, 218064, 218074, 218164</p> <p>Manufactured in 2019 – Serial numbers 219067ZAC, 219101ZAC, 219112ZAC</p> <p>Manufactured in 2020 – Serial numbers 220050K, 220070, 220092, 220120Z, 220172ZAC</p> <p>Manufactured in 2021 – 221015, 221017, 221018, 221033Z, 221037, 221089, 221090Z, 221113, 221114, 221119, 221120, 221225, 221268, 221269</p>
<b>Product Description</b>	Mobile grain dryer
<b>Country of Origin</b>	Italy
<b>Counterfeit</b>	Not counterfeit
<b>Risk Level</b>	Serious
<b>Risk Type</b>	Hazard – injuries from entrapment/crushing



<b>Risk Description</b>	<p>The bottom cone of the drying chamber has two removeable panels which act as an inspection door to allow access for maintenance and cleaning. The panels are retained in place with channels on the machine and additional bolts. The machine can be operated with the guards removed and the guards do not adequately prevent the risk of injury from contact with the moving internal stirrer arms of the grain dryer. This product does not meet the requirements of The Supply of Machinery (Safety) Regulations 2008. The machine presents a serious risk of injuries from crushing and/or entanglement.</p>
<b>Corrective Measures</b>	<p>Users must not operate the grain dryer with the inspection door panels removed. We recommend that users contact their supplier for information about how to bring existing machines into compliance.</p> <p>The product was withdrawn from the GB market until it could be brought into compliance.</p> <p>The GB suppliers have been required to contact all persons previously supplied with the product to provide them with revisions of information.</p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Health and Safety Executive