



Puhui IR Preheating Plate, T-8280

Aspect	Details
<p>Images</p>	
<p>Alert Number</p>	<p>2207-0049</p>
<p>Product Type</p>	<p>Electrical appliances and equipment – Preheating plate</p>
<p>Product Identifiers</p>	<p>Batch No: RVG3355-220228-0009-565 Other: G3355-T8280JRQ00000001V2, 6/16, GBLFD-GC0091-73, IN30</p>
<p>Product Description</p>	<p>Blue and yellow Infrared IC pre-heat plate with metal bars</p>
<p>Country of Origin</p>	<p>China</p>
<p>Counterfeit</p>	<p>Unknown</p>
<p>Risk Type</p>	<p>Electric shock</p>
<p>Risk Level</p>	<p>Serious</p>
<p>Risk Description</p>	<p>The product presents a serious risk of electric shock as the appliance was inadequately earthed and the clamping means was not adequately secured against accidental loosening. The cord set did not comply with BSEN 60799 and The plug on this sample failed to comply with BS1363-1 as The dimensions of the sleeved parts of the pins differed from the metal parts of the pins. This resulted in a distinct step between the two. This could cause damage to the socket and undue wear and tear to the sleeve, potentially causing an electric shock to users. The instructions supplied with this sample were considered to be inadequate. They did not contain adequate safety information and details to ensure the correct and safe use of the product. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.</p>
<p>Corrective Measures</p>	<p>The import has been rejected at the border</p>
<p>Online Marketplace</p>	<p>N/A</p>
<p>Notifier</p>	<p>Local Authority Trading Standards</p>