

Defence Equipment and Support Secretariat #2043 Maple 0a Ministry of Defence Abbey Wood Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

Our Reference: FOI2022/01038 Date: 11 February 2022

Dear xxxxx.

I am writing about your email of 25 January 2022, requesting the following information:

'I have downloaded and searched the Merlin documents but could not find any service history reports for the below mentioned Ex MOD Land Rover Defender Wolf. Please can you provide me with the Usage-, Service-, Fault-, Modification- and Maintanance History along with any other information or photos you hold for the following vehicle: In Service Registration Number: LP72AA Manufacturer: Land Rover Model: Defender Wolf (SWB) L3 Description: TRUCK UTY LIGHT (TUL) (HS) 4X4 GS SOFT TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR) Chassis Number: SALLDAA67WA140938 EAC/MAC: NB42203100 Date in Service: 07/07/1998.'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

Annex A - Transfer History

Annex B - Inspection History Annex C - Service History

Annex D - Modification History (redacted)

Annex E - Fault History (redacted)

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Commercially sensitive information in the Modification History (Annex D), and Fault History, (Annex E) relate to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Modification History and Fault History provide details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

` '		
Yours	CINCA	r 🗅 l v /
i oui s		і Сіў,

**DE&S Secretariat** 

## VEHICLE DETAILS

	NATO Stock		Contract		
ERM	Number	Asset Code	Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
				TRUCK UTY LIGHT (TUL) (HS) 4X4 GS SOFT TOP LAND	Army/NATO
LP72AA	2320998939741	NB42203100	LV2A/088DUM	ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
09/07/1998	SALLDAA67WA140938	N/K		

## **VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LP72AA	3		CA005A	JSCS ASHCHURCH		36542AA	09/07/1998	
LP72AA	4	24/09/1998	A4420A	HQ CTG BG	42562A	4901	24/09/1998	
`LP72AA	4	17/03/2004	A0587A	3 SCOTS	999	999	17/03/2004	H/T
LP72AA	4	31/07/2005	A4420A	HQ CTG BG		73	31/07/2005	H/T
LP72AA	4	13/03/2008	A0582A	1 YORKS	999	53159	13/03/2008	H/T
LP72AA	3	14/03/2009	A5969A	TFSU (UK)	61911	746DD	22/04/2009	
LP72AA	4	12/01/2011	A1038A	LOGISTIC SVCS NESBS ASHCHURCH	1631D	999	12/01/2011	
LP72AA	1	16/09/2013	CA005A	JSCS ASHCHURCH	999999	7131AA	16/09/2013	
LP72AA		02/12/2013		DSG COLCHESTER			03/12/2013	
LP72AA		03/09/2014		156 REGT RLC			16/09/2014	
LP72AA		03/07/2019		OSVP HOLDINGS			03/07/2019	

Work Objects	ļ									
Control November										
Serial Number: NSN:	LP72AA 2320998939741									
NSN:	2320998939741									
Criteria:							-			
Repair Level:	ALL									
Work Object Status:	Closed				-					
Mission Impact:	ALL				-					
Fault State:	ALL						-			
Escalate Work:	ALL						-			-
Work Request ID:										-
Assigned Work Status:	ALL				-		·			
Working Organisation:					-					
Repair Section:							***************************************			
						-				
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Lev	el Fault State	Work Status	Estimated Repair Time Working Organisat	ion Repair Section	
000000-00AB9FEA		No	Annual Brake Test (2)	18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
00000-00712835		No	6 Monthly 6534 Insp		Level 1			000:00		***************************************
000000-00541A26		No	MEI (2)		Level 2	Fully Fit		000:00	238LAD	
000000-00AB576D		No	FMT932 (W) Mandatory Equipment Inspection (2)*	18 Mar 2020	Level 2	Fully Fit		000:00	238LAD	
000000-00ABA37A			Annual Headlight Alignment Check (2)	18 Apr 2020	Level 2	Fully Fit	CL	000:00	238LAD	
000000-004DFC19		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-007CC34B		No	MEI (2)		Level 2	Fully Fit		000:00	238LAD	
000000-00ABA357		No	FMT930 Landworthiness (AR)		Level 1	Fully Fit	CL	000:00	238LAD	
00000-00ABA0EF		No	Annual Headlight Alignment Check (2)	18 Apr 2020	Level 2	Fully Fit	CL	000:00	238LAD	
000000-00506E3D			6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00	238LAD	
000000-00ABA25B			FMT930 Landworthiness (AR)		Level 1	Fully Fit		000:00	238LAD	
000000-009471A1			6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00	238LAD	
000000-00AB9FEC				18 Sep 2019	Level 2	Fully Fit	CL	000:00	238LAD	
00000-00AB4B8C			MEI (2)		Level 2	Fully Fit		000:00	238LAD	
000000-005A36AC			6 Monthly 6534 Insp		Level 1			000:00		
000000-00ABA0EE				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
000000-00ABA098				18 Sep 2019	Level 1	Fully Fit		000:00	238LAD	
000000-0087A626			6 Monthly 6534 Insp		Level 1			000:00		
000000-00AB5773			FMT930 Landworthiness (AR)		Level 1	Fully Fit		000:00	238LAD	
000000-00ABA39E			6 Monthly 6534 Insp		Level 1	Fully Fit		000:00	238LAD	
000000-00541A44			6 Monthly 6534 Insp		Level 1	Fully Fit		000:00	238LAD	
000000-00AB5770				18 Mar 2020	Level 2	Fully Fit		000:00	238LAD	
000000-00ABA096 000000-00436010				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
000000-00436010 000000-0032E690			6 Monthly 6534 Insp		Level 1			000:00		
			MEI (2)		Level 2			000:00		
000000-009E7F6D 000000-00089447			6 Monthly 6534 Insp First Parade Insp (AR)(1)		Level 1	Fully Fit		000:00	238LAD	
000000-00089447			First Parade Insp (AR)(1)		Level 1			000:00		
000000-000E4B8B			MEI (2)		Level 1			000:00		
000000-0000F320			6 Monthly 6534 Insp		Level 2 Level 1	Cully Cit		000:00	220115	
00000-00860264 000000-00AB9FEB				18 Apr 2020	Level 1	Fully Fit Fully Fit		000:00	238LAD	
000000-00ABA2FA				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
000000-0050370A			MEI (2)	10 Apr 2020	Level 2	Non-Taskworthy		000:00	238LAD 238LAD	
00000-00ABA097				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD 238LAD	
00000-00ABA2FC				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD 238LAD	
00000-00ABA2FB				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD 238LAD	
00000-004DFB8C			6 Monthly 6534 Insp	20.1pi 2020	Level 1	- any ric		000:00	238LAD	
00000-00ABA0ED				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
00000-00656D20			MEI (2)		Level 2	Fully Fit		000:00	238LAD	
00000-003CC3A2			6 Monthly 6534 Insp		Level 1			000:00	23000	
00000-00ABA379				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
00000-00ABA378				18 Apr 2020	Level 2			000:00	238LAD	
00000-00ABA095				18 Apr 2020	Level 2	Fully Fit		000:00	238LAD	
00000-00AB9FE9				18 Apr 2020	Level 2			000:00	238LAD	
000000-003CC3A1			MEI (2)	- F	Level 2			000:00	230000	
00000-00937A3F			MEI (2)		Level 2	Fully Fit		000:00	238LAD	
			6 Monthly 6534 Insp		Level 1	Fully Fit		000:00	238LAD	
000000-007CC3DC										

Work Objects										
		ļ				-				
erial Number:	LP72AA									
ISN:	2320998939741				-					
Criteria:										
Repair Level:	ALL									
Work Object Status:	Closed									
Mission Impact:	ALL						1			
ault State:	ALL				1		1			
Escalate Work:	ALL				1					
Work Request ID:					<u> </u>	<del> </del>	<del> </del>			
Assigned Work Status:	ALL						1			
Norking Organisation:										
Repair Section:										
	work Request ID		Maintenance Event Name					Estimated Repair Time	Working Organisation	
000000-0094717B		No		17 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-0059EA1D		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-004D3CBE		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-0087A84B		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-00656D07		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		Level 1	Fully Fit	CL	000:00		238LAD
00000-0070ECA6		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-0032E662		No		25 Mar 2020	Level 1			000:00		
00000-0094717C		No		17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-00506E2E		No		17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-00AB9EBF		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1			000:00		
00000-00937A3D		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	25 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
000000-0032E664		No	Yearly/20000 Kms	17 Mar 2020	Level 1			000:00		
00000-00937A3E		No	2 Yearly/40000 Kms	25 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-00656D05		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	25 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-00656D02		No	2 Yearly/40000 Kms	25 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
000000-0066021E		No	Yearly/20000 Kms	17 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-009E7F69		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
000000-0032E663		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1			000:00		
00000-007CC366		No	Yearly/20000 Kms	17 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-003CC3B9		No	Yearly/20000 Kms	17 Mar 2020	Level 1			000:00		
00000-003CC3B6		No	2 Yearly/40000 Kms	25 Mar 2020	Level 1			000:00		
00000-000DE574		No	6 Monthly/10000 Kms	17 Sep 2019	Level 1		CL	000:00		
00000-000893B9		No	Weekly (AR)(1)	1	Level 1		CL	000:00		
00000-0009872F				17 Mar 2020	Level 1		CL	000:00	***************************************	
00000-000F609F				17 Sep 2019	Level 1		CL	000:00		
00000-003CC3BA		No		16 Mar 2024	Level 1			000:00		
00000-00ABA09C		No		16 Mar 2024	Level 1	-		000:00		
00000-0070EC85			OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		Level 2	Fully Fit	CL	000:00		238LAD
00000-003CC3B8				17 Sep 2019	Level 1			000:00		-30170
00000-00436019				17 Sep 2019	Level 1	-		000:00		
00000-007CC3B9				17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD
00000-00937A3B				25 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-005036DD				17 Mar 2020	Level 1	Fully Fit	CL	000:00		238LAD
00000-003CC3BC		No		16 Mar 2024	Level 2	. July 110		000:00		ZJOLAU
00000-003CC3B7		***********************		25 Mar 2020	Level 1			000:00	*************************	
00000-00ABA0C9				16 Mar 2024	Level 2	-		000:00	•	
00000-00ABA0E9		<del></del>		17 Mar 2020	Level 1	Culler Cit	CL	CHICAGO SAN THE THE THE THE THE SAN TH		220/12
00000-00AB4B88		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	17 IVIAT 2020	Level 1	Fully Fit	CL	000:00 000:00		238LAD
00000-0032E083		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	25 Mar 2020	Level 1					
00000-005CC388		No				F. II. Fis		000:00		
.00000-00000220		INU	o Monthly 10000 Kms	17 Sep 2019	Level 1	Fully Fit	CL	000:00		238LAD

Work Objects															T
Serial Number:	LP72AA														
NSN:	2320998939741								***************************************					1	
										1					
Criteria:															
Repair Level:	ALL														
Work Object Status:	Closed														***************************************
Mission Impact:	ALL													-	
Fault State:	ALL									1					-
Escalate Work:	ALL													***************************************	
Work Request ID:															·
Assigned Work Statu	s: ALL													1	
Working Organisation	n:														
Repair Section:														-	
														1	
Modification Event II	Modification Num	nber Modification Description	Work Request ID	Escalate Wo	rk Production Classification/In	Service Classification Modificat	ion Type Apply When Usage Equ	als Embody by Target Date	Usage Counter Units Fault St	ate Wo	ork Status	Repair Level	Working Organisation	n Repair Section	Estimated Renair Tir
000000-006F5498	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI		, , , , ,	Fully Fi			Level 2		238LAD	
000000-006F4783	00017	Introduction of Battery Retention		No	1/A	UTI				skworthy CL		Level 2		238LAD	- (CSS) (MARKET SEE
000000-00701B2E	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI			Fully Fi			Level 2		238LAD	
000000-007190AE	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI			Fully Fi			Level 2			- Parameter State of the Parameter State of t
000000-0068DADB	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				skworthy CL		Level 2		238LAD	
000000-00618E31	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI			Fully Fi			Level 2			
000000-00701333	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI			Fully Fi			Level 2			
000000-006F6A6C	00030	Front Belt Protection Sleeves		No	1/A	UTI			Non-Ta	skworthy CL		Level 2			
000000-00728769	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				skworthy CL		Level 2		-	NEW TOTAL
													····	1	
													/·······		******************************

Work Objects			· · · · · · · · · · · · · · · · · · ·	***********************	********	Ţ				r	·				·
work Objects				-									-		-
Serial Number:	LP72AA					<del> </del>							+		
NSN:	2320998939741		<b>†</b> ************************************								***************************************				-
Criteria:															1
	ALL														
Work Object Status: Mission Impact:	ALL														
Fault State:	ALL										ļ				
Escalate Work:	ALL												+		
Work Request ID:	7166														
Assigned Work Status:	ALL		†			1			***************************************						
Working Organisation:															_
Repair Section:			1												-
Fault ID	Work Request ID	Fault Description	Work Status		Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation		Estimated Repair Time	
000000-00B1B26C 000000-00B1F0E7		Foglamp switch mtg panel cracked. SNVE 377 - SWIVEL HOUSING		Fully Fit Non-Taskworthy		Level 1					TUL HS GS SOFT TOP		238LAD		
000000-00B21CF0		SIVE 37 - SWIVEL HOUSING				Level 1			N/A N/A		TUL HS GS SOFT TOP				-
000000-00AA3CA7	***************************************	Headlamps losing reflective quality				Level 2				Inspection Failure	TUL HS GS SOFT TOP		238LAD		
000000-00A2101F	***************************************	Foglamp switch stiff operation,				Level 2				Fallure	TUL HS GS SOFT TOP		238LAD		
000000-00AC8516		Rear seat cushions torn	Closed	Fully Fit	No	Level 1		12 Jul 2018			TUL HS GS SOFT TOP		1000.0		
000000-00804137		1 X Vehicle battery not holding charge.	Closed			Level 1				Fallure	TUL HS GS SOFT TOP		238LAD		
000000-COADE9FB		RHR SHOCK ABSORBER TOP BUSH EYE DAMAGED				Level 2		18 Sep 2018	N/A	Damage	TUL HS GS SOFT TOP		238LAD		
000000-0088507A		Stone chip in I/h btm corner of windscreen. (OBS)				Level 2				Damage	TUL HS GS SOFT TOP				1
000000-00AA4451		L/H Door top assy damaged.				Level 2				Damage	TUL HS GS SOFT TOP		238LAD		4
000000-00AGE5BD 000000-008BED4B		Slight oil leak at rear diff pinion oil seal				Level 2				Failure	TUL HS GS SOFT TOP				-
000000-008BED4B 000000-0097E7BB		Spare tyre cracks in sidewall (OBS)  L/H/F Tyre showing signs of perishing (OBS).				Level 1				Failure Non Specific	TUL HS GS SOFT TOP				
000000-0097E78B		1 x Stud stripped at rear diff housing.				Level 1				Non Specific Failure	TUL HS GS SOFT TOP		238LAD		
000000-009C889F		A statu sample at real unit mosting.  Carryout Modification No 46				Level 1		21 Sep 2016 01 Aug 2017		Modification	TUL HS GS SOFT TOP		238LAD		
000000-00A4135D		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery isolation Switch.							N/A	Inspection	TUL HS GS SOFT TOP				
000000-00A0830B		W/Screen washer jet assy damaged				Level 2				Damage	TUL HS GS SOFT TOP				
000000-00A0E541		Hazard switch mtg panel cracked	Closed	Fully Fit		Level 2			N/A	Damage	TUL HS GS SOFT TOP	1	1		
000000-00A0E619		Both front seat backrest handle grips missing.				Level 1		16 Mar 2017	N/A		TUL HS GS SOFT TOP		238LAD		
000000-0097E80F		Rear brake pads getting low(OBS).				Level 2					TUL HS GS SOFT TOP		238LAD		
000000-0097E815		Suspect slight oil leakage from I/h/r Cylinder head bolt.(OBS).				Level 2			N/A	Inspection	TUL HS GS SOFT TOP	ļ	238LAD		
000000-00885051 000000-00863CF8		slight play at stg column top u/) Renew speedo cable.				Level 2			N/A	Fallure	TUL HS GS SOFT TOP		238LAD		
000000-00863CF8						Level 2 Level 1		09 Jan 2015 01 Dec 2016		Failure Failure	TUL HS GS SOFT TOP		238LAD		-
000000-009F289F		Towing strop missing from CES R/H Air vent lever assy broken.				Level 2					TUL HS GS SOFT TOP		238LAD		
000000-009C8897		Renew reverse light lens.				Level 1				Fallure	TUL HS GS SOFT TOP		238LAD		
000000-009C8892	-	Renew reverse light switch	Closed			Level 2					TUL HS GS SOFT TOP		23RLAD		
000000-008E3185		Map light inoperative				Level 2				Fallure	TUL HS GS SOFT TOP		238LAD		
000000-00988856		RENEW MAIN FUEL FILTER ELEMENT	Closed	Fully Fit	No	Level 1					TUL HS GS SOFT TOP		238LAD		
000000-0097E7B0		L/H/ Tail light inoperative.		Non-Taskworthy		Level 2				Fallure	TUL HS GS SOFT TOP		238LAD		
000000-0097E794		Renew brake fluid.		Non-Taskworthy		Level 2			N/A		TUL HS GS SOFT TOP		238LAD		
000000-0097E77F		1 x Battery u/s	Closed	Non-Taskworthy	No	Level 1			N/A	Failure	TUL HS GS SOFT TOP		238LAD		-
000000-0097E771 000000-009620F2		Front bumper bent I/h/s.  Check No2 hall locat to go a tightness or our calculation (E.S.) 50062				Level 2					TUL HS GS SOFT TOP		238LAD		
000000-009620F2	-	Check No2 ball joint torque tightness as per safety notice LE SNVE 00063  Carryout balljoint safety check i.a.w James SNVE Dated 16,12.15		Non-Taskworthy Fully Fit		Level 2 Level 2			N/A N/A	Inspection	TUL HS GS SOFT TOP		238LAD 238LAD		
000000-0090E22C		Cult you doubter safety Circle Law James Sieve Dated 16,12,13		Non-Taskworthy		Level 1					TUL HS GS SOFT TOP		238LAD		
000000-008DE229		Electrical fault on lights.		Non-Taskworthy		Level 2					TUL HS GS SOFT TOP		238LAD		
000000-00876609	T	Signt play at stg col" top u/j OBS.				Level 2			N/A	Failure	TUL HS GS SOFT TOP	1	238LAD		
000000-008BED63		Instrument panel Insecure.	Closed	Fully Fit	No	Level 2		08 Sep 2015		Failure	TUL HS GS SOFT TOP	1	238LAD		
000000-008BED5A	610000011100011000	R/H Wiper requires repositioning				Level 2		08 Sep 2015		Failure	TUL HS GS SOFT TOP		238LAD		
000000-008BED52		Handbrake requires adjustment.		Non-Taskworthy		Level 2			N/A	Failure	TUL HS GS SOFT TOP		238LAD		
000000-008BD009 000000-0089A0BF		Carryout B6534 B1 drivers inspection. MEI RE-INSPECTION				Level 1			N/A		TUL HS GS SOFT TOP		238LAD		
000000-00894081		MEI RE-RISPECTION Slight play at rear prop rear U/j				Level 2					TUL HS GS SOFT TOP		238LAD		
000000-00885043		Sagit pay at ear pripried O/3 (OII leakage at ear rocker cover gasket				Level 2 Level 2				Fallure Fallure	TUL HS GS SOFT TOP		238LAD 238LAD		-
000000-00876615		Officekage R/H/S of Engine.				Level 2					TUL HS GS SOFT TOP	·	238LAD		
000000-0088502C		Excess play in cooling fan viscous unit.	Closed	Fully Fit	No	Level 2					TUL HS GS SOFT TOP		238LAD		
000000-00885083		5 x Fuses damaged in main fuse box.		Non-Taskworthy		Level 1		26 Mar 2015	N/A	Fallure	TUL HS GS SOFT TOP		238LAD		
000000-00885048	1	Oil leakage at timing cover breather pipe		Non-Taskworthy		Level 2		26 Mar 2015	N/A	Fallure	TUL HS GS SOFT TOP				
000000-008765F6		Adjust accelerator pedal stop.				Level 2					TUL HS GS SOFT TOP		238LAD		
000000-0086F042 000000-0085D970		Fuel leakage from fuel tank area.	Closed	Non-Taskworthy		Level 2				Fallure	TUL HS GS SOFT TOP		23BLAD		
000000-00850970		Speedometer Inoperative. Towing Pintle Assembly		Non-Taskworthy Limited Role		Level 2 Level 2					TUL HS GS SOFT TOP		238LAD		
000000-00843994 000000-0083A2A3		Towing mitter Assembly Carryout receipt inspection from DSG				Level 2			N/A	Inspection Inspection	TUL HS GS SOFT TOP		-		
000000-00680454		insp Steering Drop Arm Tab Washer		Non-Taskworthy					N/A		TUL HS GS SOFT TOP		+		
000000-00798035		Inspect tyres for damage							N/A	Inspection	TUL HS GS SOFT TOP				
000000-00800820		Ignition Switch Missing	Closed	Fully Fit	No	Level 1		09 Apr 2014	N/A	Inspection	TUL HS GS SOFT TOP	***************************************	-		
000000-00800826		Front Shock Turrets Corroded & Shocks U/S			No	Level 1			N/A	Inspection	TUL HS GS SOFT TOP				4
000000-00800829		Panhard Rod Bolt Worn				Level 1			N/A		TUL HS GS SOFT TOP				1
000000-00800828		Rear Linkarm & Radius arm Bushes Worn/Split				Level 1			N/A		TUL HS GS SOFT TOP				-
000000-0080082E 000000-00800830		Steering Damper Bushes Split Track Rnd Bent				Level 1			N/A	Inspection	TUL HS GS SOFT TOP				
000000-00800830		Front Prop & U/J Excessive Play				Level 1 Level 1			N/A N/A		TUL HS GS SOFT TOP				
000000-00800835		Soft Footwells Holed				Level 1			N/A	Inspection	TUL HS GS SOFT TOP	·			
000000-00800836		O/5 Door Checkstrap Bracket Broken				Level 1			N/A	Inspection	TUL HS GS SOFT TOP				
000000-00800839		Dash Clocks Insecure				Level 1			N/A		TUL HS GS SOFT TOP				
000000-00800838		Front Number Plate Damaged				Level 1					TUL HS GS SOFT TOP	1	1		
000000-0080083D		Exhaust Tailpipe Has Been Slash-cut (Sharp Edges)				Level 1			N/A	Inspection	TUL HS GS SOFT TOP				
000000-00800842		Fuel Flexi Rubber Filler Neck Split				Level 1			N/A	Inspection	TUL HS GS SOFT TOP				
000000-00800847		Rearview Mirror Missing				Level 1			N/A	Inspection	TUL HS GS SOFT TOP				1
000000-0080084C 000000-00800852		Orivers Seat Frame Fixings Damaged				Level 1			N/A	Inspection	TUL HS GS SOFT TOP				-
000000-00800852		Stowage Brackets On Bonnet Missing GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09		Fully Fit Non-Taskworthy		Level 1			N/A	Inspection	TUL HS GS SOFT TOP		ļ		
000000-00798012 000000-00094C13	<del> </del>	GOUDTEAN GOD TYPES Manufactured in South Africa cracking file Ref OSVP/64/40/04/09  [6 MTHLY SERVICE]		Non-Taskworthy Non-Taskworthy		Level 1		23 Jun 2013 17 Oct 2007	N/A	Fallure	TUL HS GS SOFT TOP				
000000-0008CD51		Initial Usage				Level 1		25 Sep 2007			TUL HS GS SOFT TOP		-		-
000000-0008CD87		Initial Maintenance				Level 1		25 Sep 2007			TUL HS GS SOFT TOP	<b></b>	†		
															1