

Defence Equipment and Support Secretariat #2043 Maple 0a Ministry of Defence Abbey Wood Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

Our Reference: FOI2022/04636 Date: 22 April 2022

Dear

I am writing about your emails of 3 April and 8 April 2022, requesting the following information:

'I have recently purchased an ex-military Land Rover Defender TUM. I have checked the released MERLIN database and the vehicle service history is not contained in the available published MERLIN extract. I would like to submit a FOi request for the following information:

1) Vehicle military service history (Units served etc, as contained in MERLIN) 2) Any Maintenance Records I Work I Faults I Modifications objects related to this vehicle. Vehicle Registration: HH27AA Description: Land Rover 4x4 TUM HS FFR hard top 2.5 L TR Turbo/DSL Manfr: Rover Group LTD Serial No: SALLDBA67TA998855 date into service 31-8-96'

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

Annex A - Transfer History (redacted)

Annex B - Service History

Annex C - Modification History

Annex D - Fault History (redacted)

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the Transfer History (Annex A), relating to classified information, has been redacted in accordance with Sections 26(1) (a) and (b) (Defence) and Section 38(1) (a) and (b) (Health and Safety). Section 26 applies to information that if disclosed would or would likely; prejudice the defence of the British Islands or any colony; and/or the capability, effectiveness or security of the Armed Forces of the Crown or any forces cooperating with them. Section 38 applies to information that if disclosed would or would likely; endanger the physical or mental health of any individual; or endanger the safety of any individual.

In addition, commercially sensitive information in the Fault History (Annex D) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As these exemptions are qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, releasing some of the Transfer History (Annex A) would divulge information that could be used to compromise the ability of UK Armed Forces to carry out operations safely; by revealing information about vehicle modifications which could assist adversaries to plan attacks against equipment and endanger the lives of personnel. The Fault History (Annex D) provides details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
	000000000744	ND5000400	1. VOA (0.00 D.L.NA	TRUCK UTY MED (TUM) (HS) 4X4 FFR HARD TOP LAND	Army/NATO
HH27AA	2320998939744	NB50203100	LV2A/088DUM	ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
02/09/1996	SALLDBA67TA998855	15L01223A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
HH27AA	3	01/09/1996	CA005A	JSCS ASHCHURCH	CAPITA	20645AA	02/09/1996	***************************************
HH27AA	4	18/08/2000	A0606A	3 PARA	287	12	18/05/2000	H/T
HH27AA	4	20/03/2001	A0829A	101LOGX	187	1218	24/05/2001	S19
HH27AA	4	11/05/2006	A3858A	3 MEDICAL REGIMENT	3	2661	01/06/2006	X27
HH27AA	2	30/12/2012	A1246W	4LOGSP-QM-FTX RLS	999	999	30/12/2012	
HH27AA		21/03/2013		12 LOG SP SQN 6 CS SQN			21/03/2013	
HH27AA		18/02/2014		EQUIPMENT POOL			18/02/2014	
HH27AA		03/04/2014		SEF (UK) ASHCHURCH			08/05/2014	
HH27AA		02/05/2018		215 SIG SQN			03/05/2018	
HH27AA		11/05/2018		21 SIG REGT			11/05/2018	

erial Number:	HH27AA					1					
ISN:	2E+12							-11.1.111111111111111111111111111111111			
		WIRATAANIAA			***************************************				11-1-11-11-11-11-11-11-11-11-11-11-11-1		
Criteria:											
Repair Level:	ALL				\ <u></u>	-	İ		***************************************		
Work Object Status:	Closed			·						<u> </u>	
Mission Impact:	ALL					-				 	
	ALL				ļ		ļ				
	ALL				}					-	
Work Request ID:	ALL				<u> </u>						
Assigned Work Status:	ALL			·	-		·····			·	
Working Organisation:	ALL.			_	-						
	ļ				}						
Repair Section:					}						
A. I. I		.1	A 4							CD 1 C	İ.,
	·	***************************************	Maintenance Event Name			v Fault Stat	e work Stat		working	Repair Sec	tion
000000-001107A9	No		6 Monthly/10000 Kms	03-Jan-20				000:00		ļ	
000000-0022DB86	No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	02-Jan-25		Fully Fit	LL	000:00		ļ	
000000-001107A8	No		Yearly/20000 Kms	04-Jan-20			ļ	000:00		-	ļ
000000-00202A53	No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	02-Jan-25		<u> </u>		000:00		ļ	
000000-00942CE2	No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	03-Jan-21			ļ	000:00			
000000-0011067C	No		5 Yearly/100000 Kms (1)		Level 1			000:00		ļ	
000000-001106A3	No		6 Yearly/120000 Kms (2)		Level 2			000:00			
000000-001BB68F	No		6 Monthly/10000 Kms	03-Jan-20		-		000;000		ļ	
000000-001BB9B2	No		Yearly/20000 Kms	04-Jan-20		<u> </u>		000:00			
000000-001BB68E	No		Yearly/20000 Kms	04-Jan-20		ļ		000:00		1	
000000-0011061D	No		6 Monthly/10000 Kms	03-Jan-20				000:00			
000000-0024EB52	No		6 Monthly/10000 Kms	03-Jan-20	Level 1			00:00			
000000-00163D50	No		6 Monthly/10000 Kms	03-Jan-20	Level 1			00:00			
000000-00942CE1	No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	02-Jan-25	Level 2			00:00			
000000-00942CE3	No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	03-Jan-24	Level 2			00:00			
000000-0022DB9E	No		6 Monthly/10000 Kms	03-Jan-20	Level 1	Fully Fit	CL	000:00			
000000-00143849	No		5 Yearly/100000 Kms (1)		Level 1			000:00			
000000-001BB9B3	No		6 Monthly/10000 Kms	03-Jan-20	Level 1			000:00	·	-	
000000-000150F7	No		Yearly/20000 Kms	04-Jan-20	Level 1		CL	000:00			
000000-00015144	No		2 Yearly/40000 Kms	03-Jan-21	Level 1		CL	000:00	A		!
000000-00013E3B	No		6 Monthly/10000 Kms	03-Jan-20	d,		V-100115-0-0-1	000:00			
000000-00102DB2	No		6 Monthly/10000 Kms	03-Jan-20				000:00		ļ	
000000-0004D67E	No		First 1600 Kms (AR)		Level 2			000:00			
000000-0004D67F	No		Weekly (AR)(1)		Level 1	-	CL	000:00		-	
000000-00102EF2	No		Yearly/20000 Kms	04-Jan-20		-	CL	00:00			
000000-0004D7D3	No		First 1600 Kms (AR)	U 7 3011 E	Level 2			000:00			
000000-0004D7D4	No		Weekly (AR)(1)	-	Level 1	1	CL	000:00			
000000-0004D7D4	No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	03-Jan-21		-	CL	000:00		-	
000000-00202A33	No		6 Monthly/10000 Kms	03-Jan-20				000:00			
Andrew Control of the				03-Jan-20		-	I THE RESERVE TO A PROPERTY OF THE PARTY OF			ļ	
000000-00942CE4	No		6 Monthly/10000 Kms	Section 1111 and the second section 1111	·		ļ	000:00	ļ	ļ	
000000-00942CE6	No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	03-Jan-21		N :		000:00		 	ļ
000000-009B194F	No		6 Monthly/10000 Kms	03-Jan-20		Non-Task		000:00		ļ	
000000-00942CE7	No		Yearly/20000 Kms	04-Jan-20				000:00		-	
000000-0024EB51	No		Yearly/20000 Kms	04-Jan-20		-		00:00		ļ	<u> </u>
000000-00942CE0	No		2 Yearly/40000 Kms	03-Jan-21		-	ļ	00:00		}	
000000-00202A5A	No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	03-Jan-21	riamanana			000:00		<u> </u>	
000000-00202A3C	No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	03-Jan-24	riginera morana a consecuenta a	4	ļ	00:00			
000000-00202A3D	No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	03-Jan-24	* f-n-r			00:00		ļ	
000000-00942CE5	No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	03-Jan-24				00:00		-	
000000-001105D9	No		2 Yearly/40000 Kms	03-Jan-21				000:00			
000000-001BB9B1	No		2 Yearly/40000 Kms	03-Jan-21	Level 1	1		00:00	lancona del como	1]
	1		·	1	1	1				1	j

Work Objects				1			1							
										***************************************				~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Serial Number:	HH27AA	7/10/10/10/10/10/10/10/10/10/10/10/10/10/			***	***************************************								
NSN:	2.32E+1	2		T	***************************************									
		777 Indiana 1995												The second secon
Criteria:				1									1	
Repair Level:	ALL	PPOINTILLE AND AND AND AND AND AND AND AND AND AND				(
Work Object Status:	Closed													
Mission Impact:	ALL													
Fault State:	ALL													1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Escalate Work:	ALL													
Work Request ID:										1		Î		
Assigned Work Status:	ALL													
Working Organisation:		A STATE OF THE STA												
Repair Section:													i	
		7 (19 (19 (19 (19 (19 (19 (19 (19 (19 (19												27 27 20 2 20 20 20 20 20 20 20 20 20 20 20 2
		Magazina da angan mangan											1	
Modification Event ID	Modifica	tic Modification Description	Work Red	q Escalate	W Producti	oı Modifica	ti Apply Wh	Embody b L	Jsage Cot	Fault State W	ork Stat Re	oair Lev W	orking C Rep	air Sec Estimated Repair Time
000000- 0069427A	4	6 FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Tasky CL	. Lev	rel 2		000:00
000000-0000F8F9	3	8 Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit CL	. Lev	el 1		
000000-0000E292	3	7 Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit CL	. Lev	el 1		
000000-00012C9C	2	0 8 Metre Mast Mount Installation Kit		No	-/-	UTI				Fully Fit CL	. Lev	el 1		
000000-00024869	3	5 Fitting of Emergency Hammer	1	No	1/A	UTI				Non-Tasky CL	. Lev	ei 2		
000000-0001FD04	3	3 Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit CL	. Le	rel 2		Committee of the Commit
000000-00009E18		4 Fiitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit CL				
000000-00018E03		2 Roof Mounted Communication Installation (Blanking Plate Only)		No	-/	RTI				Fully Fit CL				
000000-0000CE5D	1	4 Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit CL	-			
000000-00016C0B		3 Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit CL				
000000-00010AFB	3	1 Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants		No	-/-	UTI				Fully Fit CL				
000000-0000EF2F	1	8 Fitting of Front Windscreen and Side and Rear Window Protection Screens		No	-/-	UTI	1			Fully Fit CL		11.1.1111.aux1s11.00cm		Post II I I donat
000000-00012482	2	5 Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Fully Fit CL			1	of contract of the contract of
000000-00011910	2	9 Spare Wheel Adaptor Plates; Left and Right Hand Installation	1	No	-/-	UTI				Fully Fit CL				
000000-00020777	2	7 Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit CL				
000000-00012AFA	2	4 Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit CL				
000000-000237CC	1	9 Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit CL				}
000000-0002407F	3	0 Front Belt Protection Sleeves		No	1/A	UTI				Fully Fit CL				
000000-0000FEDD	3	2 Project SHOEHORN Revised Weight Data Plate		No	-/	UTI				Fully Fit CL				
000000-00018E66	1	7 Introduction of Battery Retention		No	1/A	UTI				Fully Fit CL				
000000-00021D97		6 Radio Battery Isolation Switch and Power Import / Export System		No	-/	RTI]			Fully Fit Cl				
000000-0001FB5E	_ 1	2 Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI			-,,,	Fully Fit Cl				
000000-0000AEFB		1 Radio Rack Fixings		No	-/	RTI				Fully Fit CL				
000000-0000B71E		8 Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit Cl				3100-1000-201-201-201-201-201-201-201-201
000000-0000B5B1		7 TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit CL				
000000-00022878		6 Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit CL				
000000-000160E0	2	8 FITTING OF REAR ANTI-ROLL BAR (RARB)		No	-/	UTI				Fully Fit CL				
			T	1										
					-									

				·							epinananian on an	prostructoral set source a	
Work Objects			-		<u> </u>	<u> </u>			-				
											<u> </u>		-
erial Nun HH27AA						ļ							
ISN: 2.32E+12	2		_		<u> </u>	<u> </u>					ļ	, ,	-
				;	<u>.i</u>						ļ.		
Criteria:				<u> </u>		1			<u> </u>				
Repair Lev ALL				1						1			1
Work ObjeClosed									7				
Mission In ALL		LOCAL PROPERTY OF THE PARTY OF	111 2.2				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
ault State ALL		~		1						1			
scalate WALL						·			· †	ļ			
Vork Request ID:						·	***************************************		·	 	·	ļ	
		-	-	<u> </u>									
Assigned VALL				·	<u> </u>					ļ			-
Norking Organisatio	on:										-		
Repair Section:				damentana	.,								
ault ID Work Req	Fault Description	Work Sta	t Fault Stat	Escalate \	A Repair Le	v Batch Faul F	ault Occurrence Dat	e Mission I	n Reason Fo	Level 3 D	Working C	Repair Se	edEstimated Rep
000000-00BB62FA	Asbestos Decontamination Cleaning Required	Closed	Limited R	c No	Level 1		09-Jun-	20 N/A	Ban	TUM HS	FR HARD T	OP	
A00185-24BB4006	CARRY OUT THEATRE ENTRY EXAMINATION	Closed	Non-Task	No	Level 2		01-Aug-	18 N/A	Inspection	TUM HS	FR HARD T	OP	
000000-00AB3915	FIRE EXTINGUISHER OUT OF DATE	Closed	Non-Task	No	Level 1		16-May-		Inchection	TIIM HS	FR HARD T	np	
			Fully Fit		Level 2		18-May-						
000000-00AB39A7	CARRY OUT RECEIPT INSPECTION	Closed			. ģ. 1 s - m. 1 m. 1	200000 00					FR HARD T		
000000-00843600	Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	000000-00	na-Oct-	14 Degrade	inspection	I FOIN HS	רת חאאט וי	UP	
	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post												
000000-00A43A4C	embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Fully Fit	No	Level 2	000000-00	31-Jul-	17 N/A	Inspection	TUM HS	FR HARD T	OP	
000000-0095EEF4	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Task	vNo	Level 2	000000-00	14-Jan-	16 N/A	Closed No	TUM HS	FR HARD T	OP	
00000-006F74D7	RENEW FRONT BRAKE DISK GUARD LOWER BRACKETS	Closed	Fully Fit		Level 2		15-Feb-				FR HARD T		
000000-006F74E2	RENEW BKT FOR BRAKE LINE AT SWIVEL HOUSING R/H	Closed		No	Level 2		15-Feb-				FR HARD T		
000000-005F74E2	INVESTIGATE OIL LEAK AT FRONT DIFF	Closed	Fully Fit	No	Level 2		11-Jan-			-[FR HARD T		
			ARI		representation and the second					de un mercum nee			
	BONNET STAY RETAINING CLIP U/S	Closed		No	Level 2		26-Apr-				FR HARD T		-
000000-007835B6	BONNET SAFETY CATCH INCORRECTLY SECURED	Closed		No	Level 2		26-Apr-				FR HARD T		
000000-00797D5D	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000-00	24-Jun-		Failure	TUM HS	FR HARD T	OP	
000000-0079AD98	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00	25-Jun-	13 N/A	inspection	TUM HS	FR HARD T	OP	
00000-006F74CE	RENEW REAR DOOR LOCK	Closed	Fully Fit	No	Level 2		15-Feb-	12 N/A	Closed No	TUM HS	FR HARD T	OP	
000000-007611CD	PLEASE CARRYOUT DISPOSAL INSPECTION	Closed	Fully Fit	No	Level 2		28-Jan-	13 N/A	Inspection	TUM HS	FR HARD T	OP	
000000-006E62C4	REQUIRES MOD 20 (8M MAST MOUNT)	Closed		No	Level 2		12-Dec-				FR HARD T		-
000000-000202C4	RENEW PANHARD ROD	Closed	Non-Task		Level 2		05-Mar-				FR HARD T		
						-ii-							
000000-0077015A	RECTIFY RH SEAT RAILS NOT LOCKING OUT	Closed	Non-Task	-0.0	Level 2		05-Mar-				FR HARD T		
000000-0077017B	BOOT SPLIT AT LH TRACK ROD END	Closed	Non-Task	rijem i somo me somo m	Level 2		05-Mar-				FR HARD T		
000000-00770167	BALL JOINT GAITER SPLIT AT WISHBONE	Closed	Non-Task	v No	Level 2		05-Mar-	13 N/A	Inspection	nTUM HS I	FR HARD T	OP	
000000-00761860	CARRY OUT YEARLY SERVICING	Closed	Fully Fit	No	Level 1		28-Jan-	13 N/A	Servicing	TUM HS I	FR HARD T	OP	
000000-00761865	CARRY OUT YEARLY SERVICING	Closed	Fully Fit	No	Level 2		28-Jan-	13 N/A			FR HARD T		
000000-0076186E	CARRY OUT MEI	Closed	Fully Fit	No	Level 2	1	28-Jan-				FR HARD T		
000000-00757E19	BONNET CATCH BENT	Closed	Fully Fit	No	Level 2		13-Dec-				FR HARD T		
					-0.								
	INVESTIGATE OIL LEAK AT BELL HOUSING	Closed	Fully Fit		Level 2		10-Jan-				FR HARD T		
	CCARRY OUT 6 YEARLY OOPM	Closed	Non-Task		Level 2		14-Jun-				FR HARD T		
000000-0074D813	CARRY OUT 6M SERVICE L2	Closed	Non-Task	v No	Level 2		12-Nov-	12 N/A	Servicing	TUM HS	FR HARD T	OP	
00000-0074D830	CARRY OUT OOPM 6YRLY CAMBELT TABLE 5 SERIAL 6	Closed	Non-Task	No	Level 2		12-Nov-	12 N/A	Servicing	TUM HS I	FR HARD T	OP	
000000-0074D800	CARRY OUT 6534 L1 INSPECTION	Closed	Non-Task	No	Level 1		12-Nov-	12 N/A	Inspectio	nTUM HS I	FR HARD T	OP	
000000-0074D80E	CARRY OUT 6M SERVICNG L1	Closed	Non-Task		Level 1		12-Nov-				FR HARD T		
000000-007426C4	CARRY OUT MEI	Closed	Non-Task		Level 2		16-Oct-				FR HARD T		han.
000000-007436C3	CARRY OUT 12 MONTHLY L1 AND L2 SERVICE	Closed	Non-Task		Level 2		16-Oct-				FR HARD T		
000000-006F74F4	REPAINT FRONT NUMBER PLATE	Closed	Fully Fit		Level 1		16-Feb-				FR HARD T		wite
00000-0071ED66	CHECK REMUS 1 MODIFICATION HAS BEEN CARRIED OUT	Closed	Fully Fit		Level 2		20-Jun-				FR HARD T		
00000-006F74F9	REPAINT BOTH FRONT WINGS	Closed	Fully Fit		Level 1		16-Feb-				FR HARD T		
00000-006E03B2	CARRY OUT L1 MAINT IAW AESP 2320-D-128-601 6th ED AMEND No.0 TABLE 7 COLUMN C	Closed	Non-Task	No	Level 1		23-Nov-	11 N/A	Inspectio	TUM HS	FR HARD T	OP	
000000-00000000-0	CCARRY OUT L2 MAINT IAW AESP 2320-D-128-601 6th ED AMEND No.0 TABLE 7 COLUMN C	Closed	Non-Task	No	Level 2		01-Feb-	12 N/A	Inspection	TUM HS	FR HARD T	OP	
	DICFAILED MEI RE CLASSIFY WITHIN 28 DAYS OR RETEST	Closed	Non-Task	No.	Level 2		12-Dec-	11 N/A	Inspectio	TUM HS	FR HARD T	ΩP	*****
	OCCARRY OUT MEI AFG 932 (B) INSPECTION IAW 2300-A-050-013	Closed	Non-Task		Level 2	T	23-Nov-				FR HARD T		mark f
		Closed	Non-Task	-0	Level 2		23-Nov-				FR HARD T		
	DCOIL LEAK ON SIDE OF ENGINE					<u> </u>							
#1#11%	DOVRS DOOR RUBBER SEAL DAMAGED	Closed	Fully Fit		Level 2	<u> </u>		11 N/A			FR HARD T		
	DERADIO BATTERY BOX ALARM INOP	Closed	Limited R		Level 1			11 N/A			FR HARD T		
0-000000-0000000-0	DC PASSENGER WINDOW LOCK INOP	Closed	Fully Fit	No	Level 2	<u> </u>		11 N/A	Failure	TUM HS	FR HARD T	OP	
00000-0000000-0	DEFIT REAR DOOR BLACKOUT MOD	Closed	Fully Fit	No	Level 2		10-Jan-	11 N/A	Servicing	TUM HS	FR HARD T	OP	
	REPLACE DIESO INFO PLATE	Closed	Fully Fit	No	Level 1			11 N/A			FR HARD T		
00000-006E62B8	fit missing gearstick knob	Closed	Fully Fit	No	Level 1		12-Dec-				FR HARD T		
00000-006B7794	DVRS SIDE LIGHT GUARD CLIP BROKE	Closed	Fully Fit	No	Level 1			11 N/A			FFR HARD T		
000000-006B778A	BATTERY TERMINAL COVERS MISSING	Closed	Fully Fit	No	Level 1	4		11 N/A			FFR HARD T		
	PASSENGER SIDE BINS MISSING SEALS	Closed	Fully Fit	No	Level 1	<u> </u>	02-Jun-				FR HARD T		
		Closed	Non-Task	n No	Level 1		23-Jan-	12 N/A	Failure	TUM HS	FFR HARD T	OP	
000000-006EE831	BATTERIES U/S												
000000-006EE831	FRONT GRILL SNAPPED	Closed	Fully Fit		Level 1		-luL-80	11 N/A	Damage		FFR HARD T		
000000-006080EA 000000-006EE831 000000-006B7796 000000-006E03B5				No			08-Jul- 23-Nov-	C		TUM HS		OP	