



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[Redacted]

Our Reference:
FOI2022/05426
Date:
16 May 2022

Dear [Redacted]

I am writing about your email of 3 May 2022, requesting the following information:

' I am trying to find out more about my Land Rover Wolf. I bought it last year from Witham Specialised Vehicles. I have checked the Merlin registry and it is not on there. I am really enjoying restoring this vehicle and would love to find out more about it.

The original registration was PL23AA

**The chassis number is SALLDBA 67WA153741
And on the key FOB it says 20WG OPTASS MT.'**

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

- Annex A - Transfer History
- Annex B - Inspection History
- Annex C - Service History
- Annex D - Modification History (redacted)
- Annex E - Fault History (redacted)

It has proved necessary to withhold some information in accordance with a qualified exemption of the FOI Act. Some of the information in the Modification History (Annex D) and Fault History (Annex E) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, the Modification History and Fault History provides details of the time taken by MOD contractors to rectify fault reports for the vehicle concerned. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
PL23AA	2320998939744	NB50203100	LV2A/088DUM	TRUCK UTY MED (TUM) (HS) 4X4 FFR HARD TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
08/07/1998	SALLDBA67WA153741	25L07359B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
PL23AA	3		CA005A	JSCS ASHCHURCH		36374AA	08/07/1998	
PL23AA	4	23/02/2000	F7111A	JNBCR	50141A	902	06/04/2000	
PL23AA	2	06/10/2011	F6675A	RAF FORCE PROTECTION FORCE HQ	264	32698	11/10/2011	C29
PL23AA		11/06/2013		20 WG OPTAS			11/06/2013	
PL23AA		07/08/2019		7 SQN TPF			13/8/2019	
PL23AA		11/09/2019		20 WG OPTAS			17/09/2019	
PL23AA		15/4/2020		OSVP HOLDINGS			30/04/2020	

Work Objects

Serial Num PL23AA
NSN: 2.32E+12

Criteria:

Repair Lev ALL

Work Obj Closed

Mission In ALL

Fault State ALL

Escalate W ALL

Work Request ID:

Assigned \ ALL

Working Organisation:

Repair Section:

Maintena	Work Req	Escalate W	Maintenance Event Name	Next Due D	Repair Lev	Fault State	Work Stat	Estimated	Working C	Repair Section
000000-00ABE044	No		FMT930 Landworthiness (AR)		Level 1	Limited Rc	CL	000:00		
000000-00ABE025	No		FMT931 Comms (2)*	14-Oct-19	Level 2	Limited Rc	CL	000:00		
000000-007A95A7	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-00979D42	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-009E66AB	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-00ABE028	No		FMT932 (W) Mandatory Equipment Inspection (2)*	14-Apr-20	Level 2	Fully Fit	CL	000:00		
000000-005721A0	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-002AE104	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-001CB90C	No		6 Monthly 6534 Insp		Level 1		WiP	000:00		
000000-003829D3	No		6 Monthly 6534 Insp		Level 1	Non-Task	CL	000:00		
000000-00ABE029	No		FMT933 (W) Role Equipment (2)*	14-Apr-20	Level 2	Fully Fit	CL	000:00		
000000-00AD7F62	No		FMT932 (W) 6 Monthly Safety Inspection (2)	14-Oct-19	Level 2	Fully Fit	CL	000:00		
000000-00028271	No		MEI (2)		Level 2		CL	000:00		
000000-000D97EA	No		First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-000674B4	No		MEI (2)		Level 2		CL	000:00		
000000-001CB90B	No		MEI (2)		Level 2		WiP	000:00		
000000-00AD7F61	No		Annual Headlight Alignment Check (2)	14-May-20	Level 2	Fully Fit	CL	000:00		
000000-0085B7A8	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-0055EEE1	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-002C8D2B	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-00AD7F5F	No		Annual Smoke Emissions Test(2)	14-May-20	Level 2	Fully Fit	CL	000:00		
000000-00B5CDC3	No		Ad Hoc Insp (AR)		Level 1	Fully Fit	CL	000:00		
000000-006CA47E	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-0091CB36	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-006131D0	No		6 Monthly 6534 Insp		Level 1	Non-Task	WiP	000:00		
000000-00AD7F56	No		FMT934 Functional Check (1)*	14-Oct-19	Level 1	Fully Fit	CL	000:00		
000000-00AD7F60	No		Annual Brake Test (2)	14-May-20	Level 2	Fully Fit	CL	000:00		

Work Objects

Serial Num PL23AA
NSN: 2.32E+12

Criteria:
Repair Lev ALL
Work Obj Closed
Mission In ALL
Fault State ALL
Escalate WALL
Work Request ID:
Assigned V ALL
Working Organisation:
Repair Section:

Maintenai	Work Req	Escalate V	Maintenance Event Name	Next Due Date	Repair Lev	Fault State	Work Stat	Estimated	Working C	Repair Section
000000-0055EF09	No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-003D7C6D	No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	13-Apr-24 Level 1	Non-Task	CL	000:00			
000000-0085B7A6	No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-002D062E	No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	09-Oct-19 Level 1		WIP	000:00			
000000-001CB8F0	No		2 Yearly/40000 Kms	09-Oct-19 Level 1		WIP	000:00			
000000-002D05F1	No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	13-Apr-24 Level 1		WIP	000:00			
000000-002D0628	No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	09-Oct-19 Level 1		WIP	000:00			
000000-00572157	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-0091CB33	No		Yearly/20000 Kms	14-Apr-20 Level 1	Fully Fit	CL	000:00			
000000-00ABE02F	No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	13-Apr-24 Level 2	Fully Fit	CL	000:00			
000000-002C8C8E	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Non-Task	CL	000:00			
000000-003D7C52	No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	13-Apr-24 Level 2	Non-Task	CL	000:00			
000000-00572156	No		Yearly/20000 Kms	14-Apr-20 Level 1	Fully Fit	CL	000:00			
000000-002C8C90	No		Yearly/20000 Kms	14-Apr-20 Level 1	Non-Task	CL	000:00			
000000-0093EF95	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-002AE103	No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-002D05EB	No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	06-Feb-23 Level 2		WIP	000:00			
000000-001CB909	No		Yearly/20000 Kms	14-Apr-20 Level 1		WIP	000:00			
000000-006CA480	No		OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	06-Feb-23 Level 2	Fully Fit	CL	000:00			
000000-00ABE03E	No		Yearly/20000 Kms	14-Apr-20 Level 1	Fully Fit	CL	000:00			
000000-00613132	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-000F9E2C	No		6 Yearly/120000 Kms (2)	Level 2	CL	000:00				
000000-0002778E	No		2 Yearly/40000 Kms	09-Oct-19 Level 1	CL	000:00				
000000-0002778F	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	CL	000:00				
000000-00027790	No		Yearly/20000 Kms	14-Apr-20 Level 1	CL	000:00				
000000-00027791	No		Weekly (AR)(1)	Level 1	CL	000:00				
000000-00088D52	No		5 Yearly/100000 Kms (1)	Level 1	CL	000:00				
000000-0002729A	No		Yearly/20000 Kms	14-Apr-20 Level 1	CL	000:00				
000000-0002729B	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	CL	000:00				
000000-000272DB	No		Weekly (AR)(1)	Level 1	CL	000:00				
000000-000F115B	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	CL	000:00				
000000-00026438	No		Weekly (AR)(1)	Level 1	CL	000:00				
000000-000412E9	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	CL	000:00				
000000-000412EA	No		Weekly (AR)(1)	Level 1	CL	000:00				
000000-0004F6EC	No		5 Yearly/100000 Kms (1)	Level 1	CL	000:00				
000000-000D2BFB	No		Yearly/20000 Kms	14-Apr-20 Level 1	CL	000:00				
000000-000688EB	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	CL	000:00				
000000-0055EEF7	No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-002AE102	No		2 Yearly/40000 Kms	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-006CA449	No		Yearly/20000 Kms	14-Apr-20 Level 1	Fully Fit	CL	000:00			
000000-0085B7A2	No		2 Yearly/40000 Kms	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-00896A42	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-002AE0FC	No		OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	09-Oct-19 Level 1	Non-Task	CL	000:00			
000000-0055EEE5	No		2 Yearly/40000 Kms	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-0085B7A7	No		OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	09-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-00AD7E69	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-009E66AF	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-007A9584	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Fully Fit	CL	000:00			
000000-002D065B	No		OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	13-Apr-24 Level 2		WIP	000:00			
000000-001CB90A	No		6 Monthly/10000 Kms	14-Oct-19 Level 1		WIP	000:00			
000000-003829DD	No		6 Monthly/10000 Kms	14-Oct-19 Level 1	Non-Task	CL	000:00			
000000-00ABE043	No		OOPS 5 Yearly Drain/Flush And Replen Cooling System	13-Apr-24 Level 1	Fully Fit	CL	000:00			

Work Objects

Serial Number: PL23AA
 NSN: 2.32E+12
 Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Description	Work Req	Escalate	W	Production	Modifica	App	Em	Us	Fault State	Work Stat	Repair Lev	Re	Estimated Repair Time
000000-0069332E	46 FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS	No	1/A		Mod					Non-Task	CL	Level 2		
000000-006875ED	39 TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME	No	-/-		RTI					Fully Fit	CL	Level 2		
000000-006875E0	24 Fitting of Trailer Breakaway Attachment Plate	No	-/		UTI					Fully Fit	CL	Level 2		
000000-006390D3	42 Fitting a swing away spare wheel carrier, the installation of a spare wheel lifting aid, and the fitting of a rear step.	No	1/A		Mod			##		Fully Fit	CL	Level 2		
000000-00015AC3	6 Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/		RTI					Fully Fit	CL			
000000-00022F42	33 Rear Door Blackout Blind (FFR Variants) Only	No	-/-		UTI					Fully Fit	CL			
000000-00011E07	27 Input/Output Porthole for Communication Cables, Cover Modification	No	-/		UTI					Fully Fit	CL			
000000-00018F18	17 Introduction of Battery Retention	No	1/A		UTI					Fully Fit	CL			
000000-0001A080	19 Blackout Cover for Warning Light Panel	No	-/-		UTI					Fully Fit	CL			
000000-00014A7B	29 Spare Wheel Adaptor Plates; Left and Right Hand Installation	No	-/-		UTI					Fully Fit	CL			
000000-00012538	25 Fitting of Spare Wheel Lifting Aid Harness	No	1/A		UTI					Fully Fit	CL			
000000-00010D07	30 Front Belt Protection Sleeves	No	1/A		UTI					Fully Fit	CL			
000000-0000FF20	32 Project SHOEHORN Revised Weight Data Plate	No	-/		UTI					Fully Fit	CL			
000000-0000D9B1	35 Fitting of Emergency Hammer	No	1/A		UTI					Fully Fit	CL			
000000-00024EB7	38 Fitting of a New Import/Export Box Mount Bracket	No	-/-		UTI					Fully Fit	CL			
000000-000215DF	37 Fitting Glow Plug Timer Interface Harness	No	-/		UTI					Fully Fit	CL			
000000-00012DA3	20 8 Metre Mast Mount Installation Kit	No	-/-		UTI					Fully Fit	CL			
000000-00014B7F	3 Heli-lift Vehicle Modification (Hard Top Only)	No	-/		RTI					Fully Fit	CL			
000000-00018A58	12 Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit	No	1/A		RTI					Fully Fit	CL			
000000-0001E97C	16 Radio Battery Isolation Switch and Power Import / Export System	No	-/		RTI					Fully Fit	CL			
000000-0000B630	8 Input / Output Porthole for Comms / Power Cable Installation	No	-/		RTI					Fully Fit	CL			
000000-0000ABFF	7 TUAAM Earth Bonding Improvements	No	-/		RTI					Fully Fit	CL			
000000-00008BBE	2 Roof Mounted Communication Installation (Blanking Plate Only)	No	-/		RTI					Fully Fit	CL			
000000-00022A34	1 Radio Rack Fixings	No	-/		RTI					Fully Fit	CL			
000000-00003968	28 FITTING OF REAR ANTI-ROLL BAR (RARB)	No	-/		UTI					Fully Fit	CL			

Work Objects

Serial Number: PL23AA
 NSN: 2.32E+12

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Req	Fault Description	Work Stat	Fault S	Esc	Repair Lev	Ba	Fau	Miss	Rea	Lev	Wor	Repair Section	Estimated Repair Time
000000-00B1FE84		SNvE 377 - SWIVEL HOUSING	Closed	Fully Fi	No Level 1	00	##	N/A	Ins	TUM	HS	FFR	HARD TOP	
000000-00B22A86		SNvE377 - SWIVEL HOUSING	Closed	Fully Fi	No Level 1	00	##	N/A	Ins	TUM	HS	FFR	HARD TOP	
000000-00AEFADB		Replace Clutch Slave cyl	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-00AEB27		CLUTCH U/S	Closed	Non-Tz	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-00AA0CED		FAILED SMOKE TEST	Closed	Non-Tz	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-00A41EFE		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Fully Fi	No Level 2	00	##	N/A	Ins	TUM	HS	FFR	HARD TOP	
000000-00842C35		Towing Pintle Assembly	Closed	Fully Fi	No Level 2	00	##	Degr	Ins	TUM	HS	FFR	HARD TOP	
000000-00962CAC		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Fully Fi	No Level 2	00	##	N/A	Ins	TUM	HS	FFR	HARD TOP	
000000-0095C3E8		ELEC SERVICE	Closed	Fully Fi	No Level 2	##	N/A	Serv	TUM	HS	FFR	HARD TOP		
000000-008C7532		FUEL LEAK	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-008C752D		ADJUST HANDBRAKE	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-008C7528		POWER STEERING OIL LEAK	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-008C7525		REAR TOP SHOCK ABSORBER BUSH	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-008C7521		DOOR CHECK BRACKET	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-008C751C		VISCOUE FAN COUPLING	Closed	Fully Fi	No Level 2	##	N/A	Fail	TUM	HS	FFR	HARD TOP		
000000-00835FDA		SERVICING	Closed	Fully Fi	No Level 2	##	N/A	Serv	TUM	HS	FFR	HARD TOP		
000000-007EBB08		CLUTCH PEDAL FAILURE	Closed	Non-Tz	No Level 2	##	N/A	Clos	TUM	HS	FFR	HARD TOP		
000000-007975C9		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Tz	No Level 1	00	##	N/A	Fail	TUM	HS	FFR	HARD TOP	
000000-0079A62F		Inspect tyres for damage	Closed	Fully Fi	No Level 2	00	##	N/A	Ins	TUM	HS	FFR	HARD TOP	
000000-006AF044		Insp Steering Drop Arm Tab Washer	Closed	Fully Fi	No Level 2	00	##	N/A	Ins	TUM	HS	FFR	HARD TOP	
000000-005A0DBD	000000-0C	REMEI OVER THE 28 DAYS	Closed	Non-Tz	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-0057018B	000000-0C	windscreen wipers stay on when switched off	Closed	Non-Tz	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-004E23A5	000000-0C	REFIT SPARE WHEEL MOD	Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		
000000-004E23A4	000000-0C	REPAINT FUEL CAP YELLOW	Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		
000000-0057019A	000000-0C	RENEW REAR DOOR EARTHING STRAP	Closed	Fully Fi	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-005692AB	000000-0C	CARRY OUT MEI	Closed	Fully Fi	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-005692A6	000000-0C	CARRY OUT12 MONTHLY VMS	Closed	Fully Fi	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-005692A1	000000-0C	CARRY OUT12 MONTHLY SERVICE	Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		
000000-005095AB	000000-0C	TIGHTENING L/H/R SUSPENSION	Closed	Fully Fi	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-005095A1	000000-0C	OIL LEAK FROM ROCKER COVER	Closed	Fully Fi	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-004E0DA0	000000-0C		6534 Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		
000000-004E0D94	000000-0C	6 MONTHLY VM	Closed	Fully Fi	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-004E0D93	000000-0C	6 MONTHLY SERVICE	Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		
000000-004C6291	000000-0C	RENEW EXHAUST	Closed	Non-Tz	No Level 2	##			TUM	HS	FFR	HARD TOP		
000000-004084AA		Initial Maintenance	Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		
000000-0040849E		Initial Usage	Closed	Fully Fi	No Level 1	##			TUM	HS	FFR	HARD TOP		