## Recommendation Status Report: Track worker struck by a train near Surbiton station, south-west London

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of the recommendation(s), as reported to us, are described by the following categories:

## **Key to Recommendation Status**

Open (replaces Progressing and Implementation On-going)	Actions to address the recommendation are ongoing.
Closed (replaces Implemented, Implemented by alternative means, and Non- implementation)	ORR consider the recommendation to have been taken into consideration by an end implementer and evidence provided to show action taken or justification for no action taken.
Insufficient response:	The end implementer has not provided sufficient evidence that the recommendation has been taken into consideration, or if it has, the action proposed does not address the recommendation, or there is insufficient evidence to support no action being taken.
Superseded:	The recommendation has been superseded either by a newer recommendation or actions have subsequently been taken by the end implementer that have superseded the recommendation.
Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.

RAIB concern over the way that an organisation has responded to a recommendation are indicated by one of the following:

Red – RAIB has concerns that no actions have been taken in response to a recommendation.

Blue – RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

White – RAIB notes substantive actions have been reported, but the RAIB still has concerns.

## **Recommendation Status Report**



Report Title	Track worker struck by a train near Surbiton station, south-west London		
Report Number	05/2022		
Date of Incident	09/02/2021		

Rec No.	Status	RAIB Concern	Recommendation	RAIB Summary of current status
05/2022/01	Closed - I	None	The intent of this recommendation is to prevent accidents and near misses due to staff working on or near the line moving beyond safe working limits.	ORR has reported that Network Rail has reported that it has completed actions taken in response to this
			Network Rail should review whether safe systems of work in which staff are working on or near the line, and where some or all lines remain open to traffic, incorporate adequate risk controls so that members of the work group remain within the designated safe limits. The review should consider including the role of appropriate technology and whether having members of the work group undertaking multiple tasks could compromise risk controls. Network Rail should implement any necessary changes identified in accordance with a timebound plan (paragraph 139a, 139b)	recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.
			and 140).	
05/2022/02	Open	None	The intent of this recommendation is to support and improve the judgement of train drivers as to whether track workers are in close proximity to their train, and reinforce the necessary action to take if there is a possibility that track workers are likely to be struck.	ORR has reported that RDG has a proposed action plan and timescale for delivery to be taken in response to the recommendation. ORR will advise
			The Rail Delivery Group, with the support of RSSB, should identify the issues drivers face in judging the proximity of track workers to the swept path of their train. They should develop training and briefing materials to better prepare drivers to make accurate judgements as to when track workers are at risk of being struck and to react appropriately, for example by sounding the urgent warning. The Rail Delivery Group should share the resulting training and briefing material with transport undertakings (paragraph 139b).	when the status of this recommendation changes.

## **Recommendation Status Report**



05/2022/03	Closed - I	None	The intent of this recommendation is for Network Rail to understand the	ORR has reported that Network
			reasons underlying the non-compliances identified during this	Rail has reported that it has
			investigation and learn from them.	completed actions taken in
				response to this
			Network Rail should review working practices at Woking track section to	recommendation. ORR proposes
			understand the extent and nature of any non-compliances relating to safe	to take no further action unless
			systems of work and their related rules, procedures, and behaviours. This	they become aware that the
			review should seek to understand the underlying reasons behind any non-	information provided becomes
			compliances identified and if they may apply more widely to other track	inaccurate.
			sections. Network Rail should take actions to address any issues identified	
			by this review (paragraph 141)	