

## **Product Safety Report**

| Images   Details  |                              |   |  |
|---|------------------------------|---|--|
| Images  Alert Number  Product Type  Product Identifiers  ASIN: B09DG9CPY5  Product Description  Country of Origin  Countrefeit  No  Risk Type  Electric Shock  Risk Level  The product presents a serious risk of electric shock due to the transformer of the charger being of a poor internal build quality with insufficient creepage and clearnces. As a result, over time the internal components may disoldge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety)  Regulations 1994.  The product has been destroyed at the border.  Online Marketplace  Amazon – The listing has been removed by the online marketplace.  | Mimajor 12.6V Cordless Drill |   |  |
| Alert Number 2210-0084  Product Type Machinery – Cordless Drill  Product Identifiers AsiN: B09DG9CPY5  Product Description Cordless rechargeable battery drill, including a charger and accessories in a carry case.  Country of Origin China  Counterfeit No  Risk Type Electric Shock  Risk Level Serious  The product presents a serious risk of electric shock due to the transformer of the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety) Regulations 1994.  Corrective Measures  Online Marketplace  Amazon – The listing has been removed by the online marketplace.  | Aspect                       | Details   |  |
| Product Type  | Images                       | Actor charges<br>Actor |  |
| Product Identifiers  Barcode: X001H5YLUP ASIN: B09DG9CPY5  Product Description  Country of Origin  Counterfeit  Risk Type  Risk Level  Risk Level  Risk Description  Risk Type  Risk Description  Counterfeit  Risk Type  Risk Type  Risk Description  Risk Type  Risk Level  Risk Type  Risk |                              | 2210-0084   |  |
| ASIN: B09DG9CPY5  |                              | Machinery – Cordless Drill  |  |
| Country of Origin  Counterfeit  Risk Type  Electric Shock  Risk Level  Serious  The product presents a serious risk of electric shock due to the transformer of the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety) Regulations 1994.  Corrective Measures  Online Marketplace  Amazon – The listing has been removed by the online marketplace.   |                              |   |  |
| Counterfeit No  Risk Type Electric Shock  Risk Level Serious  The product presents a serious risk of electric shock due to the transformer of the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety) Regulations 1994.  Corrective Measures  Online Marketplace  Amazon – The listing has been removed by the online marketplace.   |                              | 1   |  |
| Risk Level         Serious           Risk Level         The product presents a serious risk of electric shock due to the transformer of the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety) Regulations 1994.           Corrective Measures         The product has been destroyed at the border.           Online Marketplace         Amazon – The listing has been removed by the online marketplace.  |                              | China   |  |
| Risk Level  Risk Description  | Counterfeit                  | No  |  |
| The product presents a serious risk of electric shock due to the transformer of the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety) Regulations 1994.  Corrective Measures  Online Marketplace  Amazon – The listing has been removed by the online marketplace.   | Risk Type                    | Electric Shock  |  |
| the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety) Regulations 1994.  Corrective Measures  Online Marketplace  Amazon – The listing has been removed by the online marketplace.   | Risk Level                   | Serious   |  |
| Measures  Online Marketplace  Amazon – The listing has been removed by the online marketplace.  | _                            | the charger being of a poor internal build quality with insufficient creepage and clearances. As a result, over time the internal components may dislodge and move, allowing the product to short circuit. The plug also does not meet the dimensional requirements of the relevant standard, BS 1363, meaning the user may touch the live parts when plugging in, or unplugging, the plug from a socket. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 or the Plugs & Sockets (Safety)  |  |
| Marketplace Amazon – The listing has been removed by the online marketplace.  |                              | The product has been destroyed at the border.   |  |
| Notifier Local Authority Trading Standards  |                              | Amazon – The listing has been removed by the online marketplace.  |  |
|   | Notifier                     | Local Authority Trading Standards   |  |

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <a href="https://www.gov.uk/guidance/product-recalls-and-alerts">https://www.gov.uk/guidance/product-recalls-and-alerts</a>