

Product Safety Report

Images Alert Number Product Type Product Identifiers Product Description Infrared heater with grey labelling and green buttons, supplied in brown cardboard packaging. PUHUI-branded. Country of China	PUHUI Infrared Heater T-962	
Alert Number Product Type Electrical appliances and equipment – Infrared Heater Product Identifiers Product Identifiers Product Infrared heater with grey labelling and green buttons, supplied in brown cardboard packaging. PUHUI-branded. Country of Origin Counterfeit Unknown Electric Shock Risk Level High The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Online Marketplace N/A	Aspect	Details
Product Type Product Identifiers Product Identifiers Product Infrared heater with grey labelling and green buttons, supplied in brown cardboard packaging. PUHUI-branded. Country of Origin Counterfeit Unknown Risk Type Electric Shock Risk Level High The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures N/A	Images	in lange lan
Product Identifiers Product Infrared heater with grey labelling and green buttons, supplied in brown cardboard packaging. PUHUI-branded. Country of Origin Counterfeit Risk Type Electric Shock Risk Level Risk Bescription Risk Counterfeit Risk Counterfeit Counterfeit The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures N/A		2205-0335
Infrared heater with grey labelling and green buttons, supplied in brown cardboard packaging. PUHUI-branded. Country of Origin China	Product Type	Electrical appliances and equipment – Infrared Heater
Country of Origin China Counterfeit Unknown Risk Type Electric Shock Risk Level The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures N/A		SKU: CTSHLHJT-962SJK01V2 (Includes CTSLHJT-962ASJK1V2)
Counterfeit Unknown Risk Type Electric Shock Risk Level High The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Online Marketplace		
Risk Type	Country of Origin	China
Risk Level High The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Online Marketplace	Counterfeit	Unknown
The product presents a high risk of electric shock as it is inadequately earthed. The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Online Marketplace	Risk Type	Electric Shock
The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Online Marketplace N/A	Risk Level	High
Measures The product has been destroyed at the border. Online Marketplace N/A		The product can become live, exposing the user to an electric shock hazard should they touch accessible parts. The product's plug was also noncompliant with the relevant standard, with pins closer to the periphery than permissible and sleeved parts dimensions differing from metal parts of the pins, creating a damage between the two and causing damage to the socket. The product's fuse was also noncompliant. The product also requires improvements to markings, labelling and instructions. The product does not meet the requirements of the Electrical Equipment
Marketplace N/A		The product has been destroyed at the border.
Notifier Local Authority Trading Standards		N/A
	Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts