

Product Safety Report

Alert Number Product Type Electrical appliances and equipment – Regulated DC Power Supply	Skytoppower Regulated DC Power Supply	
Alert Number 2206-0193 Product Type Electrical appliances and equipment – Regulated DC Power Supply Product Identifiers Regulated DC power supply box supplied with black supply lead, black and red cables and instruction manual packaged in brown cardboard box. Country of Origin China Counterfeit No Risk Type Electric Shock Risk Level High The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Online Marketplace Amazon – The listing has been removed by the online marketplace.	Aspect	Details
Product Type	Images	SINTOPPOWER NUCLOUS RECORDS OF FORM OF THE STATE OF THE
Product Identifiers Product Barcode: X000CCUJPD Regulated DC power supply box supplied with black supply lead, black and red cables and instruction manual packaged in brown cardboard box. Country of Origin Counterfeit No Risk Type Electric Shock Risk Level High The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Manazon – The listing has been removed by the online marketplace.		2206-0193
Product Description Regulated DC power supply box supplied with black supply lead, black and red cables and instruction manual packaged in brown cardboard box. Country of Origin Counterfeit Risk Type Electric Shock Risk Level High The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Marketplace Amazon – The listing has been removed by the online marketplace.		Electrical appliances and equipment – Regulated DC Power Supply
Country of Origin Counterfeit Risk Type Risk Level Risk Description Corrective Measures Online Marketplace Country of Origin China The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures Contact the distributor you purchased from to request redress. China Amazon – The listing has been removed by the online marketplace.	Product Identifiers	
Counterfeit No Risk Type Electric Shock Risk Level High The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures We recommend owners stop using this product immediately. Contact the distributor you purchased from to request redress. Online Marketplace Amazon – The listing has been removed by the online marketplace.		
Risk Level High The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures We recommend owners stop using this product immediately. Contact the distributor you purchased from to request redress. Online Marketplace Amazon – The listing has been removed by the online marketplace.	•	China
Risk Level Risk Description Risk Description	Counterfeit	No
The product presents a high risk of electric shock as the item was not adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. Corrective Measures We recommend owners stop using this product immediately. Contact the distributor you purchased from to request redress. Online Marketplace Amazon – The listing has been removed by the online marketplace.	Risk Type	Electric Shock
Amazon – The listing has been removed by the online marketplace adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016. We recommend owners stop using this product immediately. Contact the distributor you purchased from to request redress. Online Marketplace Amazon – The listing has been removed by the online marketplace.	Risk Level	High
Measures distributor you purchased from to request redress. Online Marketplace Amazon – The listing has been removed by the online marketplace.		adequately earthed and there was no secondary security fitted to the earth terminals to prevent from accidental loosening. This could lead to the product becoming live under fault conditions, exposing the user to an electric shock hazard. The product does not meet the requirements of the Electrical Equipment
Marketplace Amazon – The listing has been removed by the online marketplace.		i e i
Notifier Local Authority Trading Standards		Amazon – The listing has been removed by the online marketplace.
	Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts