October 2022



# Air Quality and Dust Monitoring Monthly Report - October 2022

West Northamptonshire District Council



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

### **Monthly Summary**

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken in the West Northamptonshire District Council (WNDC) during October 2022.
- 1.1.2 Figures 1 and 2 in Appendix A present the current worksites together with the dust monitoring locations for October 2022.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from <a href="www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2">www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2</a>, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites as presented in Appendix A, Figures 1 and 2, include:

#### Twyford to Greatworth

#### Radstone and Hall Farm:

- Topsoil stripping
- Bulk excavation Cutting
- Stockpile management
- Site Access Road maintenance
- Compound maintenance
- Drainage, temporary ponds
- Utilisation of haulage road for moving material

#### **Greatworth Hall:**

- Topsoil stripping
- Bulk excavation Cutting
- Stockpile management
- Site Access Road maintenance
- Drainage and temporary ponds
- Construction of landscape bunds (Brackley north Cutting)
- Utilisation of haulage road for moving material
- Compound maintenance

#### G2S

#### <u>Chipping warden – Ramac:</u>

- Topsoil stripping
- Chipping Warden green tunnel excavation
- Stockpile management
- Site Access Road maintenance
- Chipping Warden batching plant
- Compound maintenance
- Vegetation maintenance
- Utilisation of haulage road for moving material
- Appletree lane utility diversionA361 temporary overbridge installation works

#### CW Village:

- A361 temporary overbridge
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Stockpile management
- Vegetation maintenance
- Site Access Road maintenance
- Compound maintenance

#### <u>Lower Boddington:</u>

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Vegetation maintenance
- Highfurlong brook pilling works
- Bulk excavation cutting

#### Fir tree nursery:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Vegetation maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds

#### **Greatworth Village:**

- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds

#### **Lower Thorpe:**


- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Lower Thorpe pilling works


#### Blackgrounds:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- 1.1.5 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from the dust monitors presented in Figure 3. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.6 The trigger level for  $PM_{10}$  concentrations of 190 µg/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018) has been applied.
- 1.1.7 Ten (10) dust monitors are installed at worksites, where works are underway. These sites returned a medium dust risk rating.
- 1.1.8 Data capture was below 90% for multiple monitors due to a battery fault and technical issues.
- 1.1.9 There were no (0) dust trigger alerts recorded during the monitoring period (October 2022).
- 1.1.10 No (0) complaints were recorded during the reporting period.

## **Appendix A - Monitoring Locations**

Figures 1 and 2: Worksite and Monitoring locations within the WNDC





## **Appendix B - Dust Monitoring Results**

Table 1: Dust monitoring locations and October 2022 Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (μg/m³)	Minimum 1- hour PM <sub>10</sub> concentration (μg/m³)	Maximum 1- hour PM <sub>10</sub> concentration (μg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m³	1-hour data capture (%)
Chipping Warden – RAMAC	449600, 249755	Chipping Warden, West Northamptonshire	М	Yes	Yes	6.2	1.0	35.0	0	97.8
CW Village	450000, 249367	Chipping Warden, West Northamptonshire	М	Yes	Yes	6.4	1.0	36.0	0	99.7
Lower Boddington	447997, 251865	Lower Boddington, West Northamptonshire	М	Yes	Yes	6.3	1.0	42.0	0	99.5
Fir Tree Nursery	447283, 252421	Fire Tree Nursery, West Northamptonshire	М	Yes	Yes	6.2	1.0	36.0	0	83.1
Radstone	458712, 240454	Radstone Road, Brackley, West Northamptonshire	М	Yes	Yes	7.2	1.0	38.0	0	30.4
Hall Farm	458734, 239823	Hall Farm, Radstone Road	М	Yes	Yes	6.9	1.0	40.0	0	88.6
Greatworth Village	455551, 242992	Greatworth Village, Helmdon Road,	М	Yes	Yes	6.4	1.0	36.0	0	99.7
Lower Thorpe	453553, 245334	Banbury Lane, Lower Thorpe	М	Yes	Yes	6.3	1.0	36.0	0	99.5
Greatworth Hall	456179, 242763	Greatworth Hall, Greatworth	М	Yes	Yes	6.2	1.0	38.0	0	99.9
Blackgrounds	450846, 248413	Blackgrounds, West Northamptonshire	М	Yes	Yes	5.9	1.0	35.0	0	96.9

Figure 3: Continuous dust 1-hour mean indicative PM<sub>10</sub> concentration for all dust monitors

