



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

---



Our Reference:  
FOI2022/07037  
Date:  
5 July 2022

---

Dear [REDACTED],

I am writing about your email of 10 June 2022, requesting the following information:

**'I'm writing to request at your convenience for any held history on my defender wolf TUM that you may still have such as any deployments and service maintenance records that it had when in service with you .**

**ERM number HM83AA chassis number is SALLDBA67VA104604'**

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and it is confirmed that some information is held on your vehicle that can be released. This is enclosed, as follows:

- Annex A – HM83AA Vehicle History
- Annex B – Fault History (REDACTED)
- Annex C – Inspection History
- Annex D – Modifications History
- Annex E – Service History

It has proved necessary to withhold some information related to your request. This is commercially sensitive information in the Fault History (Annex B) relating to contractor repair times, which has been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As this exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

The Fault History provides details of the time taken by MOD contractors to rectify fault reports on HM83AA. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail [CIO-FOI-IR@mod.gov.uk](mailto:CIO-FOI-IR@mod.gov.uk)). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Secretariat

**VEHICLE DETAILS**

<b>ERM</b>	<b>NATO Stock Number</b>	<b>Asset Code</b>	<b>Contract Number</b>	<b>Description</b>	<b>Colour</b>
<b>(a)</b>	<b>(b)</b>	<b>(c)</b>	<b>(d)</b>	<b>(e)</b>	<b>(f)</b>
HM83AA	2320999086914	NB50203170	LV2A/088DUM	TRUCK UTY MED (HS) 4X4 FFR HARD TOP LAND ROVER 2.5LTR TURBO DSL W/EEGR BOWMAN SH	Army/NATO Green IRR

<b>Date In Service</b>	<b>Chassis Number</b>	<b>Engine No.</b>	<b>Cast</b>	<b>Cast Date</b>
<b>(g)</b>	<b>(h)</b>	<b>(i)</b>	<b>(j)</b>	<b>(k)</b>
22/03/1997	SALLDBA67VA104604	25L00293A		

**VEHICLE HISTORY**

<b>ERM</b>	<b>Key No.</b>	<b>RIV Date</b>	<b>UIN</b>	<b>Unit Title</b>	<b>RIV No.</b>	<b>RCP No.</b>	<b>RCP Date</b>	<b>Batch</b>
<b>(a)</b>	<b>(b)</b>	<b>(c)</b>	<b>(d)</b>	<b>(e)</b>	<b>(f)</b>	<b>(g)</b>	<b>(h)</b>	<b>(i)</b>
HM83AA	3	21/03/1997	CA005A	JSCS ASHCHURCH	CAPITA	25073AA	22/03/1997	
HM83AA	4	08/05/1997	A1249A	RDG	29967A	1203	20/05/1997	
HM83AA	4	03/12/1999	A1259A	2 PWRR	999	999	03/12/1999	R31
HM83AA	4	29/02/2000	A2454A	KINGS ROYAL HUSSARS (ARMD REGT)	6	177	15/03/2000	R31
HM83AA	4	28/11/2008	A0580A	2 MERC	94735	17	03/02/2009	Z89
HM83AA	2	13/02/2009	A3313A	LTF(W)	18	39	13/02/2009	Z90
HM83AA		22/05/2019		OSVP HOLDINGS			28/05/2019	

Work Objects

Serial Number: HM83AA  
 NSN: 2320998939744

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00ACB02B		MEI - CREW - TIGHTEN LOOSE LH WING MIRROR L	Closed	Fully Fit	No	Level 1		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00ACB031		MEI - CREW - Front LH headlight guard missing	Closed	Fully Fit	No	Level 1		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AF10BA		VM - Replace ignition barrel	Closed	Limited Role	No	Level 2		06 Nov 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00ACB022		MEI - CREW - Remove rear LH tyre valve extension tube	Closed	Limited Role	No	Level 1		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00ACB038		MEI - VM - Oil seepage at cyclonic breather	Closed	Limited Role	No	Level 2		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00ACB041		MEI - VM - Oil seepage at hose from engine to oil cooler	Closed	Limited Role	No	Level 2		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00ACB062		MEI - VM - Rectify vehicle wobbles when driven over 50mph	Closed	Fully Fit	No	Level 2		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00ACB059		MEI - VM - Front RH indicator light inop.	Closed	Fully Fit	No	Level 2		19 Jul 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AB5BCF		VM - Replace Panhard Rod	Closed	Fully Fit	No	Level 2		24 May 2018	N/A	Damage	TUM HS FFR HARD TOP			000:00
000000-00AB6291		Carry out in-inspection	Closed	Fully Fit	No	Level 2		21 May 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A9A2B7		front anti roll bar bushes us	Closed	Non-Taskworthy	No	Level 2		06 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A9A2B0		no.3 & no 4 ball joints us	Closed	Non-Taskworthy	No	Level 2		02 Mar 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A9835D		Replace A frame balljoint	Closed	Non-Taskworthy	No	Level 2		27 Feb 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A9835F		Investigate why interior fan is not working	Closed	Non-Taskworthy	No	Level 2		27 Feb 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A5D01E		Fan cowlng insecure.	Closed	Non-Taskworthy	No	Level 2		28 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A5D022		Tow hook requires greasing.	Closed	Fully Fit	No	Level 1		28 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A5D015		Renew vehicle batteries.	Closed	Fully Fit	No	Level 1		28 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A45724		RL_LAD_RENEW WATER PUMP	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A45722		RL_LAD_REAR SHOCK ABSORBERS	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A45715		RL_LAD_RENEW PASSENGER SEAT BELT	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A4571E		RL_LAD_INV LEAK @ BELL HOUSING	Closed	Fully Fit	No	Level 2		01 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A45729		RL_LAD_INVESTIGATE POOR CLUTCH OPERATION	Closed	Non-Taskworthy	No	Level 2		01 Aug 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00991059		BDSG FOR SERVICE AND INSPECTION	Closed	Non-Taskworthy	No	Level 2		11 May 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-009615C1		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003207	19 Jan 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00842687		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUM HS FFR HARD TOP			
000000-0079A11B		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP			
000000-007970A0		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUM HS FFR HARD TOP			
000000-000B9B11		RENEW SA 80 STOWAGE PADS.	Closed	Fully Fit	No	Level 1		17 Jan 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-000B9B51		RENEW BOWMAN CABLE ACCESS COVERS. REAR	Closed	Fully Fit	No	Level 1		17 Jan 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-0015135C		FIT MISSING TERMINAL COVERS	Closed	Fully Fit	No	Level 1		23 Apr 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-001A47B8		RENEW ALL DOOR LOCKS	Closed	Fully Fit	No	Level 1		04 Jun 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-001A47B8		REPLACE AIR INLET BOLT	Closed	Fully Fit	No	Level 1		04 Jun 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-001EDBAA		REPLACE REAR VIEW MIRROR	Closed	Fully Fit	No	Level 1		01 Jul 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-001FC123		REPLACE PADDING ON PASSENGER SIDE OF DASH	Closed	Fully Fit	No	Level 1		08 Jul 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-002138D7		REPLACE BONNET STAY STOWAGE CLIP	Closed	Fully Fit	No	Level 1		17 Jul 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-0021394F		REPLACE RH JERRYCAN BIN DOOR SEALS	Closed	Fully Fit	No	Level 1		17 Jul 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-00213965		SECURE LHR CAM POLE HOLDER	Closed	Fully Fit	No	Level 1		17 Jul 2008	N/A	Failure	TUM HS FFR HARD TOP			
000000-006B562C		Replace Component	Closed	Fully Fit	No	Level 1		06 Jul 2011	N/A	Modification	TUM HS FFR HARD TOP			
000000-006AE74C		Insp Steering Drop Arm Tab Washer	Closed	Fully Fit	No	Level 2	000000-000002BD	22 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP			
000000-003B4C3D		Insufficient Data	Closed	Non-Taskworthy	No	Level 1		02 Feb 2009			TUM HS FFR HARD TOP			
000000-000B9B56	000000-0027DE94	REPLACE PASSENGER DOOR SEALS	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-0015135E	000000-0027A7DD	FIT COVER TO PASSENGER SEAT BELT FEMALE CLIP	Closed	Fully Fit	No	Level 1		23 Apr 2008			TUM HS FFR HARD TOP			
000000-001EDBAE	000000-0027DE94	REPLACE REAR DOOR LOWER HINGE/STOP ASSY	Closed	Fully Fit	No	Level 1		01 Jul 2008			TUM HS FFR HARD TOP			
000000-0021392A	000000-0027E759	REPLACE PASSENGER DOOR EARTHING STRAP	Closed	Fully Fit	No	Level 1		17 Jul 2008			TUM HS FFR HARD TOP			
000000-001A47B9	000000-0027C5AB	RENEW HEAD LIGHT GUARD CLIPS	Closed	Fully Fit	No	Level 1		04 Jun 2008			TUM HS FFR HARD TOP			
000000-001FC111	000000-0027DE94	REPLACE PASSENGE DOOR HANDLE/LATCH ASSY	Closed	Fully Fit	No	Level 1		08 Jul 2008			TUM HS FFR HARD TOP			
000000-002138DA	000000-0027E759	FIT SPARE TYRE INFLATION MOD	Closed	Fully Fit	No	Level 1		17 Jul 2008			TUM HS FFR HARD TOP			
000000-003483BF	000000-0028624A	INVESTIGATE COOLENT CONTAMINATED	Closed	Non-Taskworthy	No	Level 2		04 Dec 2008			TUM HS FFR HARD TOP			
000000-003483E5	000000-0028624A	ENGINE U/S	Closed	Non-Taskworthy	No	Level 2		04 Dec 2008			TUM HS FFR HARD TOP			
000000-0033DAF2	000000-002859CD	SUSPECTED ENGINE SEIZED	Closed	Non-Taskworthy	No	Level 2		27 Nov 2008			TUM HS FFR HARD TOP			
000000-002F8414	000000-002854DB	RENEWING TIMING BELT	Closed	Non-Taskworthy	No	Level 2		06 Nov 2008			TUM HS FFR HARD TOP			
000000-001FC10F	000000-0027DE94	REPLACE DVRS DOOR HANDLE ASSY	Closed	Fully Fit	No	Level 1		08 Jul 2008			TUM HS FFR HARD TOP			
000000-0021398D	000000-0027E759	SECURE L/H/R CAM POLE HOLDER	Closed	Fully Fit	No	Level 1		17 Jul 2008			TUM HS FFR HARD TOP			
000000-0021399F	000000-0027E759	STEAM CLEAN UNDERSIDE OF VEHICLE	Closed	Fully Fit	No	Level 1		17 Jul 2008			TUM HS FFR HARD TOP			
000000-001EDBAB	000000-0027DE94	REPLACE ASH TRAY	Closed	Fully Fit	No	Level 1		01 Jul 2008			TUM HS FFR HARD TOP			
000000-002C2850		6mthly lvl 2	Closed	Non-Taskworthy	No	Level 2		16 Oct 2008			TUM HS FFR HARD TOP			
000000-002C283C	000000-00282E9A	6 mthly lvl 1	Closed	Non-Taskworthy	No	Level 1		16 Oct 2008			TUM HS FFR HARD TOP			
000000-002A1FD8	000000-0028223B	RENEW OIL SUMP	Closed	Non-Taskworthy	No	Level 2		06 Oct 2008			TUM HS FFR HARD TOP			
000000-0021A6F0	000000-0027EA55	CARRYOUT 2 YEARLY SERVICE LEVEL 1 TASKS	Closed	Non-Taskworthy	No	Level 1		22 Jul 2008			TUM HS FFR HARD TOP			
000000-0021A6F3	000000-0027EA55	CARRYOUT 2 YEARLY SERVICE LEVEL 2 TASKS	Closed	Non-Taskworthy	No	Level 2		22 Jul 2008			TUM HS FFR HARD TOP			
000000-00253DD3		RENEW HEATER CONTROL END	Closed	Fully Fit	No	Level 1		26 Aug 2008			TUM HS FFR HARD TOP			
000000-00253E00		RENEW RH HEADLIGHT BOTTOM BKT	Closed	Fully Fit	No	Level 1		26 Aug 2008			TUM HS FFR HARD TOP			
000000-00253E08		RENEW BUNG LHS OF FUSE BOX	Closed	Fully Fit	No	Level 1		26 Aug 2008			TUM HS FFR HARD TOP			
000000-001FC187	000000-0027DE94	REPLACE REAR DOOR LATCH ASSY	Closed	Fully Fit	No	Level 1		08 Jul 2008			TUM HS FFR HARD TOP			
000000-0021159F		Renew front anti roll bar + bushes	Closed	Non-Taskworthy	No	Level 2		16 Jul 2008			TUM HS FFR HARD TOP			
000000-000B9B46	000000-002702C1	RENEW REAR TOWING CLAMP AND PINS	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9ADE	000000-002702C1	RENEW DVRS DOOR PANEL	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-0015135B	000000-0027A7DD	FIT NEW BATTERY CLAMP	Closed	Fully Fit	No	Level 1		23 Apr 2008			TUM HS FFR HARD TOP			
000000-000CA06E		PUDET IN FOR REPAIR RADIO REPAIR CELL	Closed	Fully Fit	No	Level 1		04 Feb 2008			TUM HS FFR HARD TOP			
000000-00129D1B	000000-00279C0A	CARRY OUT 1 YEARLY SERVICE	Closed	Fully Fit	No	Level 2		07 Apr 2008			TUM HS FFR HARD TOP			
000000-000B9B28	000000-002702C1	REPLACE DIESEL ONLY LABEL ON SIDE BIN	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B3C	000000-002702C1	RENEW REAR DOOR SEALS	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000F3207	000000-00277D4B	INVESTIGATE FLOATING STEERING AT 40MPH + GETS WORSE WITH SPEED	Closed	Non-Taskworthy	No	Level 2		06 Mar 2008			TUM HS FFR HARD TOP			
000000-000B9B60	000000-002702C1	RENEW MAP LIGHT ASSY	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B58	000000-002702C1	SECURE PASSENGER SIDE MIRROR ARM	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B5C	000000-002702C1	SECURE VEHICAL BATTERIES 2 X CLAMP HOOKS	Closed	Non-Taskworthy	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9ADB	000000-002702C1	RENEW HEAD LAMP GRILL AND CLIPS	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9AE9	000000-002702C1	RENEW STEERING WHEEL	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B53	000000-002702C1	STENCIL TPS ABOVE WHEEL ARCHERS	Closed	Fully Fit	No	Level 1		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B68	000000-002702C3	INVESTIGATE REAR DISC AND PADS WORN	Closed	Fully Fit	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B6E2E	000000-0026F7AF	6 MONTHLY LEVEL 2 JOBS	Closed	Non-Taskworthy	No	Level 2		16 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9AF4	000000-002702C3	INV SLOPPY GEAR LEVER MOVEMENT	Closed	Fully Fit	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B09	000000-002702C3	INVESTIGATE H/S/T WARNING LIGHTS ON DRIVERS PANEL INOP	Closed	Fully Fit	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B39	000000-002702C3	RENEW REAR DOOR HANDLE	Closed	Fully Fit	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B70	000000-002702C3	INVESTIGATE REAR LINK ARM BOLTS AND BUSHES BADLY WORN	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B73	000000-002702C3	INVESTIGATE STEERING DAMPER BUSH WORN	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B78	000000-002702C3	INVESTIGATE NO BALL JOINT WORN	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B80	000000-002702C3	INVESTIGATE FRONT LINK ARM BOLTS AND BUSHES FRONT AXEL FOR WEAR	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B84	000000-002702C3	INVESTIGATE ENGINE SUMP GASKET LEAK	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B89	000000-002702C3	INVESTIGATE REAR DIFR REAR SEAL LEAKING	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B9B8D	000000-002702C3	INVESTIGATE FRONT SHOCK ABSORBERS AND BUSHES WORN	Closed	Non-Taskworthy	No	Level 2		17 Jan 2008			TUM HS FFR HARD TOP			
000000-000B6E0A	000000-0026F7AF	6 MONTHLY LEVEL 1 JOBS	Closed	Non-Taskworthy	No	Level 1		16 Jan 2008			TUM HS FFR HARD TOP			
000000-0007B898		RENEW LHR SHOCK ABSORBER BTM B												

Work Objects

Serial Number: HM83AA  
 NSN: 2320998939744

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0016ABBE		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-006C1E28		No	MEI (2)	19 Jul 2019	Level 2			000:00		
000000-006C1E29		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-001AB7C6		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-00873215		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1	Fully Fit	CL	000:00		
000000-0016B8DE		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-003D0B18		No	MEI (2)	19 Jul 2019	Level 2			000:00		
000000-00084112		No	MEI (2)	19 Jul 2019	Level 2		CL	000:00		
000000-0009D705		No	MEI (2)	19 Jul 2019	Level 2		CL	000:00		
000000-0009D564		No	MEI (2)	19 Jul 2019	Level 2		CL	000:00		
000000-0000EF75		No	First Parade Insp (AR)(1)		Level 1		CL	000:00		
000000-00018FEA		No	MEI (2)	19 Jul 2019	Level 2		CL	000:00		
000000-0005A1C0		No	MEI (2)	19 Jul 2019	Level 2		CL	000:00		
000000-0016B8DD		No	MEI (2)	19 Jul 2019	Level 2			000:00		
000000-008565F3		No	MEI (2)	19 Jul 2019	Level 2	Fully Fit	CL	000:00		
000000-0023597C		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-005DAF35		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-009BC3A4		No	MEI (2)	19 Jul 2019	Level 2	Non-Taskworthy	CL	000:00		
000000-0051AA1D		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		
000000-0023597B		No	MEI (2)	19 Jul 2019	Level 2			000:00		
000000-00A060DB		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0092563C		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1	Limited Role	CL	000:00		
000000-0051AA08		No	MEI (2)	19 Jul 2019	Level 2			000:00		
000000-003D0B19		No	6 Monthly 6534 Insp	04 Apr 2019	Level 1			000:00		

## Work Objects

Serial Number: HM83AA  
NSN: 2320998939744

## Criteria:

Repair Level: ALL  
Work Object Status: Closed  
Mission Impact: ALL  
Fault State: ALL  
Escalate Work: ALL  
Work Request ID:  
Assigned Work Status: ALL  
Working Organisation:  
Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0068F845	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS	000000-00330545	No	1/A	Mod				Non-Taskworthy	CL	Level 2		LTF IBES	000:00
000000-0061B473	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit					
000000-0061B467	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061B476	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00018968	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 1			
000000-0061B472	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061B46C	00032	Project SHOEHORN Revised Weight Data Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061B469	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0001EDE4	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL	Level 1			
000000-0061B468	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061B477	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061B475	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0000D18A	00016	Radio Battery Isolation Switch and Power Import / Export System		No	-/	RTI				Fully Fit	CL	Level 1			
000000-0061B466	00019	Blackout Cover for Warning Light Panel		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061B46A	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0000A6E8	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL	Level 1			
000000-00009342	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit	CL				
000000-00008B79	00002	Roof Mounted Communication Installation (Blanking Plate Only)		No	-/	RTI				Fully Fit	CL				
000000-000228FE	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL				
000000-0000DAD8	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL				
000000-00000071	00028	FITTING OF REAR ANTI-ROLL BAR (RARB)		No	-/	UTI				Fully Fit	CL				

Work Objects

Serial Number: HM83AA  
 NSN: 2320998939744

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-006C1E40		No	Weekly (AR)(1)		Level 1			000:00		
000000-00A060ED		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-003D0B09		No	Weekly (AR)(1)		Level 1			000:00		
000000-0051AA11		No	2 Yearly/40000 Kms	05 Sep 2019	Level 1			000:00		
000000-001AB7CF		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-008565CB		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	04 Sep 2019	Level 1	Fully Fit	CL	000:00		
000000-002AD449		No	Weekly (AR)(1)		Level 1			000:00		
000000-0023597F		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	04 Dec 2018	Level 2			000:00		
000000-006C1E3F		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-0051AA13		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	04 Sep 2019	Level 1			000:00		
000000-00301788		No	Weekly (AR)(1)		Level 1			000:00		
000000-0087321E		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1	Fully Fit	CL	000:00		
000000-002C2772		No	Weekly (AR)(1)		Level 1			000:00		
000000-0092562B		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1	Fully Fit	CL	000:00		
000000-00235983		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-00235982		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	04 Sep 2019	Level 1			000:00		
000000-00A060AA		No	Yearly/20000 Kms	03 Oct 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-008565C9		No	2 Yearly/40000 Kms	05 Sep 2019	Level 1	Fully Fit	CL	000:00		
000000-00873222		No	Yearly/20000 Kms	03 Oct 2019	Level 1	Fully Fit	CL	000:00		
000000-006C1E3E		No	Yearly/20000 Kms	03 Oct 2019	Level 1			000:00		
000000-0020EB4E		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	03 Sep 2022	Level 1			000:00		
000000-0018754C		No	5 Yearly/100000 Kms (1)		Level 1			000:00		
000000-005DAF7F		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-008565C6		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	03 Sep 2022	Level 1	Fully Fit	CL	000:00		
000000-003D0B07		No	Yearly/20000 Kms	03 Oct 2019	Level 1			000:00		
000000-001DE7A6		No	Weekly (AR)(1)		Level 1			000:00		
000000-000F3B91		No	Yearly/20000 Kms	03 Oct 2019	Level 1		CL	000:00		
000000-000760B2		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-000BD2CA		No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-00075FDB		No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00		
000000-00076070		No	2 Yearly/40000 Kms	05 Sep 2019	Level 1		CL	000:00		
000000-000E3BC6		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-000818F8		No	Yearly/20000 Kms	03 Oct 2019	Level 1		CL	000:00		
000000-000817EE		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-000F4823		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-000FF327		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-000959E7		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-00095A3C		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-0009594B		No	Yearly/20000 Kms	03 Oct 2019	Level 1		CL	000:00		
000000-000A19D7		No	2 Yearly/40000 Kms	05 Sep 2019	Level 1		CL	000:00		
000000-000EFD5A		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-000B6AEE		No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-0000D366		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-00016F03		No	Yearly/20000 Kms	03 Oct 2019	Level 1		CL	000:00		
000000-000F09DB		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-0003655D		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-00059814		No	2 Yearly/40000 Kms	05 Sep 2019	Level 1		CL	000:00		
000000-00059815		No	Yearly/20000 Kms	03 Oct 2019	Level 1		CL	000:00		
000000-00059816		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1		CL	000:00		
000000-00068370		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-0051AA12		No	Yearly/20000 Kms	03 Oct 2019	Level 1			000:00		
000000-0051AA14		No	Weekly (AR)(1)		Level 1			000:00		
000000-0020EB4D		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	03 Sep 2022	Level 2			000:00		
000000-002C0383		No	Weekly (AR)(1)		Level 1			000:00		
000000-0016B8E5		No	Yearly/20000 Kms	03 Oct 2019	Level 1			000:00		
000000-00235980		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	04 Sep 2019	Level 1			000:00		
000000-008565CA		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	04 Sep 2019	Level 1	Fully Fit	CL	000:00		
000000-008565ED		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	03 Sep 2022	Level 2	Fully Fit	CL	000:00		
000000-0016B8E6		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-00235981		No	Weekly (AR)(1)		Level 1			000:00		
000000-005DAF80		No	Weekly (AR)(1)		Level 1			000:00		
000000-003D0B08		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-0051AA16		No	6 Monthly/10000 Kms	04 Apr 2019	Level 1			000:00		
000000-0023597E		No	2 Yearly/40000 Kms	05 Sep 2019	Level 1			000:00		
000000-0051AA15		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	04 Sep 2019	Level 1			000:00		
000000-00235984		No	Yearly/20000 Kms	03 Oct 2019	Level 1			000:00		