



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:
FOI2023/01292
Date:
07 February 2023

Dear [REDACTED]

I am writing about your email of 31 January 2023, requesting the following information:

I am the new owner of an ex-MoD Land Rover Wolf TUM FFR, with the following details:

*In Service Registration Number: KV15AA
Chassis Number: SALLDBA68VA118151
Engine Number: 25L02065A
EAC/MAC: NB50208100
Date of Manufacture: 27.07.1997
Date in Service: 27.07.1997*

The MERLIN Database has no further information. I am seeking any additional information, to include James history, service history, basing locations, and any accident reports.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex B) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

Defence Equipment & Support

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KV15AA	2320999086916	NB50208180	LV2A/088DUM	TRUCK UTY MED (HS) 4X4 FFR HARD TOP LHD LAND ROVER 2.5LTR TURBO DSL W/EEGR BOWMAN BF LAS	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
30/07/1997	SALLDBA68VA118151	25LO2065		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KV15AA	3	29/07/1997	CA005A	JSCS ASHCHURCH	CAPITA	28091AA	30/07/1997	
KV15AA	4	15/09/1997	A0325B	HQ STORES TP 65 FD PK SQN	33389A	358	21/11/1997	
KV15AA	4	21/11/1997	A0325A	39ENGR-65SQN		358	21/11/1997	
KV15AA	4	11/03/1999	A9038A	UK ENGR REGT LOG SQN	361	0063A33	31/03/1999	
KV15AA	4	27/08/1999	A0325A	39ENGR-65SQN	61	0358A68	06/09/1999	
KV15AA	4	01/04/2001	A9038A	UK ENGR REGT LOG SQN	555	555	01/04/2001	B83
KV15AA	4	25/10/2001	A0325A	39ENGR-65SQN	84	286	25/10/2001	B83
KV15AA	4	05/11/2004	A9107B	RE FD SP SQN CS ENGR REGT	363	1082	05/11/2004	H/T
KV15AA	4	16/04/2005	A0325A	39ENGR-65SQN	216	61127	24/06/2005	H/T
KV15AA	4	11/01/2013	A4406A	3 CS BN REME	999	999	11/01/2013	
KV15AA	4	11/04/2013	CA358A	62 MAT SQN	162	578	22/04/2013	

KV15AA	2	09/06/2013	A5992D	TFSU (G)	3300	5113	11/07/2013	
KV15AA		27/04/2018		6 ACS BN REME			10/05/2018	
KV15AA		15/05/2018		6 ACS BN REME 3 ARMD COY			15/05/2018	
KV15AA		03/02/2019		DK22 LMI BG HICON			03/02/2019	
KV15AA		14/05/2019		RTR			17/06/2019	

Work Objects

Serial Number: KV15AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Work Fault Description	Work Status	Work Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work Closed No Action	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
A00185-25DA6000		FFR BLT SLACK	Closed	Fully Fit	No	Level 2		04 Nov 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
A00101-273D8000		WINDSCREEN WIPERS U/S	Closed	Fully Fit	No	Level 2		02 Mar 2019	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00B23CE9		SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00B2135F		SNvE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			
A00201-25D86001		FFR BELT BELT SLIGHTLY SLACK	Closed	Fully Fit	No	Level 2		03 Nov 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A876DE		Intermittant fault at fuel gauge.	Closed	Fully Fit	No	Level 2		15 Jan 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A8F821		FIT ANTENNA MAST BRACKET	Closed	Fully Fit	No	Level 2		04 Feb 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A575B6		Refit antenna mast bracket	Closed	Fully Fit	No	Level 2		11 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A8902A	000000-0032A5BF	Replace brake fluid.	Closed	Fully Fit	No	Level 2		17 Jan 2018	N/A	Servicing	TUM HS FFR HARD TOP			000:00
000000-00A876DD		Air vents below windscreen not watertight.	Closed	Fully Fit	No	Level 2		15 Jan 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A575B5		MOD 46 outstanding	Closed	Fully Fit	No	Level 1		11 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			000:00
000000-00A5FD2D	000000-0032A5BF	Carry out Improved Air Filtration MOD as per AESP 2320-D-128-421 Inst 4	Closed	Fully Fit	No	Level 2		02 Oct 2017	N/A	Modification	TUM HS FFR HARD TOP			000:00
000000-00A575AF	000000-0032A5BF	Renew bonnet webbing straps x2	Closed	Fully Fit	No	Level 1		10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A575AD	000000-0032A5BF	Renew rear axle A-frame balljoint boot	Closed	Fully Fit	No	Level 2		10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00

000000-00A575AA	000000-0032A5BF	Convoy light inop	Closed	Fully Fit	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A9	000000-0032A5BF	Renew rear brake pads	Closed	Fully Fit	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A8	000000-0032A5BF	Secure front shock absorber bushes	Closed	Fully Fit	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A7	000000-0032A5BF	Fit missing rubber grommets to battery box	Closed	Fully Fit	No	Level 1	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A4	000000-0032A5BF	Fit fuel filler cap diesel only label	Closed	Fully Fit	No	Level 1	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A6	000000-0032A5BF	Renew R/H fog light lens	Closed	Fully Fit	No	Level 1	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A1	000000-0032A5BF	Fit missing spacers to sun visors	Closed	Fully Fit	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575A0	000000-0032A5BF	Renew no 2 steering balljoint	Closed	Non- Taskworthy	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A5759F	000000-0032A5BF	Fit chassis crossmember at g box correctly	Closed	Non- Taskworthy	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575B7	000000-0032A5BF	Fit all brake bleed nipple dust covers	Closed	Fully Fit	No	Level 2	10 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00	
000000-00A575B4		C.E.S. not presented for inspection	Closed	Limited Role	No	Level 1	11 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP		
000000-00A575B2		Bowman system req. checking by operator	Closed	Limited Role	No	Level 1	11 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP		
000000-00A575B1		Fire extinguisher not presented	Closed	Limited Role	No	Level 1	11 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP		
000000-00A42D4A	000000-0032A5BF	CARRY OUT ANNUAL MEI	Closed	Non- Taskworthy	No	Level 2	30 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP		
000000-00A43A46		variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction	Closed	Limited Role	No	Level 2	000000-00004560	31 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-0085A4E5		CARRY OUT ALL NON-TASKWORTHY REPAIR ACTIONS	Closed	Non- Taskworthy	No	Level 2	01 Dec 2014	N/A	Failure	TUM HS FFR HARD TOP		
000000-0085A4E3		CARRY OUT ALL FULLY FIT REPAIR ACTIONS	Closed	Fully Fit	No	Level 2	01 Dec 2014	N/A	Failure	TUM HS FFR HARD TOP		
000000-008B78A1		JAMES ACTIVITY	Closed	Fully Fit	No	Level 2	17 Aug 2015	N/A	Inspection	TUM HS FFR HARD TOP		
000000-00831E27		x2 SEAT TRACK SCREWS MISSING	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Closed No Action	TUM HS FFR HARD TOP		
000000-00831E13		AIR FILTER MOUNTS U/S	Closed	Fully Fit	No	Level 2	27 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP		
000000-00831E1D		L/H BIN SEAL MISSING	Closed	Fully Fit	No	Level 2	27 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP		
000000-007D4A40		MOD 27	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Closed No Action	TUM HS FFR HARD TOP		
J05537-14B08000		Renew Tail light	Closed	Fully Fit	No	Level 2	01 Nov 2014	N/A	Damage	TUM HS FFR HARD TOP		
000000-008435F9		Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	000000-00001F58	09 Oct 2014	Degraded Inspection	TUM HS FFR HARD TOP		

000000-007D4A00	REPLACE MISSING INNER DOOR PANEL RIVETS	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Failure	TUM HS FFR
000000-007D4A2A	ADJUST ENGINE COOLANT FROM -30 TO -37 DEGREES	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Closed No Action	HARD TOP TUM HS FFR
000000-00831E24	RENEW SPARE TYRE	Closed	Limited Role	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-007D4A1E	FRONT LEFT TYRE BELOW 3.0 MM TREAD WEAR DO NOT USE OF ROAD	Closed	Limited Role	No	Level 2	09 Dec 2013	N/A	Failure	HARD TOP TUM HS FFR
000000-007D4A0F	REPLACE SPARE WHEEL TYRE BELOW MIN TREAD WEAR LIMIT	Closed	Limited Role	No	Level 2	09 Dec 2013	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E11	AUX BELT U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E33	CLUTCH SLAVE CYLINDER U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E32	COPPER WASHER MISSING AT ENG SUMP	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E37	L/H RADIOUS ARM REAR BUSH U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E1F	BOTH REAR SHOCKS U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-0083B28E	SHOCK MOUNT U/S	Closed	Non-Taskworthy	No	Level 2	24 Sep 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E36	INVESTIGATE OIL SEAP AT L/H/F STUB AXLE	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Closed No Action	HARD TOP TUM HS FFR
000000-007D4A3D	TIGHTEN UP SWITCHES ON STEERING COLUMN	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Closed No Action	HARD TOP TUM HS FFR
000000-00831E25	TYRE INFLATION MOD BKT NOT FITTED CORRECTLY	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Closed No Action	HARD TOP TUM HS FFR
000000-00831E31	TRACK ROD CLAMP LOOSE	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E3C	CONVOY LIGHT CEASED	Closed	Limited Role	No	Level 2	28 Aug 2014	N/A	Closed No Action	HARD TOP TUM HS FFR
000000-007D49FC	INDICATOR LIGHT COMES ON WHEN NO TRAILER CONNECTED	Closed	Non-Taskworthy	No	Level 2	09 Dec 2013	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E3A	CHECK AND TIGHTEN ALL PROP BOLTS	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E2F	No2,3,4 BALL JOINTS U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E1A	PASS WIPER BLADE U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-007D4A2D	REPLACE BALL JOINT ON DROP ARM	Closed	Non-Taskworthy	No	Level 2	09 Dec 2013	N/A	Failure	HARD TOP TUM HS FFR
000000-007D4A05	REPLACE DRIVER SIDE SEAT COVER	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E21	L/H/R FOG LENSE U/S	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR
000000-00831E2C	VEH BATTERY CLAMP SCREW MISSING	Closed	Non-Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	HARD TOP TUM HS FFR

000000-00831E28	DVR SEATR CUSHION DAMAGED	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-00831E29	FUEL GUAGE BACK LIGHT INOP	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-00831E16	TIGHTEN JUBILEE CLIPS IN ENGINE COMPARTMENT	Closed	Fully Fit	No	Level 2	28 Aug 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00831E10	ALTERNATOR BELT U/S	Closed	Non- Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-00831E0C	BOTTOM STEERING LINKAGE U/J LOOSE	Closed	Non- Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-00831E09	TURBO U/S	Closed	Non- Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-007795AD	Carry out Oil change	Closed	Fully Fit	No	Level 1	25 Mar 2013	N/A	Servicing	TUM HS FFR HARD TOP	
000000-007D4A17	REPLACE BOTTOM COUPLING SHAFT FLEXIBLE (ON STEERING BOX SIDE)	Closed	Non- Taskworthy	No	Level 2	09 Dec 2013	N/A	Failure	TUM HS FFR HARD TOP	
000000-007D4A27	STEAM CLEAN ENGINE	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-007D4A24	STEAM CLEAN UNDER SIDE OF VEHICLE	Closed	Fully Fit	No	Level 2	09 Dec 2013	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00831E0D	ACCELERATOR LINKAGE LOOSE AT F.I.P	Closed	Non- Taskworthy	No	Level 2	28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP	
000000-00831E06	LOCK WASHER MISSING AT STARTER MOTOR LIVE.	Closed	Non- Taskworthy	No	Level 2	28 Aug 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-007D4A09	REPLACE FAULTY FUEL FILLER CAP	Closed	Non- Taskworthy	No	Level 2	09 Dec 2013	N/A	Failure	TUM HS FFR HARD TOP	
000000-007A342A	RENEW SOUTH AFRICA TYRES R/H/F + L/H/R GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non- Taskworthy	No	Level 2	16 Jul 2013	Aborted	Closed No Action	TUM HS FFR HARD TOP	
000000-00797D56	Inspect tyres for damage	Closed	Non- Taskworthy	No	Level 1	000000- 0000081A 23 Jun 2013	N/A	Failure	TUM HS FFR HARD TOP	
000000-0079AD91	LH Steering Ball Joint	Closed	Fully Fit	No	Level 2	000000- 00000835 25 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP	
000000-007628ED	RH Steering Ball Joint	Closed	Non- Taskworthy	No	Level 2	29 Jan 2013	N/A	Failure	TUM HS FFR HARD TOP	
000000-007628B2	LH Anti Roll Ball Joint	Closed	Non- Taskworthy	No	Level 2	29 Jan 2013	N/A	Failure	TUM HS FFR HARD TOP	
000000-007628B1	"NO SMOKING" sign missing in cabin as per JSP800	Closed	Fully Fit	No	Level 1	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-00760466	CARRY OUT MAINT IAW 2320-D-128-601 TABLE 7 COL A 6 MONTHLY	Closed	Fully Fit	No	Level 1	24 Jan 2013	N/A	Servicing	TUM HS FFR HARD TOP	
000000-00760467	CARRY OUT MAINT IAW 2320-D-128-601 TABLE 7 COL A 6 MONTHLY	Closed	Fully Fit	No	Level 2	24 Jan 2013	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-0076046A	PLEASE CARRY OUT 6534 INSPECTION	Closed	Fully Fit	No	Level 1	24 Jan 2013	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-0072D846	Heater lever knop missing	Closed	Fully Fit	No	Level 2	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	000:00

000000-0072D865	Veh.-jack u/s	Closed	Fully Fit	No	Level 1	06 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072E689	recert 933 b after vehicle jack renewed	Closed	Limited Role	No	Level 2	09 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072D84B	Radio battery test buzzer inop	Closed	Fully Fit	No	Level 2	06 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C67AC	Outstanding Mod Instr No 33 (Rear door blackout blind) -PR-	Closed	Fully Fit	No	Level 2	04 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-007477AD	CARRY OUT OOPM SER 3 IAW 2320-D-128-601 TABLE 5	Closed	Fully Fit	No	Level 2	26 Oct 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-0073DDD5	CARRY OUT MAINT IAW 2360-D-128-601 TABLE 5 SER 3 COOLING SYSTEM (5 YEARLY)	Closed	Fully Fit	No	Level 2	27 Sep 2012	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-0073DDD0	CARRY OUT MAINT IAW 2320-D-128-601 TABLE 5 SER 2.1 AND 2.2 5 YEARLY	Closed	Fully Fit	No	Level 1	26 Sep 2012	N/A	Closed No Action	TUM HS FFR HARD TOP	
000000-00747431	CARRY OUT OOPM SER 2.1 IAW 2320-D-128-601 TABLE 5	Closed	Fully Fit	No	Level 1	25 Oct 2012	N/A	Servicing	TUM HS FFR HARD TOP	
000000-00747434	CARRY OUT OOPM SER 2.1 IAW 2320-D-128-601 TABLE 5	Closed	Fully Fit	No	Level 2	25 Oct 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-0074743B	CARRY OUT OOPM SER 3 IAW 2320-D-128-601 TABLE 5	Closed	Fully Fit	No	Level 2	25 Oct 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-007477AB	CARRY OUT OOPM SER 3 IAW 2320-D-128-601 TABLE 5	Closed	Fully Fit	No	Level 1	26 Oct 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-00725CBF	CARRY OUT MAINT IAW 2320-D-128-601 TABLE 7 COL B(12 MONTHLY)	Closed	Fully Fit	No	Level 2	12 Jul 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-00725CBA	CARRY OUT MAINT IAW 2320-D-128-601 TABLE 7 COL B(12 MONTHLY)	Closed	Fully Fit	No	Level 1	12 Jul 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-0072D856	Drivers door key lock inop	Closed	Fully Fit	No	Level 2	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072D84D	Rear door stop inop	Closed	Fully Fit	No	Level 2	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072D86E	To be recertified within 28 days of 932W Inspection date	Closed	Non-Taskworthy	No	Level 2	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072D848	Clean and presserve Veh.-battery box	Closed	Fully Fit	No	Level 1	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072D844	Free play on both rear shock absorber bottem rubber	Closed	Fully Fit	No	Level 2	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006C67B1	Outstanding Mod Instr No 38 (inport / export box mounting bkt) -PR-	Closed	Fully Fit	No	Level 2	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-0072D831	3.3.7.1.1.4 Excessive side movement of the brake pedal	Closed	Non-Taskworthy	No	Level 2	07 Aug 2012	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006FB575	CARRY OUT L1 &L2 MAINT AS PER 2320-D-128-601 TABLE 7 COL A (6 MONTHLY)	Closed	Fully Fit	No	Level 2	29 Feb 2012	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-006C9E16	Free play in alternator pulley bearing	Closed	Fully Fit	No	Level 2	14 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C67A7	Outstanding Mod Instr No 27 (Input / output porthole cover)	Closed	Fully Fit	No	Level 2	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C679A	Free play on brake pedal sleeve	Closed	Fully Fit	No	Level 2	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	

000000-006C6788	Number plate lamp glasses broken	Closed	Fully Fit	No	Level 2	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006C67B5	Outstanding Mod Instr No 39 (TUM (HS) Remus1 safety Mod)	Closed	Fully Fit	No	Level 2	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C678D	Emergency hammer missing	Closed	Fully Fit	No	Level 1	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-006C67A1	CES - Items not shown for M.E.I.	Closed	Limited Role	No	Level 1	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006C9E13	Front & rear brake pads nearing wear limit	Closed	Fully Fit	No	Level 2	14 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	000:00
000000-006BFD93	CARRY OUT L1 OOP MAINTENANCE TASKS AS PER 2320-D-128-601 TABLE 5 SER 4 (AIR CLEANER)	Closed	Fully Fit	No	Level 1	04 Aug 2011	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-006BFD89	AS PER 2320-D-128-601 TABLE 7 COL C & RENEW BRAKE FLUID (24 MONTHLY)	Closed	Fully Fit	No	Level 2	04 Aug 2011	N/A	Servicing	TUM HS FFR HARD TOP	000:00
000000-006C6777	Radio batteries not fitted	Closed	Limited Role	No	Level 1	05 Sep 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005EFA79	Renew fuel leak off pipe	Closed	Fully Fit	No	Level 2	07 Apr 2011	N/A	Failure	TUM HS FFR HARD TOP	000:00
000000-005002BA	R/h/r bumper requires repainting -PR-	Closed	Fully Fit	No	Level 1	04 May 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-006AF8BF	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000002D1 22 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005EFA72	Blanking plate for LH spare wheel mounting diffy	Closed	Fully Fit	No	Level 1	07 Apr 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-004A53A6	Renew driver door seal demand No 8770 -PR-	Closed	Fully Fit	No	Level 1	30 Nov 2009	N/A	Failure	TUM HS FFR HARD TOP	
000000-005EFA60	Fuel leak off pipe @ FIP banjo union	Closed	Non-Taskworthy	No	Level 2	07 Apr 2011	N/A	Failure	TUM HS FFR HARD TOP	
000000-005EFA47	Secure wing mirrors	Closed	Fully Fit	No	Level 1	07 Apr 2011	N/A	Inspection	TUM HS FFR HARD TOP	
000000-005EFA44	Horn inop	Closed	Non-Taskworthy	No	Level 2	07 Apr 2011	N/A	Failure	TUM HS FFR HARD TOP	
000000-005EFA42	Brake lights inop	Closed	Non-Taskworthy	No	Level 2	07 Apr 2011	N/A	Failure	TUM HS FFR HARD TOP	
000000-005EF23F	CARRY OUT L1 AND L2 MAINT AS PER 2320-D-128-601 TAB 7 COL A 6 MTHLY	Closed	Fully Fit	No	Level 2	06 Apr 2011	N/A	Servicing	TUM HS FFR HARD TOP	
000000-005B2E02	CARRY OUT L1 OOPM AS PER 2320-D-128-601 TAB 5 SER 1 (ENG OIL & FILTER)	Closed	Fully Fit	No	Level 1	05 Nov 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004F577B	RENEW REAR DOOR SEAL ON DMD 9859 -PR-	Closed	Fully Fit	No	Level 1	15 Apr 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-004F591D	Fix missing hard top blanking plate	Closed	Fully Fit	No	Level 1	15 Apr 2010	N/A	Failure	TUM HS FFR HARD TOP	
000000-0059FC0A	Clear and rectify faults on JAMES (TUM (HS) Remus 1 safety and compliance programme)	Closed	Fully Fit	No	Level 2	12 Oct 2010			TUM HS FFR HARD TOP	
000000-0059FC34	Outstanding Mod - AESP 2320-D-128-811 No 38	Closed	Fully Fit	No	Level 2	12 Oct 2010			TUM HS FFR HARD TOP	
000000-0059FC01	(Import / export box mounting brackets)	Closed	Fully Fit	No	Level 2	12 Oct 2010			TUM HS FFR HARD TOP	

000000-0059FBF5	000000- 002C9B63	Outstanding Mod - AESP 2320-D-128-811 No 33 (rear door blackout blind)	Closed	Fully Fit	No	Level 2	12 Oct 2010	TUM HS FFR HARD TOP
000000-0059FBE8	000000- 002C9B63	Outstanding Mod - AESP 2320-D-128-811 No 27 (Input / output porthole covers)	Closed	Fully Fit	No	Level 2	12 Oct 2010	TUM HS FFR HARD TOP
000000-0059F2E8	000000- 002C9B63	Secure batts correctly	Closed	Fully Fit	No	Level 1	11 Oct 2010	TUM HS FFR HARD TOP
000000-0059F2E7	000000- 002C9B63	Hazard light switch inop	Closed	Fully Fit	No	Level 1	11 Oct 2010	TUM HS FFR HARD TOP
000000-0059F2E2	000000- 002C9B63	Centralise steering wheel	Closed	Fully Fit	No	Level 2	11 Oct 2010	TUM HS FFR HARD TOP
000000-0059F2DE	000000- 002C9B63	Secure fuse box cover	Closed	Fully Fit	No	Level 1	11 Oct 2010	TUM HS FFR HARD TOP
000000-0059F2DD	000000- 002C9B63	Carry out L1 & L2 maintenance as per AESP 2320- D128-601 table 7 col b	Closed	Fully Fit	No	Level 2	11 Oct 2010	TUM HS FFR HARD TOP
000000-004F48F7	000000- 002B3486	No 2 ball joint rubber boot split -PR-	Closed	Fully Fit	No	Level 2	14 Apr 2010	TUM HS FFR HARD TOP
000000-005002B3	000000- 002B3486	Brake lamps inop (1.3.2a)	Closed	Non- Taskworthy	No	Level 2	04 May 2010	TUM HS FFR HARD TOP
000000-005002A2	000000- 002B3486	L/h headlamp insecure and cannot be adjusted (1.2.4b.)	Closed	Non- Taskworthy	No	Level 2	04 May 2010	TUM HS FFR HARD TOP
000000-004EB332	000000- 002B3486	mod 37	Closed	Fully Fit	No	Level 2	25 Mar 2010	TUM HS FFR HARD TOP
000000-004EB32D	000000- 002B3486	mod 35 (emergency hammer)	Closed	Fully Fit	No	Level 2	25 Mar 2010	TUM HS FFR HARD TOP
000000-004EB329	000000- 002B3486	mod 20 (8m mast)	Closed	Fully Fit	No	Level 2	25 Mar 2010	TUM HS FFR HARD TOP
000000-004FFB35	000000- 002AF290	RTA with civilian interest	Closed	Non- Taskworthy	No	Level 2	03 May 2010	TUM HS FFR HARD TOP
000000-004F48F5	000000- 002AF290	Pass door earth strap u/s	Closed	Fully Fit	No	Level 1	14 Apr 2010	TUM HS FFR HARD TOP
000000-004F48F4	000000- 002AF290	Carry out L1 & L2 maint as per AESP 2320-D-128- 601 table 7 col a	Closed	Fully Fit	No	Level 2	14 Apr 2010	TUM HS FFR HARD TOP
000000-004DE441	000000- 002AAE9D	DOOR LOCKS INOP	Closed	Fully Fit	No	Level 2	09 Mar 2010	TUM HS FFR HARD TOP
000000-004A5399	000000- 002AB4BF	replace rifle clip foam	Closed	Fully Fit	No	Level 1	30 Nov 2009	TUM HS FFR HARD TOP
000000-004A538B	000000- 002AB4BF	renew seat belt mod	Closed	Fully Fit	No	Level 1	30 Nov 2009	TUM HS FFR HARD TOP
000000-004DEA7C	000000- 002AB060	Carry out L2 maint as per AESP 2320-D-128-601 table 5 ser 6	Closed	Fully Fit	No	Level 2	09 Mar 2010	TUM HS FFR HARD TOP
000000-004A5386	000000- 002A080B	repaint fuel cap	Closed	Fully Fit	No	Level 1	30 Nov 2009	TUM HS FFR HARD TOP
000000-004A5370	000000- 002A080B	missing battery terminal covers	Closed	Fully Fit	No	Level 1	30 Nov 2009	TUM HS FFR HARD TOP
000000-004118C1	000000- 0029DEDC	Check for correct fitting of r/h headlamp bulb	Closed	Fully Fit	No	Level 1	08 Apr 2009	TUM HS FFR HARD TOP
000000-003E3EC8	000000- 0029DEDC	renew clutch pedal rubber -PR-	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP

000000-004A539C	Renew driver door seal	Closed	Fully Fit	No	Level 1	30 Nov 2009	TUM HS FFR HARD TOP
000000-004A538E	renew seat belt mod	Closed	Fully Fit	No	Level 1	30 Nov 2009	TUM HS FFR HARD TOP
000000-00411915	000000- 0029DEDC Carry out general instr. No 12 (Stowage bin stickers)	Closed	Fully Fit	No	Level 1	08 Apr 2009	TUM HS FFR HARD TOP
000000-0046CEB2	000000- 00295B70 renew electrical lead ends to sigs battry terminals	Closed	Limited Role	No	Level 2	18 Aug 2009	TUM HS FFR HARD TOP
000000-004868B2	000000- 0029A820 Renew brake light switch	Closed	Non- Taskworthy	No	Level 2	12 Oct 2009	TUM HS FFR HARD TOP
000000-0047E16C	000000- 0029A820 Please carry out service as per 2320-D-128-601 table 7 col C and renew brake fluid	Closed	Fully Fit	No	Level 2	24 Sep 2009	TUM HS FFR HARD TOP
000000-003E3ED8	000000- 0028B737 fit venting tubes to sig batterys -PR-	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP
000000-004118D0	000000- 0028B737 Refit radio battery vent tubing correctly	Closed	Fully Fit	No	Level 1	08 Apr 2009	TUM HS FFR HARD TOP
000000-004118B4	Remove l/h spare wheel mounting tube	Closed	Fully Fit	No	Level 2	08 Apr 2009	TUM HS FFR HARD TOP
000000-00456FDF	replace water pump tensioner pulley	Closed	Non- Taskworthy	No	Level 2	14 Jul 2009	TUM HS FFR HARD TOP
000000-0043EFE0	investigate turbo blowing	Closed	Limited Role	No	Level 2	25 Jun 2009	TUM HS FFR HARD TOP
000000-003E3ED2	000000- 0028B737 renew dvrs bottom seat -PR	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP
000000-003E3EC4	000000- 0028B737 refit seat belt mod -PR	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP
000000-003E3EB8	000000- 0028B737 renew dvr wing mirror -PR-	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP
000000-004118BD	Renew radio battery cable end terminal	Closed	Fully Fit	No	Level 2	08 Apr 2009	TUM HS FFR HARD TOP
000000-004118AF	Reroute hand throtle cable correctly above fuel hose	Closed	Fully Fit	No	Level 2	08 Apr 2009	TUM HS FFR HARD TOP
000000-0041191E	Carry out reclassification by DATE 06.05.09 otherwise rebook for complete Insp.	Closed	Fully Fit	No	Level 1	08 Apr 2009	TUM HS FFR HARD TOP
000000-004118AC	(2.2 1f) Secure steering box universal joint	Closed	Non- Taskworthy	No	Level 2	08 Apr 2009	TUM HS FFR HARD TOP
000000-004118A6	(3.1 6b) Adjust parking brake	Closed	Non- Taskworthy	No	Level 2	08 Apr 2009	TUM HS FFR HARD TOP
000000-00412BE0	000000- 0028B330 Renew brake light switch	Closed	Fully Fit	No	Level 2	14 Apr 2009	TUM HS FFR HARD TOP
000000-003E3EE1	pas side swivel pin housing leaking	Closed	Non- Taskworthy	No	Level 2	18 Mar 2009	TUM HS FFR HARD TOP
000000-003E3EDC	free of front and rear lash down points	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP
000000-003E3ECF	free off heater direction switches	Closed	Fully Fit	No	Level 1	18 Mar 2009	TUM HS FFR HARD TOP
000000-003C8B10	000000- 002871C6 Replace vehicle alternator	Closed	Non- Taskworthy	No	Level 2	05 Feb 2009	TUM HS FFR HARD TOP

000000-0015BA60	000000-00284C15	Renew fuel filler hose (deteriorated)	Closed	Fully Fit	No	Level 2	29 Apr 2008	TUM HS FFR HARD TOP
000000-003B0F10	000000-002788BB	Seat Belts frayed	Closed	Non- Taskworthy	No	Level 2	30 Jan 2009	TUM HS FFR HARD TOP
000000-0015BA88	000000-00276C98	Rect jack inop (1043 action reqd)	Closed	Fully Fit	No	Level 1	29 Apr 2008	TUM HS FFR HARD TOP
000000-0038520B	000000-00276C98	New Seals required for jerry can storage bins	Closed	Fully Fit	No	Level 1	14 Jan 2009	TUM HS FFR HARD TOP
000000-0015BAC4		Carry out cannister stowage compartment sticker gen instr	Closed	Fully Fit	No	Level 1	29 Apr 2008	TUM HS FFR HARD TOP
000000-0029614F		tail lights inop	Closed	Non- Taskworthy	No	Level 2	26 Sep 2008	TUM HS FFR HARD TOP
000000-00296662		replace u/s starter motor	Closed	Non- Taskworthy	No	Level 2	26 Sep 2008	TUM HS FFR HARD TOP
000000-0015BAD7		Rect batteries flat	Closed	Limited Role	No	Level 1	29 Apr 2008	TUM HS FFR HARD TOP
000000-0015BA4B	000000-0027AF25	Adjust handbrake (excessive lever travel)	Closed	Fully Fit	No	Level 2	29 Apr 2008	TUM HS FFR HARD TOP
000000-0015BA75	000000-0027AF25	Renew rear door earthing strap	Closed	Fully Fit	No	Level 2	29 Apr 2008	TUM HS FFR HARD TOP
000000-0015BA24	000000-0027AF25	Carry out emissions test (facilities unavailable)	Closed	Non- Taskworthy	No	Level 2	29 Apr 2008	TUM HS FFR HARD TOP
000000-00092E28		OBSERVE CRANKSHAFT FRONT SEAL LEAKING	Closed	Fully Fit	No	Level 2	11 Oct 2007	TUM HS FFR HARD TOP
000000-00091128	000000-00273371	brake lights inop	Closed	Non- Taskworthy	No	Level 2	09 Oct 2007	TUM HS FFR HARD TOP
000000-00092E14		RENEW BRAKE LIGHT SWITCH	Closed	Non- Taskworthy	No	Level 2	11 Oct 2007	TUM HS FFR HARD TOP
000000-00092E1D		RENEW REAR SHOCK ABSORBERS	Closed	Non- Taskworthy	No	Level 2	11 Oct 2007	TUM HS FFR HARD TOP
000000-00092E21		RENEW STEERING DAMPER	Closed	Non- Taskworthy	No	Level 2	11 Oct 2007	TUM HS FFR HARD TOP
000000-000138B2	000000-0027275D	Carry out Gen intr No 7 (stowage bin stickers)	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138A5	000000-0026BC8F	Carry out Mod No 24 (Trl breakaway plate)	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138A6	000000-0026BC8F	Carry out Mod No 29 (Spare wheel adaptor plate)	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-000659F3		ANNUAL MEI, renew lock barrel on fuel filler cap	Closed	Fully Fit	No	Level 2	30 Apr 2007	TUM HS FFR HARD TOP
000000-0007845B	000000-0027080A	Brake Lights In-op	Closed	Non- Taskworthy	No	Level 2	05 Jul 2007	TUM HS FFR HARD TOP
000000-0001C612	000000-0026E39F	Inspect and repair Power steering pipe	Closed	Fully Fit	No	Level 2	12 Jun 2006	TUM HS FFR HARD TOP
000000-000659F1	000000-0026E39F	ANNUAL MEI, brake lights inop	Closed	Non- Taskworthy	No	Level 2	30 Apr 2007	TUM HS FFR HARD TOP
000000-000659F4	000000-0026E39F	ANNUAL MEI, INV oil leak at power steering box.	Closed	Non- Taskworthy	No	Level 2	30 Apr 2007	TUM HS FFR HARD TOP

000000-0005ACD3	000000-0026D204	Rear lights in-op	Closed	Non-Taskworthy	No	Level 2	20 Mar 2007	TUM HS FFR HARD TOP
000000-0001D276	000000-0026C3D2	INSPECT AND REPAIR WINDOW WIPERS	Closed	Fully Fit	No	Level 2	15 Jun 2006	TUM HS FFR HARD TOP
000000-0004DFB8	000000-0026BA4E	Brake Lights In-Op	Closed	Non-Taskworthy	No	Level 2	12 Feb 2007	TUM HS FFR HARD TOP
000000-00031776	000000-0026DB4B	please carry out 1 yearly vm tasks	Closed	Fully Fit	No	Level 2	vm tasks 04 Oct 2006	TUM HS FFR HARD TOP
000000-0001D270	000000-0026C3D2	STONE CHIP ON LEFT HANDSIDE OF THE WINDSCREEN	Closed	Fully Fit	No	Level 2	15 Jun 2006	TUM HS FFR HARD TOP
000000-00031B2E	000000-0026DBC1	Brake Lights in-op (not fuses or bulbs)	Closed	Non-Taskworthy	No	Level 2	05 Oct 2006	TUM HS FFR HARD TOP
000000-00031B30	000000-0026DBC1	rear shock absorbers lower bushes worn	Closed	Non-Taskworthy	No	Level 2	05 Oct 2006	TUM HS FFR HARD TOP
000000-00031B35	000000-0026DBC1	rear axle radius arm bushes worn	Closed	Non-Taskworthy	No	Level 2	05 Oct 2006	TUM HS FFR HARD TOP
000000-00031B49	000000-0026DBC1	windscreen cracked centre right	Closed	Non-Taskworthy	No	Level 2	05 Oct 2006	TUM HS FFR HARD TOP
000000-00031B4B	000000-0026DBC1	rh tracta seal leaking	Closed	Non-Taskworthy	No	Level 2	05 Oct 2006	TUM HS FFR HARD TOP
000000-00031B4D	000000-0026DBC1	adj handbrake- excessive reverse travel	Closed	Non-Taskworthy	No	Level 2	05 Oct 2006	TUM HS FFR HARD TOP
000000-0000A53A	000000-0026AF51	RECTIFY WIPERS DO NOT RETURN TO PARK	Closed	Fully Fit	No	Level 2	08 Feb 2006	TUM HS FFR HARD TOP
000000-0001E9D8	000000-0026C67E	Engine wont start	Closed	Non-Taskworthy	No	Level 2	27 Jun 2006	TUM HS FFR HARD TOP
000000-0001D252	000000-0026C3D1	NUMBER PLATE REQUIRES PAINTING	Closed	Fully Fit	No	Level 1	15 Jun 2006	TUM HS FFR HARD TOP
000000-0001D262	000000-0026C3D1	REPLACE FRONT TOW PIN	Closed	Fully Fit	No	Level 1	15 Jun 2006	TUM HS FFR HARD TOP
000000-0001D263	000000-0026C3D1	REPLACE FUEL CAP	Closed	Fully Fit	No	Level 1	15 Jun 2006	TUM HS FFR HARD TOP
000000-0001D268	000000-0026C3D1	STENCILS REQUIRED ON ENGINE	Closed	Fully Fit	No	Level 1	15 Jun 2006	TUM HS FFR HARD TOP
000000-000138B0	000000-0026BC8F	Fit diffi key ID tag	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138B3	000000-0026BC8F	932 Fit diffi battery restraint	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138B4	000000-0026BC8F	932 Renew wiper blades	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138AB	000000-0026BC04	932 Renew rear axle shock absorbers (R/H seeping)	Closed	Non-Taskworthy	No	Level 2	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138AC	000000-0026BC04	932 Renew steering damper	Closed	Fully Fit	No	Level 2	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138AD	000000-0026BC04	Correctly fit front R/H brake hose	Closed	Fully Fit	No	Level 2	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138AE	000000-0026BC04	932 Rect oil seepage from base of strg reservoir and associated piping	Closed	Non-Taskworthy	No	Level 2	21 Apr 2006	TUM HS FFR HARD TOP

000000-000138AF	000000-0026BC04	Renew rocker cover breather hose (perished)	Closed	Fully Fit	No	Level 2	21 Apr 2006	TUM HS FFR HARD TOP
000000-000138B1	000000-0026BC04	Rect light warning lamp inop	Closed	Fully Fit	No	Level 2	21 Apr 2006	TUM HS FFR HARD TOP
000000-00014C9E	000000-0026BE88	Please carry out 6 Monthly VM Tasks	Closed	Non- Taskworthy	No	Level 2	08 May 2006	TUM HS FFR HARD TOP
000000-00013901	000000-0026BC8F	932 Present Veh jack for annual examination	Closed	Fully Fit	No	Level 1	21 Apr 2006	TUM HS FFR HARD TOP
000000-00008CE6	000000-0026AD32	Hand Brake not working Fully	Closed	Non- Taskworthy	No	Level 2	27 Jan 2006	TUM HS FFR HARD TOP
000000-0000A1F1	000000-0026AE5E	RECTIFY WIPERS INOP	Closed	Non- Taskworthy	No	Level 2	06 Feb 2006	TUM HS FFR HARD TOP
000000-0000A1F4	000000-0026AE5E	RENEW No 4 INJECTOR COPPER WASHER	Closed	Non- Taskworthy	No	Level 2	06 Feb 2006	TUM HS FFR HARD TOP
000000-00002620		Initial Usage	Closed	Fully Fit	No	Level 1	08 Nov 2005	TUM HS FFR HARD TOP
000000-00002624		Initial Maintenance	Closed	Fully Fit	No	Level 1	08 Nov 2005	TUM HS FFR HARD TOP

Work Objects

Serial Number: KV15AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated		Working Organisation	Repair Section
								Repair Time	Working Organisation		
000000-0045D124		No	MEI (2)	04 Nov 2019	Level 2	Fully Fit	CL	000:00			
000000-00497E9D		No	MEI (2)	04 Nov 2019	Level 2	Non-Taskworthy	CL	000:00			
000000-0098E804		No	6 Monthly 6534 Insp	06 May 2019	Level 1	Fully Fit	CL	000:00			
000000-00443D23		No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00			
000000-0017FEF7		No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00			
000000-0058D977		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-00497EA1		No	6 Monthly 6534 Insp	06 May 2019	Level 1	Non-Taskworthy	CL	000:00			
000000-001FC6E5		No	MEI (2)	04 Nov 2019	Level 2			000:00			
000000-0087DBDD		No	MEI (2)	04 Nov 2019	Level 2	Non-Taskworthy	CL	000:00			
000000-001FC6E6		No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00			

000000-0087DC06	No	6 Monthly 6534 Insp	06 May 2019	Level 1	Taskworthy	CL	000:00
000000-0016365A	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-002420BE	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-00443D24	No	First Parade Insp (AR)(1)		Level 1	Non-		000:00
000000-00892AD4	No	MEI (2)	04 Nov 2019	Level 2	Taskworthy	CL	000:00
000000-000E36B9	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-000D3693	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-000D3A33	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-0007FB43	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-0007FB44	No	First Parade Insp (AR)(1)		Level 1			000:00
000000-000896D5	No	First Parade Insp (AR)(1)		Level 1			000:00
000000-000965A3	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-000487F1	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-00443D22	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-0058D976	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-0017FEF6	No	MEI (2)	04 Nov 2019	Level 2			000:00
A00185-25DA6001	No	6 Monthly 6534 Insp	06 May 2019	Level 1	Fully Fit	CL	000:00
000000-006D517C	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-00245948	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-00163641	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-0090AEF1	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
A00185-25DA6000	No	MEI (2)	04 Nov 2019	Level 2	Fully Fit	CL	000:00
000000-001C114B	No	6 Monthly 6534 Insp	06 May 2019	Level 1			000:00
000000-0058D975	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-006D517B	No	MEI (2)	04 Nov 2019	Level 2			000:00
000000-00008857	No	MEI (2)	04 Nov 2019	Level 2			000:00

Work Objects

Serial Number: KV15AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment Target Date	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006941F4	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-0000F795	00038	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit	CL	Level 1			
000000-0000FAC4	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL				
000000-00012E72	00020	8 Metre Mast Mount Installation Kit		No	-/-	UTI				Fully Fit	CL				
000000-00008E79	00002	Roof Mounted Communication Installation (Blanking Plate Only)		No	-/	RTI				Fully Fit	CL				
000000-0000D4A2	00016	Radio Battery Isolation Switch and Power Import / Export System		No	-/	RTI				Fully Fit	CL				
000000-00025E0D	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Fully Fit	CL				
000000-0000B930	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL				
000000-0000A9FB	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL				
000000-000091EE	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit	CL				
000000-0001FF15	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL				
000000-0001E975	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit	CL				
000000-0001940E	00014	Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit	CL				
000000-00010942	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants)		No	-/-	UTI				Fully Fit	CL				
000000-0000FOCD	00018	Fitting of Front Windscreen and Side and Rear Window Protection Screens		No	-/-	UTI				Fully Fit	CL				
000000-0000B450	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL				

000000-0000E077	00037	Fitting Glow Plug Timer Interface Harness	No	-/	UTI	Fully Fit	CL
000000-000242A7	00017	Introduction of Battery Retention	No	1/A	UTI	Fully Fit	CL
000000-000238CC	00025	Fitting of Spare Wheel Lifting Aid Harness	No	1/A	UTI	Fully Fit	CL
000000-00020FC9	00035	Fitting of Emergency Hammer	No	1/A	UTI	Fully Fit	CL
000000-00020CC0	00027	Input/Output Porthole for Communication Cables, Cover Modification	No	-/	UTI	Fully Fit	CL
000000-00015C18	00030	Front Belt Protection Sleeves	No	1/A	UTI	Fully Fit	CL
000000-000137D9	00019	Blackout Cover for Warning Light Panel	No	-/-	UTI	Fully Fit	CL
000000-000126F5	00024	Fitting of Trailer Breakaway Attachment Plate	No	-/	UTI	Fully Fit	CL
000000-00011A45	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation	No	-/-	UTI	Fully Fit	CL
000000-0000FD77	00032	Project SHOEHORN Revised Weight Data Plate	No	-/	UTI	Fully Fit	CL
000000-000002B3	00028	FITTING OF REAR ANTI-ROLL BAR (RARB)	No	-/	UTI	Fully Fit	CL

Work Objects

Serial Number: KV15AA
 NSN: 2320998939968

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0034B0B9		No	2 Yearly/40000 Kms	01 Feb 2020	Level 1	Fully Fit	CL	000:00		
000000-001AA1A3		No	OOPS 3 Monthly/5000 Kms		Level 2			000:00		
000000-0019FA4A		No	OOPS Cooling System (AR)		Level 2			000:00		
000000-002072BD		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	16 Mar 2022	Level 1			000:00		
	000000-0032A5BF									
000000-00892AA0		No	Yearly/20000 Kms	08 Apr 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0019F9DE		No	OOPS Drain/Replenish Eng Oil And Renew Oil Filter (AR)(2)		Level 2			000:00		
000000-0095C9CC		No	Battery Test		Level 1			000:00		
000000-000017EF		No	Yearly/20000 Kms	08 Apr 2019	Level 1		CL	000:00		
000000-00001815		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-000BCE43		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-000795DA		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-00089715		No	Yearly/20000 Kms	08 Apr 2019	Level 1		CL	000:00		
000000-00089713		No	2 Yearly/40000 Kms	01 Feb 2020	Level 1		CL	000:00		
000000-00089714		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-000DE8F3		No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00		
000000-0009514B		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-000A2DF2		No	Yearly/20000 Kms	08 Apr 2019	Level 1		CL	000:00		
000000-000A2DF3		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-00077FB8		No	Yearly/20000 Kms	08 Apr 2019	Level 1		CL	000:00		
000000-0007856E		No	Yearly/20000 Kms	08 Apr 2019	Level 1		CL	000:00		
000000-00008C72		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-00023729		No	2 Yearly/40000 Kms	01 Feb 2020	Level 1		CL	000:00		
000000-0002372A		No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL	000:00		
000000-0002372B		No	Yearly/20000 Kms	08 Apr 2019	Level 1		CL	000:00		
000000-0003E6A5		No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00		
000000-00264C2A		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	09 Sep 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-002072A5		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	01 Feb 2020	Level 1			000:00		
000000-0043C38E		No	Battery Test		Level 1			000:00		
000000-00184553		No	6 Monthly/10000 Kms	05 May 2019	Level 1			000:00		
000000-0043C38F		No	Equipment Check		Level 1			000:00		

000000-002186FE	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	16 Mar 2022	Level 2				000:00
000000-00245931	No	6 Monthly/10000 Kms	05 May 2019	Level 1				000:00
000000-002072C9	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	09 Sep 2019	Level 1				000:00
000000-0045D1E3	No	6 Monthly/10000 Kms	05 May 2019	Level 1	Fully Fit	CL		000:00
000000-0098E7EE	No	6 Monthly/10000 Kms	05 May 2019	Level 1	Fully Fit	CL		000:00
000000-001538DE	No	6 Monthly/10000 Kms	05 May 2019	Level 1				000:00
000000-002182B9	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	16 Mar 2022	Level 1				000:00
000000-0095C9CD	No	Equipment Check		Level 1				000:00
000000-0019FA2F	No	OOPS Replace Camshaft Timing Belt (AR)(2)		Level 2				000:00
000000-002072C1	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	22 Aug 2020	Level 2				000:00
000000-0045D12C	No	2 Yearly/40000 Kms	01 Feb 2020	Level 1	Fully Fit	CL		000:00
000000-0007FD44	No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL		000:00
000000-00006880	No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL		000:00
000000-000454A0	No	6 Monthly/10000 Kms	05 May 2019	Level 1		CL		000:00
000000-00184551	No	2 Yearly/40000 Kms	01 Feb 2020	Level 1				000:00
000000-002072BC	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	16 Mar 2022	Level 2				000:00
000000-0019FA04	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (AR)(1)		Level 1				000:00
A00182-25D8C001	No	6 Monthly/10000 Kms	05 May 2019	Level 1	Fully Fit	CL		000:00
000000-001C1160	No	6 Monthly/10000 Kms	05 May 2019	Level 1				000:00
000000-0045D1E2	No	Yearly/20000 Kms	08 Apr 2019	Level 1	Fully Fit	CL		000:00
000000-00209C5B	No	6 Monthly/10000 Kms	05 May 2019	Level 1				000:00
000000-00184552	No	Yearly/20000 Kms	08 Apr 2019	Level 1				000:00
000000-00209C5A	No	Yearly/20000 Kms	08 Apr 2019	Level 1				000:00
000000-0019FA49	No	OOPS Drain And Replenish GBox Oil (AR)(2)		Level 2				000:00
000000-0045D1C7	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	01 Feb 2020	Level 1	Fully Fit	CL		000:00