



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]
[REDACTED]

Our Reference:
FOI2023/04343
Date:
19 April 2023

Dear [REDACTED]

I am writing about your email of 30 March 2023, requesting the following information:

I am interested in the history of an ex-military Land rover defender wolf 90 I have checked the released MERLIN database and the vehicle service history is not contained in the available published MERLIN extract . Therefore I submit a FOI request for the following information:

- 1) Vehicle military service history (Units served etc, as contained in MERLIN/James)
- 2) Any Maintenance Records / Work objects related to this vehicle.

Vehicle Registration: LM24AA

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex B) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

Defence Equipment & Support

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LM24AA	2320998939741	NB42203100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 GS SOFT TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
25/03/1998	SALLDAA67VA123742	N/K		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LM24AA	3		CA005A	JSCS ASHCHURCH		33012AA	25/03/1998	
LM24AA	4	21/10/1998	A3723A	9 TLR RLC	43361A	3421	22/10/1998	
LM24AA	3	10/11/2010	A5969A	TFSU (UK)	117897	3530DD	17/11/2010	
LM24AA	4	29/01/2011	A0132A	HQ 7 ARMD BDE	2313D	64	02/02/2011	
LM24AA	3	15/02/2011	A5969A	TFSU (UK)	999999	3849DD	15/02/2011	
LM24AA	4	12/07/2011	A4003A	AACEN	3235D	112474	13/01/2012	
LM24AA	1	04/06/2013	CA005A	JSCS ASHCHURCH	101934	6594AA	12/06/2013	
LM24AA		08/10/2013		DSG STIRLING			09/10/2013	
LM24AA		02/06/2014		BATUK DIO			27/08/2014	
LM24AA		22/07/2017		BATUK BG FLEET 1			22/07/2017	
LM24AA		19/01/2021		BATUK			21/01/2021	

LM24AA		02/11/2021		OSVP HOLDINGS			04/06/2022	
--------	--	------------	--	---------------	--	--	------------	--

Work Objects

Serial Number: LM24AA
 NSN: 2320998939741

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00BDB801	000000-0034E448	Rectify seepage at top cover gasket	Closed	Non-Taskworthy	No	Level 2		06 Oct 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BDB80E	000000-0034E448	Renew tailgate bottom seal	Closed	Non-Taskworthy	No	Level 2		06 Oct 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BDB83D	000000-0034E448	Secure LH door cover loose	Closed	Non-Taskworthy	No	Level 2		06 Oct 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BDB814	000000-0034E448	Rectify wiper intermittent inop.	Closed	Non-Taskworthy	No	Level 2		06 Oct 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F21	000000-0034E448	RENEW R/H WIPER BLADE	Closed	Non-Taskworthy	No	Level 1		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F25	000000-0034E448	NON STARTER BATTERIES VOLTAGE TOO LOW	Closed	Non-Taskworthy	No	Level 1		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F0C	000000-0034E448	LHS REAR BUMP PLATE DAMAGED	Closed	Fully Fit	No	Level 2		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F09	000000-0034E448	ALL WHEEL TOQUE INDICATORS NOT FITTED	Closed	Fully Fit	No	Level 1		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F06	000000-0034E448	REPLACE X2 FRONT GRILLE SCREWS	Closed	Fully Fit	No	Level 2		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F0F	000000-0034E448	RENEW CLUTCH FLUID DIRTY	Closed	Non-Taskworthy	No	Level 2		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD5F04	000000-0034E448	TAIL GATE EARTH STRAP NOT FITTED	Closed	Non-Taskworthy	No	Level 2		21 Sep 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BD589B	000000-0034E448	BATTERY FAIL TO START	Closed	Fully Fit	No	Level 2		20 Sep 2020	N/A	Failure	TUL HS GS SOFT TOP			000:00
000000-00BC7147	000000-0034B2D2	Renew both headlights (beam adjuster U/S)	Closed	Non-Taskworthy	No	Level 2		02 Aug 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BC51B3	000000-0034B2D2	Rectify vehicle fitted with anon EGR FIP	Closed	Non-Taskworthy	No	Level 2		26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00
000000-00BC7144	000000-0034B2D2	Renew LH stub axle	Closed	Non-Taskworthy	No	Level 2		02 Aug 2020	N/A	Inspection	TUL HS GS SOFT TOP			000:00

000000-00BC51E6	000000-0034B2D2	Rectify play at panhard rod	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BC51CF	000000-0034B2D2	Renew EGR modulator mount rubber	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BC51B8	000000-0034B2D2	Rectify coolant leak at thermostart hose	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BC51A8	000000-0034B2D2	Top up coolant	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BC51D8	000000-0034B2D2	Rectify oil seepage at LH tractor seal	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BC51A5	000000-0034B2D2	Renew drivers door lock	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA3F7	000000-0034B2D2	EXCESSIVE BLACK SMOKE-FAILED SMOKE TEST.	Closed	Non-Taskworthy	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA40C		SANITARY INSPECTION CARRIED OUT. ombuyah	Closed	Non-Taskworthy	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA64A	000000-0034B2D2	CARRY OUT 2 YRLY SERV	Closed	Non-Taskworthy	No	Level 2	22 Jun 2020	N/A	Servicing	TUL HS GS SOFT TOP	000:00	
000000-00BBA404	000000-0034B2D2	NO KEYS FOR THE DOORS.	Closed	Non-Fully Fit	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA3F0	000000-0034B2D2	R/H/S TIE ROD END BOOT SPLIT	Closed	Non-Taskworthy	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA3EE	000000-0034B2D2	BONNET STAY CLIP U/S	Closed	Non-Fully Fit	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA3E9	000000-0034B2D2	R/H/S BOTTOM DOOR HINGES PLAYS.	Closed	Non-Fully Fit	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BBA3E4	000000-0034B2D2	BATTERIES INSECURE.	Closed	Non-Taskworthy	No	Level 2	22 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00	
000000-00BC5222		Rectify oil leak at sump rear	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00	
000000-00BC5229		Rectify oil at T-box	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00	
000000-00BC522D		Renew both gun mount rubbers	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00	
000000-00BC5232		Secure RH side mirror arm	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00	
000000-00BC5219		Renew EGR pipe to brake booster	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00	
000000-00BC5237		Renew RH tool bin cracked + spray paint	Closed	Non-Taskworthy	No	Level 2	26 Jul 2020	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00	
000000-00B21D28		SNVE377 - SWIVEL HOUSING	Closed	Non-Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Inspection	TUL HS GS SOFT TOP	000:00
000000-00BB98DA	000000-0034B2D2	carry out sanitary inspection	Closed	Non-Taskworthy	No	Level 2		21 Jun 2020	N/A	Inspection	TUL HS GS SOFT TOP	000:00
000000-00B1F121		SNVE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Closed No Action	TUL HS GS SOFT TOP	000:00

Reference	Description	Status	Role	Priority	Level	Code	Date	Severity	Action	Category	Time
000000-00A413CC	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-00004519	28 Jul 2017	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-00962043	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003209	20 Jan 2016	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-008439E0	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Closed No Action	TUL HS GS SOFT TOP	000:00
000000-00800905	REMUS PROG	Closed	Fully Fit	No	Level 2		06 Jan 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-00764566	LM24AA QUARANTINE FOR CAST	Closed	Non-Taskworthy	No	Level 1		14 Jan 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-006C827F	FIT SKI RACK	Closed	Fully Fit	No	Level 2		08 Sep 2011	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-006C827D	REPLACE CANOPY	Closed	Fully Fit	No	Level 1		08 Sep 2011	N/A	Cannibalisation	TUL HS GS SOFT TOP	
000000-0079B06D	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS GS SOFT TOP	
000000-007BE79C	BROKEN KEY IN IGNITION BARREL	Closed	Fully Fit	No	Level 2		03 Oct 2013	Degraded	Closed No Action	TUL HS GS SOFT TOP	
000000-0079804B	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUL HS GS SOFT TOP	
000000-00742D42	000000-002DDAB4 WIPERS STAYING ON	Closed	Fully Fit	No	Level 2		15 Oct 2012	Degraded	Inspection	TUL HS GS SOFT TOP	
000000-00734645	000000-002DC8A3 LM24AA-CARRY OUT L2 MAINT IAW AESP-2320-D-126-601 TABLE 7 COLUMN B	Closed	Fully Fit	No	Level 2		04 Sep 2012	N/A	Servicing	TUL HS GS SOFT TOP	
000000-00734649	000000-002DC8A3 LM24AA- CARRY OUT MEI	Closed	Fully Fit	No	Level 2		04 Sep 2012	N/A	Inspection	TUL HS GS SOFT TOP	
000000-00739E64	000000-002DC8A3 INSPECT SEEPAGE FROM OIL SUMP RUBBER OF BOTH REARSIDE SHOCK	Closed	Fully Fit	No	Level 2		18 Sep 2012	N/A	Inspection	TUL HS GS SOFT TOP	
000000-00739E3C	000000-002DC8A3 ABSORBERS FRAYING	Closed	Fully Fit	No	Level 2		18 Sep 2012	N/A	Inspection	TUL HS GS SOFT TOP	
000000-00739DB7	000000-002DC8A3 GEAR BOX FLUID LEVEL BOLT STUCK-UNABLE TO CHECK FLUID LEVEL	Closed	Fully Fit	No	Level 2		18 Sep 2012	N/A	Inspection	TUL HS GS SOFT TOP	
000000-0073463D	LM24AA-CARRY OUT L1 MAINT IAW AESP 2320-D-126-601 TABLE 7 COLUMN B	Closed	Fully Fit	No	Level 1		04 Sep 2012	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8280	FIT EMERGENCY LIGHTS AND SIREN (MOD 8)	Closed	Fully Fit	No	Level 2		08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	000:00
000000-006F8725	000000-002D7A9D LM24AA - L2 MAINT MSI	Closed	Fully Fit	No	Level 2		21 Feb 2012	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006E5855	000000-002D691A LM24AA - TIMING BELT SNAPPED	Closed	Fully Fit	No	Level 2		08 Dec 2011	N/A	Failure	TUL HS GS SOFT TOP	
000000-006DADF6	000000-002D61D7 IN INSPECTION ON RETURN FROM DSG TIDWORTH	Closed	Fully Fit	No	Level 2		08 Nov 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006CE6E7	OOP MAINT IAW AESP 2320-D-126-601 TABLE 5 SERIAL 5 (TIMING BELT)	Closed	Fully Fit	No	Level 2		29 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	

000000-006C8268		OOP MAINT IAW AESP 2320-D-126-601 TABLE 5 SERIAL 4 (AIR CLEANER)	Closed	Non- Taskworthy	No	Level 2	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8261		OOP MAINT IAW AESP 2320-D-126-601 TABLE 5 SERIAL 3 (COOLING SYSTEM)	Closed	Non- Taskworthy	No	Level 2	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8259		OOP MAINT IAW AESP 2320-D-126-601 TABLE 5 SERIAL 2 (GEARBOX OIL)	Closed	Non- Taskworthy	No	Level 2	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8251		OOP MAINT IAW AESP 2320-D-126-601 TABLE 5 SERIAL 1 (ENGINE OIL DRAIN AND REPLACE)	Closed	Non- Taskworthy	No	Level 2	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8245		L2 MAINT MEI	Closed	Non- Taskworthy	No	Level 2	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8241		L2 MAINT IAW AESP 2320-D-126-601 TABLE 7 COLUMN C	Closed	Non- Taskworthy	No	Level 2	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C823E		L1 MAINT IAW AESP 2320-D-126-601 TABLE 7 COLUMN C	Closed	Non- Taskworthy	No	Level 1	08 Sep 2011	N/A	Servicing	TUL HS GS SOFT TOP	
000000-006C8289		REMOVE 325QN LOGO FROM THE WINDSCREEN	Closed	Fully Fit	No	Level 1	08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006C8287		REMOVE ASHCHURCH NO FROM WINDSCREEN	Closed	Fully Fit	No	Level 1	08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006C8283		PAINT AL 39 CAP BLUE	Closed	Fully Fit	No	Level 1	08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006C8282		MARK UP ENGINE BAY	Closed	Fully Fit	No	Level 1	08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006C8272		PAINT NATO SOCKET YELLOW	Closed	Fully Fit	No	Level 1	08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006C826D		PAINT FUEL CAP YELLOW	Closed	Fully Fit	No	Level 1	08 Sep 2011	N/A	Inspection	TUL HS GS SOFT TOP	
000000-006B05AC		Insp Steering Drop Arm Tab Washer PLEASE CARRY OUT OIL LUBS WITH FILTER CHANGE IN ACCORDANCE WITH AESP	Closed	Non- Taskworthy	No	Level 2	000000- 00000310	22 Jun 2011	N/A	Inspection	TUL HS GS SOFT TOP
000000-005A5B26	000000- 002CB1DA	0200-A-400-013-/ARA THIS VEHICLE IS GOING TO WHM PLEASE CARRY OUT OIL LUBS WITH FILTER CHANGE IN ACCORDANCE WITH AESP	Closed	Limited Role	No	Level 2		19 Oct 2010		TUL HS GS SOFT TOP	
000000-005A5BEF	000000- 002CB202	0200-A-400-013-/ARA THIS VEHICLE IS GOING TO WFM	Closed	Limited Role	No	Level 1		19 Oct 2010		TUL HS GS SOFT TOP	
000000-0056B05D	000000- 002C3BC5	PLEASE CARRYOUT MEI. please carryout 6m L2 vm task in accordance with AESP 2320-d-128-	Closed	Non- Taskworthy	No	Level 2		08 Sep 2010		TUL HS GS SOFT TOP	
000000-0056AFD6	000000- 002C3BB9	601table 7 column a.	Closed	Non- Taskworthy	No	Level 2		08 Sep 2010		TUL HS GS SOFT TOP	
000000-0056BC3A	000000- 002C3D19	BRAKE DISC BRACKETS NEED REPLACING	Closed	Non- Taskworthy	No	Level 2		08 Sep 2010		TUL HS GS SOFT TOP	
000000-0056BC36	000000- 002C3D19	RENEW FRONT RIGHT HAND TYRE	Closed	Non- Taskworthy	No	Level 1		08 Sep 2010		TUL HS GS SOFT TOP	
000000-0056DAF1	000000- 002C438D	renew tensioner pulley	Closed	Non- Taskworthy	No	Level 2		10 Sep 2010		TUL HS GS SOFT TOP	



000000-0056AFD0	000000-002C3BB9	please carryout 6m servicing in accordance with AESP 2320-d-128-601table 7 column a.	Closed	Non-Taskworthy	No	Level 1	08 Sep 2010	TUL HS GS SOFT TOP
000000-004E67DF	000000-002AC840	RENEW HEATER DIRECTION LEVERS	Closed	Fully Fit	No	Level 2	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E67DC	000000-002AC840	RENEW NO 1 BALL JOINT	Closed	Non-Taskworthy	No	Level 2	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E67DB	000000-002AC840	RENEW STEERING DAMPER	Closed	Non-Taskworthy	No	Level 2	18 Mar 2010	TUL HS GS SOFT TOP
000000-004AB95D	000000-002A16B7	PLEASE INSPECT AND CLASSIFY CLUTCH STIFF TO OPERATE (FEMIS No 2296/29)	Closed	Limited Role	No	Level 2	10 Dec 2009	TUL HS GS SOFT TOP
000000-004A9522	000000-002A1012	LEAK/CAB FAN NOT HEATING CORRECTLY (FEMIS No 2296/28)	Closed	Limited Role	No	Level 2	07 Dec 2009	TUL HS GS SOFT TOP
000000-0049BFED	000000-0029E682	HEATER CONTROL INOP (FEMIS No 2296/24)	Closed	Fully Fit	No	Level 2	16 Nov 2009	TUL HS GS SOFT TOP
000000-00524CB7	000000-002B9340	mto/tcwo managerial EC snap inspection CES NOT COMPLETE AFTER DEPLOYMENT	Closed	Non-Taskworthy	No	Level 1	24 Jun 2010	TUL HS GS SOFT TOP
000000-004B70AE	000000-002A87DC	TO KENYA	Closed	Limited Role	No	Level 1	12 Jan 2010	TUL HS GS SOFT TOP
000000-004EB73D	000000-002AD8EF	RECTIFY FAILED H/BRAKE TEST	Closed	Non-Taskworthy	No	Level 2	25 Mar 2010	TUL HS GS SOFT TOP
000000-004E67DE	000000-002AC840	BRAKE DISC DEFLECTOR BRACKET SNAPPED	Closed	Non-Taskworthy	No	Level 2	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E4266	000000-002AC0DD	FIT MOD 37- GLOBE PLUG	Closed	Limited Role	No	Level 2	16 Mar 2010	TUL HS GS SOFT TOP
000000-004A9516	000000-002A1012	CRACK IN FRONT WINDSCREEN (IN VIEW) FEMIS No 2296/26	Closed	Fully Fit	No	Level 2	07 Dec 2009	TUL HS GS SOFT TOP
000000-0049BFF0	000000-0029E682	WIPER PARK SENSOR INOP (FEMIS No 2296/25)	Closed	Fully Fit	No	Level 2	16 Nov 2009	TUL HS GS SOFT TOP
000000-004E67E3	000000-002AC83F	FIT DIFFY RIFLE PADS	Closed	Fully Fit	No	Level 1	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E67E2	000000-002AC83F	FIT CORRECT SECURING STRAPS TO REAR CANOPY	Closed	Fully Fit	No	Level 1	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E67E0	000000-002AC83F	REPAIR RIP IN CANOPY REAR FLAP	Closed	Fully Fit	No	Level 1	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E5E58	000000-002AC589	PLEASE CARRY OUT 2 YEARLY VM TASKS IN ACCORDANCE WITH AESP 2320-D-128-601 AS PER TABLE 7 COLUMN C	Closed	Limited Role	No	Level 2	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E5E74	000000-002AC589	PLEASE CARRY OUT ALL OIL AND FILTER CHANGE IN ACCORDANCE WITH AESP 0200-A-400-013 PARA 4.1	Closed	Limited Role	No	Level 1	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E5E4D	000000-002AC589	PLEASE CARRY OUT 2 YEARLY SERVICE IN ACCORDANCE WITH AESP 2320-D-128-601 AS PER TABLE 7 COLUMN C	Closed	Limited Role	No	Level 1	18 Mar 2010	TUL HS GS SOFT TOP
000000-004E5349		PLEASE CARRY OUT 6 MONTHLY SERVICE IN ACCORDANCE WITH AESP 2320-D-128-601 AS PER TABLE 7 COLUMN A	Closed	Fully Fit	No	Level 1	17 Mar 2010	TUL HS GS SOFT TOP

000000-00482497	000000-002998EB	Please fix bonnet raise bar holding clip missing	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-004A9520	000000-002A1012	PLEASE INSPECT AND CLASSIFY BRAKES SPONGY AND BINDING	Closed	Non-Taskworthy	No	Level 2	07 Dec 2009	TUL HS GS SOFT TOP
000000-0005E73F	000000-00271FF7	CARRY OUT ROUTINE MOD 24	Closed	Fully Fit	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-004A1814	000000-0029F642	PLEASE CARRY OUT 1 YEARLY VM TASKS PLEASE CARRY OUT 1 YEARLY SERVICE IN ACCORDANCE WITH AESP 2320-D-128-601	Closed	Fully Fit	No	Level 2	24 Nov 2009	TUL HS GS SOFT TOP
000000-004A180F	000000-0029F642	AS PER TABLKE 7 COLUMN B	Closed	Fully Fit	No	Level 1	24 Nov 2009	TUL HS GS SOFT TOP
000000-004824A6	000000-002998EB	Please secure pass seat bracket	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-004824A5	000000-002998EB	Please find no-smoking sign	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-004824A2	000000-002998EB	Please re- stencil TPs	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-0048249F	000000-002998EB	Please secure dvr side headlight securing clip	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-0048249D	000000-002998EB	Please secure front reg number plate	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-00482493	000000-002998EB	Please top up AL39	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-0048248A	000000-002998EB	Please top up AL39	Closed	Fully Fit	No	Level 1	02 Oct 2009	TUL HS GS SOFT TOP
000000-0033DC31	000000-002998EB	FIT MISSING REAR SEAT BELTS AND SEATS	Closed	Fully Fit	No	Level 1	27 Nov 2008	TUL HS GS SOFT TOP
000000-0005E71A	000000-00271FF7	FIT MISSING CLIPS TO BOTH HEADLIGHT GUARDS	Closed	Fully Fit	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-0033DCF8	000000-002998EE	TIGHTEN RHR SHOCK ABSORBER	Closed	Fully Fit	No	Level 2	27 Nov 2008	TUL HS GS SOFT TOP
000000-004813D0	000000-002998EE	Please check window wipers does not turn off.	Closed	Non-Taskworthy	No	Level 2	30 Sep 2009	TUL HS GS SOFT TOP
000000-0005E747	000000-00271FF7	CARRY OUT ROUTINE MOD 30	Closed	Fully Fit	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E727	000000-00271FF7	FIT RUBBER SEAL AT NATO SOCKET	Closed	Fully Fit	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-00480BFC	000000-002993F1	Please check and repair electrical system.	Closed	Non-Taskworthy	No	Level 2	30 Sep 2009	TUL HS GS SOFT TOP
000000-0033DC59	000000-002998EE	REPAIR DAMAGE TO RHF WING AROUND HLIGHT GUARD	Closed	Fully Fit	No	Level 2	27 Nov 2008	TUL HS GS SOFT TOP
000000-004824B8	000000-002998EE	Pleas check and repair Driver side head light area dented	Closed	Fully Fit	No	Level 2	02 Oct 2009	TUL HS GS SOFT TOP
000000-004824C0	000000-002998EE	Pleas check and repair elctric fault with rear sight light	Closed	Fully Fit	No	Level 2	02 Oct 2009	TUL HS GS SOFT TOP
000000-002FC1CD	000000-00284376	Nato socket cover seal damaged.	Closed	Fully Fit	No	Level 1	07 Nov 2008	TUL HS GS SOFT TOP
000000-00339A5D	000000-00285834	Please make BLR front right hand side tyre.	Closed	Non-Taskworthy	No	Level 2	26 Nov 2008	TUL HS GS SOFT TOP

000000-00339A60	000000-00285834	Please find fault steering pulling to the right when driving.	Closed	Non-Taskworthy	No	Level 2	26 Nov 2008	TUL HS GS SOFT TOP
000000-0033EB4C	000000-00285AEC	Please carryout OOPM.	Closed	Non-Taskworthy	No	Level 1	27 Nov 2008	TUL HS GS SOFT TOP
000000-0033B2DD	000000-002858FA	Please carryout 2 Y servicing.	Closed	Non-Taskworthy	No	Level 1	26 Nov 2008	TUL HS GS SOFT TOP
000000-0033B304	000000-002858FA	Please carryout 2 Y vm task.	Closed	Non-Taskworthy	No	Level 2	26 Nov 2008	TUL HS GS SOFT TOP
000000-0033D08D	000000-0028597B	Please carryout MEI.	Closed	Non-Taskworthy	No	Level 2	26 Nov 2008	TUL HS GS SOFT TOP
000000-0009F434	000000-00275703	1X TYRE U/S	Closed	Fully Fit	No	Level 2	21 Nov 2007	TUL HS GS SOFT TOP
000000-002E960A	000000-00283EBF	Please check and rectify as necessary.Indicator Inop.	Closed	Non-Taskworthy	No	Level 2	04 Nov 2008	TUL HS GS SOFT TOP
000000-0005E71D	000000-00271FF7	STRAIGHTEN HEATER CONTROLS	Closed	Fully Fit	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E737	000000-00271FF7	FIT MISSING PARTS TO SPARE WHEEL VALVE EXTENTION	Closed	Fully Fit	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-002A4620	000000-0028232F	Please require Steering Rod and Front right and left hand side tyres worn.	Closed	Non-Taskworthy	No	Level 2	06 Oct 2008	TUL HS GS SOFT TOP
000000-002081F5	000000-0027E2F6	CARRY OUT 6M VM TASKS	Closed	Non-Taskworthy	No	Level 2	14 Jul 2008	TUL HS GS SOFT TOP
000000-0005E6EB	000000-0027D01B	REMOVE STICKERS FROM WINDSCREEN	Closed	Fully Fit	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E702	000000-0027D01B	RENEW CLUTCH PEDAL BOOT	Closed	Fully Fit	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E709	000000-0027D01B	FIT CORRECT PINS TO REAR TOWEYE	Closed	Fully Fit	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-000BCD44	000000-00270A8B	Shock obsevoir	Closed	Non-Taskworthy	No	Level 2	17 Jan 2008	TUL HS GS SOFT TOP
000000-0009F417	000000-002756FB	TIGHTEN REAR AXLE BALL JOINT AND REAR LIMK ARMS	Closed	Non-Taskworthy	No	Level 2	21 Nov 2007	TUL HS GS SOFT TOP
000000-0008589F	000000-00271FF7	RENEW WHEEL HUB BOLT	Closed	Non-Taskworthy	No	Level 2	30 Aug 2007	TUL HS GS SOFT TOP
000000-0005E719		FIT MISSING BATTERY CLAMPS	Closed	Non-Taskworthy	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E70E		TIGHTEN FRONT DIFF FILLER PLUG	Closed	Non-Taskworthy	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E717		FIT WASHER TO ENGINE SUMP PLUG	Closed	Non-Taskworthy	No	Level 1	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E728		OIL LEAK AT POWER STEERING RESEVIOR	Closed	Non-Taskworthy	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-0005E730		RENEW RH TRACTA SEAL	Closed	Non-Taskworthy	No	Level 2	28 Mar 2007	TUL HS GS SOFT TOP
000000-0003508B	000000-0026E191	RENEW RH WING	Closed	Fully Fit	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-0003B623	000000-0026C218	HOLES IN THE FLOOR REAR	Closed	Fully Fit	No	Level 2	22 Nov 2006	TUL HS GS SOFT TOP

000000-0002C1D2	000000-0026E191	brakes, suspension	Closed	Non-Taskworthy	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-0002C1D3	000000-0026E191	dent right front wing	Closed	Non-Taskworthy	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-00035080	000000-0026E191	RENEW BRAKE MASTER CYLINDER	Closed	Non-Taskworthy	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-00035089	000000-0026E191	RENEW NO 1 BALL JOINT	Closed	Non-Taskworthy	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-0003508C	000000-0026E191	WIPER MOTOR FAILS TO PARK	Closed	Fully Fit	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-00035090	000000-0026E191	FREE OFF HEATER CONTROLS	Closed	Fully Fit	No	Level 2	07 Sep 2006	TUL HS GS SOFT TOP
000000-00015990		FAN AND COOLANT	Closed	Non-Taskworthy	No	Level 2	08 May 2006	TUL HS GS SOFT TOP
000000-000095A0		Insufficient Data	Closed	Non-Taskworthy	No	Level 1	31 Jan 2006	TUL HS GS SOFT TOP
000000-00003FB2		Initial Usage	Closed	Fully Fit	No	Level 1	06 Dec 2005	TUL HS GS SOFT TOP

Work Objects

Serial Number: LM24AA
 NSN: 2320998939741

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated	Working Organisation	Repair Section
								Repair Time		
000000-00CEC37A		No	Yearly/20000 Kms	17 Aug 2021	Level 1	Fully Fit	CL	000:00		
000000-00186A81		No	Weekly (AR)(1)		Level 1			000:00		
000000-003CC52D		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Aug 2022	Level 1	Non-Taskworthy	CL	000:00		
000000-00BA4D07		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Aug 2022	Level 1			000:00		
000000-00BA4D05		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	13 Dec 2022	Level 2			000:00		
000000-00186A82		No	5 Yearly/100000 Kms (1)		Level 1			000:00		
A00503-2D7C0000		No	Yearly/20000 Kms	17 Aug 2021	Level 1	Fully Fit	CL	000:00		

A00503-2D7C0005	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Aug 2022	Level 1	Fully Fit	CL	000:00	
000000-00BA4D08	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Aug 2022	Level 1			000:00	
000000-001CBAB7	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1			000:00	
000000-00CAD56B	000000- 0034B2D2	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1	Fully Fit	CL	000:00
000000-00186A80	No	Yearly/20000 Kms	17 Aug 2021	Level 1			000:00	
000000-00BA4BC6	No	Yearly/20000 Kms	17 Aug 2021	Level 1			000:00	
000000-00186A83	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1			000:00	
000000-00BA4D2E	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1			000:00	
000000-00BA4D2F	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1			000:00	
A00503-2D7C0004	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Aug 2022	Level 1	Fully Fit	CL	000:00	
000000-00BA4BC7	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1			000:00	
000000-00198149	No	6 Yearly/120000 Kms (2)		Level 2			000:00	
000000-00215378	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1			000:00	
000000-00186A7F	No	First 1600 Kms (AR)		Level 2			000:00	
000000-00BA4D5A	No	Yearly/20000 Kms	17 Aug 2021	Level 1			000:00	
000000-003CC530	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Aug 2022	Level 1	Non- Taskworthy	CL	000:00	
000000-00BA4BE1	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1			000:00	
000000-001FFA26	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Aug 2022	Level 1			000:00	
000000-003CC52B	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1	Non- Taskworthy	CL	000:00	

					Non-		
000000-003CC52F	No	Yearly/20000 Kms	17 Aug 2021	Level 1	Taskworthy	CL	000:00
000000-00073124	No	Yearly/20000 Kms	17 Aug 2021	Level 1		CL	000:00
000000-00073135	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-00074156	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-000D3232	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00
000000-000754C7	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-00077967	No	Weekly (AR){1}		Level 1		CL	000:00
000000-00076F8F	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0007D90D	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1		CL	000:00
000000-0007D88D	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-0007D88E	No	Yearly/20000 Kms	17 Aug 2021	Level 1		CL	000:00
000000-00037D86	No	Weekly (AR){1}		Level 1		CL	000:00
000000-000C3D0A	No	Weekly (AR){1}		Level 1		CL	000:00
000000-000DE3CE	No	Weekly (AR){1}		Level 1		CL	000:00
000000-00083AC3	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-000EE5E7	No	Weekly (AR){1}		Level 1		CL	000:00
000000-00038D4C	No	Weekly (AR){1}		Level 1		CL	000:00
000000-00039098	No	Weekly (AR){1}		Level 1		CL	000:00
000000-00038FA6	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0003A334	No	Weekly (AR){1}		Level 1		CL	000:00
000000-000C3E7E	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-000E487A	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0003AAB7	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0003A9A0	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0003C063	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0003B5E2	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0003B744	No	Weekly (AR){1}		Level 1		CL	000:00
000000-0008D9C0	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-0008D660	No	Yearly/20000 Kms	17 Aug 2021	Level 1		CL	000:00
000000-0009C2B5	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00
000000-000BF150	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1		CL	000:00

000000-000A9DEB	No	Yearly/20000 Kms	17 Aug 2021	Level 1		CL	000:00	
000000-000DFA79	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00	
000000-000745B8	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1		CL	000:00	
000000-000A9683	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00	
000000-000DD945	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-0003B489	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-000E974F	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00	
000000-000F9F24	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-00BA4D30	No	Yearly/20000 Kms	17 Aug 2021	Level 1			000:00	
000000-000341E7	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-000D0F52	No	Yearly/20000 Kms	17 Aug 2021	Level 1		CL	000:00	
000000-000D9A30	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00	
000000-000D9EF2	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-00034945	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-0003B595	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-0003F0BE	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-00042B11	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-000459FE	No	Weekly (AR)(1)		Level 1		CL	000:00	
000000-00042B2F	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1		CL	000:00	
000000-00042B30	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL	000:00	
000000-000FB958	No	Yearly/20000 Kms	17 Aug 2021	Level 1		CL	000:00	
000000-000D1ED5	No	Weekly (AR)(1)		Level 1		CL	000:00	
		OOPS 6 Yearly/120000 Kms						
000000-00BA4BC8	No	Camshaft Timing Belt (2)		Level 2			000:00	
A00503-2D7C0001	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1	Fully Fit	CL	000:00	
000000-00215377	No	Weekly (AR)(1)		Level 1			000:00	
		OOPS 2 Yearly/40000 Kms						
		Replace Air Cleaner Element						
000000-001FFA23	No	(1)	17 Aug 2022	Level 1			000:00	
		OOPS 2 Yearly/40000 Kms						
		Replace Air Cleaner Element						
000000-00CAD56C	000000-0034B2D2	No	(1)	17 Aug 2022	Level 1	Fully Fit	CL	000:00

000000-001FFA25	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	13 Dec 2022	Level 1				000:00
000000-00215376	No	Yearly/20000 Kms	17 Aug 2021	Level 1				000:00
000000-001FFA24	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	13 Dec 2022	Level 2				000:00
000000-00186A7E	No	2 Yearly/40000 Kms	12 Aug 2022	Level 1				000:00
000000-00BA4D06	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	13 Dec 2022	Level 1				000:00
000000-00CAD56D	000000- 0034B2D2 No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Aug 2022	Level 1	Fully Fit	CL		000:00
A00503-2D7C0003	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	17 Aug 2022	Level 1	Fully Fit	CL		000:00
000000-00CEC37D	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1	Fully Fit	CL		000:00
A00503-2D7C0002	No	Yearly/20000 Kms	17 Aug 2021	Level 1	Fully Fit	CL		000:00
000000-003CC52E	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1	Non- Taskworthy	CL		000:00
000000-001FFA3E	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		Level 2				000:00
000000-000653AB	No	6 Yearly/120000 Kms (2)		Level 2		CL		000:00
000000-00068567	No	6 Monthly/10000 Kms	11 Feb 2021	Level 1		CL		000:00

Work Objects

Serial Number: LM24AA
 NSN: 2320998939741

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodied by Target Date	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0068E279	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00618D67	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-0000DC7E	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-00023C58	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-000130BC	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00011ECA	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00010C40	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00009CD0	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL				
000000-00021138	00017	Introduction of Battery Retention		No	1/A	UTI				Fully Fit	CL				
000000-000142BD	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants		No	-/-	UTI				Fully Fit	CL				
000000-0001A5A4	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit	CL				
000000-0002210A	00014	Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit	CL				

Work Objects

Serial Number: LM24AA
 NSN: 2320998939741

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request		Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated	Working Organisation	Repair Section
	Escalate Work	ID						Repair Time		
000000-00D0A084	No		FMT932 (W) 6 Monthly Safety Inspection (2)	16 Feb 2021	Level 2			000:00		
000000-00D0A087	No		Annual Brake Test (2)	17 Sep 2021	Level 2			000:00		
000000-00D0A085	No		FMT934 Functional Check (1)*	16 Feb 2021	Level 1			000:00		
000000-00D0A083	No		FMT930 Landworthiness (AR)		Level 1			000:00		
000000-00BA4D77	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-002153A0	No		First Parade Insp (AR)(1)		Level 1			000:00		
000000-00D0A082	No		FMT933 (W) Role Equipment (2)*	17 Aug 2021	Level 2			000:00		
A00503-2D7C0007	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
A00503-2D7C0006	No		6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-00186A8E	No		First Parade Insp (AR)(1)		Level 1			000:00		

000000-00BA4D75	No	6 Monthly 6534 Insp FMT932 (W) Mandatory		Level 1			000:00
000000-00D0A086	No	Equipment Inspection (2)*	17 Aug 2021	Level 2			000:00
000000-00186A8F	No	6 Monthly 6534 Insp		Level 1			000:00
000000-00D0B5C2	No	FMT930 Landworthiness (AR)		Level 1	Fully Fit	CL	000:00
000000-00D0A081	No	Annual Smoke Emissions Test(2)	17 Sep 2021	Level 2			000:00
000000-0021539F	No	MEI (2)		Level 2			000:00
000000-000D318B	No	MEI (2)		Level 2		CL	000:00
000000-0007D90B	No	MEI (2)		Level 2		CL	000:00
000000-0007D90C	No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-00087CDD	No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-0008EC92	No	MEI (2)		Level 2		CL	000:00
000000-000A8441	No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-000A9B34	No	MEI (2)		Level 2		CL	000:00
000000-0002366A	No	MEI (2)		Level 2		CL	000:00
000000-000DCABC	No	MEI (2)		Level 2		CL	000:00
		Annual Headlight Alignment					
000000-00D0A088	No	Check (2)	17 Sep 2021	Level 2			000:00
000000-002153A1	No	6 Monthly 6534 Insp		Level 1			000:00
					Non-		
000000-003CC4FD	No	MEI (2)		Level 2	Taskworthy	CL	000:00
000000-00186A8D	No	MEI (2)		Level 2			000:00
					Non-		
000000-003CC519	No	6 Monthly 6534 Insp		Level 1	Taskworthy	CL	000:00
000000-00D0A080	No	First Parade Insp (AR)(1)		Level 1			000:00
000000-001CBA39	No	6 Monthly 6534 Insp		Level 1			000:00
000000-00BA4D73	No	MEI (2)		Level 2			000:00