




**SALVUS micropoint gas cooker hoses - Male thread end connection issue**

Aspect	Details
Images	 <p>Hose showing pin in place      Hose showing pin not in place</p>
Alert Number	2305-0120
Product Type	Gas appliances and components – Gas Hose
Product Identifiers	Brand: Salvus Affected lines: BFGHENEM-100 SALVUS 1.00M EN 14800 Gas Hose Elbow Micropoint and BFGHENEM-125 SALVUS 1.25M EN 14800 Gas Hose Elbow Micropoint Sales period of affected hoses: January 2019 to December 2022
Product Description	Black and yellow angled micropoint gas hoses.
Country of Origin	China
Counterfeit	Genuine
Risk Type	Fire
Risk Description	<p>The product has been recalled as it has been identified that a very small percentage (1.2%) of their SALVUS branded 1m and 1.25m angled micropoint gas hoses may have a missing pin from the 3-pin array that holds the male thread swivel section joint on to the gas hose itself. The missing pin represents a risk that continued movement and twisting could cause other pins to fall out. If all pins fall out, the male connector section could detach from the hose section and gas will continue to flow from the hose.</p> <p>The product does not comply with the Gas Appliances (Enforcement) and Miscellaneous Amendments Regulations 2018.</p>
Corrective Measures	Recall of the product from end users. For further information, please see: <a href="https://registeredgasengineer.co.uk/technical/safety-alert-031/">https://registeredgasengineer.co.uk/technical/safety-alert-031/</a>



Office for Product  
Safety & Standards

## Product Recall

<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards.