March 2023



Air Quality and Dust Monitoring Monthly Report - March 2023

West Northamptonshire District Council



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken in the West Northamptonshire (WNDC) during March 2023.
- 1.1.2 Figures 1 and 2 in Appendix A present the current worksites together with the dust monitoring locations for March 2023.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figures 1 and 2, include:

Twyford to Greatworth

Radstone and Hall Farm:

- Topsoil Stripping
- Bulk Excavation
- Site Access Road Maintenance and Utilisation
- Haulage Road Maintenance and Utilisation
- Drainage
- Stockpile Management

Greatworth Hall:

- Topsoil Stripping
- Stockpile Management
- Bulk Excavation

- Utilisation and maintenance of Haulage and Site Access Roads
- Utility Diversion works

G2S

Chipping warden - Ramac:

- Chipping warden Green tunnel PPCC erection
- Green Tunnel maintenance for PCC erection
- Bulk earthworks
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Chipping warden batching plant
- General maintenance
- Stockpile management
- Vegetation maintenance
- Site Access Road maintenance
- Compound maintenance
- Water management
- Ditch maintenance
- Plant maintenance
- Material processing

CW Village:

- Chipping warden Green tunnel PPCC erection
- Green Tunnel maintenance for PCC erection

- Bulk earthworks
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Chipping warden batching plant
- General maintenance
- Stockpile management
- Vegetation maintenance
- Site Access Road maintenance
- Compound maintenance
- Water management
- Ditch maintenance
- Plant maintenance
- Material processing

Lower Boddington:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Vegetation maintenance
- High furlong brook viaduct
- Bulk excavation cutting

- Water management
- Ditch maintenance

Fir tree nursery:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Vegetation maintenance
- Site access road maintenance
- Water management
- Ditch maintenance

Greatworth Village:

- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds

Lower Thorpe:

- Topsoil stripping
- Stockpile management


- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds


Blackgrounds:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Vegetation maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Water management
- Ditch maintenance
- 1.1.5 Dust monitoring locations and results are presented in Appendix B, Table 1, together with a line chart of monthly data from the dust monitor presented in Figure 3. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.6 The trigger level for PM₁₀ concentrations of 190 μg/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.7 Data capture was below 90% for the Radstone monitor due to a fault with the pump. Monitor will need to be retrieved for investigation/ repair. The Hall Farm monitor also had low data capture due to a fault with the monitor.
- 1.1.8 There were no (0) dust alerts recorded during the monitoring period (March 2023).
- 1.1.9 No (0) complaints were received during the reporting period.

Appendix A - Monitoring Locations

Figures 1 and 2: Worksite and Monitoring locations within the WNDC





Appendix B - Dust Monitoring Results

Table 1: Dust monitoring locations and March 2023 Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (μg/m³)	Minimum 1- hour PM ₁₀ concentration (μg/m³)	Maximum 1- hour PM ₁₀ concentration (μg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m ³	1-hour data capture (%)
Chipping Warden – RAMAC	449600, 249755	Chipping Warden, West Northamptonshire	М	Yes	Yes	5.3	1.0	25.0	0	99.1
CW Village	450000, 249367	Chipping Warden, West Northamptonshire	М	Yes	Yes	5.6	1.0	25.0	0	96.1
Lower Boddington	447997, 251865	Lower Boddington, West Northamptonshire	М	Yes	Yes	5.2	1.0	23.0	0	99.1
Fir Tree Nursery	447283, 252421	Fir Tree Nursery, West Northamptonshire	М	Yes	Yes	5.4	1.0	22.0	0	99.1
Radstone	458712, 240454	Radstone Road, Brackley, West Northamptonshire	М	Yes	Yes	5.9	1.0	22.0	0	11.4
Hall Farm	458734, 239823	Hall Farm, Radstone Road	М	Yes	Yes	6.1	1.0	27.0	0	71.9
Greatworth Village	455551, 242992	Greatworth Village, Helmdon Road,	М	Yes	Yes	5.4	1.0	22.0	0	99.1
Lower Thorpe	453553, 245334	Banbury Lane, Lower Thorpe	М	Yes	Yes	5.3	1.0	25.0	0	99.1
Greatworth Hall	456179, 242763	Greatworth Hall, Greatworth	М	Yes	Yes	5.4	1.0	25.0	0	98.3
Blackgrounds	450846, 248413	Blackgrounds, West Northamptonshire	М	Yes	Yes	5.6	1.0	27.0	0	99.2

Figure 3: Continuous dust 1-hour mean indicative PM₁₀ concentration for all dust monitors

