Recommendation Status Report: Near miss at Farnborough North footpath level crossing

This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of the recommendation(s), as reported to us, are described by the following categories:

Key to Recommendation Status

Open (replaces Progressing and Implementation On-going)	Actions to address the recommendation are ongoing.		
Closed (replaces Implemented, Implemented by alternative means, and Non- implementation)	ORR consider the recommendation to have been taken into consideration by an end implementer and evidence provided to show action taken or justification for no action taken.		
Insufficient response:	The end implementer has not provided sufficient evidence that the recommendation has been taken into consideration, or if it has, the action proposed does not address the recommendation, or there is insufficient evidence to support no action being taken.		
Superseded:	The recommendation has been superseded either by a newer recommendation or actions have subsequently been taken by the end implementer that have superseded the recommendation.		
Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.		

RAIB concern over the way that an organisation has responded to a recommendation are indicated by one of the following:

Red – RAIB has concerns that no actions have been taken in response to a recommendation.

Blue – RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

White – RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Recommendation Status Report



Report Title	Near miss at Farnborough North footpath level crossing		
Report Number 04/2023			
Date of Incident	19/05/2022		

Rec No.	Status	RAIB Concern	Recommendation	RAIB Summary of current status
04/2023/01	Closed - I	Blue	The intent of this recommendation is to improve the control of risk at	ORR has reported that Network
			footpath level crossings where there is known to be a history of safety	Rail has reported that it has
			incidents, and where timescales to implement long-term safety	completed actions taken in
			improvements are uncertain.	response to this
				recommendation. ORR proposes
			Network Rail should review its processes associated with the risk	to take no further action unless
			assessment of footpath level crossings. Where mitigation measures have	they become aware that the
			been implemented to control the risks associated with user behaviour	information provided becomes
			(such as how groups of people behave), Network Rail should ensure that	inaccurate.
			an effective method of identifying and managing any ongoing residual risk	
			is provided and that this takes account of available operational experience	
			and previous safety assessments. As part of this process, Network Rail	
			should specifically consider what actions should be adopted to control risk	
			during the period in which longer term mitigation measures are being	
			implemented, and to review the situation if, and when timescales change	
			(paragraph 113b).	
04/2023/02	Open	None	The intent of this recommendation is that temporary and interim crossing	ORR has reported that Network
			attendant roles are subject to suitable training and competency	Rail has a proposed action plan
			management.	and timescale for delivery to be
				taken in response to the
			Network Rail should review the role of temporary and interim crossing	recommendation. ORR will advise
			attendants nationally, including that currently in use at Farnborough	when the status of this
			North. This review should consider the nature of the tasks undertaken by	recommendation changes.
			crossing attendants and whether these are safety-critical in nature. Based	
			on this review, Network Rail should develop and implement appropriate	
			requirements for developing and managing the competency of this role, in	
			line with industry good practice and any applicable legislative	

Recommendation Status Report



		requirements (paragraph 115). This recommendation may apply to other	
		comparable roles on Network Rail managed infrastructure.	