

Product Safety Report

Voyor Coffee Beaster	
Vevor Coffee Roaster	
Aspect	Details
Images	
Alert Number	2208-0303
Product Type	Machinery – Coffee roaster
Product Identifiers	Model: JMS-007 Barcode: JMS00702016304
Product Description	Black and silver coffee roaster
Country of Origin	China
Counterfeit	Unknown
Risk Type	Electric shock, fire, explosion
Risk Level	Serious
Risk Description	The product presents as serious risk of electric shock as it failed the electrical strength test as breakdown occurred before full test voltage was applied. The plug face did not meet the dimensional requirements of BS1363 because the distance between the outside edge and the input measured too small at 7.3mm which is below the 9.5mm standard, further presenting an electric shock hazard. The product also presents a risk of fire/explosion as the fuse did not contain a ballast and had friction fit end caps. The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016 and Plugs & Sockets (Safety) Regulations 1994.
Corrective Measures	Destruction of the product
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts