




| VEVOR Ultrasonic Cleaner | |
|---------------------------------|---|
| Aspect | Details |
| Images |  |
| Alert Number | 2203-0390 |
| Product Type | Electrical appliances and equipment – Ultrasonic Cleaner |
| Product Identifiers | Brand: Vevor Model: JPS-10A Other Product Identifiers: RVG33555-211124-0042-1074 G3355-JPS-10ACSBQXJ0001V2 BPQXJ10L000000001V2 JPS-100ACSBQXJX01V2 JPS 20ACSBQXJ0001V2 QXJ15LXNS00000001V2 QXNGDHJ6L220VOP3ZV2 |
| Product Description | Silver rectangular unit with control panel on the front and a lid. |
| Country of Origin | China |
| Counterfeit | Unknown |
| Risk Level | Serious |
| Risk Type | Electric Shock |
| Risk Description | <p>The product presents a serious risk of electric shock as the appliance was inadequately earthed and was not adequately secured against accidental loosening, which may electrocute consumers. The plug on this sample failed to comply with BS1363-1 and the fuse had not been supplied with any granular filler. The filler is required to ensure the safe operation of the fuse under fault conditions.</p> <p>The product does not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.</p> |
| Corrective Measures | <p>The product has been recalled from end users. For further information, access the Vevor recall webpage at: https://uk.vevor.com/pages/Product-Recall-Statement</p> <p>The import has been rejected at the border and destroyed.</p> |
| Online Marketplace | N/A |
| Notifier | Local Authority Trading Standards |