






<b>Russell Hobbs Gas Hobs</b>	
<b>Aspect</b>	<b>Details</b>
<b>Product Type</b>	Gas appliances and components – Gas Hob
<b>Product Identifiers</b>	List of affected models attached below.
<b>Product Description</b>	Gas hob supplied with elbow joint on the connecting pipework.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	No
<b>Risk Level</b>	Serious
<b>Risk Type</b>	Poisoning, burns or gas explosion and/or fire.
<b>Risk Description</b>	<p>The elbow on the connecting pipework of affected gas hobs can fail resulting in a significant gas leak, regardless of whether the hob is switched on and in use. Hazards resulting from a gas leak include burns, fire and explosion and poisoning from inhalation. The risk levels vary from low risk to serious risk, with the risk presented from fire and explosion being the worst case. The risk of fire and explosion in traditional built residences is high risk, and the risk of fire and explosion in a caravan or leisure homes is serious risk.</p> <p>The products are not in conformity with the requirements of Regulation 2016/426.</p>
<b>Corrective Measures</b>	<p>Russell Hobbs have initiated a modification programme for certain products in scope of the safety issue. OPSS is urging all affected members of the public, including those unsure whether they are affected or not, to check the model links and contact the manufacturer.</p> <p>While all affected consumers should check the model links, owners and consumers in caravans, leisure homes and motorhomes should do this as a matter of urgency. If they are using an affected appliance with Liquefied Petroleum Gas (LPG), they should disconnect it from the LPG cylinder immediately.</p> <p>Owners and consumers in domestic premises should continue to be vigilant. If they smell gas or are concerned that their product poses a risk, they should contact the National Gas Emergency Helpline for their area (0800 111 999 in England, Wales and Scotland, and 0800 002 001 in Northern Ireland) or a Gas Safe registered installer.</p> <p>Contact Russell Hobbs to arrange a free of charge modification via:</p> <ul style="list-style-type: none"><li>• Tel: 0800 046 5396</li><li>• The Russell Hobbs website: <a href="https://mda.russellhobbs.com/important-safety-alert-action-required-product-safety-repair-russell-hobbs-gas-hob">https://mda.russellhobbs.com/important-safety-alert-action-required-product-safety-repair-russell-hobbs-gas-hob</a>.</li></ul>



## Product Safety Report






	<p>Alternatively, go to <a href="https://gashobsrepair.mktpoint.com">https://gashobsrepair.mktpoint.com</a> to enter your details.</p> <p>This follows a suspension notice issued by OPSS requiring manufacturers to stop the supply of affected models.</p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Office for Product Safety and Standards

### List of Affected Model Numbers

PSD Reference Number	Model Numbers	Image
2307-0001	RH60GH402B	
2307-0002	RH60GH402B/01	
2307-0003	RH60GH402SS	



## Product Safety Report

2307-0004	RH60GH402SS/01	
2307-0005	RH60GH403B	
2307-0006	RH60GH403DS	
2307-0007	RH60GH403DS/01	
2307-0009	RH60GH403SS	








## Product Safety Report

2307-0010	RH60GH403SS/01	
2307-0011	RH75GH601B	
2307-0013	RH75GH601B/01	
2307-0014	RH75GH601SS	
2307-0019	RH75GH601SS/01	








## Product Safety Report

2307-0020	RH75GH602B	
2307-0021	RH75GH602DS	
2307-0022	RH75GH602SS	
2307-0023	RH75GH602SS/01	
2307-0024	RH86GH701B	





## Product Safety Report

2307-0025	RH86GH701B/01	
2307-0026	RH86GH701SS	
2307-0027	RH86GH701SS/01	
2307-0029	RH86GH702B	
2307-0030	RH86GH702DS	



## Product Safety Report

2307-0033	RH86GH702SS	
2307-0034	RH86GH702SS/01	