




<b>Salomon MTN ski touring bindings</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2310-0250
<b>Product Type</b>	Hobby / sports equipment - Ski Touring Binding
<b>Product Identifiers</b>	Brand: Salomon Manufacturing period: 1 <sup>st</sup> May 2022 to 31 <sup>st</sup> March 2023. Please refer to page 2 for a list of affected models.
<b>Product Description</b>	A variation of ski-touring binding models.
<b>Country of Origin</b>	Romania
<b>Counterfeit</b>	No
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	<p>Under certain conditions, unexpected breakage of the spring guiding axis may occur, causing the ski boot to disconnect from the ski. Failure of the toe component may lead a skier to lose control or fall, and consequently suffer injuries.</p> <p>The affected products do not meet the requirements of the General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	The product has been recalled from end users. For further information, please access the Salomon safety notice here: <a href="https://www.salomon.com/en-gb/safety-notice">https://www.salomon.com/en-gb/safety-notice</a>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards.



## Product Recall

**Affected models:**

Model	Reference	Colour
MTN TOUR	L41773900+	Black/Titan
MTN PURE	L41774000+	Black/Titan
MTN SUMMIT 12 BR	L47327200+	Orange/Burnt
MTN SUMMIT 9 BR	L47327300+	Titan
MTN SUMMIT 5 BR	L47327500+	Gold
MTN SUMMIT 12 LSH	L47327700+	Orange