




<b>Fibre Optic Visual Fault Laser sold via Amazon</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	
<b>Alert Number</b>	2311-0218
<b>Product Type</b>	Laser pointers - Fibre Optic Visual Fault Laser
<b>Product Identifiers</b>	Barcode: X001RZV7V1 Other Amazon identifier: FBA15GZG6MYSU000002
<b>Product Description</b>	A black laser used to find faults in fibre optics packaged in a white cardboard box.
<b>Country of Origin</b>	China
<b>Counterfeit</b>	No
<b>Risk Level</b>	Serious
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	<p>The product presents a serious risk of injuries at it has been identified that the 'glint' mode flashes below 3hz, which can trigger photosensitive epilepsy. The labelling is inaccurate for a laser product in the UK, and is rated between Class 3R or 3B, which could cause injury to the user.</p> <p>The product does not meet the requirements of The General Product Safety Regulations 2005.</p>
<b>Corrective Measures</b>	The import has been rejected at the border and destroyed.
<b>Online Marketplace</b>	Amazon
<b>Notifier</b>	Local Authority Trading Standards.