



Ministry
of Defence



DE&S Policy Secretariat

DESSEC-PolSecLE-JSC-WPNS@mod.gov.uk

Defence Equipment & Support
Maple 0a #2043
MOD Abbey Wood
Bristol BS34 8JH

Reference: FOI2023/15909

03 January 2024

Dear [REDACTED]

I am writing about your email of 19 December 2023, requesting the following information:

Therefore I submit a FOI request for the following information:

- 1) *Vehicle military service history (Units served etc, as contained in MERLIN)*
- 2) *Any Maintenance Records / Work objects related to this vehicle.*

Vehicle Registration: ME97AA

Description: TRUCK UTILITY MEDIUM TUM HS 12/24 4X4 LAND ROVER GS SOFT TOP 110 4X4 DIESEL.

VIN number: SALLDBA67WA147674

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History (redacted)
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault and Modification Histories (annexes B and D) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's

commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
ME97AA	2320998939963	NB50103101	LV2A/088DUM	TRUCK UTY MED (TUM HS) 4X4 SOFT TOP LANDROVER 2.5LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
03/06/1998	SALLDBA67WA147674	25LO6418B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
ME97AA	3		CA005A	JSCS ASHCHURCH		34975AA	03/06/1998	
ME97AA	4	27/07/1998	A0565A	1YORKS-MUNSTER	41178A	609	31/07/1998	
ME97AA	4	03/12/2001	A0580A	2MERC	1	1	03/12/2001	H/T
ME97AA	4	27/09/2005	A2240A	RGBWLI	U/K	U/K	28/09/2005	H/T
ME97AA	2	19/01/2007	A0563A	1RIFLES	37732	57770	30/01/2007	H/T
ME97AA		28/06/2022		OSVP HOLDINGS			28/06/2022	

Work Objects

Serial Number: ME97AA
 NSN: 2320998939963

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault			Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
							Group ID	Occurrence Date	Mission Impact					
000000-0083FB63		MEI-933-ADVISORIES-46-NO BRIDGE MARKINGS FITTED	Closed	Fully Fit	No	Level 1		20 May 2019	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0083FB5F		MEI-933-ADVISORIES-1-WINDOW FELTS NEED REPLACING	Closed	Fully Fit	No	Level 1		20 May 2019	N/A	Inspection	SOFT TOP	TUM HS GS	000:00	
000000-0083FB28		MEI-932-ADVISORIES-6.2-RH FRONT DOOR FRAME SPLITTING	Closed	Fully Fit	No	Level 2		20 May 2019	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0085DA60		DAMAGED CANOPY	Closed	Fully Fit	No	Level 1		21 Aug 2019	Degraded	Action	SOFT TOP	TUM HS GS	000:00	
000000-0083FB1A		MEI-932-ADVISORIES-0.1-FRONT NUMBER PLATE NEEDS REPAINTING	Closed	Fully Fit	No	Level 1		20 May 2019	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0083FB1E		Hazard Switch Inop	Closed	Non-Taskworthy	No	Level 2		20 May 2019	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0086F10B		TEAR IN ROOF CANOPY	Closed	Fully Fit	No	Level 1		13 Oct 2019	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0086F111		TYRE PRESSURE LABELS MISSING FROM WHEEL STATIONS	Closed	Fully Fit	No	Level 1		13 Oct 2019	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0089CB2A		BRAKE FLUID DISCOLOURED REQUIRES FLUSH AND CLUTCH	Closed	Fully Fit	No	Level 2		04 Mar 2020	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0089CB30		SLIGHT PLAY IN STEERING BOX	Closed	Fully Fit	No	Level 2		04 Mar 2020	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0089CB47		O/S TAIL LIGHT COVER FADED	Closed	Fully Fit	No	Level 1		04 Mar 2020	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0089CB54		FRONT RADIUS ARM BUSHES N/S AND O/S CHASSIS REQUIRES A DROP TEST AND CROSS MEMBER REQUIRES REMOVAL TO ASSES CHASSIS LEG	Closed	Non-Taskworthy	No	Level 2		04 Mar 2020	N/A	Action	SOFT TOP	TUM HS GS	000:00	
000000-0089CB75			Closed	Non-Taskworthy	No	Level 4		02 Mar 2020	No Effect	Inspection	SOFT TOP	TUM HS GS	000:00	
000000-0089CB7F		INVESTIGATE NOISE FROM ENGINE AND GEARBOX WIRE FOUND WRAPPED AROUND N/S WHEEL STATION AND STEERING LINKAGES REQUIRES REMOVAL	Closed	Non-Taskworthy	No	Level 2		03 Mar 2020	No Effect	Action	SOFT TOP	TUM HS GS	000:00	
000000-0089CB88			Closed	Taskworthy	No	Level 1		04 Mar 2020	N/A	Action	SOFT TOP	TUM HS GS	000:00	


000000-0089CB95	REPLACE REAR TAILGATE LOWER SEAL	Closed	Fully Fit	No	Level 2	04 Mar 2020	N/A	Action	Closed No	TUM HS GS	0000:00
000000-0089CBAE	VIBRATION FROM ENGINE AT FRONT DAMPER	Closed	Non-Taskworthy	No	Level 3	02 Mar 2020	No Effect	Action	Closed No	TUM HS GS	0000:00
000000-008F364E	HORN BRACKET CORRODED	Closed	Fully Fit	No	Level 2	07 Dec 2020	No Effect	Action	Closed No	TUM HS GS	0000:00
000000-00C11467	replace exhaust muffler	Closed	Non-Taskworthy	No	Level 2	24 Mar 2021	No Effect	Action	Closed No	TUM HS GS	0000:00
000000-00C1146E	replace washer pump	Closed	Taskworthy	No	Level 2	24 Mar 2021	No Effect	Failure	Failure	TUM HS GS	0000:00
000000-00C11474	replace oil dipstick tube	Closed	Taskworthy	No	Level 2	24 Mar 2021	No Effect	Failure	Failure	TUM HS GS	0000:00
000000-00C65FD0	Vehicle Batteries won't hold charge	Closed	Taskworthy	No	Level 2	13 Dec 2021	No Effect	Action	Closed No	TUM HS GS	0000:00
000000-00C65FD1	Screen washer jet missing	Closed	Taskworthy	No	Level 2	13 Dec 2021	No Effect	Action	Closed No	TUM HS GS	0000:00
000000-00C66136	5 x wheel nut indicators missing	Closed	Fully Fit	No	Level 1	14 Dec 2021	N/A	Action	Closed No	TUM HS GS	0000:00
000000-00C66137	Spare wheel missing	Closed	Limited Role	No	Level 1	14 Dec 2021	N/A	Action	Closed No	TUM HS GS	0000:00
000000-00C6613C	Steering Drag link missing	Closed	Non-Taskworthy	No	Level 2	13 Dec 2021	No Effect	Action	Closed No	TUM HS GS	0000:00
000000-00C66141	Wing mirror missing	Closed	Taskworthy	No	Level 1	14 Dec 2021	N/A	Action	Closed No	TUM HS GS	0000:00
000000-0089CB5B	NO SMOKE TEST CARRIED OUT DUE TO NON TASK WORTHY FAULTS	Closed	Taskworthy	No	Level 2	04 Mar 2020	N/A	Action	Closed No	TUM HS GS	0000:00
000000-0089CB14	UNABLE TO CARRY OUT RBT DUE TO NON TASK WORTHY FAULTS	Closed	Non-Taskworthy	No	Level 2	04 Mar 2020	N/A	Action	Closed No	TUM HS GS	0000:00
000000-0089CB62	OIL LEAKS FROM FRONT AND REA CRANK SHAFT SEALS	Closed	Taskworthy	No	Level 2	04 Mar 2020	N/A	Action	Closed No	TUM HS GS	0000:00
000000-00C38D44	Seat	Closed	Fully Fit	No	Level 2	19 Jul 2021	N/A	Action	Closed No	TUM HS GS	0000:00
000000-0089CB9F	COOLANT LEVEL LOW	Closed	Non-Taskworthy	No	Level 1	04 Mar 2020	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-0089CB97	ENGINE OIL BELOW MIN	Closed	Taskworthy	No	Level 1	04 Mar 2020	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-0083FB57	MEI 933 DEFECTS -43- CES/AF B6530 NOT PRESENTED - CES details not presented at the time of inspection, must be	Closed	Limited Role	No	Level 1	20 May 2019	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-0083FB55	MEI 933 DEFECT -45- JACK NOT PRESENTED, SER NO. N/K, NO 2029 SEEN - to travel in convoy with another vehicle holding	Closed	Limited Role	No	Level 1	20 May 2019	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-0083FB4B	MEI 933 DEFECT -10- FIRE EXTINGUISHER NOT PRESENTED - CES details not presented at time of inspection must be inspected	Closed	Limited Role	No	Level 1	20 May 2019	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-008855E5	INVESTIGATE SULPHUR SMELL & BATTERIES SMOKING	Closed	Taskworthy	No	Level 2	10 Dec 2019	N/A	Action	Closed No	TUM HS GS	0000:00
000000-0083FC4B	WORK CARRIED OUT AS PER CUSTOMER REQUEST - SALES ORDER 8B0158169	Closed	Fully Fit	No	Level 2	29 May 2019	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-0083FB5A	MEI-933-DEFECTS-49-UNABLE TO ROAD TEST-FAILED MEI	Closed	Non-Taskworthy	No	Level 2	20 May 2019	N/A	Inspection	Inspection	TUM HS GS	0000:00
000000-00AB2F4A	NO TYRE PRESSURE MARKINGS ON VEHICLE	Closed	Limited Role	No	Level 1	16 May 2018	N/A	Inspection	Inspection	TUM HS GS	0000:00

000000-00B3FBF4	BAAN-281-0002/0038-FINAL OUT INSPECTION & BRAKE TEST	Closed	Fully Fit	No	Level 2	28 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FBE1	BAAN-271-7053-WELD REPAIR DOOR FRAME MOUNTING RH	Closed	Fully Fit	No	Level 2	27 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FBD6	BAAN-271-3885-CARRY OUT DIAGNOSTIC CHECKS TO CHARGING SYSTEM	Closed	Fully Fit	No	Level 2	27 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FBC7	BAAN-271-1971-RE-CHECK WHEEL NUT TORQUE	Closed	Fully Fit	No	Level 2	27 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FBA5	BAAN-271-1915/1928-R&R LH & RH AXLE 2	Closed	Fully Fit Non-	No	Level 2	27 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FB10	MEI-932-DEFECTS-4.13-BATTERIES U/S	Closed	Taskworthy	No	Level 2	20 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FB09	MEI-932-DEFECTS-3.4-FRONT WIPER BLADES SPLIT	Closed	Taskworthy	No	Level 2	20 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FB06	MEI-932-DEFECTS-1.1-RH & LH REAR METAL BRAKE PIPES INSECURE	Closed	Taskworthy	No	Level 2	20 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B3FB01	MEI-932-DEFECTS-1.1-REAR BRAKES-WRONG BRAKE PADS FITTED	Closed	Taskworthy	No	Level 2	20 May 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00B20B2A	SNVE 377 - SWIVEL HOUSING	Closed	Taskworthy	No	Level 1	000000-000000-0000697A	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00
000000-00B2369C	SNVE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	0000697B	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00
000000-00B1E4EB	INSPECT N/S SWIVEL HOUSING AS PER 20190326_SNVE_LANDROVER_ALL_VAR_SWIVEL_HOUSING_FA	Closed	Taskworthy	No	Level 2	28 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00AF9DC7	*COMPLETE* EXCESSIVE PLAY IN REAR TRAILING ARM BUSHES	Closed	Fully Fit	No	Level 2	29 Nov 2018	N/A	Servicing	TUM HS GS SOFT TOP	0000:00	
000000-00AF9DDA	REPLACE O/S DOOR HINGES	Closed	Fully Fit	No	Level 1	29 Nov 2018	N/A	Servicing	TUM HS GS SOFT TOP	0000:00	
000000-00AF9D5A	REPLACE N/S SEAT BASE	Closed	Fully Fit	No	Level 2	29 Nov 2018	N/A	Servicing	TUM HS GS SOFT TOP	0000:00	
000000-00964C22	DRIVERS SEAT RIPPED	Closed	Fully Fit	No	Level 2	24 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP	0000:00	
000000-00AF9DC9	REPLACE TURBO TO INTER COOLER HOSES	Closed	Fully Fit	No	Level 2	29 Nov 2018	N/A	Servicing	TUM HS GS SOFT TOP	0000:00	
000000-00AB2F58	GREASE CONTAMINATION ON O/S/R HUB	Closed	Fully Fit	No	Level 2	16 May 2018	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00AB2F5E	T-BOX SEEPAGE	Closed	Fully Fit	No	Level 2	16 May 2018	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00AEBADB	DEAD BATTERIES	Closed	Taskworthy	No	Level 1	22 Oct 2018	N/A	Non Specific	TUM HS GS SOFT TOP	0000:00	
000000-00AB2F63	ENGINE OIL SEEPAGE NEAR OIL FILTER	Closed	Fully Fit	No	Level 2	16 May 2018	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00AB2F5A	ROCKER COVER SEEPAGE	Closed	Fully Fit	No	Level 2	16 May 2018	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	
000000-00ABA8FF	FUEL TANK MOUNTING BOLTS DAMAGED	Closed	Taskworthy	No	Level 2	06 Jun 2018	N/A	Failure	TUM HS GS SOFT TOP	0000:00	
000000-00AB2F19	NO WHEEL TORQUE INDICATORS FITTED	Closed	Role	No	Level 1	16 May 2018	N/A	Closed No Action	TUM HS GS SOFT TOP	0000:00	
000000-00A5E980	WORK CARRIED OUT AS PER CUSTOMER REQUEST - SALES ORDER 880142405	Closed	Fully Fit	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	0000:00	

000000-00A5E710	AFB 6534 - ADVISORIES - 18 - 4 X BONNET STRAPS ROTTEN	Closed	Fully Fit	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00A5E70E	AFB 6534 - ADVISORIES - 13 - DAMAGE TO FRONT BUMPER LH FRONT WING SLIGHT DAMAGE TO RH FRONT WING TAIL GATE	Closed	Fully Fit	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00A5E70A	AFB 6534 - ADVISORIES - 11 - SLIGHT DAMAGE TO RH FRONT CHASSIS BENT IN ONE SIDE	Closed	Fully Fit	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00A5E706	AFB 6534 - ADVISORIES - 8 - RH REAR WHEEL GREASE CAP MISSING	Closed	Fully Fit Limited	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00A26EF0	CES, JACK & EXTINGUISHER NOT PRESENTED FOR 933 INSPECTION.	Closed	Role	No	Level 1	24 May 2017	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00A26EEF	SLIGHT DAMAGE TO RH OF CHASSIS - FULLY FIT	Closed	Fully Fit	No	Level 2	24 May 2017	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-009655DB	OBTAIN ENGINE NUMBER AND UPLOAD TO JAMES AS PER JSP932 GIL 212	Closed	Fully Fit	No	Level 1	26 Jan 2016	N/A	Action	TUM HS GS SOFT TOP	
000000-00964C09	OBS TRACTOR SEALS	Closed	Fully Fit	No	Level 2	25 Jan 2016	N/A	Action	TUM HS GS SOFT TOP	
000000-008DCAF8	REPLACE FRONT NUMBER PLATE	Closed	Fully Fit	No	Level 1	20 Nov 2015	N/A	Action	TUM HS GS SOFT TOP	
000000-00AA01EF	BATTERIES NO CHARGE.	Closed	Fully Fit	No	Level 1	19 Mar 2018	N/A	Found	TUM HS GS SOFT TOP	
000000-00964BFA	TASK COMPLETE - INSPECT FUEL TANK FOR LEAKS	Closed	Fully Fit	No	Level 2	24 Jan 2016	N/A	Inspection	TUM HS GS SOFT TOP	
000000-00A461D5	RTI INSPECTION	Closed	Non- Taskworthy	Yes	Level 2	30 Jul 2017	N/A	Action	TUM HS GS SOFT TOP	
000000-00A43327	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment	Closed	Limited Role	No	Level 2	000000- 00004550	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00964C16	FRONT O/S WING SLIGHT DAMAGE	Closed	Fully Fit Limited	No	Level 2	25 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-008DCBED	REMOVE STICKER RESIDUE FROM WINDSCREEN	Closed	Role	No	Level 1	20 Nov 2015	N/A	Action	TUM HS GS SOFT TOP	
000000-008DCBCD	REPLACE N/S DEMISTER GOMMIT AND REMOVE DETRITUS FROM WITHIN DASH.	Closed	Limited Role	No	Level 1	20 Nov 2015	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-008DCB8A	SECURE/ FIT SPARE WHEEL VALVE HOLDER MOD	Closed	Fully Fit Limited	No	Level 1	20 Nov 2015	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-008DCB5F	SECURE N/S/F CREW SEAT	Closed	Role	No	Level 1	20 Nov 2015	N/A	Action	TUM HS GS SOFT TOP	
000000-008DCB39	REPLACE O/S STORAGE BIN SEAL	Closed	Fully Fit	No	Level 1	20 Nov 2015	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-008DCAE4	FIT LOCKABLE FUEL CAP	Closed	Fully Fit Non- Taskworthy	No	Level 1	20 Nov 2015	N/A	Action	TUM HS GS SOFT TOP	
000000-00A5E6FD	Baan 820 - 1.0072 serv carry out 12 monthly service no parts	Closed	Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	
000000-00A5E70B	Baan 830 - 1.1706 RENEW FRONT BUMPER	Closed	Taskworthy	No	Level 2	04 Oct 2017	N/A	Accident	TUM HS GS SOFT TOP	
000000-00A5E712	Baan 830 - 2.7160 REMOVE & REFIT WING ASSY LHF	Closed	Taskworthy	No	Level 2	04 Oct 2017	N/A	Accident	TUM HS GS SOFT TOP	
000000-00A5E71E	Baan 830 - 3.7191 REMOVE & REFIT WING ASSY RHF	Closed	Taskworthy	No	Level 2	04 Oct 2017	N/A	Accident	TUM HS GS SOFT TOP	
000000-00A5E724	Baan 830 - 4.7186 RENEW WING OUTER WING PANEL LHF	Closed	Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP	

000000-00A5E72D	Baan 830 - 5.6356 RENEW WING OUTER WING PANEL RHF	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E754	Baan 830 - 6.8880 PAINT INCIDENTAL ITEMS	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E768	Baan 830 - 7.4531 REMOVE & REFIT HEADLIGHT LH	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Accident	TUM HS GS SOFT TOP
000000-00A5E76D	Baan 830 - 8.4536 REMOVE & REFIT HEADLIGHT RH	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Accident	TUM HS GS SOFT TOP
000000-00A5E775	Baan 830 - 9.4543 REMOVE & REFIT INDICATOR LHF	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E779	Baan 830 - 10.4548 REMOVE & REFIT INDICATOR RHF	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E77E	Baan 830 - 11.4600 REMOVE & REFIT SIDE LIGHT LHF	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E785	Baan 830 - 12.4602 REMOVE & REFIT SIDE LIGHT RHF	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E78D	Baan 830 - 13.7227 REMOVE AND REFIT AIR VENT RH	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E796	Baan 830 - 14.7228 REMOVE AND REFIT AIR VENT LH	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E7A4	Baan 830 - 15.4070 REMOVE AND REFIT WASHER RESERVOIR	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E872	Baan 830 - 16.1476 RENEW HUB CAP RH 2ND AXLE	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E883	Baan 830 - 18.6003 RENEW BONNET FRONT WEB STRAPS	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E906	Baan 830 - 19.5511 RENEW QTY 1 CANOPY REAR CORDS	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E912	Baan 830 - 19.5511 RENEW QTY 1 CANOPY REAR CORDS	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E94C	Baan 830 - 20.6695 RESECURE CREW SEAT LHR	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E95E	Baan 830 - 21 - 21.6695 RESECURE CREW SEAT LHR (INC DRILL & RIVNUT WINGS FOR VENTS)	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E968	Baan 840 - 1.0002 CARRY OUT FINAL OUT INSPECTION/ASSESSMENT	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E974	Baan 840 - 2.0013 CHECK & ADJUST HEADLIGHT ALIGNMENT	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E6F3	Baan 261 - 1.2002 carry out 933 inspection	Closed	Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A5E6E4	Baan 260 - 2.0040 CARRY OUT 6 MONTHLY SAFETY INSPECTION <3.5 TONS, AFB 6534 INSPECTION	Closed	Non-Taskworthy	No	Level 2	04 Oct 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-0080CADD	REPLACE O/S TAIL LIGHT LENS	Closed	Fully Fit Limited	No	Level 1	19 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCAA1	REPLACE MISSING BONNET CES BONNET STRAPS	Closed	Role	No	Level 1	19 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCB56	REPLACE TAILGATE SEAL	Closed	Fully Fit	No	Level 1	20 Nov 2015	N/A	Action	TUM HS GS SOFT TOP
000000-008DCB48	SELURE O/S TAILGATE LANYARD AT BODY	Closed	Fully Fit	No	Level 1	19 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP

000000-008DCB91	REPAIR / REPLACE MAP LIGHT	Closed	Fully Fit	No	Level 1	19 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-00A03524	FUEL FILTER BANJO BOLT SNAPPED	Closed	Non-Taskworthy	No	Level 2	16 Feb 2017	N/A	Failure	TUM HS GS SOFT TOP
000000-009F959E	BATTERIES DISCHARGING REGULARLY, PLEASE INVESTIGATE	Closed	Non-Taskworthy	No	Level 1	23 Jan 2017	N/A	Specific	TUM HS GS SOFT TOP
000000-00A26EF2	FAULTS AS PER 932 DATED 08/03/17	Closed	Non-Taskworthy	No	Level 2	24 May 2017	N/A	Inspection	TUM HS GS SOFT TOP
000000-009BF69C	BATTERIES NOT HOLDING A CHARGE	Closed	Fully Fit	No	Level 1	29 Aug 2016	N/A	Failure	TUM HS GS SOFT TOP
000000-008DCED3	JOB COMPLETE - SECURE N/S INNER WING	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCECD	CLOSE - RENEW REAR BRAKE PADS	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCEC2	COMPLETE. SUPPLY ISSUE. REPLACE A FRAME BALL JOINT	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCC2A	CLOSE - REPLACE NUMBER 2 AND 3 BALL JOINT	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCAB4	COMPLETE, CLOSE ON RECEIPT OF SPARES *DEMISTER LEVER	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-0099688A	6 YEARLY SERVICE	Closed	Fully Fit	No	Level 2	23 May 2016	N/A	Servicing	TUM HS GS SOFT TOP
000000-008C7E6B	Complete, close on receipt of spares, keys lost, replace all locks and ignition barrel	Closed	Fully Fit	No	Level 2	30 Sep 2015	N/A	Non Specific	TUM HS GS SOFT TOP
000000-009BB183	REPLACE O/S/R INNER HUB SEAL	Closed	Non-Taskworthy	No	Level 2	10 Aug 2016	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-009AC4F3	REPLACE U/S SPILL RAIL	Closed	Non-Taskworthy	No	Level 2	05 Jul 2016	N/A	Inspection	TUM HS GS SOFT TOP
000000-009B248E	REPLACE U/S HANDBRAKE CABLE	Closed	Non-Taskworthy	No	Level 2	20 Jul 2016	N/A	Inspection	TUM HS GS SOFT TOP
000000-0089D8B0	CLOSE - REPLACE ALL FRONT ANTI ROLL BAR BUSHES AND UNI JOINTS	Closed	Fully Fit	No	Level 2	05 Jun 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCAEA	RE CERT MEI WITH IN 28 DAYS	Closed	Non-Taskworthy	No	Level 2	25 Jan 2016	N/A	Inspection	TUM HS GS SOFT TOP
000000-009657F8	REPLACE STOP LAMP SWITCH	Closed	Non-Taskworthy	No	Level 2	26 Jan 2016	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCED7	REMOVE SPARE WHEEL VALVE EXTENDER MOD FROM N/S FRONT WHEEL	Closed	Non-Taskworthy	No	Level 1	20 Nov 2015	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-00960D84	Check No2 ball joint torque tightness as per safety notice LE SNVE 00063	Closed	Non-Taskworthy	No	Level 2	000000-000031EF	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-008DCECB	FUEL LEAK AT REAR OF ENGINE	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCEBE	REPLACE FRONT BRAKE DISC AND PADS	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCB22	SECURE BOTH FRONT EYE BROWS	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCB30	ADJUST O/S DOOR/ DOOR LOCK / DOOR STRIKER	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008DCAEF	INVESTAGE WHY SHOE HORN WIEGHT PLATE FITTED TO VEHICLE	Closed	Fully Fit	No	Level 2	20 Nov 2015	N/A	Inspection	TUM HS GS SOFT TOP



000000-008473DA	000000-008473DA	HEADLIGHT GRILL NEEDS FITTING (HOLES NEED MAKING)	Closed	Fully Fit	No	Level 2	15 Oct 2014	N/A	Modification	TUM HS GS
000000-00848845	002FDCC6	REPLACE WINDSCREEN (STONE CHIP)	Closed	Non-Taskworthy	No	Level 1	16 Sep 2014	N/A	Damage	SOFT TOP TUM HS GS SOFT TOP

Work Objects

Serial Number: ME97AA
 NSN: 2320998939963

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL

Working Organisation:
 Repair Section:

Maintenance Event ID	ID	Work Request		Escalate	Maintenance Event Name	Next Due Date	Repair		Work Status	Estimated	
		Work	No				Level	Fault State		Repair Time	Working Organisation
000000-009773CF		No	No	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00	
000000-0080FA37		No	No	No	MEI (2)		Level 2			000:00	
000000-00B9B150		No	No	No	FMT933 (W) Role Equipments (2)*	13 Oct 2020	Level 2	Fully Fit	CL	000:00	
000000-00B9BF60		No	No	No	Annual Brake Test (2)	12 Nov 2020	Level 2	Fully Fit	CL	000:00	
000000-0080FA3A		No	No	No	6 Monthly 6534 Insp		Level 1			000:00	
								Non-			
000000-00A42FE5		No	No	No	6 Monthly 6534 Insp		Level 1	Taskworthy	CL	000:00	
000000-00B9BF5E		No	No	No	Annual Smoke Emissions Test(2)	12 Nov 2020	Level 2	Fully Fit	CL	000:00	
000000-009773C2		No	No	No	MEI (2)		Level 2	Fully Fit	CL	000:00	
000000-0093C9FD		No	No	No	6 Monthly 6534 Insp		Level 1			000:00	
000000-00B9BF62		No	No	No	FMT934 Functional Check (1)*	13 Apr 2020	Level 1	Fully Fit	CL	000:00	
					FMT932 (W) 6 Monthly Safety Inspection (2)	02 Sep 2020	Level 2	Fully Fit	CL	000:00	

000000-00B07AA4	No	MEI (2) FMT932 (W) Mandatory Equipment				Level 2 Taskworthy CL	Non-Taskworthy CL	000:00
000000-00B9B14E	No	Inspection (2)*	13 Oct 2020			Level 2 Fully Fit CL	Fully Fit CL	000:00
000000-008905E4	No	6 Monthly 6534 Insp				Level 1	Non-Taskworthy CL	000:00
000000-0048905E	No	6 Monthly 6534 Insp				Level 1 Taskworthy CL	Taskworthy CL	000:00
000000-0080FA39	No	MEI (2)				Level 2	Non-Taskworthy CL	000:00
000000-0089BF61	No	Annual Headlight Alignment Check (2)	12 Nov 2020			Level 2 Fully Fit CL	Fully Fit CL	000:00
000000-00B9C006	No	FMT930 Landworthiness (AR)				Level 1 Fully Fit CL	Fully Fit CL	000:00
000000-00B9B1B1	No	Annual Brake Test (2)	12 Nov 2020			Level 2 Fully Fit CL	Fully Fit CL	000:00
000000-00705CAA	No	6 Monthly 6534 Insp				Level 1	Non-Taskworthy CL	000:00
000000-00C39A6C	No	FMT932 (W) 6 Monthly Safety				Level 2 Taskworthy CL	Taskworthy CL	000:00
000000-0089062F	No	Inspection (2)	02 Sep 2020			Level 2	Non-Taskworthy CL	000:00
000000-00647A6C	No	6 Monthly 6534 Insp				Level 1	Non-Taskworthy CL	000:00
000000-00647A6C	No	MEI (2)				Level 2 Taskworthy CL	Taskworthy CL	000:00
000000-00B9B1B0	No	Annual Smoke Emissions Test(2)	12 Nov 2020			Level 2 Fully Fit CL	Fully Fit CL	000:00
000000-00647A7A	No	6 Monthly 6534 Insp				Level 1 Taskworthy CL	Non-Taskworthy CL	000:00
000000-00B07AA0	No	6 Monthly 6534 Insp				Level 1 Taskworthy CL	Non-Taskworthy CL	000:00
000000-00528D47	No	6 Monthly 6534 Insp				Level 1	Non-Taskworthy CL	000:00
000000-00B9B1B2	No	Annual Headlight Alignment Check (2)	12 Nov 2020			Level 2 Fully Fit CL	Fully Fit CL	000:00
000000-00489072	No	MEI (2)				Level 2 Taskworthy CL	Non-Taskworthy CL	000:00
000000-00B8C034	No	FMT934 Functional Check (1)*	13 Apr 2020			Level 1 Fully Fit CL	Taskworthy CL	000:00

Work Objects

Serial Number: ME97AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006F6E8B	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F4B8B	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F5A45	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006E2A9F	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Taskworthy	CL	Level 2			000:00
000000-0063BDAB	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Limited Role	CL	Level 2			000:00
000000-0063BDBE	00044	This instruction details the removal of the existing six way lighting switch and the fitting of a seven way lighting switch to all variants including winter water vehicles.		No	3/A	Mod				Fully Fit	CL	Level 2			
000000-0063BD8B	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063BDBA	00030	Front Belt Protection Sleeves		No	1/A	UTI				Fully Fit	CL	Level 2			
000000-0063BDB9	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063BDB7	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Fully Fit	CL	Level 2			
000000-0063BDB6	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063BDB5	00019	Blackout Cover for Warning Light Panel		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063BDB4	00017	Introduction of Battery Retention		No	1/A	UTI				Fully Fit	CL	Level 2			
000000-006410D9	00004	Fitting Emergency Lights, Siren and Harness		No	-/	RTI				Fully Fit	CL	Level 2			
000000-0063BDBF	00042	Fitting a swing away spare wheel carrier, the installation of a spare wheel lifting aid, and the fitting of a rear step.		No	1/A	Mod		31 Oct 2016		Fully Fit					
000000-0063BDBD	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/	RTI				Fully Fit	CL				
000000-0063BDB8	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL				

Work Objects

Serial Number: ME97AA
 NSN: 2320998939963

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL

Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-007491B4	No	No	6 Monthly/10000 Kms	26 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-00AC369B	No	No	6 Monthly/10000 Kms	26 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-00483EED	No	No	OOPS 2 Yearly/20000 Kms Drain	12 Sep 2020	Level 1			000:00		
000000-008906FC	No	No	Engine Oil And Filter Change (1)	25 Sep 2020	Level 1			000:00		
000000-008906FD	No	No	Yearly/20000 Kms	26 Mar 2020	Level 1			000:00		
000000-009E9EB1	No	No	6 Monthly/10000 Kms	26 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-00528D76	No	No	6 Monthly/10000 Kms	26 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-00701A29	No	No	OOPS 6 Yearly/120000 Kms	05 Sep 2022	Level 2	Fully Fit	CL	000:00		
000000-00701A43	No	No	Camshaft Timing Belt (2)	12 Sep 2020	Level 1	Fully Fit	CL	000:00		
000000-005DB20B	No	No	2 Yearly/40000 Kms	05 Sep 2021	Level 1	Non-		000:00		
000000-00961DD1	No	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	26 Mar 2020	Level 1	Taskworthy	CL	000:00		
	No	No	6 Monthly/10000 Kms	26 Mar 2020	Level 1			000:00		

000000-009E9EAF	No	OOPS 2 Yearly/40000 Kms Replace	12 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-009E9EAE	No	Air Cleaner Element (1)	25 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-009E4C8D	No	Yearly/20000 Kms	12 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-00811DC6	No	2 Yearly/40000 Kms	26 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00705C19	No	6 Monthly/10000 Kms	25 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-005E8E630	No	Yearly/20000 Kms	26 Mar 2020	Level 1	Taskworthy	CL	000:00
000000-009E9EB0	No	6 Monthly/10000 Kms	12 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-0046E163	No	OOPS 2 Yearly/20000 Kms Drain	26 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00694AAB	No	Engine Oil And Filter Change (1)	26 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00701A41	No	6 Monthly/10000 Kms	05 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-00705D88	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	12 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-005DBEBD	No	OOPS 2 Yearly/20000 Kms Drain	03 Nov 2020	Level 2	Taskworthy	CL	000:00
000000-00550F0F	No	Engine Oil And Filter Change (1)	25 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-00483EEF	No	OOPS 5 Yearly/155000 Kms Drain	26 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00B85458	No	And Replen Gearbox Oil (2)	26 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00705BFA	No	Yearly/20000 Kms	12 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-00B66676	No	6 Monthly/10000 Kms	25 Sep 2020	Level 1	Fully Fit	CL	000:00
000000-00483EEE	No	6 Monthly/10000 Kms	12 Sep 2020	Level 1	Fully Fit	CL	000:00
		OOPS 2 Yearly/40000 Kms Replace					
		Air Cleaner Element (1)					
		OOPS 2 Yearly/40000 Kms Replace					
		Air Cleaner Element (1)					

1 RIFLES A
COY MT