








<b>Petzl Grillon Climbing Equipment - Lanyards/Temporary Lifelines/Anchors/Hook/MGO</b>	
<b>Aspect</b>	<b>Details</b>
<b>Images</b>	 <p>GRILLON</p> <p>GRILLON HOOK European version</p> <p>GRILLON HOOK international version</p> <p>GRILLON MGO</p> <p>GRILLON anchor</p> <p>GRILLON lifeline</p>
<b>PSD Number</b>	2401-0020
<b>Product Type</b>	Personal protective equipment (PPE) - Climbing Equipment
<b>Product Identifiers</b>	Manufacturing period of affected products: October 2023 to December 2023 Please refer to the Annexes A and B for further details on the affected products.
<b>Product Description</b>	A variety of climbing equipment including an adjustable lanyard, hook, MGO connector and temporary horizontal lifeline.
<b>Country of Origin</b>	France
<b>Counterfeit</b>	No
<b>Risk Level</b>	Not provided
<b>Risk Type</b>	Injuries
<b>Risk Description</b>	<p>The affected products present a risk of injuries as it has been identified that some recently produced products do not perform their blocking function. This is because some of the ropes were mounted incorrectly in the rope adjuster.</p> <p>The affected products do not meet the requirements of the Regulation (EU) 2016/425 on Personal Protective Equipment or the Personal Protective Equipment (Enforcement) Regulations 2018.</p>
<b>Corrective Measures</b>	<p>Petzl have published a safety alert to request inspection of the affected products. For further information, or to ascertain whether your product needs to be inspected, please access the Petzl Safety Alert here: <a href="https://www.petzl.com/GB/en/Professional/recalls/2024-01-04/GRILLON-safety-alert--request-for-inspection">https://www.petzl.com/GB/en/Professional/recalls/2024-01-04/GRILLON-safety-alert--request-for-inspection</a></p>
<b>Online Marketplace</b>	N/A
<b>Notifier</b>	Local Authority Trading Standards.





## Annex A – Affected products names, images and references numbers

Product Name/Description	Image	References
GRILLON Adjustable lanyard for work positioning	 A black adjustable lanyard with a white braided rope and yellow and red connectors.	L052AA00 L052AA01 L052AA02 L052AA03 L052AA04 L052AA05 L052AA06 L052AA07
GRILLON HOOK Adjustable work positioning lanyard with HOOK connector - European version	 A black adjustable lanyard with a white braided rope, a silver hook connector, and a yellow and red connector.	L052BA00 L052BA01
GRILLON HOOK Adjustable work positioning lanyard with HOOK connector - International version	 A black adjustable lanyard with a white braided rope, a silver hook connector, and a yellow and red connector.	L052CA00 L052CA02 L052CA03
GRILLON MGO Adjustable work positioning lanyard with MGO connector	 A black adjustable lanyard with a white braided rope, a silver MGO connector, and a yellow and red connector.	L052DA00



## Product Safety Report

<p>GRILLON Quick adjustment anchor</p>		<p>L052AA00 L052AA01 L052AA02 L052AA03</p>
<p>GRILLON Temporary horizontal lifeline</p>		<p>L052AA03 L052AA04 L052AA05 L052AA06</p>

### **Annex B – List of affected batches**

L052AA00	L052AA01	L052AA02	L052AA03	L052AA04	L052AA05	L052AA06	L052AA07	L052BA00	L052BA01	L052CA00	L052CA02	L052CA03	L052DA00
23J0517607 23J0519467 23J0519789 23J0519843 23J0520091 23J0520408 23J0520925 23J0521146 23J0521254 23J0521675 23J0521677 23J0521774 23J0522352 23J0523764 23J0524116 23J0524538 23J0524545 23J0524887 23K0526089 23K0526090 23K0526091 23K0526491 23K0529769 23K0529775 23K0530087 23K0531184 23K0532226 23L0532899 23L0533162 23L0533582 23L0533860 23L0534102 23L0534103 23L0534595 23L0536435	23J0520409 23J0520683	23J0520926 23J0521777 23J0522738 23J0524111 23J0524539 23J0524890 23K0529770 23L0534434	23J0519790 23J0519844 23J0520886 23J0521255 23J0521775 23J0522353 23J0522743 23J0523129 23J0523389 23J0523761 23J0524112 23J0524543 23J0524885 23K0525335 23K0525338 23K0526487 23K0527007 23K0529771 23K0530084 23K0531185 23L0533163 23L0533167 23L0533861 23L0534431	23J0521252 23J0521537 23J0522739 23J0523125 23J0523131 23J0523390 23J0523762 23J0524113 23J0524869 23J0524886 23K0525334 23K0525339 23K0525546 23K0527006 23K0529772 23K0529776 23K0531186 23K0531515 23L0533164 23L0533857 23L0534110 23L0534432	23J0521253 23J0522740 23J0523130 23J0524114 23J0524540 23K0525340 23K0529777 23L0534433	23J0520684 23L0534382 23L0534589	23J0519240	23J0519845 23J0520410 23J0520682 23J0521256 23J0521535 23J0521678 23J0522354 23J0522741 23J0523126 23J0523387 23J0523759 23J0524117 23J0524544 23J0524889 23K0525337 23K0526488 23K0529773 23K0529778 23K0530613 23K0530614 23K0530615 23K0530616 23K0530617 23K0530618 23K0531187 23L0533165 23L0533583 23L0533862	23J0517609 23J0519469 23J0520411	23J0520944 23J0521776 23J0523763 23L0534113 23L0535451 23L0536001 23L0536437	23J0520685	23J0517610	23J0517611